


OTH-PUR-TH-RF-SKE-A-3519

Brick replacement - Gable to
chimney CS23/ Roof ER02

Revision: -


Date: 7 March 2024

Page 1 of 5
North end of
chimney



Revision: -
Date: 7 March 2024

Page 2 of 5
North end of chimney and east side of wall above gutter



Brick replacement - Gable to chimney CS23/ Roof ER02

Page 3 of 5
East side of wall above gutter




Revision: -
Date: 7 March 2024

OTH-PUR-TH-RF-SKE-A-3519

**Brick replacement - Gable to
chimney CS23/ Roof ER02**

**Page 4 of 5
South side of
gable**



**Revision: -
Date: 7 March 2024**

OTH-PUR-TH-RF-SKE-A-3519

Brick replacement - Gable to chimney CS23/ Roof ER02

Page 5 of 5
South side of gable



Revision: -
Date: 7 March 2024

OTH-PUR-TH-RF-SKE-A-3519