

RWP 98

**Cooper Street courtyard
Repairs behind rainwater
pipes at mosaic locations**

Lift 5 overview

Repair location

**Revision: -
First issue
Date: 30 May 2024**

Page 1 of 2

OTH-PUR-TH-RF-SKE-A-3649

RWP 98

**Cooper Street courtyard
Repairs behind rainwater
pipes at mosaic locations**

Lift 5 bottom

Replace missing render

Mix: 1 part NHL lime : 2 parts aggregate

Lime: St Astier NHL 3.5

Aggregate: Washed Sharp sand

Reinforcement: Bellmix flock polypropylene
fibres 18mm - 500g to 2 kg per tonne



Revision: -

First issue

Date: 30 May 2024

Page 2 of 2

OTH-PUR-TH-RF-SKE-A-3649