


Alterations to Princess Street tower catch pits

OTH-PUR-TH-RF-SKE-A-3451

Page 1 of 2 - RWP 36.1

Fix Expamet stainless steel mesh to brick using nylon plugs and stainless steel washers and screws and render flush with face of stone using lime : sand repair mortar



**Section
through catch
pit**


Sides of drop shaft to new chute to be repaired using sections of reclaimed stone cut to size and fixed with stainless steel dowels and epoxy resin

Alterations to Princess Street tower catch pits

OTH-PUR-TH-RF-SKE-A-3451

Page 2 of 2 - RWP 37.1

Fix Expa'met stainless steel mesh to brick using nylon plugs and stainless steel washers and screws and render flush with face of stone using lime : sand repair mortar



Section
through
catch pit

Sides of drop shaft to new chute to be repaired using sections of reclaimed stone cut to size and fixed with stainless steel dowels and epoxy resin