


NORTH ELEVATION AS PROPOSED



SOUTH ELEVATION AS PROPOSED

S7.3 REMOVE PAINT & ASSESS FOR REPOINTING

S7.1 EAVES LEVEL MASONRY REPAIRS

SOUTHERN SECTION EAST PITCH TO BE RETAINED INSITU AND REPAIRED refer to SCH-REP011

S7.2 REINSTATE RENDER BAND

To be read in conjunction with Schedule of Works (SCH)A002

Do not scale from this drawing - use figured dimensions only.
This design and drawing is the copyright of BB Heritage Studio Ltd and may not be reproduced in any form without prior written consent. Issue of the drawing does not impart any real or implied copyright licence.

revision / description	date
FIRST ISSUE	25.06.26

address	BBH Studio, 17 Cranworth Street, Stalybridge, SK15 2NW
director	Bernadette Bone ARB RIBACA GradDiplConsAA
phone	07813 076325
company #	8862139
web	www.bbheritagestudio.com
email	info@bbheritagestudio.com

project	Clayton Hall: Roof Repairs
client	FoCP & MCC
job no.	0254
drawing title	Repairs North & South Elevations
drawing no.	0254-al(05)036 revision -
drawing scale	1:100 @ A3