

Brick alterations to brickwork at eaves of roof NR03

Remove top courses of brick
to create 25mm ventilation
gap below top of rafter

Revision: -
First issue
Date: 15 July 2024

Page 1 of 3

OTH-PUR-TH-RF-SKE-A-3672

**Brick alterations to brickwork
at eaves of roof NR03**

Remove top courses of brick
to create 25mm ventilation
gap below top of rafter

Revision: -
First issue
Date: 15 July 2024

Page 2 of 3

OTH-PUR-TH-RF-SKE-A-3672

**Brick alterations to brickwork
at eaves of roof NR03**

Remove top courses of brick
to create 25mm ventilation
gap below top of rafter

Revision: -
First issue
Date: 15 July 2024

Page 3 of 3

OTH-PUR-TH-RF-SKE-A-3672