

Chimney CS15 stone repairs at bottom

Fill holes

Fill top of moulding
using mortar repair
mix

Revision: -
First issue
Date: 20 June 2024

OTH-PUR-TH-RF-SKE-A-3700