


Chimney CS17 repairs to bottom



Fill/ mortar repair
delaminated area

Redress delaminated face

500

160

Repoint bottom of chimney

Replace delaminated stone with
new component cut from stone
reclaimed from elsewhere on site

Fill fissure

Revision: -
First issue
Date: 22 July 2024

Page 1 of 4

OTH-PUR-TH-RF-SKE-A-3746

Chimney CS17 repairs to bottom

Repoint
bottom of
chimney

Fill hole

Redress
delaminated
face

Revision: -
First issue
Date: 22 July 2024

Page 2 of 4

OTH-PUR-TH-RF-SKE-A-3746

Chimney CS22 repairs to bottom

Redress
delaminated face

Fill hole

Fill holes

Redress
delaminated
face

Redress
delaminated
face

Revision: -
First issue
Date: 22 July 2024

Page 3 of 4

OTH-PUR-TH-RF-SKE-A-3746

**Chimney CS23
repairs to bottom**



Revision: -
First issue
Date: 22 July 2024

Page 4 of 4

OTH-PUR-TH-RF-SKE-A-3746