


Chimney CS15

Repairs to bottom south side



Fill holes

Redress and tool stone

Fill fissure

Fill recessed and fissures

Remove metal
fixing and fill hole

Revision: -
First issue
Date: 2 September 2024

OTH-PUR-TH-RF-SKE-A-3791