

Chimney CS16
Repairs to bottom north side

Fill hole

Remove bracket and fill holes

Repoint stonework

Fill fissure

Repoint stonework

Revision: -
First issue
Date: 2 September 2024

OTH-PUR-TH-RF-SKE-A-3790

OTH-PUR-TH-RF-SKE-A-3790