


Chimney CS11
Repairs to bottom east side



Redress and
tool stone

Redress and
tool stone

Fill holes

Fill hole

Redress and
tool stone

Fill hole

Revision: -
First issue
Date: 2 September 2024

OTH-PUR-TH-RF-SKE-A-3793