

Chimney CS10

Repairs to bottom south side

Tidy up pointing/ re-point

Re-dress and tool delaminated stone

Remove eye bolt and fill hole

Revision: -
First issue
Date: 12 September 2024

OTH-PUR-TH-RF-SKE-A-3802