

## Chimney CS09

### Repairs to bottom west side



Remove metal  
fixing and fill  
hole

Re-dress and tool  
delaminated stone

Repoint area of  
unsatisfactory/ poor  
quality pointing

Fill holes

Fill holes

Remove eye bolt  
and fill hole

Revision: -  
First issue  
Date: 12 September 2024

OTH-PUR-TH-RF-SKE-A-3801