

**Roof WCR10
catch pit to
rainwater pipe 83**



**Remove bricks between
principal rafter and drip and
continue boarding into gap**

**Revision: -
First issue
Date: 18 November 2024**

OTH-PUR-TH-RF-SKE-A-3869