

Decorations

- Bespoke scheme - Refer to OTH-PUR-TH-ZZ-RPT-0116
- C1 - Scheme for Tiled Cores
- C2 - Historic Scheme for Corridors
- Lift interior - Refer to ANSA information
- Link Corridor
- No paint
- Refer to Taylor Design - Type 1/Whiterock
- Refer to Taylor Design - Type 2/Paint
- S1 - Simple Scheme for Plant Rooms, Stores, ETC
- S1P - As S1 with Painted Skirting
- S2 - Scheme for Offices, Meeting Rooms, ETC
- T1 - Toilet Areas
- UPR1 - Scheme for Celebratory Unique Purpose Rooms
- UPR2 - Scheme For Middle Unique Purpose Rooms
- VHS
- VHS spaces - Refer to VHS decoration scheme

Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for key references, specification references, and colours.

For Taylor design information refer to Drawings - 00230, 00231, 00232

Scale Bars to be used as guidance only - refer to sheet size below

1:100	mm	1000		3000		5000		7000
1:200	mm	5000		8000		12000		16000
1:500	M	5		15		25		35
1:1250	M	10		30		50		70		90

Notes:
Drawings are based on survey data and may not accurately represent what is physically present.
Do not scale from this drawing. All dimensions are to be verified on site before proceeding with the work.
All dimensions are in millimeters unless noted otherwise.
Purcell shall be notified in writing of any discrepancies.

Key Plan

ISSUE	DATE	APPROVED	DRAWN	DESCRIPTION
08	19/01/2026	RS	JB	Decorations Scheme Updated to Refer to Taylor Design's Scheme, References to Taylors Schemes Added, Scheme for GF-038 Ammended
07	29/08/2025	RS	DA/AH	RFC Amendments to Decorations Scheme Plans

OUR TOWN HALL PROJECT
PURCELL
Project Office, Room 308, Town Hall, MANCHESTER M60 2LI
+44 (0) 7970 097 432
www.purcelluk.com

PROJECT STATUS	RIBA STAGE 5
CLIENT	Manchester City Council
PROJECT	OUR TOWN HALL
DRAWING TITLE	Decorations scheme plans - Level 01
SIZE & SCALE	A1: 1 : 200
DRAWING STATUS	CONSTRUCTION
JOB NUMBER	236959
DRAWING NO.	REV
OTH-PUR-TH-01-DWG-A-2802	08

© PURCELL 2019. PURCELL ® IS THE TRADING NAME OF PURCELL ARCHITECTURE LTD.

DECORATIONS PLANS PROPOSED LEVEL 01
1 : 200

Note: Some room tags may be missing or displaying incorrectly, due to ongoing model updates. These will be corrected for the next issue.