OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C04, 06-001, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

For NBS specification M60 refer to document: OTH-PUR-TH-ZZ-SPE-A-5906. For decoration schemes refer to OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. For locations of paints, refer to decorations scheme drawings OTH-PUR-TH-ZZ-DWG-A-2800-07.

Number	Name	Level	Paint Scheme	Decorations scheme type	PUR_Fit-Out Level	Area	Perimeter	PUR_Fit_Out_Ceiling	PUR_Fit_Out_Cornice Finish	PUR_Fit_Out_Beam Casing Finish	PUR_Fit_Out_Wall Finish	PUR_Fit_Out_Other Timber finishes	PUR_Fit_Out_Skirting	PUR_Blind_Box_Finish	PUR_Perimeter_Box_Finish	Notes:
01-001	Conference Hall	01		VHS	RES-01	280 m²	86354			For VHS rooms refer to Specialist Decorations Package					n/a	
01-001a	Lobby	01		VHS	RES-01	7 m²	11671			For VHS rooms refer to Specialist Decorations Package					n/a	
01-002	Ante Room	01		VHS	RES-01	33 m²	23613			For VHS rooms refer to Specialist Decorations Package					n/a	
01-003	Parlour	01		VHS	RES-01	158 m²	52072			For VHS rooms refer to Specialist Decorations Package					n/a	
01-004	Tower Room	01		VHS	RES-01	96 m²	51824			For VHS rooms refer to Specialist Decorations Package					n/a	
01-005	Reception Room	01		VHS	RES-01	151 m²	54953			For VHS rooms refer to Specialist Decorations Package					n/a	
01-006	Banqueting Room	01		VHS	RES-01	224 m²	78256			For VHS rooms refer to Specialist Decorations Package					n/a	
01-007	Finishing Kitchen	01		S1	CAT-01	24 m²	20408	Conduct repairs only. No redecorations.	Conduct repairs only. No redecorations.	Conduct repairs only. No redecorations.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours Uncrusta wallpaper to be painted with new economical paint finish NBS M60 112A.	n/a	3.6.5 New coved skirtings. NBS M50 770A/770B		n/a	
01-008	Still Room	01		S1	CAT-01	21 m²	18455	Conduct repairs only. No redecorations.	Conduct repairs only. No redecorations.	Conduct repairs only. No redecorations.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.5 New coved skirtings. NBS M50 770A/770B		n/a	
01-009	MCC/ Public Meeting Room	01	PS01	UPR2	OFF-01	54 m²	30531	1.2.4 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Strapwork to receive gold gilding as per NBS M60 190	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted in accordance with NBS M60 120A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	n/a	
01-009a	Heritage WC	01		T1	WC-01	3 m²	6869	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-009b	Heritage WC	01		T1	WC-01	3 m²	6761	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-010	Ante Room	01		UPR2	OFF-01	23 m²	19618	1.1.3 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-010a	Heritage WC	01		T1	WC-01	3 m²	6368	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-010b	Heritage WC	01		T1	WC-01	3 m²	7321	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-011	MCC/ Public Meeting Room	01	PS01	UPR2	OFF-01	32 m²	23299	1.2.4 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Strapwork to receive gold gilding as per NBS M60 190	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	n/a	
01-012	Breakout Suites	01		S2	OFF-01	31 m²	23766	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
01-013	Breakout Suites	01		S2	OFF-01	26 m²	21009	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
01-014	Breakout Suites	01		S2	OFF-01	37 m²	26423	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted in accordance with NBS M60 120A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
01-015	Male Washroom	01		T1	WC-02	20 m²	23973	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-015a	Lobby	01		S1	WC-02	6 m²	10279	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-015b	Accessible WC - Left	01		T1	WC-02	6 m²	9440	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-016	Female Washroom	01		T1	WC-02	22 m²	25299	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-017	Public Waiting Room	01	PS01	S2	OFF-01	46 m²	28182	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
01-018	Public Waiting Room	01	PS01	S2	OFF-01	36 m²	25946	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
01-019	Registrar Ceremony Room	01		UPR1	UPR-01	153 m²	58315	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, prepare (sanding existing painted finish) and redecorate all skirting with new eggshell painted finish. Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours. M60-111A.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
01-019a	Bridal Room	01		UPR1	UPR-01	11 m²	14446	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, prepare (sanding existing painted finish) and redecorate all skirting with new eggshell painted finish. M60-111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.		n/a	
01-020	MCC/Public Meeting Room	01	PS01	S2	OFF-01	33 m²	23252	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Ceiling colour to extend to picture rail	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	Ceiling colour to extend to picture rail
01-021	Catering Changing Rooms	01		S1	WC-02	36 m²	24891	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.4 Remove existing skirtings and replace with coved tiling to match floor finish. NBS M40 114		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
01-022	Catering Changing Rooms	01		S1	WC-02	33 m²	24448	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.4 Remove existing skirtings and replace with coved tiling to match floor finish. NBS M40 114		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
01-022a	Catering Circulation	01		S1	CIR-04	10 m²	14031	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-022b	2no. M WCs +1no. Shower	01		T1	WC-02	8 m²	25919	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-022c	2no. F WCs +1no. Shower	01		T1	WC-02	8 m²	15835	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-023	Glassware Store	01		S1	CAT-02	39 m²	25832	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.5 New coved skirtings. NBS M50 770A/770B		n/a	

OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C04, 06-003, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

01-024	Pot Wash	01		S1	CAT-01	33 m²	24046	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-025	China and Crockery Store	01		S1	CAT-02	26 m²	20527	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.5 New coved skirtings. NBS M50 770A/770B		n/a	
01-026	Committee Room 1	01		Committee rooms - Refer to OTH-PUR-ZZ-RPT-A-0116	UPR-01	72 m²	36532	1.2.4 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Strapwork to receive gold gilding as per NBS M60 190	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.9 Following repairs, plaster walls to recieve new economical paint finish NBS M60 112B, M60 112C, M60 112D in specialist paint scheme. Allow 1no. basecoat and 2no. finishing coats for each colour. Refer to OTH-PUR-TH-ZZ-RPT-A-0116 decorations report for specialist paint scheme. Decorative Lincrusta. Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.1 Following repairs, redecorate all timber skirting with new shellac finish NBS M60 162.	New blind boxes to be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours. Existing blind boxes to be painted in accordance with NBS M60 120A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	n/a	Decorative Lincrusta. Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours M60 507* specification for paint removal and cleaning applies to this room and can be added to the decoration report
01-027	Committee Room 2	01		Committee rooms - Refer to OTH-PUR-ZZ-RPT-A-0116	UPR-01	78 m²	36929	1.2.4 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Strapwork to receive gold gilding as per NBS M60 190	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.11 Following repairs, plaster walls to receive new economical paint finish NBS M60 112D in specialist paint scheme. Allow 1no. basecoat and 2no. finishing coats for each colour. Refer to OTH-PUR-TH-ZZ-RPT-A-0116 decorations report for specialist paint scheme	n/a	3.6.1 Following repairs, redecorate all timber skirting with new shellac finish NBS M60 162.	To be painted in accordance with NBS M60 120A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	n/a	
01-028	Committee Room 3	01		Committee rooms - Refer to OTH-PUR-ZZ-RPT-A-0116	UPR-01	62 m²	33992	1.2.4 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Strapwork to receive gold gilding as per NBS M60 190	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.12 Following repairs, plaster walls to receive new economical paint finish NBS M60 112C in specialist paint scheme. Allow 1no. basecoat and 2no. finishing coats for each colour. Refer to OTH-PUR-TH-ZZ-RPT-A-0116 decorations report for specialist paint scheme	n/a	3.6.1 Following repairs, redecorate all timber skirting with new shellac finish NBS M60 162.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	n/a	M60 507* specification for paint removal and cleaning applies to this room and can be added to the decoration report
01-028a	FM/ Housekeeping/ Building Services Storage	01		S1	ACC-01	2 m²	5343	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-028b	AV Rack Room & ICT Cabinet	01		S1	ACC-01	3 m²	8647	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-029	Furniture Store	01		S1	STO-03	51 m²	28480	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
01-030	AV Rack Room	01		S1	PLA-01	4 m²	9250	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-031	Unisex WC	01		T1	WC-02	8 m²	13633	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-032	1no. A WC	01		T1	WC-02	6 m²	9792	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-033	Great Hall	01		VHS	RES-01	447 m²	112094	Refer to Architect drawings: OTH-PUR-TH-01-DWG-A-5441 - 5449 and refer to Repair schedule OTH-PUR-TH-01-SCH-A-5915.	Refer to Architect drawings: OTH-PUR-TH-01-DWG-A-5441 - 5449 and refer to Repair schedule OTH-PUR-TH-01-SCH-A-5915.	Refer to Architect drawings: OTH-PUR-TH-01-DWG-A-5441 - 5449 and refer to Repair schedule OTH-PUR-TH-01-SCH-A-5915.	Refer to Architect drawings: OTH-PUR-TH-01-DWG-A-5441 - 5449 and refer to Repair schedule OTH-PUR-TH-01-SCH-A-5915.	Refer to Architect drawings: OTH-PUR-TH-01-DWG-A-5441 - 5449 and refer to Repair schedule OTH-PUR-TH-01-SCH-A-5915.	Refer to Architect drawings: OTH-PUR-TH-01-DWG-A-5441 - 5449 and refer to Repair schedule OTH-PUR-TH-01-SCH-A-5915.		n/a	
01-033a	Great Hall Stage	01		VHS	RES-01	26 m²	24153	Refer to Architect drawings: OTH-PUR-TH-01-DWG-A-5441 - 5449 and refer to Repair schedule OTH-PUR-TH-01-SCH-A-5915.	Refer to Architect drawings: OTH-PUR-TH-01-DWG-A-5441 - 5449 and refer to Repair schedule OTH-PUR-TH-01-SCH-A-5915.	Refer to Architect drawings: OTH-PUR-TH-01-DWG-A-5441 - 5449 and refer to Repair schedule OTH-PUR-TH-01-SCH-A-5915.	Refer to Architect drawings: OTH-PUR-TH-01-DWG-A-5441 - 5449 and refer to Repair schedule OTH-PUR-TH-01-SCH-A-5915.	Refer to Architect drawings: OTH-PUR-TH-01-DWG-A-5441 - 5449 and refer to Repair schedule OTH-PUR-TH-01-SCH-A-5915.	Refer to Architect drawings: OTH-PUR-TH-01-DWG-A-5441 - 5449 and refer to Repair schedule OTH-PUR-TH-01-SCH-A-5915.		n/a	
01-034	Cleaners Store	01		No paint	ACC-01	0 m²	0	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-035	Male Washroom	01		T1	WC-02	17 m²	19388	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-035a	Cleaner	01		T1	WC-02	0 m²	0	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-035a	Cleaner	01		T1	WC-02	2 m²	6523	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-036	Accessible WC - Left	01		T1	WC-02	6 m²	10204	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-037	Female Washroom	01		T1	WC-02	23 m²	21269	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-038	FM/ Housekeeping/ Building Services Storage	01		S1	STO-03	4 m²	16817	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-039	Catering Kitchen	01		S1	CAT-01	167 m²	86193	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.6.1 New 'box within box' perimeter partitions to be lined on inside face with 2.5mm Altro Whiterock EU Grade Extruded PVC sheet in white satin fixed with Altrofix panel adhesive. Altro bonded to 19mm marine plywood. All angles and corner bends to be thermoformed on site transition strip to coving required. NBS M50 160A	n/a	3.6.5 New coved skirtings. NBS M50 770A/770B		n/a	
01-040	FM/ Housekeeping/ Building Services Storage	01		S1	STO-03	3 m²	6873	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-041	FM/ Housekeeping/ Building Services Storage	01		S1	ACC-01	4 m²	8174	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-C01	Albert Square Corridor	01		No paint	RES-02	335 m²	156563	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-C01a	Lobby	01		No paint	RES-01	13 m²	14369	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-C01b	Lobby	01		C2	WC-02	7 m²	11195	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 113A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-C01c	Lobby	01		UPR2	RES-01	4 m²	7985	1.1.3 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-C01d	Bees Landing	01		No paint	RES-02	104 m²	44270	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-C01e	Albert Square Lift Lobby	01		S1	COR-02	16 m²	27311	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-C01f	Protected Cores Lobby	01		C1	COR-02	36 m²	31903	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	Stair soffits and stubs to be painted wit
01-C01g	ICT Cabinet	01		No paint	ACC-01	2 m²	6015	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-C01h	AV Rack Room	01		No paint	ACC-01	2 m²	5791	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-C02	Princess Street Corridor	01		No paint	RES-02	295 m²	169744	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-C02b	Lobby	01		C2	CAT-01	19 m²	24827	Conduct repairs only. No redecorations.	Conduct repairs only. No redecorations.	Conduct repairs only. No redecorations.	2.6.1 New 'box within box' perimeter partitions to be lined on inside face with 2.5mm Altro Whiterock EU Grade Extruded PVC sheet in white satin fixed with Altrofix panel adhesive. Altro bonded to 19mm marine plywood. All angles and corner bends to be thermoformed on site transition strip to coving required. NBS M50 160A	n/a	3.6.5 New coved skirtings. NBS M50 770A/770B		n/a	
01-C02c	Lobby	01		UPR2	OFF-01	13 m²	14911	1.1.3 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-C02d	Lobby	01		S2	OFF-01	10 m²	14717	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-C02e	Lobby	01		S1	WC-02	13 m²	15148	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-C02h	Circulation	01		No paint	RES-02	26 m²	28247	No paint	n/a	No paint	No paint	n/a	No paint		n/a	

OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C04, 06-001, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

01-C02i	WC Lobby	01		T1	WC-02	5 m²	9254	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-C02j	WC Lobby	01		T1	WC-02	5 m²	9934	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-C03	Lloyd Street Corridor	01		No paint	RES-02	77 m²	59622	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-C03b	Protected Cores Smoke Lobby	01		S1	COR-02	10 m²	15169	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-C04	Lloyd Street Corridor	01		No paint	RES-02	229 m²	149361	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-C04a	Goods Lift Lobby	01		C1	COR-02	19 m²	32526	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
01-C04b	Lobby	01		T1	CIR-04	43 m²	39891	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
01-C04c	Public Circulation	01		No paint	RES-02	17 m²	21840	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-C04d	Circulation	01		No paint	RES-02	2 m²	6162	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-C04e	Protected Cores Smoke Lobby	01		C1	COR-02	12 m²	20418	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
01-C04f	Lobby	01		C1	COR-02	8 m²	14198	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
01-C04e	Lobby	01		No paint	CIR-04	43 m²	40590	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-C05a	Corridor	01		S1	CAT-01	3 m²	6955	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.6.1 New 'box within box' perimeter partitions to be lined on inside face with 2.5mm Altro Whiterock EU Grade Extruded PVC sheet in white satin fixed with Altrofix panel adhesive. Altro bonded to 10mm marine plywood. All angles and corner bends to be thermoformed on site transition strip to coving required. NBS M50 160A	n/a	3.6.5 New coved skirtings. NBS M50 770A/770B		n/a	
01-C05b	Corridor	01		S1	CAT-01	3 m²	7153	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.6.1 New 'box within box' perimeter partitions to be lined on inside face with 2.5mm Altro Whiterock EU Grade Extruded PVC sheet in white satin fixed with Altrofix panel adhesive. Altro bonded to 10mm marine plywood. All angles and corner bends to be thermoformed on site transition strip to coving required. NBS M50 160A	n/a	3.6.5 New coved skirtings. NBS M50 770A/770B		n/a	
01-L01	Lloyd Street Lift	01		No paint	ACC-01	10 m²	12384	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-L03	Albert Square Lift	01		No paint	ACC-01	9 m²	11910	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-L04	Princess Lift	01		No paint	ACC-01	5 m²	9020	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-L05	Cowgar Lift	01		No paint	ACC-01	6 m²	10030	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-L08	Stage Platform Lift	01		No paint	ACC-01	2 m²	5118	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-001	Conference Hall Gallery	01		VHS	RES-01	69 m²	59439	Conduct repairs only. No redecorations.	Conduct repairs only. No redecorations.	Conduct repairs only. No redecorations.	Conduct repairs only. No redecorations.	n/a	Conduct repairs only. No redecorations.		n/a	
01-R01	Riser	01		No paint	ACC-01	3 m²	6825	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R03	Riser	01		No paint	ACC-01	3 m²	7178	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R04	Riser	01		No paint	ACC-01	1 m²	5777	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R05	Riser	01		No paint	ACC-01	1 m²	5125	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R07	Riser	01		No paint	ACC-01	6 m²	9864	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R08	Riser	01		No paint	ACC-01	0 m²	0	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R09	Riser	01		No paint	ACC-01	1 m²	4830	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R10	Riser	01		No paint	ACC-01	0 m²	1720	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R11	Riser	01		No paint	ACC-01	0 m²	0	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R13	Riser	01		No paint	ACC-01	3 m²	9883	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R14	Riser	01		No paint	ACC-01	1 m²	3710	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R15	Riser	01		No paint	ACC-01	1 m²	3609	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R16	Riser	01		No paint	ACC-01	1 m²	4053	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R17	Riser	01		No paint	ACC-01	2 m²	5820	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R18	Riser	01		No paint	ACC-01	2 m²	6439	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R19	Riser	01		No paint	ACC-01	1 m²	4914	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R19a	Riser	01		No paint	ACC-01	0 m²	1997	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R20	Riser	01		No paint	ACC-01	9 m²	13734	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R21	Riser	01		No paint	ACC-01	3 m²	8486	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R23	Riser	01		No paint	ACC-01	3 m²	8214	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R26	Riser	01		No paint	ACC-01	3 m²	8093	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R28	Riser	01		No paint	ACC-01	1 m²	4100	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R29	Riser	01		No paint	ACC-01	1 m²	5914	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-R30	Riser	01		No paint	ACC-01	0 m²	0	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-S01	Staircase 01	01		No paint	RES-02	30 m²	28597	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-S02	Grand Staircase	01		No paint	RES-01	43 m²	35652	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-S03	Grand Staircase	01		No paint	RES-01	66 m²	36354	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-S04	Princess Street Spiral Staircase	01		No paint	RES-02	30 m²	21101	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-S05	Protected Cores Evacuation Staircase	01		C1	COR-01	38 m²	33631	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
01-S06	Protected Cores Evacuation Staircase	01		No paint	COR-01	45 m²	31374	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-S07	Staircase 07	01		No paint	RES-02	40 m²	22838	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-S08	Protected Cores Evacuation Staircase	01		C1	COR-02	28 m²	24628	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
01-S09	Staircase 09	01		No paint	CIR-03	39 m²	28266	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
01-S10	Protected Cores Evacuation Staircase	01		C1	COR-02	24 m²	20403	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
01-S11	Protected Cores Evacuation Staircase	01		S1P	CIR-04	19 m²	21257	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112B, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
02-001	Accessible WC - Right	02		T1	WC-02	5 m²	9198	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
02-002	Meeting Room	02		Lord Mayors rooms - Refer to OTH-PUR-OTH-ZZ-RPT-A-0116	UPR-01	75 m²	40505	1.1.3 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.8 Following repairs, plaster walls to receive new wallpaper to NBS M60-680. Refer to OTH-PUR-TH-ZZ-RPT-A-0116 decorations report for specialist paint scheme	n/a	3.6.4 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-003	Meeting Room	02		S2	UPR-01	85 m²	42562	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.10 Following repairs, walls to receive wallpaper as per NBS M60-680. Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	n/a	3.6.4 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report		n/a	
02-004	Meeting Room	02	F502	S2	OFF-01	56 m²	32350	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-005	MCC Circulation	02	F502	S2	OFF-01	19 m²	18907	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
02-005a	MCC Meeting Room	02	F502	S2	OFF-01	22 m²	19552	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-006	Support	02		S2	OFF-01	51 m²	30651	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-007	Office	02	F502	S2	OFF-01	47 m²	30839	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-008	SMT Welfare	02		S2	WC-02	17 m²	17961	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	

OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C04, 06-003, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

02-008a	Accessible WC - Right	02		T1	WC-02	5 m²	9122	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
02-010	SMT Support	02		S2	OFF-01	85 m²	43248	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-011	Meeting Room	02	PS02	S2	OFF-01	36 m²	25701	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-012	SMT Office	02	PS02	S2	OFF-01	165 m²	57633	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted in accordance with NBS M60 120A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-013	Meeting Room	02	PS02	S2	OFF-01	33 m²	23569	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-014	Office	02	PS02	S2	OFF-01	36 m²	29032	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted in accordance with NBS M60 120A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-015	Support	02		S2	OFF-01	33 m²	24185	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-016	Accessible WC - Right	02		T1	WC-02	6 m²	10515	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	n/a	
02-017	Office	02	PS02	S2	OFF-01	38 m²	25366	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-018	Meeting Room	02	PS02	S2	OFF-01	40 m²	26745	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-019	Welfare	02		S2	WC-02	35 m²	24956	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-020	Office	02	PS02	S2	OFF-01	70 m²	33686	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-021	Support	02		S2	OFF-01	78 m²	42196	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted in accordance with NBS M60 120A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-022	Meeting Room	02	PS02	S2	OFF-01	69 m²	33551	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-023	Office	02	PS02	S2	OFF-01	51 m²	32242	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
02-024	Accessible WC - Left	02		T1	WC-02	6 m²	10283	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
02-025	MCC Storage	02		S1	ACC-01	1 m²	4707	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
02-026	Plant Room	02		No paint	ACC-01	10 m²	14805	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-026a	Plant Room	02		No paint	ACC-01	3 m²	8622	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-027	Accessible WC - Left	02		T1	WC-01	5 m²	9266	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
02-028	Organ chamber	02		O1	ACC-01	27 m²	23833	1.1.5 Redecorate with new economical paint finish NBS M60 112B. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	1.1.6 Following repairs, Redecorate with new economical paint finish NBS M60 112B. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint		n/a	
02-029	Male Washroom - Heritage	02		T1	WC-01	33 m²	31451	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
02-029a	Cleaners Store	02		No paint	ACC-01	1 m²	5489	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-030	Female Washroom - Heritage	02		T1	WC-01	41 m²	35488	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
02-031	MCC Storage	02		S1	ACC-01	3 m²	7179	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
02-032	Storage	02		S1	ACC-01	4 m²	7668	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
02-033	MCC Storage	02		S1	STO-03	10 m²	14593	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
02-C01	Protected Cores Lift Lobby	02		C1	COR-02	32 m²	33246	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
02-C02	Princess Street Corridor	02		C2	CIR-02	198 m²	138299	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 113A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
02-C02a	Circulation	02		C2	CIR-02	13 m²	14247	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
02-C02b	Circulation	02		S1	WC-02	9 m²	12173	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
02-C03	MCC Circulation	02		C2	CIR-02	73 m²	43997	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 113A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
02-C03a	Protected Cores Smoke Lobby	02		S2	COR-02	12 m²	17806	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	

OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C04, 06-001, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

02-C03b	MCC Circulation	02		S1	WC-02	22 m²	29662	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
02-C04	MCC Circulation	02		C2	CIR-02	177 m²	124581	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 111A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
02-C04a	MCC Circulation	02		S2	CIR-04	36 m²	25635	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
02-C04b	Lobby	02		No paint	CIR-03	7 m²	11978	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-C04b	Lloyd Street Link Bridge	02		S2	CIR-04	29 m²	30723	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
02-C04c	Circulation	02		C2	CIR-02	25 m²	22553	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 111A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
02-C04d	Protected Cores Smoke Lobby	02		C1	COR-02	12 m²	18354	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
02-C04e	Protected Cores Smoke Lobby	02		C1	COR-02	9 m²	14089	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
02-C04f	Protected Cores Smoke Lobby	02		C1	COR-02	7 m²	12818	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
02-C04g	Lloyd Street Link Bridge	02		C1	CIR-04	29 m²	37358	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
02-C05	Circulation	02		No paint	CIR-02	32 m²	37308	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-C05a	Circulation	02		No paint	ACC-01	10 m²	15150	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-L01	Lloyd Street Lift	02		No paint	ACC-01	10 m²	12385	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-L04	Princess Lift	02		No paint	ACC-01	6 m²	9624	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-L05	Cooper Lift	02		No paint	ACC-01	6 m²	10005	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R01	Riser	02		No paint	ACC-01	1 m²	6776	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R03	Riser	02		No paint	ACC-01	1 m²	7178	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R04	Riser	02		No paint	ACC-01	1 m²	6987	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R05	Riser	02		No paint	ACC-01	1 m²	5125	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R07	Riser	02		No paint	ACC-01	6 m²	9962	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R08	Riser	02		No paint	ACC-01	1 m²	5144	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R13	Riser	02		No paint	ACC-01	5 m²	20998	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R14	Riser	02		No paint	ACC-01	1 m²	7446	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R15	Riser	02		No paint	ACC-01	1 m²	5398	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R16	Riser	02		No paint	ACC-01	1 m²	4055	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R17	Riser	02		No paint	ACC-01	2 m²	8830	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R18	Riser	02		No paint	ACC-01	2 m²	8998	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R19	Riser	02		No paint	ACC-01	2 m²	9802	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R19a	Riser	02		No paint	ACC-01	0 m²	2467	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R20	Riser	02		No paint	ACC-01	1 m²	5341	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R21	Riser	02		No paint	ACC-01	1 m²	3866	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R23	Riser	02		No paint	ACC-01	2 m²	5349	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R26	Riser	02		No paint	ACC-01	1 m²	4653	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R28	Riser	02		No paint	ACC-01	1 m²	3857	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R29	Riser	02		No paint	ACC-01	1 m²	5764	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R30	Riser	02		No paint	ACC-01	1 m²	4701	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R30a	Riser	02		No paint	ACC-01	1 m²	3841	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-R31	Riser	02		No paint	WC-02	1 m²	5845	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-S01	Lloyd Street Spiral Staircase	02		No paint	RES-02	30 m²	20597	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-S04	Princess Street Spiral Staircase	02		No paint	RES-02	30 m²	21101	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-S05	Protected Cores Evacuation Staircase	02		C1	COR-01	33 m²	25637	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
02-S06	Protected Cores Evacuation Staircase	02		n/a	COR-01	47 m²	30125	Conduct repairs only. No redecorations.	n/a	n/a	Cleaning & repairs to terracotta. Refer to Repair package	n/a	Cleaning & repairs to stonework. Refer to Repair package.		n/a	
02-S07	Cooper Street Spiral Staircase	02		No paint	RES-02	36 m²	22274	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
02-S08	Protected Cores Evacuation Staircase	02		C1	COR-02	28 m²	29895	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
02-S09	Staircase 09	02		C2	CIR-03	37 m²	26836	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 111A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
02-S11	Protected Cores Evacuation Staircase	02		S1P	CIR-03	19 m²	26457	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
03-001	Coroners Court - Non-Jury	03		UPR3	UPR-01	111 m²	46969	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	Historic decoration to be retained and left exposed
03-002	Waiting Room	03		C2	CIR-04	30 m²	23106	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 111A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
03-003	Accessible WC - Right	03		T1	WC-02	6 m²	9626	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
03-004	Accessible WC - Left	03		T1	WC-02	5 m²	16134	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
03-005	Accessible WC - Right	03		T1	WC-02	7 m²	11350	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
03-006	All Gender WC	03		T1	WC-02	5 m²	8699	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
03-007	Area Coroner's Office	03	PS03	S2	OFF-01	17 m²	17766	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
03-008	Coroner's Office	03	PS03	S2	OFF-01	20 m²	21777	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	

OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C04, 06-003, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

03-010	Medical Examiner's Office	03	PS03	S2	OFF-01	16 m²	18943	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
03-011	First Officer's Office	03	PS03	S2	OFF-01	21 m²	20233	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted in accordance with NBS M60 120A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
03-012	Coroner's Staff Office Storage	03		S2	STO-03	43 m²	27359	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	New blind boxes to be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours. Existing blind boxes to be painted in accordance with NBS M60 120A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	
03-013	Coroner's Staff Office	03	PS03	S2	OFF-01	151 m²	58075	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
03-014	Office	03	PS03	S2	OFF-01	82 m²	48616	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
03-014a	Office	03	PS03	S2	OFF-01	8 m²	17038	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
03-015	Silver Room	03		S2	UPR-01	43 m²	25541	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
03-016	Pantry	03		S1	STO-01	27 m²	19653	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	n/a	
03-017	Business Hub	03		No paint	STO-03	6 m²	11236	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
03-018	Private Sitting Room	03	PS03	S2	OFF-01	27 m²	23600	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
03-019	Protocol Office with Meeting Room	03	PS03	S2	OFF-01	31 m²	25549	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
03-019a	Storage	03		No paint	OFF-01	7 m²	10840	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
03-020	General Staff Office with Storage	03	PS03	S2	OFF-01	37 m²	25421	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	n/a	
03-021	Lord Mayors room - Refer to OTH-PUT-TH-RPT-A-0116	03		Lord Mayors	RES-01	44 m²	27268	1.2.4 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Strapwork to receive gold gilding as per NBS M60 190	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.8 Following repairs, plaster walls to receive new wallpaper in NBS M60-680. Refer to OTH-PUR-TH-ZZ-RPT-A-0116 decorations report for specialist paint scheme	n/a	3.6.4 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report		n/a	
03-022	Lord Mayors room - Refer to OTH-PUT-TH-RPT-A-0116	03		Lord Mayors	RES-01	36 m²	23981	1.2.4 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Strapwork to receive gold gilding as per NBS M60 190	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.8 Following repairs, plaster walls to receive new wallpaper in NBS M60-680. Refer to OTH-PUR-TH-ZZ-RPT-A-0116 decorations report for specialist paint scheme	n/a	3.6.4 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report		n/a	
03-023	Banqueting/Reception	03		No paint	RES-01	42 m²	25772	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
03-023a	Store	03		No paint	STO-03	8 m²	17961	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
03-024	Office	03		S2	UPR-01	42 m²	25372	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
03-025	Private Bathroom	03		T1	WC-02	15 m²	18692	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
03-025a	WC	03		T1	UPR-01	3 m²	6905	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
03-026	1no. A WC	03		T1	WC-02	5 m²	9287	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
03-027	Breakout Room	03		S1	WC-02	13 m²	15098	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
03-028	Forward Kitchen	03		S2	CAT-01	18 m²	18346	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
03-C01	Circulation	03		C2	CIR-04	151 m²	84172	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 113A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
03-C01a	WC Lobby	03		S1	CIR-04	6 m²	11058	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
03-C01b	Coroner's Welfare	03		S2	WC-02	19 m²	18546	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
03-C01c	Corridor	03		C2	CIR-04	7 m²	10710	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 113A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
03-C01d	MCC Circulation	03		S2	CIR-04	84 m²	50623	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
03-C01e	Corridor	03		S2	CIR-04	41 m²	50736	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
03-C01f	Corridor	03		C1	CIR-04	5 m²	9301	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	Stair soffits and stubs to be painted wit
03-C01g	Corridor	03		Lord Mayors rooms - Refer to OTH-PUR-OTH-ZZ-RPT-A-0116	CIR-04	16 m²	18587	1.1.4 Redecorate with new economical paint NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 110A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
03-C01h	Protected Cores Lift Lobby	03		C1	COR-02	9 m²	15400	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
03-C04	Protected Cores Smoke Lobby	03		C1	COR-02	10 m²	14858	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
03-C04a	Protected Cores Smoke Lobby	03		C1	COR-02	6 m²	12123	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
03-C04b	Protected Cores Smoke Lobby	03		C1	COR-02	6 m²	9977	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
03-L04	Princess Lift	03		No paint	ACC-01	5 m²	9018	No paint	n/a	No paint	No paint	n/a	No paint		n/a	

OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C04, 06-003, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

03-R01	Riser	03		No paint		1 m²	4890	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
03-R03	Riser	03		No paint	ACC-01	3 m²	7411	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
03-R05	Riser	03		No paint	ACC-01	1 m²	5874	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
03-R07	Riser	03		No paint	ACC-01	2 m²	10845	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
03-R08	Riser	03		No paint	ACC-01	1 m²	5679	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
03-R09	Riser	03		No paint	ACC-01	2 m²	8031	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
03-R30	Riser	03		No paint	ACC-01	1 m²	4191	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
03-R30a	Riser	03		No paint	ACC-01	1 m²	3733	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
03-S01	Lloyd Street Spiral Staircase	03		No paint	RES-02	30 m²	20695	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
03-S04	Princess Street Spiral Staircase	03		No paint	RES-02	30 m²	21029	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
03-S05	Protected Cores Evacuation Staircase	03		C1	COR-01	32 m²	26012	1.1.7 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish **NBS M60 195.** Stair soffits and stubs to be painted with **NBS M60 181A.** allow three coats	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish **NBS M60 112C**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
03-S16	Evacuation Stair	03		No paint	COR-02	3 m²	6252	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
03-S17	Evacuation Stair	03		No paint	COR-01	2 m²	5211	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-001	Head Of Registrar's Service Office	04	PS04	S2	OFF-01	31 m²	25244	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-002	Registrar Office (1)	04	PS04	S2	OFF-01	12 m²	16308	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-002a	Registrar Office (2)	04	PS04	S2	OFF-01	11 m²	20400	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-003	Registrar Office (3)	04	PS04	S2	OFF-01	15 m²	21885	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-003a	Registrar Office (4)	04	PS04	S2	OFF-01	16 m²	16202	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-004	Registrar Office (5)	04	PS04	S2	OFF-01	11 m²	15847	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-004a	Registrar Office (6)	04	PS04	S2	OFF-01	11 m²	14288	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-005	Archive	04		S1	UPR-01	52 m²	30271	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-006	Office	04		S1	UPR-01	30 m²	23448	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-006a	Storage	04		No paint	UPR-01	4 m²	8060	No paint	n/a	No paint	No paint	n/a	No paint		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-007	Archive	04		S1	UPR-01	37 m²	25824	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-007a	Strong Room	04		S1	UPR-01	9 m²	12452	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-008	Registrar Welfare Facilities	04		S2	WC-02	44 m²	28082	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-009	Female Washroom	04		T1	WC-02	11 m²	19119	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
04-009a	MaleWashroom	04		T1	WC-02	6 m²	10479	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
04-009b	Accessible WC - Right	04		T1	WC-02	5 m²	9754	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
04-009c	Cleaners Store	04		No paint	STO-03	1 m²	5388	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-010	Registrar Office (7)	04	PS04	S2	OFF-01	13 m²	16344	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-010a	Registrar Office (8)	04	PS04	S2	OFF-01	12 m²	14917	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-011	Registrar Office (9)	04	PS04	S2	OFF-01	16 m²	16324	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-011a	Registrar Office (10)	04	PS04	S2	OFF-01	14 m²	16190	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-012	Registrar Office (11)	04	PS04	S2	OFF-01	12 m²	16654	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-012a	Registrar Office (12)	04	PS04	S2	OFF-01	12 m²	14803	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-017b	Registrar Public Waiting Room	04	PS04	S3	OFF-01			1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	New blind boxes to be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours. Existing blind boxes to be painted in accordance with NBS M60 120A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-017a	Registrar Public Waiting Room	04	PS04	S3	OFF-01			1.1.8 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-018	Meeting Room / Private Waiting Area	04	PS04	S2	OFF-01	33 m²	23733	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-019	Waiting Room	04	PS04	S2	OFF-01	36 m²	24131	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-019a	Female Washroom	04		T1	WC-02	28 m²	25464	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
04-019b	Accessible WC - Right	04		T1	WC-02	6 m²	9867	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	

OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C04, 06-003, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

04-019c	Male Washroom	04		T1	WC-02	15 m²	20692	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
04-019d	Cleaners Store	04		No paint	STO-03	2 m²	6452	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-020	Legal Meeting Room	04	PS04	S2	OFF-01	38 m²	24931	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-021	Coroner's Court Waiting Room	04	PS04	S2	OFF-01	39 m²	26130	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-022	Coroner's Court Waiting Room	04	PS04	S2	OFF-01	39 m²	26387	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-023	Family Room	04	PS04	S2	OFF-01	28 m²	21605	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-024	Jury Court	04		UPR3	UPR-01	222 m²	66639	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	New blind boxes to be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours. Existing blind boxes to be painted in accordance with NBS M60 120A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-025	Jury Room	04		S2	OFF-01	32 m²	24575	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-025a	Accessible WC - Right	04		T1	WC-02	6 m²	9929	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-026a	All Gender WC	04		T1	WC-02	3 m²	7925	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
04-026b	All Gender WC	04		T1	WC-02	3 m²	7923	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
04-026c	Accessible WC - Right	04		T1	WC-02	6 m²	10117	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
04-027	MCC Storage	04		S1	ACC-01	12 m²	16993	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
					ACC-01				n/a						To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-029	Cooling Plant Room	04		S1	ACC-01	63 m²	39322	n/a	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-030	MCC Storage	04		S1	ACC-01	12 m²	15456	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-031	MCC Storage	04		S1	STO-03	5 m²	9360	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-032	MCC Storage	04		No paint	ACC-01	1 m²	4815	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-C02	MCC Circulation	04		C2	CIR-04	189 m²	133299	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 113A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
04-C02a	Protected Cores Lobby	04		C2	CIR-04	25 m²	25749	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 113A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
04-C02b	Circulation	04		S2	OFF-01	12 m²	15127	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-C02c	Circulation	04		S2	OFF-01	16 m²	18625	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-C02d	Circulation	04		S2	OFF-01	12 m²	15038	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-C02e	Circulation	04		S1	CIR-04	5 m²	8957	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-C02f	Circulation	04		S1P	CIR-04	3 m²	7258	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112B, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-C02g	Circulation	04		S1	WC-02	9 m²	12364	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-C02h	Circulation	04		S2	OFF-01	12 m²	14555	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-C02i	Circulation	04		S2	OFF-01	15 m²	17104	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-C02j	Circulation	04		S2	OFF-01	13 m²	14895	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-C03	MCC Circulation	04		C2	CIR-04	84 m²	50872	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 113A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
04-C03a	MCC Circulation	04		No paint	ACC-01	2 m²	13109	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-C03b	Protected Cores Smoke Lobby	04		S2	COR-02	11 m²	41978	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-C03c	Circulation	04		S2	CIR-04	8 m²	13904	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-C04	MCC Circulation	04		C2	CIR-04	177 m²	125692	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 113A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
04-C04a	Circulation	04		S2	OFF-01	7 m²	12985	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-C04b	Circulation	04		C2	CIR-04	25 m²	23347	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 113A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	

OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C04, 06-003, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

04-C04c	Protected Cores Smoke Lobby	04		C1	COR-02	19 m²	28712	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
04-C04d	Lobby	04		S2	CIR-02	10 m²	13201	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-C05	MCC Circulation	04		C2	CIR-03	32 m²	34920	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 113A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
04-L01	Lloyd Street Lift	04		No paint	ACC-01	10 m²	12477	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-L05	Cooper Lift	04		No paint	ACC-01	6 m²	10030	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R13	Riser	04		No paint	ACC-01	2 m²	6249	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R14	Riser	04		No paint	ACC-01	1 m²	3562	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R15	Riser	04		No paint	ACC-01	2 m²	5732	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R16	Riser	04		No paint	ACC-01	1 m²	4731	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R17	Riser	04		No paint	ACC-01	1 m²	8463	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R18	Riser	04		No paint	ACC-01	1 m²	6544	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R19	Riser	04		No paint	ACC-01	1 m²	4622	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R20	Riser	04		No paint	ACC-01	1 m²	5118	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R21	Riser	04		No paint	ACC-01	1 m²	4456	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R21a	Riser	04		No paint	ACC-01	1 m²	4075	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R23	Riser	04		No paint	ACC-01	1 m²	4699	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R26	Riser	04		No paint	ACC-01	2 m²	5187	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R28	Riser	04		No paint	ACC-01	1 m²	3823	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R29	Riser	04		No paint	ACC-01	0 m²	3136	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R31	Riser	04		No paint	ACC-01	1 m²	5989	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R32	Riser	04		No paint	ACC-01	7 m²	10864	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-R34	Riser	04		No paint	ACC-01	8 m²	11191	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-S01	Lloyd Street Spiral Staircase	05		C3	RES-02	28 m²	31327	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 112C. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.1 Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.2 Following repairs, skirting band to receive new economical paint finish NBS M60 112B. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
04-S04	Princess Street Spiral Staircase	04		No paint	RES-02	31 m²	20099	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-S06	Protected Cores Evacuation Staircase	04		No paint	COR-01	45 m²	28637	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-S07	Cooper Street Spiral Staircase	04		No paint	RES-02	36 m²	22357	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
04-S08	Protected Cores Evacuation Staircase	04		C1	COR-02	29 m²	24442	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
04-S09	Staircase 09	04		C2	CIR-03	38 m²	27010	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 113A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
04-S11	Protected Cores Evacuation Staircase	04		S1	CIR-04	9 m²	12099	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
04-S17	Staircase	04		S2	COR-02	5 m²	9341	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-001	MCC Meeting Room	05	PS05	S3	OFF-02	109 m²	46595	1.1.8 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Trusses, beams, painted architraves and corbels to be in skirting colour. Panels and surrounds in white cotton.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	see notes	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	Trusses, beams, painted architraves and corbels to be in skirting colour. Panels and surrounds in white cotton.
05-002	Commercial Welfare Facilities	05		S2	WC-02	10 m²	13241	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
05-002a	Female Washroom	05		T1	WC-02	30 m²	23135	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
05-002b	Cleaners Store	05		No paint	WC-02	2 m²	6563	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-002c	Accessible WC - Left	05		T1	WC-02	5 m²	9257	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
05-003	Male Washroom	05		T1	WC-02	30 m²	34692	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
05-004	Commercial Office	05	PS05	S3	OFF-02	149 m²	58554	1.1.8 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	Bookshelves to be painted with skirting colour. Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	Bookshelves to be painted with skirting colour. Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116
05-005	Commercial Office	05	PS05	S3	OFF-02	44 m²	26043	1.1.8 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	n/a	
05-006	Commercial Office	05	PS05	S1	OFF-02	105 m²	45623	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116. Skirting colour to run to junction of door and wall	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	n/a	Skirting colour to run to junction of door and wall
05-007	Commercial Office	05	PS05	S3	OFF-02	45 m²	26083	1.1.8 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	n/a	
05-008	Commercial Office	05	PS05	S3	OFF-02	131 m²	64936	1.1.8 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
05-008a	Commercial Storage	05		S1	ACC-01	5 m²	9208	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
05-009	Commercial Meeting Room	05	PS05	S3	OFF-02	27 m²	18411	1.1.8 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Cornices white and timber trusses in skirting colour and specification NBS M60 111A	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	n/a	Cornices white and timber trusses brown
05-010	Commercial Office	05	PS05	S3	OFF-02	75 m²	40076	1.1.8 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
05-011	Commercial Office	05	PS05	S2	OFF-02	55 m²	30762	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	Picture rail and painted architraves to be in skirting colour
05-012	Commercial Meeting Room	05	PS05	S2	OFF-02	33 m²	25191	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
05-013	Access And Maintenance	05		S1	ACC-01	5 m²	10717	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
05-014	Store	05		S1	OFF-02	15 m²	15172	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-C01	Commercial Circulation	05		C3	CIR-04	276 m²	143455	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 112C. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.1 Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.2 Following repairs, skirting band to receive new economical paint finish NBS M60 112B. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.		n/a	
05-C01a	Corridor	05		C3	CIR-04	5 m²	8612	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 112C. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.1 Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.2 Following repairs, skirting band to receive new economical paint finish NBS M60 112B. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.		n/a	
05-C01c	Commercial Circulation	05		S1	CIR-04	22 m²	26733	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	Remove boxing to trusses

OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C04, 06-003, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

05-C01d	Circulation	05		S1	CIR-04	19 m^2	17984	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
05-C02a	Protected Cores Lobby	05		C1	COR-02	19 m^2	22128	1.1.7 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish **NBS M60 195**. Stair soffits and stubs to be painted with **NBS M60 181A**. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish **NBS M60 112C**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
05-C02b	Lobby	05		S1	COR-02	3 m^2	7668	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
05-C04	Protected Cores Smoke Lobby	05		S1	COR-02	45 m^2	41865	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
05-C04b	Protected Cores Smoke Lobby	05		S1	COR-02	15 m^2	16152	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
05-L04	Princess Lift	05		No paint	ACC-01	5 m^2	9092	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-L09	Lloyd St Split Lift	05		No paint	ACC-01	4 m^2	8300	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-L10	Princess St Split Lift	05		No paint	ACC-01	4 m^2	8111	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-R01	Riser	05		No paint	ACC-01	4 m^2	7725	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-R03	Riser	05		No paint	ACC-01	4 m^2	8055	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-R05	Riser	05		No paint	ACC-01	1 m^2	4311	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-R07	Riser	05		No paint	ACC-01	1 m^2	5577	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-R08	Riser	05		No paint	ACC-01	1 m^2	5999	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-R09	Riser	05		No paint	COR-02	1 m^2	5299	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-R30	Riser	05		No paint	COR-02	1 m^2	3906	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-R30a	Riser	05		No paint	COR-02	1 m^2	3896	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-R30c	Riser	05		No paint	ACC-01	0 m^2	0	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-S01	Lloyd Street Spiral Staircase	05		No paint	RES-02	3 m^2	6612	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-S04	Princess Street Spiral Staircase	05		No paint	RES-02	31 m^2	20908	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-S11	Protected Cores Evacuation Staircase	05		S1	CIR-04	9 m^2	12592	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
05-S16	Evacuation Stair	05		C1	COR-02	9 m^2	15834	1.1.7 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish **NBS M60 195**. Stair soffits and stubs to be painted with **NBS M60 181A**. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish **NBS M60 112C**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
05-S18	Protected Cores Evacuation Staircase	05		No paint	COR-02	9 m^2	12155	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
05-S20	Staircase	05		C1	COR-02	8 m^2	13979	1.1.7 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish **NBS M60 195**. Stair soffits and stubs to be painted with **NBS M60 181A**. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish **NBS M60 112C**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
06-001	Commercial Office	06	PS06	S1	OFF-02	34 m^2	27962	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-002	Commercial Office	06	PS06	S1	OFF-02	37 m^2	26950	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-003	Commercial Meeting Room	06	PS06	S1	OFF-02	39 m^2	27629	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	2.5.3 Following repairs, Prepare (sanding existing painted finish) and redecorate all timber panelling with new traditional flat oil eggshell painted finish **NBS M60 110A**, colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-004	Commercial Office	06	PS06	S1	OFF-02	32 m^2	25045	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	2.5.3 Following repairs, Prepare (sanding existing painted finish) and redecorate all timber panelling with new traditional flat oil eggshell painted finish **NBS M60 110A**, colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-005	Commercial Office	06	PS06	S1	OFF-02	56 m^2	31821	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-006	Commercial Office	06	PS06	S1	OFF-02	43 m^2	28884	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-007	Commercial Office	06	PS06	S1	OFF-02	37 m^2	25983	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-008	Female Washroom	06		T1	WC-02	25 m^2	20223	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
06-008a	Accessible WC - Right	06		T1	WC-02	6 m^2	9762	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
06-009	Male Washroom	06		T1	WC-02	20 m^2	20621	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-009a	Cleaners Cupboard	06		No paint	ACC-01	1 m^2	3297	No paint	n/a	No paint	No paint	n/a	No paint		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-010	Commercial Welfare Facilities	06	PS06	S2	OFF-02	34 m^2	27714	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-011	Commercial Office	06	PS06	S1	OFF-02	43 m^2	31382	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-012	Commercial Office	06	PS06	S1	OFF-02	34 m^2	27152	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-013	Commercial Meeting Room	06	PS06	S1	OFF-02	29 m^2	22122	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-014	Access And Maintenance	06		No paint	ACC-01	35 m^2	26582	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
06-015	Commercial Meeting Room	06	PS06	S1	OFF-02	32 m^2	27206	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	2.5.3 Following repairs, Prepare (sanding existing painted finish) and redecorate all timber panelling with new traditional flat oil eggshell painted finish **NBS M60 110A**, colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
06-016	Male Washroom	06		T1	WC-02	11 m^2	13556	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
06-016a	Accessible WC	06		T1	WC-02	6 m^2	13248	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
06-016b	Female Washroom	06		T1	WC-02	12 m^2	16141	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
06-016c	Cleaners	06		No paint	ACC-01	1 m^2	4560	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
06-017	Commercial Office	06	PS06	S1	OFF-02	34 m^2	29506	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	2.5.3 Following repairs, Prepare (sanding existing painted finish) and redecorate all timber with new traditional flat oil eggshell painted finish **NBS M60 110A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-018	Commercial Office	06	PS06	S1	OFF-02	42 m^2	28098	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	

OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C04, 06-001, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

06-019	Commercial Office	06		PSD6	S1	OFF-02	68 m²	41948	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-020	Commercial Office	06		PSD6	S1	OFF-02	68 m²	38587	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-021	Commercial Office	06		PSD6	S1	OFF-02	73 m²	54941	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-022	Commercial Meeting Room	06		PSD6	S1	OFF-02	0 m²	0	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-023	Accessible WC - Left	06		T1	WC-02	6 m²	10267	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
06-C02a	Landing / Circulation	06			S1	COR-02	9 m²	16557	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
06-C02b	Commercial Circulation	06		PSD6	S1	OFF-02	10 m²	16565	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	Painted architraves along corridor to be painted in white cotton
06-C02c	Commercial Circulation	06			S1	CIR-04	11 m²	21490	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
06-C02d	Commercial Circulation	06			S1	CIR-04	8 m²	13078	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
06-C02e	Commercial Circulation	06		PSD6	S1	OFF-02	9 m²	13156	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
06-C02f	Lift Landing	06			C2	COR-02	4 m²	8804	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 113A. Any timber ceiling panels to be painted in Eggshell M60 111A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
06-C03	Circulation	06			S1	ACC-01	60 m²	36262	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
06-C05a	Protected Cores Smoke Lobby	06			C1	COR-02	7 m²	12573	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and studs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
06-C03b	Corridor	06			S1	CIR-04	4 m²	9233	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
06-C04	Commercial Circulation	06			S1	CIR-04	21 m²	29343	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
06-C04a	Commercial Circulation	06		PSD6	S1	OFF-02	28 m²	23232	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
06-C04b	Commercial Circulation	06			S2	WC-02	37 m²	35393	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
06-C04c	Protected Cores Smoke Lobby	06			C1	COR-02	11 m²	17896	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and studs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
06-L01	Lloyd Street Lift	06			No paint	ACC-01	10 m²	12381	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
06-L05	Cooser Lift	06			No paint	ACC-01	6 m²	10030	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
06-L09	Lloyd St Satir Lift	06			No paint	ACC-01	4 m²	8302	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
06-R13	Riser	06			No paint	ACC-01	3 m²	10159	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
06-R18	Riser	06			No paint	WC-02	2 m²	8060	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
06-R19	Riser	06			No paint	ACC-01	1 m²	8113	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
06-R20	Riser	06			No paint	ACC-01	1 m²	11714	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
06-R21	Riser	06			No paint	ACC-01	2 m²	9502	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
06-R30	Riser	06			No paint	ACC-01	2 m²	9709	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
06-S08	Protected Cores Evacuation Staircase	06			C1	COR-02	27 m²	41451	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and studs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
06-S16	Evacuation Stair	06			S1	COR-02	10 m²	14669	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
06-S18	Evacuation Stair	06			S1	COR-02	9 m²	12089	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
06-S19	Commercial Circulation	06			S1	CIR-04	11 m²	15100	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
06-S20	Evacuation Stair	06			C1	COR-02	7 m²	13442	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and studs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
07-001	No Functional Use	07			No paint	ACC-01	114 m²	65299	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-002	No Functional Use	07			No paint	ACC-01	31 m²	34482	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-003	No Functional Use	07			No paint	ACC-01	26 m²	22461	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-004	No Functional Use	07			No paint	ACC-01	115 m²	85856	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-005	No Functional Use	07			No paint	ACC-01	54 m²	40412	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-006	No Functional Use	07			No paint	ACC-01	23 m²	19361	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-007	No Functional Use	07			No paint	ACC-01	58 m²	54754	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-008	No Functional Use	07			No paint	ACC-01	55 m²	38185	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-009	No Functional Use	07			No paint	ACC-01	102 m²	73463	No paint	n/a	No paint	No paint	n/a	No paint		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
07-010	Access And Maintenance	07			No paint	ACC-01	21 m²	29175	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-011	Access And Maintenance	07			No paint	ACC-01	12 m²	15761	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-012	Access And Maintenance	07			No paint	ACC-01	51 m²	29503	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-013	Access And Maintenance	07			No paint	ACC-01	23 m²	19542	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-014	Access And Maintenance	07			No paint	ACC-01	6 m²	11827	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-015	Access And Maintenance	07			No paint	ACC-01	29 m²	21396	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-016	Access And Maintenance	07			No paint	ACC-01	43 m²	27634	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-C01	Protected Cores Smoke Lobby	07			No paint	COR-02	7 m²	13010	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-C02	Access And Maintenance	07			No paint	ACC-01	8 m²	12387	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-C02a	Access And Maintenance	07			No paint	ACC-01	9 m²	25722	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-R17	Riser	06			No paint	ACC-01	1 m²	4832	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-R30	Riser	07			No paint	ACC-01	2 m²	7867	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-S16	Evacuation Stair	07			No paint	ACC-01	33 m²	30244	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-S18	Access Stair	07			No paint	ACC-01	7 m²	10597	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
07-S21	Protected Cores Evacuation Staircase	07			No paint	COR-02	7 m²	16353	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-001	Staff/Pre-Arranged Visitors Reception	GF			S2	OFF-01	60 m²	31560	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Ceiling colour to extend to all of frame	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	Ceiling colour to extend to all of frame

OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C04, 06-001, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

GF-002	MCC/Public Meeting Room	GF		UPR2	UPR-01	61 m²	31581	1.1.3 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-003	Finishing Kitchen	GF		S1	CAT-01	27 m²	21817	Conduct repairs only. No redecorations.	Conduct repairs only. No redecorations.	Conduct repairs only. No redecorations.	2.6.1 New 'box within box' perimeter partitions to be lined on inside face with 2.5mm Altro Whiterock EU Grade Extruded PVC sheet in white satin fixed with Altrofix panel adhesive. Altro bonded to 19mm marine plywood. All angles and corner bends to be thermoformed on site transition strip to coving required. **NBS M50 160A**	n/a	3.6.5 New coved skirtings. **NBS M50 770A/770B**		n/a	
GF-004	Soulsture Hall Cafe'	GF		No paint	RET-02	135 m²	56491	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-005	Events Cloakroom	GF		S1	STO-03	9 m²	12271	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-006	Heater Room	GF		No paint	STO-03	18 m²	17368	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-007	Retail Space	GF		S2	UPR-01	63 m²	34019	1.2.4 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Strapwork to receive gold gilding as per **NBS M60 190**	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M50 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-008	Reception/Events Space	GF		UPR1	UPR-01	121 m²	56155	1.2.4 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Strapwork to receive gold gilding as per **NBS M60 190**	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, prepare (sanding existing painted finish) and redecorate all skirting with new eggshell painted finish. **M60-111A**. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	n/a	
GF-008a	AV Rack Room	GF		No paint	STO-03	3 m²	9846	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-008b	Store	GF		No paint	STO-03	6 m²	9566	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-009	Reception/Events Space	GF		UPR1	UPR-01	45 m²	26236	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, prepare (sanding existing painted finish) and redecorate all skirting with new eggshell painted finish **M60-111A**. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-010	Reception/Events Space	GF		UPR1a	UPR-01	50 m²	28481	1.2.4 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Strapwork to receive gold gilding as per **NBS M60 190**	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, prepare (sanding existing painted finish) and redecorate all skirting with new eggshell painted finish. **M60-111A**. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.		n/a	
GF-010a	WC	GF		T1	STO-03	5 m²	30311	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
GF-012	Family Room	GF		S1	WC-02	15 m²	18731	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-013	Baby Change with Parent & Child WC	GF		T1	WC-02	6 m²	10635	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
GF-014	Main Female Washroom	GF		T1	WC-02	35 m²	28065	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
GF-015	Accessible WC - Left	GF		T1	WC-02	5 m²	9641	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
GF-016	Cleaners Store	GF		T1	WC-02	2 m²	5998	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
GF-017	Changing Places	GF		T1	WC-02	12 m²	14007	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
GF-018	Accessible WC - Right	GF		T1	WC-02	6 m²	10091	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
GF-019	Main Male Washroom	GF		T1	WC-02	33 m²	26979	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
GF-020	Multi-Faith Room	GF	PS01	S2	OFF-01	58 m²	31097	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-020a	ICT Cabinet	GF		S1	OFF-01	3 m²	7115	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-021	MCC/Public Meeting Room	GF	PS01	S2	OFF-01	32 m²	24196	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-022	MCC/Public Meeting Room	GF	PS01	S2	OFF-01	17 m²	25315	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-023	MCC/Public Meeting Room	GF	PS01	S2	OFF-01	47 m²	30901	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-024	MCC/Catering Welfare Facilities	GF		S2	WC-02	33 m²	26887	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-025	MCC/Public Meeting Room	GF	PS01	S2	OFF-01	38 m²	26581	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-026	MCC/Public Meeting Room	GF	PS01	S2	OFF-01	46 m²	28553	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-027	Scrutiny Room	GF		UPR2	UPR-01	38 m²	26253	1.1.3 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-027a	Scrutiny Room	GF		UPR2	UPR-01	35 m²	32023	1.1.3 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-027b	Scrutiny Room	GF		UPR2	UPR-01	111 m²	45588	1.2.4 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Strapwork to receive gold gilding as per **NBS M60 190** Ceiling colour to extend to all of frieze and under side of arch reveal	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	Ceiling colour to extend to all of frieze and under side of arch reveal
GF-027c	AV Rack Room & ICT Cabinet	GF		S1	OFF-01	14 m²	18823	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	

OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C04, 06-001, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

GF-028	Catering Office	GF		S1	OFF-01	32 m²	36615	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to N8S M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-029	Catering Office	GF		S1	OFF-01	41 m²	27118	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to N8S M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-029a	Store	GF		S1	STO-03	7 m²	10482	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to N8S M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-030	Disposable Catering Storage	GF		S1	CAT-02	38 m²	25081	1.1.2 Redecorate with new economical paint finish N8S M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.5 New coved skirtings. N8S M50 770A/770B		To be painted according to N8S M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-030a	1no. A WC & Shower - RH	GF		T1	WC-02	7 m²	18220	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a	n/a	n/a		To be painted according to N8S M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-031	Finishing Kitchen	GF		S1	CAT-01	33 m²	24492	Conduct repairs only. No redecorations.	Conduct repairs only. No redecorations.	Conduct repairs only. No redecorations.	2.6.1 New 'box within box' perimeter partitions to be lined on inside face with 2.5mm Altro Whiterock EU Grade Extruded PVC sheet in white satin fixed with Altrofix panel adhesive. Altro bonded to 19mm marine plywood. All angles and corner bends to be thermoformed on site transition strip to coving required. N8S M50 160A	n/a	3.6.5 New coved skirtings. N8S M50 770A/770B		n/a	
GF-032	Finishing Kitchen	GF		S1	CAT-01	13 m²	15280	Conduct repairs only. No redecorations.	Conduct repairs only. No redecorations.	Conduct repairs only. No redecorations.	2.6.1 New 'box within box' perimeter partitions to be lined on inside face with 2.5mm Altro Whiterock EU Grade Extruded PVC sheet in white satin fixed with Altrofix panel adhesive. Altro bonded to 19mm marine plywood. All angles and corner bends to be thermoformed on site transition strip to coving required. N8S M50 160A	n/a	3.6.5 New coved skirtings. N8S M50 770A/770B		n/a	
GF-033	Public Banqueting/Receptio n	GF		UPR1	UPR-01	225 m²	69490	1.2.4 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Strapwork to receive gold gilding as per N8S M60 190	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new eggshell painted finish. N8S M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	To be painted according to N8S M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to N8S M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
GF-034	Plant Room	GF		S1	STO-03	16 m²	15822	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-035	2no. M WC + 1no. Urinals	GF		T1	WC-02	8 m²	11476	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
GF-036	Accessible WC - Left	GF		T1	WC-02	4 m²	8629	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
GF-037	3no. F WCs	GF		T1	WC-02	9 m²	12211	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
GF-038	Visitor Centre	GF		S2	VIS-01	47 m²	27662	4.4.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Refer to Mather & co information		3.6.2 traditional flat oil eggshell painted finish N8S M60 111A, Refer to Mather & co information	
GF-039	Visitor Centre	GF	V1	VIS-01	28 m²	21878	4.4.6 Redecorate with new economical paint finish N8S M60 112B. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	4.4.6 Redecorate with new economical paint finish N8S M60 112B. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 120A, Refer to Mather & co information		3.6.9 painted finish N8S M60 111A & 120A, Refer to Mather & co information	
GF-040	Visitor Centre	GF	S2/V1	VIS-01	125 m²	53643	4.1.6 Redecorate with new economical paint finish N8S M60 112AA 112B. Allow 1no. basecoat and 2no. finishing coats. Refer to Matcher & co information	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Refer to Mather & Co information	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Refer to Mather & Co information	n/a	4.1.6 Redecorate with new economical paint finish N8S M60 112AA 112B. Allow 1no. basecoat and 2no. finishing coats. Refer to Matcher & co information	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A & 120A, Refer to Mather & co information		3.6.9 painted finish N8S M60 111A & 120A, Refer to Mather & co information	
GF-040a	Store	GF		S1	STO-03	6 m²	9558	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to N8S M60 110A – Refer to Mather & Co information for colours.	
GF-041	Visitor Centre	GF		S2	VIS-01	98 m²	50234	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Refer to Mather & co information		3.6.2 traditional flat oil eggshell painted finish N8S M60 111A, Refer to Mather & co information	
GF-041a	AV Rack Room & ICT Cabinet	GF		S1	STO-03	24 m²	21029	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Refer to Mather & Co information for colours.		To be painted according to N8S M60 110A – Refer to Mather & Co information for colours.	
GF-042	Visitor Centre	GF		S2	VIS-01	27 m²	21198	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Refer to Mather & co information		3.6.2 traditional flat oil eggshell painted finish N8S M60 111A, Refer to Mather & co information	
GF-043	Visitor Centre	GF		S2	VIS-01	25 m²	20380	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Refer to Mather & co information		3.6.2 traditional flat oil eggshell painted finish N8S M60 111A, Refer to Mather & co information	
GF-044	Plant Room	GF		S1	STO-03	11 m²	14586	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-045	Female Washroom	GF		T1	WC-01	14 m²	15569	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
GF-046	Male Washroom	GF		T1	WC-01	13 m²	16877	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
GF-047	Accessible WC - Right	GF		T1	WC-01	5 m²	8064	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
GF-048	Short Term Event Storage	GF		S1	STO-03	29 m²	22868	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-049	Multi Functional Event Support	GF		S1	STO-03	31 m²	24025	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-049a	Store	GF		S1	STO-03	4 m²	8693	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-050	Store	GF		S1	STO-03	11 m²	14116	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-C01	Albert Square Corridor	GF		No paint	RES-02	312 m²	158536	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-C01a	Lloyd Street Entrance lobby	GF		No paint	RES-02	14 m²	15950	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-C01b	Public Circulation	GF		S2	COR-02	38 m²	39109	1.1.6 Redecorate with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish N8S M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish N8S M60 111A, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-C01c	Public Circulation	GF		C2	RES-02	8 m²	13425	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 113A. Any timber ceiling panels to be painted in Eggshell M60 111A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish N8S M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.2 Following repairs, plaster walls to receive new economical paint finish N8S M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	

OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C04, 06-001, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

GF-C01d	Circulation	GF			S1	CIR-04	9 m²	15295	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 112A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-C01e	Platform Lift Circulation	GF			No paint	RES-02	26 m²	22233	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-C01f	Circulation	GF			C1	RES-02	130 m²	63374	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and studs to be painted with NBS M60 181A. allow three coats	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	Stair soffits and studs to be painted wh
GF-C01g	Albert Square Entrance Lobby	GF			No paint	RES-02	58 m²	30613	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-C01h	Lift lobby	GF			C1	COR-02	17 m²	19756	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and studs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
GF-C01i	Corridor	GF			UPR1a	CIR-04	10 m²	17522	1.1.9 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report. Strapwork to receive gold gilding as per NBS M60 190	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, prepare (sanding existing painted finish) and redecorate all skirting with new eggshell painted finish. M60-111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.		n/a	
GF-C01j	Public Circulation	GF			C2	CIR-04	10 m²	14463	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 113A. Any timber ceiling panels to be painted in Eggshell M60 111A Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.2 Following repairs, plaster walls to receive new economical paint finish NBS M60 112A, M60 112B, and M60 112C in . Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a		n/a	
GF-C01k	Temporary Finishing Kitchen	GF			S1	CAT-01	25 m²	19805	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a			3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-C01l	Public Circulation	GF			No paint	CIR-04	16 m²	21502	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-C02	Public Circulation	GF			No paint	RES-02	271 m²	183681	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-C02a	Princess Street Entrance	GF			No paint	RES-02	21 m²	19355	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-C02b	Princess Street Entrance	GF			No paint	RES-02	9 m²	11464	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-C02c	Princess Street Entrance Circulation	GF			No paint	ACC-01	1 m²	4348	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-C02e	Corridor	GF			S1	WC-02	9 m²	25017	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a			3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-C02f	Public Circulation	GF			S1	WC-02	15 m²	15739	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a			3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-C02g	Public Circulation	GF			No paint	RES-02	13 m²	17997	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-C02h	Corridor	GF			S1	WC-01	13 m²	15290	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a			3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-C03	Public Circulation	GF			No paint	RES-02	78 m²	48712	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-C03a	Cooper Street Entrance Lobby	GF			No paint	RES-02	18 m²	21670	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-C03b	Protected Cores Smoke Lobby	GF			C3	CIR-03	10 m²	16697	1.2.2 Plaster ceiling panels between plaster cornices and beam casings to be painted in emulsion paint M60 112C. Any timber ceiling panels to be painted in Eggshell M60 111A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.1 Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	2.2.2 Following repairs, skirting band to receive new economical paint finish NBS M60 112B. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.		n/a	
GF-C04	Public Circulation	GF			No paint	RES-02	233 m²	149502	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-C04a	Goods Lift Lobby	GF			C1	COR-02	18 m²	32627	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and studs to be painted with NBS M60 181A. allow three coats	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
GF-C04b	Catering Circulation	GF			S1	CIR-04	4 m²	8237	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a			3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-C04c	Protected Cores Smoke Lobby	GF			C1	COR-02	13 m²	21946	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and studs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
GF-C04d	Lobby	GF			C1	COR-02	8 m²	14411	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and studs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
GF-C04e	Police Bridge	GF			No paint	VIS-01	15 m²	18786	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-C04f	Protected Cores Smoke Lobby	GF			C1	COR-02	10 m²	13646	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and studs to be painted with NBS M60 181A. allow three coats	n/a	n/a	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
GF-C04h	Lobby	GF			S1	STO-03	8 m²	11728	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a			3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-C05	Public Circulation	GF			S2	VIS-01	36 m²	34789	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-C05a	Public Circulation	GF			S2	VIS-01	4 m²	7810	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-C06	MCC Circulation	GF			No paint	CIR-03	38 m²	30586	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-C06a	MCC Circulation	GF			S1	CIR-03	7 m²	14247	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a			3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-L01	Lloyd Street Lift	GF			No paint	ACC-01	10 m²	12396	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-L02	Albert Sq Platform Lift	GF			No paint	CIR-01	4 m²	7883	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-L03	Albert Square Lift	GF			No paint	ACC-01	0 m²	21010	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-L04	Princess Lift	GF			No paint	ACC-01	5 m²	8801	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-L05	Cooper Lift	GF			No paint	ACC-01	6 m²	10030	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-L06	Goods Lift	GF			C1	ACC-01	14 m²	15671	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and studs to be painted with NBS M60 181A. allow three coats	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
GF-L07	Goods Lift	GF			C1	ACC-01	14 m²	14885	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and studs to be painted with NBS M60 181A. allow three coats	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
GF-R01	Riser	GF			No paint	ACC-01	0 m²	3863	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R02	Riser	GF			No paint	ACC-01	1 m²	15047	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R03	Riser	GF			No paint	ACC-01	1 m²	4788	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R04	Riser	GF			No paint	ACC-01	1 m²	4841	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R05	Riser	GF			No paint	ACC-01	2 m²	4041	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R06	Riser	GF			No paint	ACC-01	0 m²	2142	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R07	Riser	GF			No paint	ACC-01	0 m²	3438	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R08	Riser	GF			No paint	ACC-01	2 m²	5103	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R09	Riser	GF			No paint	ACC-01	2 m²	3899	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R10	Riser	GF			No paint	ACC-01	0 m²	2166	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R11	Riser	GF			No paint	ACC-01	0 m²	690	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R12	Riser	GF			No paint	ACC-01	0 m²	3853	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R13	Riser	GF			No paint	ACC-01	3 m²	9994	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R14	Riser	GF			No paint	ACC-01	0 m²	2718	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R16	Riser	GF			No paint	ACC-01	1 m²	5697	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R17	Riser	GF			No paint	ACC-01	1 m²	4659	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R18	Riser	GF			No paint	ACC-01	1 m²	4846	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R19	Riser	GF			No paint	ACC-01	1 m²	4589	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R20	Riser	GF			No paint	PLA-01	10 m²	14215	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R21	Riser	GF			No paint	ACC-01	1 m²	3915	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R22	Riser	GF			No paint	ACC-01	0 m²	2132	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R23	Riser	GF			No paint	ACC-01	3 m²	7289	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R24	Riser	GF			No paint	ACC-01	3 m²	7921	No paint	n/a	No paint	No paint	n/a	No paint		n/a	

OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-CHL, 06-001, 06-009, 06-0012, 06-CHRs, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

GF-R25	Riser	GF		No paint	ACC-01	4 m²	8501	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R26	Riser	GF		No paint	ACC-01	2 m²	8936	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R27	Riser	GF		No paint	ACC-01	6 m²	2720	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R28	Riser	GF		No paint	ACC-01	1 m²	3651	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-R29	Riser	GF		No paint	ACC-01	1 m²	3812	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-S01	Lloyd Street Spiral Staircase	GF		No paint	RES-02	33 m²	20778	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-S02	Grand Staircase	GF		No paint	RES-02	15 m²	36410	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-S03	Grand Staircase	GF		No paint	RES-02	15 m²	35584	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-S04	Princess Street Spiral Staircase	GF		No paint	RES-02	30 m²	21094	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-S05	Protected Cores Evacuation Staircase	GF		C1	COR-01	24 m²	40118	1.1.7 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish **NBS M60 195**. Stair soffits and stubs to be painted with **NBS M60 181A**. allow three coats	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish **NBS M60 112C**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-S06	Protected Cores Evacuation Staircase	GF		No paint	COR-01	33 m²	12944	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-S07	Cooper Street Spiral Staircase	GF		No paint	RES-02	38 m²	22579	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-S08	Protected Cores Evacuation Staircase	GF		C1	COR-02	30 m²	42539	1.1.7 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish **NBS M60 195**. Stair soffits and stubs to be painted with **NBS M60 181A**. allow three coats	n/a	No paint	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish **NBS M60 112C**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
GF-S09	MCC Circulation	GF		No paint	CIR-03	31 m²	22589	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-S10	Protected Cores Evacuation Staircase	GF		C1	COR-02	25 m²	23150	1.1.7 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish **NBS M60 195**. Stair soffits and stubs to be painted with **NBS M60 181A**. allow three coats	n/a	No paint	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish **NBS M60 112C**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
GF-S11	Protected Cores Evacuation Staircase	GF		S1P	CIR-04	19 m²	20358	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	n/a	1.4.2 Following plaster repairs, all walls to receive new matt emulsion paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 112B**. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-S12	Staircase	GF		No paint	CIR-03	2 m²	7544	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
GF-S13	Staircase	GF		S1	CIR-04	6 m²	6977	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-S14	MCC Circulation	GF		S1	CIR-03	10 m²	13082	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
GF-S15	Protected Cores Evacuation Staircase	GF		No paint	CIR-03	28 m²	28205	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-001	Heating Plant Room	LG		K1	PLA-01	118 m²	62425	2.2.5 Ceiling to be painted with new mineral paint finish **NBS M60 118A**. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint	2.2.5 Exposed brickwork surfaces to be painted with new mineral paint finish **NBS M60 118A**. Allow 1no. basecoat and 2no. finishing coats.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 118A**. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-004	MCC M Changing Rooms with 4no. Showers	LG		T1	WC-02	32 m²	28655	1.1.2 Redecorate with new economical paint finish **NBS M60 113A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 110A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-004a	WC	LG		T1	WC-02	5 m²	7139	1.1.2 Redecorate with new economical paint finish **NBS M60 113A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 110A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-004b	1no. A Shower	LG		T1	WC-02	8 m²	11105	1.1.2 Redecorate with new economical paint finish **NBS M60 113A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	n/a	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 110A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-005	MCC F Changing Rooms with 4no. Showers	LG		T1	WC-02	26 m²	24369	1.1.2 Redecorate with new economical paint finish **NBS M60 113A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 110A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-005a	WC	LG		T1	WC-02	3 m²	7416	1.1.2 Redecorate with new economical paint finish **NBS M60 113A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 110A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-006	MCC Furniture Store	LG		S1	STO-01	84 m²	39283	1.1.2 Redecorate with new economical paint finish **NBS M60 113A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	No paint		n/a	
LG-006a	Service Route	LG		No Paint	STO-01	36 m²	40447	1.1.2 Redecorate with new economical paint finish **NBS M60 113A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	No paint		n/a	
LG-006b	Platform Lift Maintenance Access	LG		K1	ACC-01	28 m²	31900	2.2.5 Ceiling to be painted with new mineral paint finish **NBS M60 118A**. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint	2.2.5 Exposed brickwork surfaces to be painted with new mineral paint finish **NBS M60 118A**. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint		n/a	
LG-007	FM Store	LG		No Paint	STO-02	56 m²	43207	No paint	n/a	No paint	No paint	n/a	n/a		n/a	
LG-008	MCC Heritage Store	LG		S1	STO-01	54 m²	30773	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-008a	Service Route	LG		No Paint	ACC-01	9 m²	27589	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-009	MCC Heritage Storage	LG		S1	STO-01	52 m²	33403	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-009a	Service Route	LG		No Paint	ACC-01	22 m²	27871	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-009b	MCC Heritage Storage	LG		No Paint	STO-01	5 m²	9438	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-009c	MCC Heritage Storage	LG		No Paint	STO-01	3 m²	7602	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-010	MCC Heritage Storage	LG		S1	STO-01	43 m²	27914	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-010a	Service Route	LG		No Paint	ACC-01	9 m²	27633	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-011	MCC Heritage Storage	LG		S1	STO-01	41 m²	29256	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-011a	Service Route	LG		No Paint	ACC-01	16 m²	30527	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-012	Collection Management Workshop	LG		S1	STO-01	55 m²	36435	1.1.6 Redecorate with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish **NBS M60 120A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 111A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-012a	Plant Room	LG		No Paint	ACC-01	6 m²	12905	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-013	Accessible WC - Left	LG		T1	WC-02	5 m²	9162	1.1.2 Redecorate with new economical paint finish **NBS M60 113A**. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish **NBS M60 110A**, Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-014	Portcullis room	LG		No Paint	ACC-01	14 m²	24762	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-015	Plant Area	LG		K2	PLA-01	95 m²	36416	**NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint	Exposed brickwork surfaces to be painted with new mineral paint finish **NBS M60 118A**. Allow 1no. basecoat and 2no. finishing coats. New partitions to receive **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint		n/a	
LG-016	FM Storage	LG		No Paint	STO-02	34 m²	25776	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-017	Plant Area	LG		K2	PLA-01	30 m²	21984	**NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint	Exposed brickwork surfaces to be painted with new mineral paint finish **NBS M60 118A**. Allow 1no. basecoat and 2no. finishing coats. New partitions to receive **NBS M60 112A**. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint		n/a	
LG-017a	Plant Room	LG		No Paint	PLA-01	2 m²	5730	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-018	FM Storage	LG		No Paint	STO-02	35 m²	30561	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-019	Plant Area	LG		K1	PLA-01	56 m²	33774	2.2.5 Ceiling to be painted with new mineral paint finish **NBS M60 118A**. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint	2.2.5 Exposed brickwork surfaces to be painted with new mineral paint finish **NBS M60 118A**. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint		n/a	
LG-020	Plant Area	LG		K1	PLA-01	33 m²	25503	2.2.5 Ceiling to be painted with new mineral paint finish **NBS M60 118A**. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint	2.2.5 Exposed brickwork surfaces to be painted with new mineral paint finish **NBS M60 118A**. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint		n/a	
LG-020a	Plant Room	LG		No Paint	PLA-01	10 m²	13999	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-021	Water Tank Room	LG		K1	PLA-01	38 m²	29768	2.2.5 Ceiling to be painted with new mineral paint finish **NBS M60 118A**. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint	2.2.5 Exposed brickwork surfaces to be painted with new mineral paint finish **NBS M60 118A**. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint		n/a	
LG-021a	Plant Room	LG		K1	PLA-01	12 m²	16268	No paint	n/a	No paint	2.2.5 Exposed brickwork surfaces to be painted with new mineral paint finish **NBS M60 118A**. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint		n/a	
LG-024	MCC Storage	LG		No Paint	STO-02	28 m²	21071	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-024a	Incoming water and gas room	LG		No Paint	STO-02	22 m²	21196	No paint	n/a	No paint	No paint	n/a	No paint		n/a	

OTH-PUR-TH-ZZ-SCH-A-58D4
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C04, 06-001, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

LG-025	Ventilation Plant Room	LG		No Paint	PLA-01	39 m²	30468	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-026	LV Switchroom	LG		K2	PLA-01	22 m²	21161	NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint	Exposed brickwork surfaces to be painted with new mineral paint finish NBS M60 118A. Allow 1no. basecoat and 2no. finishing coats. New partitions to receive NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint		n/a	
LG-026a	Plant Room	LG		No Paint	PLA-01	17 m²	27999	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-027	Plant Area	LG		No Paint	PLA-01	32 m²	46728	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-027a	Plant Area	LG		K2	PLA-01	55 m²	55449	NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint	Exposed brickwork surfaces to be painted with new mineral paint finish NBS M60 118A. Allow 1no. basecoat and 2no. finishing coats. New partitions to receive NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint		n/a	
LG-027b	Plant Area	LG		K2	PLA-01	12 m²	14071	NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint	Exposed brickwork surfaces to be painted with new mineral paint finish NBS M60 118A. Allow 1no. basecoat and 2no. finishing coats. New partitions to receive NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint		n/a	
LG-027c	Plant Area	LG		No Paint	PLA-01	23 m²	29899	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-028	Plant Room	LG		No Paint	PLA-01	103 m²	105146	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-028a	LV Switchroom 1	LG		K1	PLA-01	18 m²	18993	No paint	n/a	No paint	2.2.5 Exposed brickwork surfaces to be painted with new mineral paint finish NBS M60 118A. Allow 1no. basecoat and 2no. finishine coats.	n/a	No paint		n/a	
LG-028b	RMU Room 1	LG		No Paint	PLA-01	8 m²	11260	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-028c	RMU Room 2	LG		No Paint	PLA-01	8 m²	11320	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-028d	Plant Area	LG		K2	PLA-01	15 m²	15290	NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint	Exposed brickwork surfaces to be painted with new mineral paint finish NBS M60 118A. Allow 1no. basecoat and 2no. finishing coats. New partitions to receive NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint		n/a	
LG-028e	ENWL Substation (External Supplier)	LG		No Paint	PLA-01	25 m²	20319	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-028f	Plant Area	LG		No Paint	PLA-01	6 m²	10132	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-028g	Plant Room	LG		No Paint	PLA-01	5 m²	9752	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-030	Wine and Liquor Store	LG		S1	CAT-02	50 m²	22086	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.5 New coved skirtings. NBS M50 770A/770B		n/a	
LG-031	Plant Area	LG		No Paint	ACC-01	31 m²	22843	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-032	Bin Store	LG		No Paint	CAT-02	57 m²	36291	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-033	Deliveries/Holding Storage	LG		No Paint	CAT-02	41 m²	31219	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-034	Linen Store	LG		S1	CAT-02	41 m²	28137	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.5 New coved skirtings. NBS M50 770A/770B		n/a	
LG-035	Dry/Ambient Catering Storage	LG		S1	CIR-01	7 m²	10849	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-036	Catering Storage	LG		S1	CAT-02	71 m²	35408	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.5 New coved skirtings. NBS M50 770A/770B		n/a	
LG-036a	Ventilation Plant Room	LG		No paint	PLA-01	27 m²	22595	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-037	FM Storage	LG		No paint	STO-02	82 m²	42295	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-038	FM Storage	LG		No paint	STO-02	94 m²	46406	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-038b	Caterine Storage	LG		No paint	CIR-01	45 m²	38938	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-039	Plant Area	LG		No paint	CIR-01	9 m²	12700	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-040	Heatine Plant Room	LG		No paint	PLA-01	20 m²	20870	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-042	Plant Area	LG		K1	PLA-01	17 m²	18118	No paint	n/a	No paint	2.2.5 Exposed brickwork surfaces to be painted with new mineral paint finish NBS M60 118A. Allow 1no. basecoat and 2no. finishine coats.	n/a	No paint		n/a	
LG-043	Welfare Facilities	LG		K1	WC-02	20 m²	21642	2.2.5 Ceiling to be painted with new mineral paint finish NBS M60 118A. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint	2.2.5 Exposed brickwork surfaces to be painted with new mineral paint finish NBS M60 118A. Allow 1no. basecoat and 2no. finishing coats.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 110A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-043a	Lobby	LG		K1	CIR-01	5 m²	9988	No paint	n/a	No paint	2.2.5 Exposed brickwork surfaces to be painted with new mineral paint finish NBS M60 118A. Allow 1no. basecoat and 2no. finishing coats.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 110A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-043b	Accessible WC - Left	LG		T1	WC-02	7 m²	11317	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 110A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-043c	Office	LG		K1	UPR-01	69 m²	51882	No paint	n/a	No paint	2.2.5 Exposed brickwork surfaces to be painted with new mineral paint finish NBS M60 118A. Allow 1no. basecoat and 2no. finishing coats.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 110A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	n/a	
LG-043d	FM Storage	LG		S1	STO-02	42 m²	25076	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-044	Store	LG		No paint	ACC-01	2 m²	8341	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-046	MCC Staff Activity Room Welfare	LG		S1	WC-02	80 m²	39381	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	
LG-046a	MCC Female Changing Rooms	LG		T1	WC-02	9 m²	16312	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 110A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-046b	MCC Male Changing Rooms	LG		T1	WC-02	9 m²	16312	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 110A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-046c	Cleaners Cupboard	LG		K2	WC-02	2 m²	5766	NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint	Exposed brickwork surfaces to be painted with new mineral paint finish NBS M60 118A. Allow 1no. basecoat and 2no. finishing coats. New partitions to receive NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint		n/a	
LG-046d	Staff Recovery/Rest	LG		S1	WC-02	8 m²	11385	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-046e	Accessible Shower & WC - Right	LG		T1	WC-02	7 m²	10880	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 110A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-047	Police Cells	LG		S1	VIS-02	11 m²	13497	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-048	Police Cells	LG		S1	VIS-02	11 m²	13520	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-049	Police Cells	LG		No paint	VIS-02	11 m²	13602	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-050	Police Cells	LG		No paint	VIS-02	11 m²	13432	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-051	Police Cells	LG		No paint	VIS-02	11 m²	13622	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-052	Plant Room	LG		No paint	PLA-01	35 m²	34543	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-053	Ventilation Plant Room	LG		No paint	PLA-01	61 m²	35970	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-054	Ventilation Plant Room	LG		No paint	PLA-01	61 m²	42001	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-056	Plant Area	LG		No paint	PLA-01	4 m²	9218	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-057	Ventilation Plant Room	LG		No paint	PLA-01	48 m²	32645	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-057a	Ventilation Plant Room	LG		No paint	PLA-01	18 m²	17095	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-057b	Ventilation Plant Room	LG		No paint	PLA-01	21 m²	21731	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-058	MCC Circulation	LG		No paint	ACC-01	3 m²	7850	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-059	Storage	LG		No paint	ACC-01	6 m²	8954	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-C01	Albert Street Corridor	LG		No paint	CIR-01	270 m²	152928	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-C01c	Plant Circulation	LG		No paint	CIR-01	10 m²	12506	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-C01d	Protected Cores Lift Lobby	LG		No paint	COR-01	24 m²	27026	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-C01e	MCC Circulation	LG		S1	COR-01	69 m²	63938	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-C01g	MCC Circulation	LG		No paint	CIR-01	55 m²	49824	No paint	n/a	No paint	No paint	n/a	No paint		n/a	

OTH-PUR-TH-ZZ-SCH-A-5804
Fit Out and Decorations Schedule
Revision: 20 - Rooms 05-C06, 06-001, 06-009, 06-0012, 06-C04b, 07-009 updated
Issue Date: 28/08/25 by: EW Checked by RS
Status: For Construction - Project Status: Stage 5

LG-C01h	Circulation	LG			T1	WC-02	8 m²	11750	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 120A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-C01i	Circulation	LG			S1	WC-02	5 m²	9235	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-C01j	Lobby	LG			S1	CIR-01	8 m²	12332	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-C01k	Portcullis room	LG			No paint	CIR-01	12 m²	16481	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-C01l	MCC Lift Lobby	LG			S1	COR-02	7 m²	11163	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-C01m	Protected Cores Lift Lobby	LG			S1	COR-01	17 m²	22500	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-C01o	Lift Lobby	LG			K2	COR-02	18 m²	32985	NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint	Exposed brickwork surfaces to be painted with new mineral paint finish NBS M60 118A. Allow 1no. basecoat and 2no. finishing coats. New partitions to receive NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint		n/a	
LG-C01p	Stair Lobby	LG			No paint	CIR-01	5 m²	10139	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-C02	Plant Circulation	LG			No paint	CIR-01	151 m²	115940	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-C02a	Plant Circulation	LG			No paint	CIR-01	14 m²	14152	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-C02b	Plant Circulation	LG			No paint	CIR-01	18 m²	20049	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-C02c	Plant Circulation	LG			No paint	PLA-01	9 m²	14392	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-C03	Protected Cores Lobby	LG			No paint	CIR-01	57 m²	46660	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-C03b	MCC Circulation	LG			No paint	CIR-01	4 m²	8093	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-C03c	Protected Cores Smoke Lobby	LG			No paint	CIR-01	11 m²	16096	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-C03d	Protected Cores Lift Lobby	LG			C1	COR-02	20 m²	29642	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	No paint	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
LG-C03e	Plant Circulation	LG			No paint	CIR-01	5 m²	9815	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-C04	Circulation	LG			No paint	CIR-01	88 m²	89210	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-C04b	Goods Lift Lobby	LG			C1	CAT-02	22 m²	38111	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
LG-C05	MCC Circulation	LG			S1	CIR-01	19 m²	21980	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-C05a	Public Circulation	LG			S2	CIR-01	28 m²	40447	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-C05c	Public Circulation	LG			S2	CIR-01	11 m²	14607	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-C05e	Public Circulation	LG			S2	CIR-01	12 m²	16774	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-C05g	MCC Circulation	LG			S2	CIR-01	20 m²	22461	1.1.6 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-C05h	MCC Circulation	LG			T1	WC-02	7 m²	11883	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 120A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-C06b	Stair Lobby	LG			S1	CIR-01	10 m²	14127	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-L01	Lloyd Street Lift	LG			No paint	ACC-01	8 m²	12266	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-L02	Lloyd Street Lift	LG			No paint	ACC-01	0 m²	0	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-L03	Albert Square Lift	LG			No paint	ACC-01	9 m²	11910	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-L04	Princess Lift	LG			No paint	ACC-01	5 m²	8857	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-L05	Copper Lift	LG			No paint	ACC-01	7 m²	11195	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-L06	Goods Lift	LG			C1	ACC-01	14 m²	14945	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
LG-R01	Riser	LG			No paint	ACC-01	1 m²	9597	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R02	Riser	LG			No paint	ACC-01	0 m²	3083	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R03	Riser	LG			No paint	ACC-01	2 m²	6435	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R04	Riser	LG			No paint	ACC-02	1 m²	4932	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R05	Riser	LG			No paint	ACC-01	1 m²	4599	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R06	Riser	LG			No paint	ACC-01	4 m²	10600	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R07	Riser	LG			No paint	ACC-01	1 m²	3815	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R08	Riser	LG			No paint	ACC-01	0 m²	2919	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R09	Riser	LG			No paint	PLA-01	2 m²	7496	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R11	Riser	LG			No paint	ACC-01	0 m²	908	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R12	Riser	LG			No paint	ACC-01	0 m²	2586	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R13	Riser	LG			No paint	PLA-01	3 m²	9175	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R14	Riser	LG			No paint	ACC-01	0 m²	3265	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R17	Riser	LG			No paint	ACC-01	1 m²	4569	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R18	Riser	LG			No paint	ACC-01	1 m²	4199	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R19	Riser	LG			No paint	ACC-01	1 m²	4316	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R20	Riser	LG			No paint	ACC-01	1 m²	4205	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R21	Riser	LG			No paint	ACC-01	1 m²	3589	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R23	Riser -Chimney Stack	LG			No paint	PLA-01	3 m²	6945	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R26	Riser	LG			No paint	ACC-01	2 m²	5981	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-R28	Riser	LG			No paint	ACC-01	1 m²	3658	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-S01	Lloyd Street Spiral Staircase	LG			No paint	RES-02	30 m²	38005	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-S04	Princess Street Spiral Staircase	LG			No paint	RES-02	25 m²	31384	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-S05	Protected Cores Evacuation Staircase	LG			C1	COR-01	26 m²	30737	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-S07	Cooper Street Spiral Staircase	LG			No paint	RES-02	38 m²	22067	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-S10	Protected Cores Evacuation Staircase	LG			C1	COR-02	53 m²	25106	1.1.7 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.Any Exposed steelwork to receive new micaceous iron oxide painted finish NBS M60 195. Stair soffits and stubs to be painted with NBS M60 181A. allow three coats	n/a	No paint	2.2.6 To new cores. Following repairs, plaster walls to receive new economical paint finish NBS M60 112C. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	n/a	3.6.3 Wall ceramic tile design from floor to dado. Refer to tiling information.		n/a	
LG-S12	MCC Circulation	LG			No paint	CIR-01	5 m²	12902	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-S13	Staircase	LG			S1	CIR-01	4 m²	8264	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-S14	Public Circulation	LG			S1	CIR-01	11 m²	15751	1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.3 Following plaster repairs, All wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.		n/a	
LG-S15	Protected Cores Evacuation Staircase	LG			No paint	PLA-01	14 m²	16891	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
ZZ-U07	Cooper St Platform Lift	GF			No paint	ACC-01	1 m²	4914	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-Q29	Cleaners Store	LG		K1	No paint	18993	3 m²	No paint	No paint	n/a	No paint	No paint	n/a	No paint		n/a	
LG-008c	Service Route	LG			No paint				1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	No paint	2.2.5 Exposed brickwork surfaces to be painted with new mineral paint finish NBS M60 118A. Allow 1no. basecoat and 2no. finishing coats.	n/a	No paint		n/a	
LG-008d	MCC furniture store	LG			S1				1.1.2 Redecorate with new economical paint finish NBS M60 113A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.5 Exposed brickwork surfaces to be painted with new mineral paint finish NBS M60 118A. Allow 1no. basecoat and 2no. finishing coats. Refer to OTH-PUR-TH-ZZ-DWG-A-2800 - 2807 and OTH-PUR-TH-ZZ-RPT-A-0116 for colours	n/a	No paint		n/a	
LG-007a	Portcullis room	LG			No Paint				No paint	n/a	No paint	No paint	n/a	n/a		n/a	
04-017c	Registrar Public Waiting Room	04			S3				1.1.8 Redecorate with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Cornices to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	1.4.1 Following plaster repairs, all Beam Casings to receive new eggshell paint finish NBS M60 120A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	2.2.4 Following repairs, all wall surfaces to be painted with new economical paint finish NBS M60 112A. Allow 1no. basecoat and 2no. finishing coats. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116 decorations report.	n/a	3.6.2 Following repairs, Prepare (sanding existing painted finish) and redecorate all skirting with new traditional flat oil eggshell painted finish NBS M60 111A. Final colours as per OTH-PUR-TH-ZZ-RPT-A-0116.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.	To be painted according to NBS M60 110A – Refer to OTH-PUR-TH-ZZ-RPT-A-0116 for colours.		