Hi All,

I have attached the lightning protection risk assessment that Arup have conducted using the StrikeRisk software according to BS EN 62305-02 (2012).

It was found that the risk of loss of cultural heritage in the structure cannot be determined, as there is no risk of fire or physical damage due to explosion from a lightning strike.

It was also found that the risk of loss of economic value is 0, due to the external lighting circuit being in the zone outside the memorial.

Therefore, there is no requirement for a lightning protection system (LPS) on the memorial.

Kind regards,

Melissa Goodchild
She/her/hers
Graduate Engineer (Building Services – Electrical)
MEng (Hons) IET

Arup
6th Floor,
3 Piccadilly Place,
Manchester,
M1 3BN,
United Kingdom
[redacted]
arup.com

Follow us
LinkedIn Twitter Instagram YouTube Facebook