




Blue Area Highlights Retaining Wall between car park and NLM

Red area highlights where the New Little Mill Walls & Windows have been used as a retaining wall.


Land Ownership – Red Line
See photo 3 & 4
for this area
See photo 1
Photo 2 & 5 Area in Question
1.69 in

Retaining Wall Built between NLM & Waulk Mill GL's 3-6

Photo 1






Photo 2 Retaining Wall can be seen on left running into NLM Wall and Stops there, Area where shrubs shown has no form of retaining ground other than using NLM Walls & Windows


Photo 3 – Example of ground & Area where shrubs removed against NLM windows which are only temporarily bricked up


Photo 5