
NEW MOUNT STREET
ELEVATION MARKUPS TO ACCOMPANY
SCHEDULE OF REPAIR WORKS TO EXTERIOR
AXIS ARCHITECTURE
22-06-18



BUILDING 1 ATRIUM SIDE



NAPLES STREET 1/2

TILED ROOF

3-22

6879

BRICK

BRICK

6886

7056

7052

1-30

1-29

7056

1-28

BRICK

G27

G26

G25

6949

BRICK 7055

Plate

LG20

BRICK

LG19

LG18

Sign

VE

VE

Recess

BRICK

8084

FOURTH

▽26273

✳

WINDOW CORRECTION TO 5 UPPER WINDOWS
ORIGINAL WINDOWS WERE PATTERNED IN FROM
ADJACENT WINDOWS AS THEY ARE NOT VISIBLE
FROM THE GROUND SURVEY POSITIONS

THIRD

▽22593

SECOND

▽19097

FIRST

▽15585

GROUND

▽12088

BASEMENT

▽8453


NAPLES STREET 2/2

33541
7013
CONCRETE
4no. A/C UNITS
AC
28653
4-4
4-3
* UPDATED
* UPDATED
28626
BRICK
Aerial
Aerial
7017
6971
3-38
3-37
3-36
3-35
3-34
BRICK
6973
BRICK
2-37
2-35
2-34
2-33
6972
6974
7015
BRICK
2-36
BRICK
1-40
1-38
1-37
1-36
CCTV
16362
6970
1-39
VE
VE
6968
6963
G37
7014
BRICK
G35
G 34
G33
COOPERATIVE PRINTING SOCIETY LTD
6967
Brackets
G36
6969
Fan
VE
VE
Roller shutter
LG28
LG26
LG25
BRICK
9917
Damp


← RAILINGS TO 5no. LOWER GRD FLOOR WINDOWS REMOVED AND BRICKWORK MADE GOOD. →

SCHOOL STREET 1/2

POINT TO RECORD WINDOW.




SCHOOL STREET 2/2



LOWER GROUND FLOOR WINDOWS LG 1 to LG 14. RAILINGS TO BE REMOVED & BRICKWORK MADE GOOD. ALLOW FOR EPOXY REPAIR TO ALL STONE CILLS

NEW MOUNT STREET 1/3

28653




LOWER GROUND FLOOR WINDOWS LG1 TO LG14. RAILINGS TO BE REMOVED AND BRICKWORK MADE GOOD. ALLOW FOR EPOXY REPAIR TO ALL STONE CILLS.

NEW MOUNT STREET 2/3




NEW MOUNT STREET 3/3



LUDGATE STREET 1/2



LUDGATE STREET 2/2




ELE V1

NO COVERAGE ON PHOTOGRAPHIC SURVEY

ALL A/C UNITS, CABLING + PIPEWORK TO BE REMOVED AND BRICKWORK MADE GOOD.

ATRIUM - BUILDING 2

SEE
NAPLES STREET
2/2.



NO COVERAGE ON PHOTO SURVEY.

ALL A/C UNITS, CABLING + PIPEWORK TO BE REMOVED AND BRICKWORK MADE GOOD.

ATRIUM - BUILDING 1