


Service voids and altro flooring to be installed in female wc, full redecoration to A-spec



Damaged floor tiles and staining to mosaic tiling within female wc vanity area



Service voids and altro flooring to be installed in male wc, full redecoration to A-spec



Replace vanity units in male as A-spec upgrade