
543	Lansbury House M16 8AH	T8	36cm	Cherry	Poor	M	9m	6m	Crown reduce 20%	Causing wall damage, monitor/repair
568		T7	Multi	Horse Chestnut	Ok	Y	10m	7m	Crown reduce 20%	Remove elderberry causing damage to fence
537		T6	16cm	Elm	Good	Y	7m	2m	Reduce 20%	
529		T4	55cm	Sycamore	Good	M	16m	10m	Reduce 20%	
589		T5	60cm	Sycamore	Good	M	16m	10m	No work	
598		T3	24cm	Sycamore	Good	M	14m	6m	Crown reduce 20%	
1406		T2	70cm	Lime	Good	M	12m	8m	Crown reduce 20%	
59		T1	40cm	Sycamore	Good	Y	10m	6m	Crown reduce 20%, crown lift	



Lansbury House, Manchester