Tag_number	Address	Tree_species	Condition	Age	DBH_(cm)	Height_(m)	Width_(m)	Work_required
NO TAG MAP 15 G3	FRONT OF 23 BURTON ROAD WITHINGTON MANCHESTER M20 3GB	HOLLY/HAWTHORN	Good	Mature	MULTI	UP TO 9M	N/A	CROWN RAISE FOR 2.4M CLEARANCE OVER PAVEMENT AND PATH/STAIRS AND 5.2M OVER ROAD
2126 MAP 15 T35	FRONT OF 23 BURTON ROAD WITHINGTON MANCHESTER M20 3GB	Sycamore	Good	Mature	60	17	12	CROWN RAISE FOR 5.2M CLEARANCE OVER ROAD
NO TAG MAP 15 T36	FRONT OF 23 BURTON ROAD WITHINGTON MANCHESTER M20 3GB	Hawthorn	Poor	Intermediate	MULTI	8	6	REMOVE DEAD STEM AND YOUNG STEM THAT IS UNSTABLE (tied to ash tree)
2127 MAP 15 T37	FRONT OF 23 BURTON ROAD WITHINGTON MANCHESTER M20 3GB	Lime	Good	Mature	44	16	9	CROWN RAISE FOR 5.2M CLEARANCE OVER ROAD AND 2.4M OVER PAVEMENT
2128 MAP 15 T38	FRONT OF 25 BURTON ROAD WITHINGTON MANCHESTER M20 3GB	Beech	Good	Mature	62	19	12	CROWN RAISE FOR 5.2M CLEARANCE OVER ROAD AND 2.4M OVER PAVEMENT
2130 MAP 15 T40	FRONT OF 25 BURTON ROAD WITHINGTON MANCHESTER M20 3GB	Lime	Good	Mature	32	18	11	CROWN RAISE FOR 2.4M CLEARANCE OVER PAVEMENT AND 5.2M OVER ROAD
2137 MAP 15 T47	REAR OF 29 BURTON ROAD WITHINGTON MANCHESTER M20 3GB	Crab	Good	Intermediate	MULTI	9	10	CROWN RAISE FOR 3M CLEARANCE OVER PARKING AREA
2139 MAP 15 T49	REAR OF 29 BURTON ROAD WITHINGTON MANCHESTER M20 3GB	Cherry	Good	Mature	MULTI	13	13	CROWN RAISE FOR 2.4M CLEARANCE OVER PATH ON ADJACENT PROPERTY



Map 15 Brigadier Close M20 3BX and Burton Road M20 3GB, Withington, Manchester

Scheme - Waterloo Court



PLANNING AND BUILDING CONTROL
12 MAY 2014