Reference 1 – 4 Eaton Road, Crumpsall M8 5DY




Image for the purposes of illustrating the location of the tree that is located within the Lane Conservation Area

Tree Number	Tree Species	Work Requested	Reason for work
T1	Ash *(Fraxinus excelsior)*	Remove tree to ground level	There is significant decay at the base of the tree – see images attached. A probe inserted into the soft rot went to a depth of at least 18cm The tree is located at the side of a footpath on the perimeter of a school. The tree is within striking distance of property and cars parked in the adjacent car park. There is therefore a high risk of harm to people and/or property should it fail.
T2	Sycamore *(Acer pseudoplatanus)*	Shown on diagram for information only	



Image of T1 – showing proximity of the footpath which runs between the driveway and the school



Image of the significant decay at the base of T1