Central Trees Ltd
Trickley Coppice Farm
Coppice Lane
Middleton
Tamworth Staffs, B78 2BU
T: 0121 748 1071
F: 0121 748 1074
E: info@ctsmanagement.co.uk
Company Reg: 15252621
VAT No: 452 7763 70

Vendor NO 1000434634

QUOTATION

Quotation Ref: 10609 **Date:** 20/5/25

Client: Sanctuary
For the attention of: Amy Scott


Location of work: 17 – 21 Wellington Road, Manchester, MI6 8FX

What3Words:

TPO's – Any TPO's on trees?


Description:


In the rear communal car park, there is a multi-stemmed Ash tree(tree No 958 on below map) which is growing against the wall and damaging the coping stones. The resident is complaining about birds roosting in the tree and soiling her car and has raised concerns about the safety of the wall due to the tree damaging it





Recommendations: Fell to ground as reasonably practical Treat stump to inhibit regrowth Remove arisings Access to the car park is in Alness road. Location of the tree is W.3.W:Advice.Amber.Acting	
Subtotal **VAT** **Total**	
Special Instructions: lowering kit **Surveyor: John Perry** **Administrator: James Perry**	




Reproduced from the Ordnance Survey® mapping with the permission of The Controller of Her Majesty's Stationery Office. © Crown Copyright. Unauthorised reproduction infringes Crown Copyright and may lead to prosecution or civil proceedings.
OS Licence No. UNKNOWN
Licensed to UNKNOWN
Carlton Grange, Wellington Road 17 - 21, Whalley Range M16 8EX
WELLINGTON ROAD
Carlton Grange
12
11
10
15
14
12a
96
tree 958Ash tree to Fell
958
960
957
956
22
954
955
953
El Sub Sta
ARBORtrack