WinCan

Project

Project Name: CHORLTON F5-F6

Project Date: 24/03/2025

Inspection Standard: MSCC5 Sewers & Drainage GB (SRM5 Scoring)

WinCan

Table of Contents

Project Name	Project Number	Project Date
CHORLTON F5-F6		24/03/2025

Project Information P-1

Scoring Summary P-2

Section Profile P-3

Section Summary P-4

Section Item 1: F5 > F6 (F5X) 1

WinCan

Project Information

Project Name	Project Number	Project Date
CHORLTON F5-F6		24/03/2025

WinCan

Scoring Summary

Project Name	Project Number	Project Date
CHORLTON F5-F6		24/03/2025

Structural Defects

Section	PLR	Grade	Description
All inspected pipes are in an acceptable structural condition (< grade 3).			

Service / Operational Condition

Section	PLR	Grade	Description
All inspected pipes are in an acceptable service condition (< grade 3).			

Abandoned Surveys

Section	PLR	Description
All inspections complete, none are abandoned.		

Information

These scoring summaries are based on the SRM grading from the WRc.

WinCan

Section Profile

Project Name	Project Number	Project Date
CHORLTON F5-F6		24/03/2025

Circular, 150 mm

Item No.	Upstream Node	Downstream Node	Date	Road	Material	Total Length	Inspected Length
1	F5	F6	24/03/2025		Polyvinyl chloride	42.22 m	42.22 m

Total: 1 Inspection x Circular 150 mm = 42.22 m Total Length and 42.22 m Inspected Length

Total: 1 Inspection = 42.22 m Total Length and 42.22 m Inspected Length

WinCan

Section Summary

Project Name	Project Number	Project Date
CHORLTON F5-F6		24/03/2025

Number of sections	1
Total length of sections	42.22 m
Total length of inspected sections	42.22 m
Total length of not inspected sections	0.00 m
Number of abandoned inspections	0
Number of section inspection photos	2
Number of section inspection videos	1
Number of section inspection scans	0
Number of section inclination measurements	0

PLR:	F5X	**Upstream Node:**	F5
Inspection Direction:	Downstream	**Downstream Node:**	F6
Inspected Length:	42.22 m	**Dia/Height:**	150 mm
Total Length:	42.22 m	**Material:**	Polyvinyl chloride

No.	m+	Code	Observation
1	0.00	MH	Start node, manhole, reference: F5
2	0.00	WL	Water level, 0% of the vertical dimension
3	42.22	MHF	Finish node, manhole, reference: F6

WinCan

Section Inspection - 24/03/2025 - F5X

Item No.	Insp. No.	Date:	Time:	Client`s Job Ref	Weather	Pre Cleaned	PLR
1	1	24/03/25	6:50	Not Specified	Not Specified	Not Specified	F5X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	Not Specified	Not Specified	Not Specified	Not Specified	Not Specified

Town or Village:		**Inspection Direction:**	Downstream	**Upstream Node:**	F5
Road:		**Inspected Length:**	42.22 m	**Upstream Pipe Depth:**	
Location:		**Total Length:**	42.22 m	**Downstream Node:**	F6
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:		**Dia/Height:**	150 mm
Flow Control:		**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:		**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:366




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: F5			
0.00	WL	Water level, 0% of the vertical dimension	00:00:00	F5X_fcc375e1-f68c-4f79-bdb0-7	
42.22	MHF	Finish node, manhole, reference: F6: BACKDROP	00:03:28	F5X_0c4d6199-4a85-4c7f-b701	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0


WinCan

Section Pictures - 24/03/2025 - F5X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
1	Downstream	F5X		



F5X_fcc375e1-f68c-4f79-bdb0-749290abdcd7_20250324_203631_503.jpg, 00:00:00, 0.00 m
Water level, 0% of the vertical dimension



F5X_0c4d6199-4a85-4c7f-b701-2d65df3edc0a_20250324_203754_802.jpg, 00:03:28, 42.22 m
Finish node, manhole, reference: F6, BACKDROP