WinCan

Project

Project Name: CHORLTON WILBRAHAM ROAD FOUL

Project Date: 14/10/2024

Inspection Standard: MSCC5 Sewers & Drainage GB (SRM5 Scoring)

WinCan

Table of Contents

Project Name	Project Number	Project Date
CHORLTON WILBRAHAM ROAD FOUL		14/10/2024

Project Information P-1

Scoring Summary P-2

Section Profile P-3

Section Summary P-4

Section Item 1: F3 > F6 (F3X) 1

Section Item 2: F6 > F7 (F6X) 3

Section Item 3: F7 > F8 (F7X) 5

Section Item 4: F8 > F9 (F8X) 7

WinCan

Project Information

Project Name	Project Number	Project Date
CHORLTON WILBRAHAM ROAD FOUL		14/10/2024

WinCan

Scoring Summary

Project Name	Project Number	Project Date
CHORLTON WILBRAHAM ROAD FOUL		14/10/2024

Structural Defects

Section	PLR	Grade	Description
All inspected pipes are in an acceptable structural condition (< grade 3).			

Service / Operational Condition

Section	PLR	Grade	Description
All inspected pipes are in an acceptable service condition (< grade 3).			

Abandoned Surveys

Section	PLR	Description
All inspections complete, none are abandoned.		

Information

These scoring summaries are based on the SRM grading from the WRc.

WinCan

Section Profile

Project Name	Project Number	Project Date
CHORLTON WILBRAHAM ROAD FOUL		14/10/2024

Circular, 150 mm

Item No.	Upstream Node	Downstream Node	Date	Road	Material	Total Length	Inspected Length
1	F3	F6	14/10/2024		Polyvinyl chloride	8.08 m	8.08 m
2	F6	F7	14/10/2024		Polyvinyl chloride	22.66 m	22.66 m
3	F7	F8	14/10/2024		Polyvinyl chloride	19.68 m	19.68 m
4	F8	F9	14/10/2024		Polyvinyl chloride	24.86 m	24.86 m

Total: 4 Inspections x Circular 150 mm = 75.28 m Total Length and 75.28 m Inspected Length

Total: 4 Inspections = 75.28 m Total Length and 75.28 m Inspected Length

WinCan

Section Summary

Project Name	Project Number	Project Date
CHORLTON WILBRAHAM ROAD FOUL		14/10/2024

Number of sections	4
Total length of sections	75.28 m
Total length of inspected sections	75.28 m
Total length of not inspected sections	0.00 m
Number of abandoned inspections	0
Number of section inspection photos	6
Number of section inspection videos	4
Number of section inspection scans	0
Number of section inclination measurements	0

PLR:	F3X	**Upstream Node:**	F3
Inspection Direction:	Upstream	**Downstream Node:**	F6
Inspected Length:	8.08 m	**Dia/Height:**	150 mm
Total Length:	8.08 m	**Material:**	Polyvinyl chloride

No.	m+	Code	Observation
1	0.00	MH	Start node, manhole, reference: F6
2	0.00	WL	Water level, 0% of the vertical dimension
3	8.08	MHF	Finish node, manhole, reference: F3

PLR:	F6X	**Upstream Node:**	F6
Inspection Direction:	Downstream	**Downstream Node:**	F7
Inspected Length:	22.66 m	**Dia/Height:**	150 mm
Total Length:	22.66 m	**Material:**	Polyvinyl chloride

No.	m+	Code	Observation
1	0.00	MH	Start node, manhole, reference: F6
2	0.00	WL	Water level, 0% of the vertical dimension
3	22.66	MHF	Finish node, manhole, reference: F7

PLR:	F7X	**Upstream Node:**	F7
Inspection Direction:	Downstream	**Downstream Node:**	F8
Inspected Length:	19.68 m	**Dia/Height:**	150 mm
Total Length:	19.68 m	**Material:**	Polyvinyl chloride

No.	m+	Code	Observation
1	0.00	MH	Start node, manhole, reference: F7
2	0.00	WL	Water level, 0% of the vertical dimension
3	19.68	MHF	Finish node, manhole, reference: F8

WinCan

Section Summary

Project Name	Project Number	Project Date
CHORLTON WILBRAHAM ROAD FOUL		14/10/2024

PLR:	F8X	**Upstream Node:**	F8
Inspection Direction:	Downstream	**Downstream Node:**	F9
Inspected Length:	24.86 m	**Dia/Height:**	150 mm
Total Length:	24.86 m	**Material:**	Polyvinyl chloride

No.	m+	Code	Observation
1	0.00	MH	Start node, manhole, reference: F8
2	0.00	WL	Water level, 0% of the vertical dimension
3	24.86	MHF	Finish node, manhole, reference: F9

WinCan

Section Inspection - 14/10/2024 - F3X

Item No.	Insp. No.	Date:	Time:	Client`s Job Ref	Weather	Pre Cleaned	PLR
1	1	14/10/24	11:34	Not Specified	Not Specified	Not Specified	F3X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	Not Specified	Not Specified	Not Specified	Not Specified	Not Specified

Town or Village:		**Inspection Direction:**	Upstream	**Upstream Node:**	F3
Road:		**Inspected Length:**	8.08 m	**Upstream Pipe Depth:**	
Location:		**Total Length:**	8.08 m	**Downstream Node:**	F6
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:		**Dia/Height:**	150 mm
Flow Control:		**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:		**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:70	Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: m F6						
	0.00	MH	Start node, manhole, reference: F6			
	0.00	WL	Water level, 0% of the vertical dimension	00:00:00	F3X_fd47faeb-dbeb-40bc-b6fe-	
	8.08	MHF	Finish node, manhole, reference: F3: MANHOLE IN WORK AREA WILL BE CLEANED PRIOR TO INSPECTION	00:00:49		
F3 Depth: m						

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

WinCan

Section Pictures - 14/10/2024 - F3X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
1	Upstream	F3X		



F3X_fd47faeb-dbeb-40bc-b6fe-79808137f94c_20241014_204458_435.jpg, 00:00:00, 0.00 m
Water level, 0% of the vertical dimension

WinCan

Section Inspection - 14/10/2024 - F6X

Item No.	Insp. No.	Date:	Time:	Client`s Job Ref	Weather	Pre Cleaned	PLR
2	1	14/10/24	11:50	Not Specified	Not Specified	Not Specified	F6X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	Not Specified	Not Specified	Not Specified	Not Specified	Not Specified

Town or Village:		**Inspection Direction:**	Downstream	**Upstream Node:**	F6
Road:		**Inspected Length:**	22.66 m	**Upstream Pipe Depth:**	
Location:		**Total Length:**	22.66 m	**Downstream Node:**	F7
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:		**Dia/Height:**	150 mm
Flow Control:		**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:		**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:197



Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: F6			
0.00	WL	Water level, 0% of the vertical dimension	00:00:00	F6X_acf553c1-9e9c-4371-98f6-	
22.66	MHF	Finish node, manhole, reference: F7	00:01:28	F6X_3a2944c0-51ec-4741-a91	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

WinCan

Section Pictures - 14/10/2024 - F6X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
2	Downstream	F6X		



F6X_acf553c1-9e9c-4371-98f6-80900c891641_20241014_204653_620.jpg, 00:00:00, 0.00 m
Water level, 0% of the vertical dimension



F6X_3a2944c0-51ec-4741-a91c-d6b346f714ba_20241014_204733_493.jpg, 00:01:28, 22.66 m
Finish node, manhole, reference: F7

WinCan

Section Inspection - 14/10/2024 - F7X

Item No.	Insp. No.	Date:	Time:	Client`s Job Ref	Weather	Pre Cleaned	PLR
3	1	14/10/24	11:39	Not Specified	Not Specified	Not Specified	F7X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	Not Specified	Not Specified	Not Specified	Not Specified	Not Specified

Town or Village:		**Inspection Direction:**	Downstream	**Upstream Node:**	F7
Road:		**Inspected Length:**	19.68 m	**Upstream Pipe Depth:**	
Location:		**Total Length:**	19.68 m	**Downstream Node:**	F8
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:		**Dia/Height:**	150 mm
Flow Control:		**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:		**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:171




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: F7			
0.00	WL	Water level, 0% of the vertical dimension	00:00:00	F7X_7ac0dae5-2b16-446b-8d1	
19.68	MHF	Finish node, manhole, reference: F8	00:01:32		

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

WinCan

Section Pictures - 14/10/2024 - F7X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
3	Downstream	F7X		



F7X_7ac0dae5-2b16-446b-8d14-9da5ed21ea37_20241014_204851_166.jpg, 00:00:00, 0.00 m
Water level, 0% of the vertical dimension

WinCan

Section Inspection - 14/10/2024 - F8X

Item No.	Insp. No.	Date:	Time:	Client`s Job Ref	Weather	Pre Cleaned	PLR
4	1	14/10/24	11:41	Not Specified	Not Specified	Not Specified	F8X

Operator	Vehicle	Camera	Preset Length	Legal Status	Alternative ID
Not Specified	Not Specified	Not Specified	Not Specified	Not Specified	Not Specified

Town or Village:		**Inspection Direction:**	Downstream	**Upstream Node:**	F8
Road:		**Inspected Length:**	24.86 m	**Upstream Pipe Depth:**	
Location:		**Total Length:**	24.86 m	**Downstream Node:**	F9
Surface Type:		**Joint Length:**		**Downstream Pipe Depth:**	

Use:	Foul	**Pipe Shape:**	Circular
Type of Pipe:		**Dia/Height:**	150 mm
Flow Control:		**Material:**	Polyvinyl chloride
Year Constructed:	Not Specified	**Lining Type:**	No Lining
Inspection Purpose:		**Lining Material:**	No Lining

Comments:
Recommendations:

Scale: 1:216




Position [m]	Code	Observation	MPEG	Photo	Grade
0.00	MH	Start node, manhole, reference: F8			
0.00	WL	Water level, 0% of the vertical dimension	00:00:00	F8X_b9a79234-771e-4b02-934	
24.86	MHF	Finish node, manhole, reference: F9	00:01:47	F8X_346404e3-13f9-43c0-91a2	

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	**STR Peak**	**STR Mean**	**STR Total**	**STR Grade**	**SER No. Def**	**SER Peak**	**SER Mean**	**SER Total**	**SER Grade**
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0

WinCan

Section Pictures - 14/10/2024 - F8X

Item No.	Inspection Direction	PLR	Client`s Job Ref	Contractor`s Job Ref
4	Downstream	F8X		



F8X_b9a79234-771e-4b02-9343-4801078c968d_20241014_205018_827.jpg, 00:00:00, 0.00 m
Water level, 0% of the vertical dimension



F8X_346404e3-13f9-43c0-91a2-c96654c9a2f7_20241014_205109_004.jpg, 00:01:47, 24.86 m
Finish node, manhole, reference: F9