

DO NOT SCALE FROM THIS DRAWING
ALL DIMENSIONS MUST BE CHECKED ON SITE BY CONTRACTOR PRIOR TO CONSTRUCTION




TYPICAL ELEVATION




TYPICAL ELEVATION WITH ROOF AND FLASHING INTERSECTION

EXISTING TERRACOTTA TURRET TYPICAL DETAIL



ROOFPLAN

**Turret**
1 : 20



Allow for replacing flashing to turret roof abutment and Turret

Vegetation and moss growth between mortar joints to be removed




Allow for sympathetically cleaning facades by hand and without the use of abrasive/corrosive chemicals




Crack to Terracotta arch head detail

Allow for repointing entire Turrets, contractor to remove existing mortar with care and replace with a Lime based alternative TBC once testing results confirmed for an original match







PROPOSED TYPICAL ELEVATION




PROPOSED TYPICAL ELEVATION WITH ROOF AND FLASHING INTERSECTION

PROPOSED TERRACOTTA TURRET TYPICAL DETAIL




PROPOSED ROOFPLAN

| Rev | Date | Int | Description |
|---|---|---|---|

btp ARCHITECTS
RIBA Chartered Practice

CLIENT:
Guinness Partnership

PROJECT:
India House Whitworth Street Manchester

DESCRIPTION:
Turret

PURPOSE OF ISSUE:
S0

| DRAWN BY: | CHECKED | DATE: | SCALE @ A1: |
|---|---|---|---|
| VS | ED | 30/09/24 | 1 : 20 |

| JOB NO: | STATUS CODE: | DRAWING NO: | REV |
|---|---|---|---|
| 4545 | S0 | 206 | |

FILE IDENTIFIER:
IH-BTP-00-DR-A-4545_206

Elizabeth House 486 Didsbury Road Heaton Mersey Stockport SK4 3BS
0161 443 1221 info@bernardtaylor.co.uk www.btparchitects.co.uk