



Allow for assessing Terracotta conditions and repointing to the underside of the arch

Allow for cleaning all plinths and ledges of detritus before repairing hairline cracks and surface damage


Working from the top downwards, existing mortar to be carefully removed, without damaging adjacent masonry or widening joints, to a minimum depth of 30mm.

Allow for replacing Terracotta pieces, refer to Terracotta Schedule




Typanum Pediment Chimney Plan Proposed
1 : 20

Hopper Gutter detail
1 : 10




Front Elevation - Whitworth Street - Pediment (EL2) Proposed
1 : 50



Side Elevation (EL1) Proposed
1 : 50

Side Elevation (EL3) Proposed
1 : 50



Timber lead roof deck covering
1 : 10

DO NOT SCALE FROM THIS DRAWING
ALL DIMENSIONS MUST BE CHECKED ON SITE BY CONTRACTOR PRIOR TO CONSTRUCTION



Image 01 - Top rear of Tympanum



Image 02 - Top front of Tympanum



Image 03 - Tympanum return to Chimney

Rev	Date	Int	Description
1	02/12/24	VS	Additional details added

btp ARCHITECTS
RIBA Chartered Practice

CLIENT:
Guinness Partnership

PROJECT:
India House Whitworth Street Manchester

DESCRIPTION:
Tympanum Pediment Chimney Detail Proposed

PURPOSE OF ISSUE:
S0

DRAWN BY:	CHECKED	DATE:	SCALE @ A1:
LJ	VS	30/09/24	As indicated

JOB NO:	STATUS CODE:	DRAWING NO:	REV
4545	S0	204	1

FILE IDENTIFIER:
IH-BTP-00-DR-A-4545_204.1

Elizabeth House 486 Didsbury Road Heaton Mersey Stockport SK4 3BS
0161 443 1221 info@bernardtaylor.co.uK www.btparchitects.co.uk