


DO NOT SCALE FROM THIS DRAWING
ALL DIMENSIONS MUST BE CHECKED ON SITE BY CONTRACTOR PRIOR TO CONSTRUCTION

EXISTING







Side Elevation (EL1)
1 : 50



Front Elevation - Whitworth Street - Pediment (EL2)
1 : 50



Side Elevation (EL3)
1 : 50



Typanum Pediment Chimney Detail
1 : 20



Tympanum interior wall damage (EL2a)

Cracking (EL2a)

Previous infill repair

Cracking (EL2b)

Cracking to base plint to Tympanum (EL2a)





Allow for removing flashing substitute and replacing with Code 4 Lead or higher (EL2Pb)

Allow for repointing between Terracotta pieces



Parapet wall once weathered coping damage and cracking to Terracotta (EL2Pa)

Allow for removing existing flashing, new flashing to extend minimum 600mm up (EL2Pc)




Cracking to base plinth to Tympanum (EL2a)

Cracking to Tympanum (EL2a)

Cracking (EL2a)







Allow for replacing with wider diameter outlet with provision for rainwater overflow (EL1Pa)

Cracking to base of Chimney (EL3b)

Cracking to plinth (EL1a)

Cracking to plinth (EL3a)

Allow for removing existing vegetation and making good with Lead capping





Rev	Date	Int	Description

btp ARCHITECTS
RIBA Chartered Practice

CLIENT:
Guinness Partnership

PROJECT:
India House Whitworth Street Manchester

DESCRIPTION:
Tympanum Pediment Chimney Detail Existing

PURPOSE OF ISSUE:
S0

DRAWN BY:	CHECKED	DATE:	SCALE @ A1:
LJ	VS	30/09/24	As indicated

JOB NO:	STATUS CODE:	DRAWING NO:	REV
4545	S0	203	

FILE IDENTIFIER:
IH-BTP-00-DR-A-4545_203

Elizabeth House 486 Didsbury Road Heaton Mersey Stockport SK4 3BS
0161 443 1221 info@bernardtaylor.co.uk www.btparchitects.co.uk