

Recently viewe
Green Walk
22
green
walk
E
N
W
G1
T1
T2
G1
College Rd
Manley park primary
school



G1 to drawback



T1 to remove



Original feature wall being impacted by T1



Proximity of T1 stump to wall (at the very back)





Slim self seeded cherry with scarring up the base