
PHOTOGRAPHS-EXTERIOR

CCTV CAMERAS RINGED IN RED



HILTON STREET

Note: the existing cameras shown are proposed to be replaced with black colour and relocated to new positions under the current LBC Application.




STEVENSON SQUARE

PHOTOGRAPHS-INTERIOR

CABLE ROUTES INSIDE THE BUILDING- REFER TO REFERENCE NUMBERS ON DRAWING L2-02 FOR LOCATIONS OF PHOTOGRAPHS

HILTON STREET CAMERA

PHOTOS IN LOCATION **REF 1.**








HILTON ST- FORMER ADT ALARMS HOLE IN ORIGINAL EXTERNAL WALL-ADT BLACK CABLE CAN BE REMOVED AND HOLE CAN BE RE-USED FOR NEW CCTV CABLE. THE NEW CABLE FOLLOWS THE SAME ROUTE AS OTHER CABLES.

PHOTO IN LOCATION **REF 2.**



ALL EXISTING WIRING RUNS ON TOP OF INTERNAL ORIGINAL DECORATIVE CORNICE. THE NEW CABLE FOLLOWS THE SAME ROUTE AS OTHER CABLES.


PHOTO IN LOCATION **REF 3.**





CABLE EXITS LOBBY THROUGH EXISTING ORIGINAL WALL ABOVE ORIGINAL CORNICE AT HIGH LEVEL AND RUNS ALONG BEAM INTO NON-ORIGINAL CABLE CONTAINMENT TRAY RUNNING FULL LENGTH OF SALON.

PHOTOS IN LOCATION **REF 4.**

PERSON OBLITERATION








NON-ORIGINAL CABLE CONTAINMENT TRAY RUNNING FULL LENGTH OF SALON.


PHOTOS IN LOCATION **REF 5.**



CABLE TERMINATIONS AT CCTV /ALARM CONTROL BOX SHOWN IN RED CIRCLE

STEVENSON SQUARE CAMERA

PHOTOS IN LOCATION **REF 6.**





CABLE FROM EXTERIOR THROUGH ORIGINAL MASONRY AND RUN ALONG TOP OF EXISTING ORIGINAL CORNICE AROUND REAR OF CUPBOARD.

PHOTO IN LOCATION **REF 7.**



CABLE FROM REAR OF NON-ORIGINAL CUPBOARD EXITS NEXT TO CCTV CAMERA RINGED IN RED AND FOLLOWS BEAM LINE AT HIGH LEVEL IN THE SAME WAY AS FOR THE HILTON STREET CAMERA. INTO THE NONORIGINAL FULL LENGTH CABLE CONTAINMENT AT HIGH LEVEOL. THEN INTO THE CCTV/ALARM BOX AS SHOWN ON PLAN.

END OF PHOTOGRAPHIC RECORD