





ELEVATION ON NEW ARCHED OPENING
(NEWTON ST AND COURTYARD ELEVATIONS)



SECTION 1
SECTION THROUGH NEW ARCHED OPENING



SECTION 2
SECTION THROUGH NEW HUNG-STRUCTURE
SUPPORTING LEVEL 01 FLOOR BEAM



EXISTING BEAM - COLUMN BEARING STRENGTHENING DETAIL

STANDARD NOTES

1. THIS DRAWING IS TO BE READ IN CONJUNCTION WITH ALL RELEVANT ARCHITECT'S AND ENGINEER'S DRAWINGS AND THE SPECIFICATIONS.
2. THIS DRAWING SHOULD NOT BE SCALED.
3. ALL DIMENSIONS ARE TO BE VERIFIED BY THE CONTRACTOR ON SITE.
4. ALL DISCREPANCIES SHOULD BE REPORTED TO C.A./E.A. PRIOR TO THE COMMENCEMENT OF WORKS.

© CIVIC LIMITED

NOTES:

DATE	REV	DESCRIPTION	DRAWN	CHKD
01.04.2026	P01	RIBA STAGE 3 ISSUE	HEK	JB

CIVIC

team-civic.com

PROJECT

MARLSBRO HOUSE, MANCHESTER

TITLE

SHEET 2 - FLOOR REPAIRS & STRENGTHENING

DRAWING STATUS	STATUS CODE
RIBA STAGE 3	-

CE PROJECT No.	SCALE @ A1	DATE CREATED	DRAWN	CHECKED
1698-01	NTS	MAR.26	HEK	JB

DRAWING No.	REV
1698-CIV-XX-ZZ-D-S-81021	P01