Cedar Mount Academy
Preliminary Risk Assessment

Job Number	Report Date	Client
LKC261292	**18th May 2026**	**Black Cat Building Consultancy**

DOCUMENT QUALITY ASSURANCE

Site Address	Gorton Education Village, 50 Wembley Rd, Manchester M18 7DT
Report Title	Phase 1 Preliminary Risk Assessment
Job Number	LKC261292
Client	Black Cat Building Consultancy

Revision	0	**Date of Issue**	19/05/2026
Document Ref:	LKC261292-A1-PRA-Cedar Mount Academy R0		
Status	Final		
Written By	Alex Evans, Christopher Kay		
Approved By	Catherine Baranek		

DISCLAIMER

This report has been prepared by LK Consult Ltd (LKC) who have exercised such professional skill, care and diligence as may reasonably be expected of a properly qualified and competent consultant, experienced in preparing reports of a similar scope.

However, to the extent that the report is based or relies upon information contained in records, reports or other materials provided to LKC, which have not been independently produced or verified, LKC gives no warranty, representation, or assurance as to the accuracy or completeness of such information.

This report is prepared solely for the benefit of the client named above. It may not be relied upon by or submitted to a third party for their reliance for the purposes of valuation, mortgage, insurance, and regulatory approval until all invoices have been settled in full.

Those using this information in subsequent assessments or evaluations do so at their own risk.

TABLE OF CONTENTS

1. Introduction 1
2. Historical Review 2
2.1. Historical Map Review 2
3. Environmental Setting 3
4. Preliminary Conceptual Model 4
4.1. Introduction 4
4.2. Potential Contaminants 4
4.3. Potential Receptors 5
4.4. Potential Pathways 5
4.5. Preliminary Contamination Conceptual Model 5
5. Preliminary Geotechnical Risk Assessment 8
6. Summary Conclusions and Recommendations 9
6.1. Summary Conclusions 9
6.2. Recommendations 10

Figures and Plan

Site Location
Proposed Development Plan

Appendices

Appendix A – Historical Maps
Appendix B – Envirocheck Report
Appendix C – Historical BGS Boreholes
Appendix D – Risk Evaluation
Appendix E – References

1. Introduction

LK Consult Ltd (LKC) has been commissioned to carry out a Phase 1 Preliminary Risk Assessment (PRA) for Cedar Mount Academy, Manchester.

In accordance with current guidance (including LCRM[1] and the National Planning Policy Framework (NPPF)[2]), the PRA will include a review of the current site use, site history, geology, hydrogeology, hydrology, mineral search, and a landfill search. Information gathered from the desk study will be used to develop a contamination conceptual model for the site.

In addition, the information gathered will be used to identify potential geotechnical constraints associated with the redevelopment of the site.

Based on the findings of this report, an appropriate site investigation can be derived, if required.

A summary of the site details is presented in Table 1-1. The site location and proposed development plans are appended.

Location	Within Gorton Education Village, South-west of Wembley Road, Gorton, South-east Manchester. Centred at National Grid Reference 388470E, 394810N.
Area	750m^2.
Topography	64 metres Above Ordnance Datum (AOD). Site is approximately level.
Current Site Use	Outdoor communal courtyard within the Cedar Mount Academy grounds with covered shelter-like structure.
Proposed Development	Proposed extension to the west of the existing dining hall to include additional seating, a larger queuing area and 'survery' along with increased kitchen storage space.

Table 1-1: Summary of site details.

2. Historical Review

2.1. Historical Map Review

In compiling the site history, LKC consulted Envirocheck historical mapping (Appendix A) and other public domain maps / aerial photography.

Table 2-1 summarises features on site. Table 2-2 summarises potentially contaminative land uses within approximately 50m and potentially infilled features within approximate 250m.

Site Features	Location on Site	Dates Present		Comments
		From	To	
Pink Bank Plantation	Whole Site	1848	1848	Feature only present on 1848 mapping.
Pond	N	1894	1938	Covers the northern half of the site. Feature no longer present after 1938 mapping.
Playing Field / Open Space	Whole Site	1933	2006	Named as Melland Playing Field 1933 to 1955. From 1974-2006 woodland (non-coniferous woodland) is shown on site. Site is redeveloped by 2009.
School	Whole Site	2009	2026	The area has been developed as a school complex (Gorton Education Village). The site lies within the school grounds, adjacent to the building with a shelter present in the west. It is understood from available online information that Gorton Education Village began construction in 2006 and opened in 2008.

Table 2-1: Summary of site features. Dates are based on available historical map editions.

Surrounding Area Features	Distance (m)	Direction	Dates Present		Comments
			From	To	
2no. Ponds	105, 210	W, E	1848	1848	Features only present on 1848 mapping.
Pit	105	SW	1894	1894	Adjacent to Print Works Farm. No longer present by 1907 mapping.
Nico Ditch	125	N	1848	2026	Feature still present on current (2026) mapping, labelled as a drain. Labelled as Nico Ditch from 1848-1974 (online information suggests this was a historic defensive fortification dug between the 5th and 11th century).
Pond	200	SW	1848	1923	Feature no longer present on 1933 mapping.
Reservoir	230	S	1848	1955	Feature unlabelled until 1894 mapping. Associated with Levenshulme Works. Feature no longer present on 1958 mapping.
Gorton Education Village	Onsite and within the surrounding land		2009	2026	Constructed in 2006 and opened in 2008. The site is split between Melland High School to the south and Cedar Mount Academy to the north. The campus buildings lie to the north and east of the site boundary with playing fields and a yard to the west.

Table 2-2: Summary of potentially contaminative features within 50m and potentially infilled features within 250m. Dates are based on available historical map editions.

3. Environmental Setting

A summary of environmental settings is presented in Table 3-1, based on a review of available environmental data.

Categories[data sources]			Details
Geology[1, 2, 3]	Artificial Ground		No BGS recorded artificial ground.
	Superficial Deposits		Devensian Till (diamicton).
	Bedrock		Chester Formation (sandstone).
	BGS Logs (100m)		BH Ref: SJ89SE168, 100m SE: Filled ground to 1m, grey silty clay to 4m, loose peat to 10m, stiff brown clay to 27m, sand and gravel to 37m, sandstone to 73m.
Hydro-geology[1]	Aquifer Designation	Superficial	Secondary Undifferentiated Aquifer.
		Bedrock	Principal Aquifer.
	Source Protection Zone (SPZ)		Site not within an SPZ.
	Groundwater Abstractions (100m)		None.
Hydrology[1]	Surface Watercourses (100m)		None.
	Flooding Risk[1, 4]		Flood Zone 1.
	Surface Water Abstractions (100m)		None.
	Discharge Consents (onsite)		None.
	Pollution Incidents (onsite)		None.
Minerals & Mining[1,5]	Coal Mining		Not within a Coal Reporting Area. Not within a Development High Risk Area.
	Surface Mineral Extractions (250m)		None.
	Non-Coal Mining Area		No hazard.
Ground Stability[1]	Collapsible Ground		Very low hazard.
	Compressible Ground		No hazard.
	Ground Dissolution		No hazard.
	Landslide		Very low hazard.
	Running Sand		Very low hazard.
	Shrinking / Swelling Clay		Very low hazard.
Landfill Sites (250m)[1]	Known / Registered		234m S – 'Levenshulme Trading Estate'. Industrial and Special waste type. Operational dates not supplied.
	Potentially Infilled Land (non-water and water), based on Envirocheck Report		5no. features: 1m NW, 135m W, 190m N, 227m E, 229m SW, 237m S.
	Potentially Infilled Sites, based on LKC historical review		5no. features: See Table 2-1 and Table 2-2.
Radon Potential[1]			<1% of homes above Action Level. No protective measures are necessary in the construction of new dwellings or extensions.
Designated Sites (50m)[1]			None.
Contemporary Trade Directory (50m)[1]			None.
Fuel Station Entries (50m)[1]			None.

Table 3-1: Summary of the environmental setting.

Notes: Distance in brackets is the distance from site that features are included. Where no distance given, features relate to onsite only.

Data Sources:

1 Envirocheck Report (Appendix A & B).
2 BGS Sheet 76 1:50,000
3 http://mapapps2.bgs.ac.uk/geoindex/home.html
4 https://flood-map-for-planning.service.gov.uk/location
5 The Mining Remediation Authority Web Mapping Services (WMS) / http://coal.decc.gov.uk/en/coal/cms/publications/data/map/map.aspx.

4. Preliminary Conceptual Model

4.1. Introduction

The aim of the conceptual model is to provide a preliminary assessment of the likelihood of a pollutant linkage for each potential combination of contaminant, pathway, and receptor. A conceptual model can be used to make an informed decision on the contamination risks associated with the site and whether further site investigation work is required.

The sections below are therefore divided into potential contaminant, potential pathway and potential receptor as described in LCRM[3], on the premise that, if there is no pollutant linkage, then there will be no risk to the receptor. The final section provides an assessment of the potential pollutant linkages that may still be present on the site if redevelopment were to occur.

4.2. Potential Contaminants

Potential viable contamination sources are detailed in Table 4-1. These are split into onsite sources, offsite sources and underlying geology.

Potential Source	Contaminants
On site	
Made ground below some or all of the site associated with: Pond noted in the northern portion of the site, which may have been infilled. General groundworks / site levelling associated with the construction of the school.	Contamination dependant on the fill material, but could include: Demolition rubble, ash, and clinker: asbestos, heavy metals, sulphates, PAHs[4]. Other fill material sources: unknown organic / inorganic compounds. If organic / putrescible material: hazardous gas (principally carbon dioxide and methane). However, given the age of the infilled pond, significant gas generation is not anticipated.
Surrounding Area	
Surrounding area	No significant contamination sources within influencing distance of the site. Due to the relatively modern age of school building, this is not anticipated to be a significant source.
Offsite potentially infilled features within 250m (pits, pond, reservoir)	Given size, distance and age of features, is not considered to be a source of hazardous gas (principally carbon dioxide and methane).
Underlying Geology	
Radon Affected Area	<1% of homes above Action Level. No protective measures are necessary in the construction of new dwellings or extensions. No further consideration required.
Superficial / Bedrock	Devensian Till (diamicton) over Chester Formation (sandstone). No significant contamination sources identified.

Table 4-1: Potential contamination sources.

4.3. Potential Receptors

Potential receptors are detailed in Table 4-2.

Receptors	
Human health	Future site users (including visitors, students and site workers).
Controlled waters	No surface water receptor within 100m of the site. Secondary Undifferentiated Aquifer. Principal Aquifer.
Buildings.	
Potable water pipes.	

Table 4-2: Potential receptors.

4.4. Potential Pathways

Potential pathways are detailed in Table 4-3.

Pathways		
Soil	Human health[5] (school - proposed development area comprises building extension with no soft landscaping proposed)	Inhalation of vapours outside. Inhalation of vapours inside. Omitted: ingestion of soil, ingestion of soil-derived indoor dust, dermal contact with soil, dermal contact with soil-derived indoor dust, inhalation of soil-derived outdoor dust, inhalation of soil-derived indoor dust, ingestion of contaminated home-grown produce and ingestion of soil attached to home-grown produce.
Soil	Direct contact with receptors (services).	
Groundwater	Infiltration into the ground, through potentially contaminated material (contamination possibly going into solution). Minimal infiltration anticipated given the nature of the proposed development scheme.	
Groundwater and gas	Migration through potentially permeable strata and preferential pathways. Superficial (Till) is likely to be low permeability. Bedrock (sandstone) is likely to be relatively permeable. No preferential pathways are anticipated.	
Gas	Migration into buildings (e.g., via services) and accumulation of gases in confined spaces (potentially causing explosion if methane is present).	

Table 4-3: Potential pathways.

4.5. Preliminary Contamination Conceptual Model

The Preliminary Contamination Conceptual Model is illustrated in Table 5-4.

Generic potential pollutant linkages are described along with an assessment of the risk based upon guidance on probabilities and consequences outlined in CIRIA C552[6].

In order to assess the potential risk for each pollutant linkage, an assessment of the magnitude of the potential consequence (severity) of the risk occurring and the magnitude of the probability (likelihood) of the risk occurring has been considered and classified. This is based on the guidance provided in CIRIA C552 and further details including a risk matrix is provided in Appendix D.

The probability is based on the site history, environmental setting, pathways, and receptors.

Reasonable worst-case consequence has been assumed at this stage.

Where LKC identified a low to very low risk, targeted or low-density intrusive investigation work, a watching brief (during construction work) or no investigation work will be recommended. This will be dependent on the nature of the site and the proposed development.

Where the risk falls into the moderate/low risk, LKC will undertake an assessment to establish what further work will be required.

Where LKC identifies a moderate or higher risk, intrusive investigation work or precautionary remediation is recommended.

Recommendations are discussed further in Section 6.

Due to the minor consequence associated with the phytotoxic effect to flora (i.e., loss of plants in a landscaping scheme), the overall risk for the majority of sites will be very low to low. Where soils contain significant concentrations of heavy metals, in general there will other pollutant linkages (i.e., the risk to human health) that will trigger the requirement for remediation (e.g., a clean environmental cover system). As such the risk to flora associated with phytotoxic contaminants will not be considered further.

The risk to buildings associated with elevated sulphate will be considered as part of the geotechnical assessment and will not be included in the contamination risk assessment.

It should be noted that there may be risk from short term exposure from contaminated soil to site workers. The Preliminary Contamination Conceptual Model deals with long term exposure to key receptors. Acute risks can be easily mitigated by good environmental management of the site during site works. Standard health and safety precautions (as per HSE guidance[7]) should be adopted by all workers involved with site enabling and construction works. Therefore, this receptor is not considered in the contamination conceptual model.

PL	Contaminants of Concern (source)	Pathway	Receptor	Probability	Consequence	Risk	Assessment and Recommendations
1	-	-	-	-	-	-	No viable receptor. No soft landscaping proposed.
2	Naphthalene (PAHs - ash in made ground) Unknown volatile organic compounds (made ground – infilled pond)	Inhalation of vapours. Migration via permeable strata and preferential pathways.	Future site users.	Unlikely	Medium	Low	Unlikely probability given the nature of the development (kitchens / dining area is assumed to be well ventilated), there does not appear to be any confined spaces, and the build-up of potential volatiles is not anticipated. **Recommendation**: Investigation work to confirm the ground conditions. No testing required unless evidence of significant volatile contaminants noted within the soil.
3	Hazardous / Ground gas: methane, carbon dioxide (made ground – infilled pond)	Migration via permeable strata and preferential pathways. Inhalation of gas. Explosion in confined spaces.	Future site users. Buildings.	Unlikely	Severe	Moderate / Low	Unlikely probability given age of infilled pond onsite and surrounding historical infilled features. **Recommendations:** Investigation work to confirm the ground conditions. Gas monitoring / precautionary gas protection measures only required if there is a significant gas source identified.
4	PAHs, metals, other organic / inorganic compounds (made ground – infilled pond)	Migration via permeable strata. Perched waters migration.	Groundwater	Unlikely	Medium	Low	Unlikely probability given significant mobile contaminants not anticipated (given size of feature) and superficial till likely to limit the downward migration of contaminants into the Principal Aquifer. **Recommendations:** Investigation work to confirm the ground conditions. No water sampling or leaching tests required unless evidence of significant potentially mobile contamination is identified in the soil.
5	Naphthalene (ash in made ground) Unknown organic compounds (made ground – infilled pond)	Permeation of pipes. Ingestion of tainted water supply.	Future site users. Water pipes.	Likely	Medium	Moderate	Likely as made ground (of unknown constituents) could be present at potential pipeline depth. **Recommendations:** Confirmation of depth and location of potable water pipes in the proposed extension area. If present within the made ground, sampling and analysis of soils at anticipated pipeline depths (c. 0.75-1.35mbgl). Water pipe assessment required.

Table 4-4: Preliminary Contamination Conceptual Model.
Notes: PL = Pollutant Linkage. Contaminant of Concern (CoC) - See Table 5-1 for contamination sources. See Section 7 for recommendations.

5. Preliminary Geotechnical Risk Assessment

Table 5-1 summarises the possible geotechnical constraints of the site, based on the site history, and environmental settings. Investigation work will be required to confirm the risks and provide a detailed geotechnical assessment and foundation design.

Coal Mining	Site is not within a Development High Risk Area. No further assessment required.
Slope Stability	Site is relatively flat. No further assessment required.
Envirocheck Ground Stability Hazards	No to low hazard identified. No further action required.
Made Ground	Unknown depth and constituent of made ground across the site. A pond was previously present in the northern half of the site – which could contain organic materials and made ground.
Superficial	Unknown strength of soils for foundation design. Clay anticipated below the site. Strata may be variable giving differential settlement.
Bedrock	Unknown depth to bedrock.
Groundwater	Unknown depth and variability of groundwater. Shallow / fluctuating groundwater can affect the strength of the soil, particularly in granular ground. Shallow groundwater can also affect construction works.
Plasticity	Plasticity of clay deposits should be confirmed, particularly where trees are present or proposed, to identify the shrink / swell risk.
Sulphate	Unknown sulphate content of the made ground and natural.

Table 5-1: Summary of geotechnical constraints.

6. Summary Conclusions and Recommendations

6.1. Summary Conclusions

Table 6-1 summarises the site details, historical review, environmental settings.

Current Site Use	Outdoor communal courtyard within the Cedar Mount Academy grounds with covered shelter-like structure.
Proposed Development	Proposed extension to the west of the existing dining hall to include additional seating, a larger queuing area and survery along with increased kitchen storage space.
Main Historical Features	Onsite: Pink Bank Plantation, Pond, Playing Field / Open Space, School. Surrounding Area: Ponds, Nico Ditch, Pit, Reservoir, Gorton Education Village.
Geology / Hydrogeology	Artificial: No BGS recorded artificial. Superficial: Devensian Till (diamicton). Secondary Undifferentiated Aquifer. Bedrock: Chester Formation (sandstone). Principal aquifer.
Landfills / Infilled ground	No recorded landfills. Potentially infilled ground identified.

Table 6-1: Summary of site details, historical review, environmental settings.

A preliminary contamination conceptual model has been produced by LKC, which is summarised in Table 6-2.

Pollutant Linkage	**Contaminants**	**Risk**
PL1: Human health risk from direct contact with receptors – no pollutant linkage as there is no pathway (hardstood only).	N/A	**N/A**
PL2: Volatile contaminants posing a risk to receptors via the inhalation of vapours.	Naphthalene, other volatile contaminants	**Low**
PL3: Gas posing a risk to buildings and receptors via the migration of gas into building causing explosion and asphyxiation.	Hazardous / Ground Gas	**Moderate / Low**
PL4: Mobile contamination posing a risk to controlled waters via the migration through permeable strata.	PAHs, metals, other organic / organic contaminants	**Low**
PL5: Organic contaminants posing a risk to receptors.	Naphthalene, other organic contaminants	**Moderate**

Table 6-2: Summary risk table.

A preliminary geotechnical assessment has been carried out by LKC. Table 6-3 summarises the geotechnical constraints.

Coal Mining	Site is not within a Development High Risk Area. No further assessment required.
Slope Stability	Site is relatively flat. No further assessment required.
Made Ground	Unknown depth and constituent of made ground across the site.
Superficial	Unknown strength of soils for foundation design.
Bedrock	Unknown depth to bedrock.
Groundwater	Unknown depth and variability of groundwater.
Plasticity	Plasticity of clay deposits should be confirmed.
Sulphate	Unknown sulphate content of the made ground and natural.

Table 6-3: Summary of geotechnical constraints.

Based upon the available information, LKC conclude there is a viable contamination and geotechnical risk and therefore further assessment is recommended.


6.2. Recommendations

Recommendations are provided in Table 6-4.

Contamination Status	There is sufficient information on the potential contaminative status of the site to allow conditional approval of a planning application, based on the proposed end use detailed in the PRA.
Further Assessment Recommendations	Phase 2 investigation to be carried out in line with current guidance, including BS10175[8], BS5930[9] CIRIA C665[10], RB17[11] and BS8485[12].
Type of Investigation Work	Boreholes.
PL 1, 2, 5	Intrusive investigation work recommended to confirm ground conditions across the site. Testing of contaminants of concern based on preliminary conceptual model and field observations (PID tests and visual / olfactory evidence).
PL 3	Intrusive investigation to confirm ground conditions. If significant gas source and pathway identified, gas monitoring or gas protection measures may be required.
PL 4	Intrusive investigation to confirm ground conditions. Groundwater sampling, subject to ground conditions encountered.
Reporting	Information from the above can be used to carry out a contamination and geotechnical assessment and provide a remediation strategy for the site.


Table 6-4: Recommendations.

Figures



Existing Dining Plan

Scale 1:100@A0



Proposed Dining Plan

Scale 1:100@A0

This drawing is copyright and remains the property of Black Cat Building Consultancy.

All drawings are to be read in conjunction with all accompanying information. All dimensions must be checked and verified on site before commencing any work or producing drawings.

Any discrepancy's found should be imediately notified to Black Cat Building Consultancy.

Once drawing is in general circulation Black Cat Building Consultancy take no responsibility for the accuracy or information taken from them.

Rev	Description	Dr By	Ap By	Date
A	Extension increased to include additional kitchen space	RB	AMcG	24.10.2025

CLIENT NAME
Bright Futures Educational Trust

CONTRACT/PROJECT NAME
GEV
Dining Room Extension

DRAWING TITLE
Existing and Proposed Plans

PROJECT NUMBER	DATE
	05.08.2025
DRAWING NUMBER	**REVISION**
BFET-GEV-DRE-00-P-00-001	A
SCALE	**DRAWN BY**
1:100 @A0	RB
ISSUE STATUS	**APPROVED BY**
Comment	AMcG

THE LIGHTWELL
67-63 BROWN ST
MANCHESTER
M2 2JG
0161 359 4313
enquiries@blcconsultancy.co.uk
BLACK CAT
BUILDING CONSULTANCY

0 0.5 1m 2m 5m

1:100

Appendix A – Historical Maps

Historical Mapping Legends

Ordnance Survey County Series 1:10,560

Gravel Pit
Sand Pit
Other Pits
Quarry
Shingle
Orchard
Osiers
Reeds
Marsh
Mixed Wood
Deciduous
Brushwood
Fir
Furze
Rough Pasture
Arrow denotes flow of water
Trigonometrical Station
Site of Antiquities
Bench Mark
Pump, Guide Post, Signal Post
Well, Spring, Boundary Post
·285 Surface Level
Sketched Contour
Instrumental Contour
Main Roads
Fenced
Un-Fenced
Minor Roads
Fenced
Un-Fenced
Sunken Road
Raised Road
Road over Railway
Railway over River
Railway over Road
Level Crossing
Road over River or Canal
Road over Stream
Road over Stream
County Boundary (Geographical)
County & Civil Parish Boundary
Administrative County & Civil Parish Boundary
Co. Boro. Bdy. County Borough Boundary (England)
Co. Burgh Bdy. County Burgh Boundary (Scotland)
R.D. Bdy. Rural District Boundary
Civil Parish Boundary

Ordnance Survey Plan 1:10,000

Chalk Pit, Clay Pit or Quarry
Gravel Pit
Sand Pit
Disused Pit or Quarry
Refuse or Slag Heap
Lake, Loch or Pond
Dunes
Boulders
Coniferous Trees
Non-Coniferous Trees
Orchard
Scrub
Coppice
Bracken
Heath
Rough Grassland
Marsh
Reeds
Saltings
Building
Direction of Flow of Water
Shingle
Sand
Glasshouse
Pylon
Pylon
Electricity Transmission Line
Sloping Masonry
Cutting
Embankment
Standard Gauge Multiple Track
Road Under
Road Over
Level Crossing
Foot Bridge
Standard Gauge Single Track
Siding, Tramway or Mineral Line
Narrow Gauge
Geographical County
Administrative County, County Borough or County of City
Municipal Borough, Urban or Rural District, Burgh or District Council
Borough, Burgh or County Constituency
Shown only when not coincident with other boundaries
Civil Parish
Shown alternately when coincidence of boundaries occurs

BP, BS	Boundary Post or Stone	Pol Sta	Police Station
Ch	Church	PO	Post Office
CH	Club House	PC	Public Convenience
F E Sta	Fire Engine Station	PH	Public House
FB	Foot Bridge	SB	Signal Box
Fn	Fountain	Spr	Spring
GP	Guide Post	TCB	Telephone Call Box
MP	Mile Post	TCP	Telephone Call Post
MS	Mile Stone	W	Well

1:10,000 Raster Mapping


Gravel Pit
Refuse tip or slag heap
Rock
Rock (scattered)
Boulders
Boulders (scattered)
Shingle
Mud
Sand
Sand Pit
Slopes
Top of cliff
General detail
Underground detail
Overhead detail
Narrow gauge railway
Multi-track railway
Single track railway
County boundary (England only)
Civil, parish or community boundary
District, Unitary, Metropolitan, London Borough boundary
Constituency boundary
Area of wooded vegetation
Non-coniferous trees
Non-coniferous trees (scattered)
Coniferous trees
Coniferous trees (scattered)
Positioned tree
Orchard
Coppice or Osiers
Rough Grassland
Heath
Scrub
Marsh, Salt Marsh or Reeds
Water feature
Flow arrows
MHW(S) Mean high water (springs)
MLW(S) Mean low water (springs)
Telephone line (where shown)
Electricity transmission line (with poles)
BM 123.45 m Bench mark (where shown)
Triangulation station
Point feature (e.g. Guide Post or Mile Stone)
Pylon, flare stack or lighting tower
Site of (antiquity)
Glasshouse
General Building
Important Building

LK CONSULT

Historical Mapping & Photography included:

Mapping Type	Scale	Date	Pg
Lancashire And Furness	1:10,560	1848	3
Cheshire	1:10,560	1882	4
Lancashire And Furness	1:10,560	1894	5
Cheshire	1:10,560	1899	6
Lancashire And Furness	1:10,560	1908 - 1911	7
Cheshire	1:10,560	1911	8
Lancashire And Furness	1:10,560	1922 - 1923	9
Lancashire And Furness	1:10,560	1933 - 1934	10
Cheshire	1:10,560	1938	11
Lancashire And Furness	1:10,560	1938	12
Lancashire And Furness	1:10,560	1938	13
Ordnance Survey Plan	1:10,000	1955 - 1956	14
Ordnance Survey Plan	1:10,000	1965 - 1968	15
Manchester	1:25,000	1975	16
Ordnance Survey Plan	1:10,000	1976	17
Ordnance Survey Plan	1:10,000	1981 - 1985	18
Ordnance Survey Plan	1:10,000	1987	19
Ordnance Survey Plan	1:10,000	1990 - 1993	20
10K Raster Mapping	1:10,000	1999	21
10K Raster Mapping	1:10,000	2006	22
VectorMap Local	1:10,000	2025	23

Historical Map - Slice A



Order Details

Order Number: 401117746_1_1
Customer Ref: LKC261292
National Grid Reference: 388470, 394810
Slice: A
Site Area (Ha): 0.02
Search Buffer (m): 1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk

Russian Military Mapping Legends

1:5,000 and 1:10,000 mapping

a. Not drawn to scale b. Drawn to scale

- Government and Administrative Buildings
- Military and Industrial Buildings
- Military and Communication Areas
- Subway Entrance
- Fireproof Building
- Prominent Fireproof Building
- Non-fireproof Building
- Non-fireproof Building (non-dwelling)
- Factory, mill, and flour mill, with chimneys
- Factory, mill, and flour mill, without chimneys
- Power Station, drawn to scale
- Hydroelectric Power Station
- Radio Station, drawn to scale
- Telephone Station, drawn to scale
- Abandoned Open-pit Mine or Quarry
- Open-pit Salt Mine
- Pit
- Oil Deposit or Well
- Oil Seepage
- Tailings Pile
- Fuel Storage Tanks
- Natural Gas Tank
- Bench Mark
- Drill Hole
- Burial Mound
- Triangulation Point on Burial Mound
- Single-track Railroad
- Double-track Railroad and Station Building
- Coniferous Forest
- Deciduous Forest
- Mixed Forest
- Lawns
- Citrus Orchard
- Wet Ground
- Scattered Vegetation

243,8 Values for prominent elevations

186.0 Numbers for spot elevations, depth soundings, contour lines, etc.

0,2 Velocity of the current, width of river bed, depth of river

Fractional terms: length and capacity of bridges; depth of fords and condition of the river bottom; height of forest and the diameter of trees

Russian Alphabet (For reference and phonetic interpretation of map text)

А а (A)	З з (Z)	П п (P)	Ч ч (CH)
Б б (B)	И и (I)	Р р (R)	Ш ш (SH)
В в (V)	Й й (Y)	С с (S)	Щ щ (SHCH)
Г г (G)	К к (K)	Т т (T)	ъ (–)
Д д (D)	Л л (L)	У у (U)	ы (Y)
Е е (E)	М м (M)	Ф ф (F)	ь (')
Ё ё (YO)	Н н (N)	Х х (KH)	Э э (E)
Ж ж (ZH)	О о (O)	Ц ц (TS)	Ю ю (YU or IU)
			Я я (YA or IA)

1:25,000 mapping

a. Not drawn to scale b. Drawn to scale

- Government and Administrative Buildings
- Military and Industrial Buildings
- Military and Communication Areas
- Subway Entrance
- Partly Demolished Buildings
- Demolished Buildings
- Built-Up Area with Fireproof Buildings Predominant
- Built-Up Area with Non-Fireproof Buildings Predominant
- Individual Fireproof Building
- Prominent Industrial Building
- Individual Dwelling, Fireproof
- Ruins of an Individual Dwelling
- Factory or Mill Chimney
- Factory or Mill with Chimney
- Factory or Mill without Chimney
- Mine or Open Pit Mine
- Operating Shaft or Mine
- Non-Operating Shaft or Mine
- Salt Mine
- Tailings Pile
- Pit
- Stone Quarry
- Gas Pump or Service Station
- Fuel Storage or Natural Gas Tank
- Oil or Natural Gas Derrick
- Small Hydroelectric Power Station
- Power Station
- Transformer Station
- Cemetery
- Burial Mound (height in metres)
- Triangulation Point on Burial Mound
- Triangulation Point
- Bench Mark
- Bench Mark (monumented)
- Telegraph Office
- Telephone Station
- Radio Station
- Radio Tower
- Airfield or Seaplane Base
- Landing Strip
- Main Highway
- Highway under Construction
- Improved Dirt Road (former truck road)
- Double-track Railroad with First Class Station
- Dismantled Railroad
- Railroad Under Construction
- Shore Embankment
- River or Ditch with Embankment
- Well
- Water Reservoir or Rain Water Pit
- Spring
- Isobath with value
- Heavy (Index) Contour Line
- Contour Line and Value
- Half Contour Line
- Spot Elevation Value
- Coniferous
- Deciduous
- Mixed
- Scrub


Key to Numbers on Mapping

LK CONSULT

Historical Mapping & Photography included:

Mapping Type	Scale	Date	Pg
Lancashire And Furness	1:10,560	1848	3
Cheshire	1:10,560	1882	4
Lancashire And Furness	1:10,560	1894	5
Cheshire	1:10,560	1899	6
Lancashire And Furness	1:10,560	1908 - 1911	7
Cheshire	1:10,560	1911	8
Lancashire And Furness	1:10,560	1922 - 1923	9
Lancashire And Furness	1:10,560	1933 - 1934	10
Cheshire	1:10,560	1938	11
Lancashire And Furness	1:10,560	1938	12
Lancashire And Furness	1:10,560	1938	13
Ordnance Survey Plan	1:10,000	1955 - 1956	14
Ordnance Survey Plan	1:10,000	1965 - 1968	15
Manchester	1:25,000	1975	16
Ordnance Survey Plan	1:10,000	1976	17
Ordnance Survey Plan	1:10,000	1981 - 1985	18
Ordnance Survey Plan	1:10,000	1987	19
Ordnance Survey Plan	1:10,000	1990 - 1993	20
10K Raster Mapping	1:10,000	1999	21
10K Raster Mapping	1:10,000	2006	22
VectorMap Local	1:10,000	2025	23

Russian Map - Slice A



Order Details


Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



LK CONSULT


Lancashire And Furness

Published 1848


Source map scale - 1:10,560

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)



Historical Map - Slice A



Order Details


Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT

Cheshire

Published 1882

Source map scale - 1:10,560


The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)

003A00
1882
1:10,560

01000
1882
1:10,560

Historical Map - Slice A




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT


Lancashire And Furness

Published 1894


Source map scale - 1:10,560

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)



Historical Map - Slice A




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT


Cheshire

Published 1899


Source map scale - 1:10,560

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)



Historical Map - Slice A




Order Details


Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk


GORTON U.D.
GORTON
NORTH MANCHESTER
CROWCROFT PARK
LEVENSHULME U.D.
SUNNY BROW PARK
RYDER BROW
BROOKSIDE
Pink Bank Lane
Parly. Co. Div. U.D.B.
Parly. Co. Div. Union & U.D.B.
Co. Boro. By.
Belle Vue Station
Hyde Road Station
Gorton Mount High School
Levenshulme Print Works
Reddish Iron Works
Smallpox Hospital
Bull's Head Inn
Sewage Works (Gorton U.D.C.)
Refuse Destructor (Levenshulme U.D.C.)
Fallowfield Brook
Tow Path
Swing Bridge
Reservoir
Sandfold
Mill Lane
Fir Tree Farm
Summerfield House
Chemical Works
Cotton Mill
Aqueduct
Climax Engineering Works
Standard Works
Boat House
Print Works Farm
Green Bank Farm
Botany Bay Cottage
Wingate House
Rope Works
Laundry
Ash Lea
Highfield Iron Works
Carpet Works
Brick Works
Levenshulme Bleach & Dye Works
High Field Farm
Broom Ho.
Yew Tree Farm
Hotel
Library
Tool Works
Dye Works
Iron Works
Tarpaulin Works
Mount Farm
Pink Bank Cottages
Crofcroft House
Levenshulme Lodge
Gorton House
Lodges
Conduit Gorton Br.
Manchester-Central Station Line
G.C.R.
Sheffield & Midland Joint Railway
Manchester & Stockport Branch
Cemetery
Ontarion Church
St. Philip Church
Maiden's Bridge
Spring Hill Farm
Saw Mills
Fox Pub
Lower Cateknowl
Higher Cateknowl
Football Ground
Cricket Ground
Bowling Green
Tennis Courts
Recreation Ground
Sch.
Ch.
R.C. Chap.
Convent
Public Baths
Post Office
Mort. Chaps.
Lower Cottage
Gorton House
Staufield Lodge
Pump House
Swing Bridge
Brick Works
Reservoir
Reservoirs
Laundry
Refuse Destructor
Ash Lea
Highfield
Carpet Works
Tennis Courts
Recreation Ground
Boat House
Climax Engineering Works
Standard Works
Sandfold
Fir Tree Farm
Summerfield House
Pump House
Chemical Works
Cotton Mill
Aqueduct
Swing Bridge
Mill Lane
Tow Path
Reddish Iron Works
Levenshulme Print Works



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT

Cheshire

Published 1911

Source map scale - 1:10,560


The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)

003ASE
1911
1:10,560

010NE
1911
1:10,560

Historical Map - Slice A



Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



LK CONSULT


Lancashire And Furness

Published 1922 - 1923


Source map scale - 1:10,560

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)



Historical Map - Slice A



Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT

Lancashire And Furness

Published 1933 - 1934


Source map scale - 1:10,560

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)

104SE 1933 1:10,560	105SW 1934 1:10,560
111NE 1934 1:10,560	112NW 1934 1:10,560

Historical Map - Slice A




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk


387200
387400
387600
387800
388000
388200
388400
388600
388800
389000
389200
389400
389600
389800
396000
395800
395600
395400
395200
395000
394800
394600
394400
394200
394000
393800
393600
GORTON U.D.
GORTON
RIDER BROW
R E D D I S H
NORTH
BACK LEVENSHULME
Levenshulme Print Works
Reddish Iron Works
Cotton Mill
Chemical Works
Climax Engineering Works
Fallowfield Brook
MANCHESTER CENTRAL STATION LINE
M.S.S.C. & L.N.E.R.
STOCKPORT, DISLEY & WOODLEY JUNCTION CANAL
Refuse Destructor Levenshulme U.D.C.
Levenshulme Bleach & Dye Wks.
Reservoir
Filter Beds
Sluice
Aqueduct
Swing Bridge
Fire Sta.
Pump House
Boat House
Sandfold
Stanfold Lodge
Gorton House
Gorton Lodges
Spring Hill Farm
High Field Farm
Print Works Farm
Rope Works
Saw Mills
Lower Cottage
Crow Hall
Condyke
Maiden's Br.
Leather Wks.
Ch.
Sch.
Sch
Cemy.
Chapl.
Tramway
Co. Boro. & Union By.
U.D. By.
Parly. Co. Div. & U.D. By.
Slice Ditch
B.M. 224·4
B.M. 207·7
B.M. 218·4
B.M. 214·3
B.M. 226·3
B.M. 256·6
B.M. 256·1
B.M. 260·2
B.M. 269·5
B.M. 259·0
B.M. 246·1
B.M. 209·1
Maiden's Br.
Gorton Station
Reddish North Station
Longford Bridge
Swing Bridge
Refuse Destructor
Levenshulme U.D.C.
Filter Beds
Reservoir
Sluice
Rope Works
Wingate Ho.
Lane
Pinfold
Ramp
Tramway
Aqueduct
Climax Engineering Works
Boat House
Sandfold
Reddish Iron Works
Cotton Mill
Chemical Works
Pump House
Fire Sta.
Swing Bridge
Longford Bridge
Levenshulme Bleach & Dye Wks.
High Field Farm
High Field
Print Works Farm
Spring Hill Farm
Saw Mills
Lower Cottage
Crow Hall
Condyke
Maiden's Br.
Leather Wks.
Gorton Station
Reddish North Station
Stanfold Lodge
Gorton House
Gorton Lodges
Ch.
Sch.
Sch
Cemy.
Chapl.
Tramway
Co. Boro. & Union By.
U.D. By.
Parly. Co. Div. & U.D. By.
Slice Ditch
B.M. 224·4
B.M. 207·7
B.M. 218·4
B.M. 214·3
B.M. 226·3
B.M. 256·6
B.M. 256·1
B.M. 260·2
B.M. 269·5
B.M. 259·0
B.M. 246·1
B.M. 209·1
NORFOLK RD
BUCKLEY ROAD
HEATHCOTE ROAD
CRAIG ROAD
KENMOOR ROAD
KENTON AVE
CRAVETON ROAD
DARRAS ROAD
TRUST ROAD
BUTTON ROAD
BALMAIN AVE
MELLAND ROAD
HEMSWORTH ROAD
WHITBURY AVE
MARSHFIELD ROAD
MARSDEN CRES
HOLMCROFT ROAD
WATLING ROAD
SUNNY BROW PARK
RYDER BROW ROAD
DEAN ROAD
ALEXANDRA ROAD
HIGHGATE DRIVE
TREE AV
CONCORDE AVE
MARKHAM AVE
GRANVILLE ROAD
ATHOL ST.
CRANBROOK ROAD
BURRFIELD ROAD
LANGDALE ROAD
BELFIELD ROAD
BELFORD CRES.
BELFORD AVE
DISCOMBE ROAD
CLAYTON AVE
KESTREL DR
LARKSPUR
MILLFIELD DR
MARSH HILL AVE
MARSH HILL CRES
MARSH HILL DR
WILLOW ST
WILLOW STREET
WILLOW GROVE
WILLOW GROVE ROAD
WILLOW GROVE STREET
WILLOW GROVE ROAD
WILLOW GROVE STREET
WILLOW GROVE ROAD
WILLOW GROVE STREET



LK CONSULT

Lancashire And Furness

Published 1938


Source map scale - 1:10,560

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)

104SE 1938 1:10,560	105SW 1938 1:10,560
111NE 1938 1:10,560	112NW 1938 1:10,560

Historical Map - Slice A




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

0 400 m

LK CONSULT


Lancashire And Furness

Published 1938


Source map scale - 1:10,560

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)



Historical Map - Slice A




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT

Ordnance Survey Plan

Published 1955 - 1956

Source map scale - 1:10,000


The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)

SJ89NE
1956
1:10,560

SJ89SE
1955
1:10,560

Historical Map - Slice A



Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT

Ordnance Survey Plan

Published 1965 - 1968

Source map scale - 1:10,000


The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)

SJ89NE
1968
1:10,560

SJ89SE
1965
1:10,560

Historical Map - Slice A



Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292



© Copyright Landmark Information Group Ltd. All Rights Reserved.

0 400 m

LK CONSULT


Manchester

Published 1975


Source map scale - 1:25,000

These maps were produced by the Russian military during the Cold War between 1950 and 1997, and cover 103 towns and cities throughout the U.K. The maps are produced at 1:25,000, 1:10,000 and 1:5,000 scale, and show detailed land use, with colour-coded areas for development, green areas, and non-developed areas. Buildings are coloured black and important building uses (such as hospitals, post offices, factories etc.) are numbered, with a numbered key describing their use.
They were produced by the Russians for the benefit of navigation, as well as strategic military sites and transport hubs, for use if they were to have invaded the U.K. The detailed information provided indicates that the areas were surveyed using land-based personnel, on the ground, in the cities that are mapped.

Map Name(s) and Date(s)



Russian Map - Slice A




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT


Ordnance Survey Plan

Published 1976


Source map scale - 1:10,000

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)



Historical Map - Slice A



Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT

Ordnance Survey Plan

Published 1981 - 1985

Source map scale - 1:10,000


The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)

SJ89NE
1981
1:10,000

SJ89SE
1985
1:10,000

Historical Map - Slice A




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT


Ordnance Survey Plan

Published 1987


Source map scale - 1:10,000

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)



Historical Map - Slice A



Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT

Ordnance Survey Plan

Published 1990 - 1993

Source map scale - 1:10,000


The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)

SJ89NE
1993
1:10,000

SJ89SE
1990
1:10,000

Historical Map - Slice A



Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



LK CONSULT

10k Raster Mapping

Published 1999

Source map scale - 1:10,000


The historical maps shown were produced from the Ordnance Survey`s 1:10,000 colour raster mapping. These maps are derived from Landplan which replaced the old 1:10,000 maps originally published in 1970. The data is highly detailed showing buildings, fences and field boundaries as well as all roads, tracks and paths. Road names are also included together with the relevant road number and classification. Boundary information depiction includes county, unitary authority, district, civil parish and constituency.

Map Name(s) and Date(s)

SJ89NE
1999
1:10,000

SJ89SE
1999
1:10,000

Historical Map - Slice A



Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000


Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk


387200
387400
387600
387800
388000
388200
388400
388600
388800
389000
389200
389400
389600
389800
396000
395800
395600
395400
395200
395000
394800
394600
394400
394200
394000
393800
393600
Stadium
Sports Centre
Recreation Ground
Gorton
Gore Brook
Sunny Brow Park
Maiden's Bridge
Gorton Lower Reservoir
Debdale
Playing Field
Allot Gdns
Cemetery
Football Ground
War Meml
Cricket Ground
Crowcroft Park
Schools
Sports Hall
Melland Field (Sports Ground)
Longden Units
Sports Ground
Reservoir
Sandfold Lane (Track)
North Reddish
Trading Estate
Depot
Green Bank Fields
Factory
Library
Levenshulme
Cricket Ground
Houldsworth Golf Course
Allowfield Brook
Highfield Country Park
Highfield House
Boro Const & Met Dist Bdy
Club House
New Mill
North Reddish Park
Pavilion
Playing Fields
Aqueduct
Depot
Tnd Est
Masts
Subway
Subways
Library
Pav
Recn Gd
Sch
Schs
Sta
PO
PW
Wks
Path
Drain
Track
Weir
FB
Hall
Pavilion
Factory
Cricket Ground
Allot Gdns
Playing Fields
Tnd Est
Boro Const & Met Dist Bdy
Nelstrop Road North
Sandfold Lane (Track)
BUCKLEY ROAD
HEATHCOTE ROAD
CRAIG ROAD
THOMSON ROAD
DARRAS ROAD
TRUST ROAD
SUTTON ROAD
HEMSWORTH ROAD
WHITSBURY AVE
MELLAND ROAD
LONGSIGHT ROAD
YEADON RD
ASHBURNHAM ROAD
ASHBURY ROAD
ASHBURTON ROAD
ASHBURNHAM DRIVE
ASHBURNHAM GROVE
ASHBURNHAM CRESCENT
ASHBURNHAM CLOSE
ASHBURNHAM PLACE
ASHBURNHAM



© Crown copyright and database rights 2026 OS AC0000813445

LK CONSULT

VectorMap Local

Published 2025

Source map scale - 1:10,000


VectorMap Local (Raster) is Ordnance Survey's highest detailed 'backdrop' mapping product. These maps are produced from OS's VectorMap Local, a simple vector dataset at a nominal scale of 1:10,000, covering the whole of Great Britain, that has been designed for creating graphical mapping. OS VectorMap Local is derived from large-scale information surveyed at 1:1250 scale (covering major towns and cities),1:2500 scale (smaller towns, villages and developed rural areas), and 1:10 000 scale (mountain, moorland and river estuary areas).

Map Name(s) and Date(s)

SJ89NE 2025 Variable

SJ89SE 2025 Variable

Historical Map - Slice A



Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details


Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk

Historical Mapping Legends

Ordnance Survey County Series and Ordnance Survey Plan 1:2,500



County Boundary (Geographical)

County & Civil Parish Boundary


Administrative County & Civil Parish Boundary

Co. Boro. Bdy. County Borough Boundary (England)

Co. Burgh Bdy. County Burgh Boundary (Scotland)

B P B S	Boundary Post or Stone	P.C.B	Police Call Box
B.R.	Bridle Road	P	Pump
E.P	Electricity Pylon	S.P	Signal Post
F.B.	Foot Bridge	St.	Sluice
F.P.	Foot Path	Sp.	Spring
G.P	Guide Post or Board	T.C.B	Telephone Call Box
M.S	Mile Stone	Tr.	Trough
M.P M.R	Mooring Post or Ring	W	Well

Ordnance Survey Plan, Additional SIMs and Supply of Unpublished Survey Information 1:2,500 and 1:1,250



County Boundary (Geographical)

County & Civil Parish Boundary

Civil Parish Boundary


Admin. County or County Bor. Boundary

L B Bdy London Borough Boundary

Symbol marking point where boundary mereing changes

BH	Beer House	P	Pillar, Pole or Post
BP, BS	Boundary Post or Stone	PO	Post Office
Cn, C	Capstan, Crane	PC	Public Convenience
Chy	Chimney	PH	Public House
D Fn	Drinking Fountain	Pp	Pump
El P	Electricity Pillar or Post	SB, S Br	Signal Box or Bridge
FAP	Fire Alarm Pillar	SP, SL	Signal Post or Light
FB	Foot Bridge	Spr	Spring
GP	Guide Post	Tk	Tank or Track
H	Hydrant or Hydraulic	TCB	Telephone Call Box
LC	Level Crossing	TCP	Telephone Call Post
MH	Manhole	Tr	Trough
MP	Mile Post or Mooring Post	Wr Pt, Wr T	Water Point, Water Tap
MS	Mile Stone	W	Well
NTL	Normal Tidal Limit	Wd Pp	Wind Pump

Large-Scale National Grid Data 1:2,500 and 1:1,250



Civil parish/community boundary

District boundary

County boundary

Boundary post/stone

Boundary mereing symbol (note: these always appear in opposed pairs or groups of three)


Bks	Barracks	P	Pillar, Pole or Post
Bty	Battery	PO	Post Office
Cemy	Cemetery	PC	Public Convenience
Chy	Chimney	Pp	Pump
Cis	Cistern	Ppg Sta	Pumping Station
Dismtd Rly	Dismantled Railway	PW	Place of Worship
El Gen Sta	Electricity Generating Station	Sewage Ppg Sta	Sewage Pumping Station
El P	Electricity Pole, Pillar	SB, S Br	Signal Box or Bridge
El Sub Sta	Electricity Sub Station	SP, SL	Signal Post or Light
FB	Filter Bed	Spr	Spring
Fn / D Fn	Fountain / Drinking Ftn.	Tk	Tank or Track
Gas Gov	Gas Valve Compound	Tr	Trough
GVC	Gas Governer	Wd Pp	Wind Pump
GP	Guide Post	Wr Pt, Wr T	Water Point, Water Tap
MH	Manhole	Wks	Works (building or area)
MP, MS	Mile Post or Mile Stone	W	Well

LK CONSULT

Historical Mapping & Photography included:

Mapping Type	Scale	Date	Pg
Cheshire	1:2,500	1872	2
Lancashire And Furness	1:2,500	1893	3
Cheshire	1:2,500	1898	4
Lancashire And Furness	1:2,500	1907 - 1908	5
Cheshire	1:2,500	1910	6
Lancashire And Furness	1:2,500	1933	7
Ordnance Survey Plan	1:1,250	1951 - 1958	8
Ordnance Survey Plan	1:2,500	1952 - 1958	9
Additional SIMs	1:1,250	1958 - 1989	10
Ordnance Survey Plan	1:1,250	1968 - 1974	11
Supply of Unpublished Survey Information	1:1,250	1974	12
Additional SIMs	1:1,250	1982 - 1991	13
Additional SIMs	1:1,250	1988	14
Large-Scale National Grid Data	1:1,250	1992	15
Large-Scale National Grid Data	1:1,250	1994 - 1995	16
Large-Scale National Grid Data	1:1,250	1995	17
Historical Aerial Photography	1:2,500	2000	18

Historical Map - Segment A13



Order Details


Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



LK CONSULT


Cheshire

Published 1872


Source map scale - 1:2,500

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

Map Name(s) and Date(s)



Historical Map - Segment A13




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



LK CONSULT


Lancashire And Furness

Published 1893


Source map scale - 1:2,500

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

Map Name(s) and Date(s)



Historical Map - Segment A13




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292



LK CONSULT


Cheshire

Published 1898


Source map scale - 1:2,500

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

Map Name(s) and Date(s)



Historical Map - Segment A13




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292



LK CONSULT


Lancashire And Furness

Published 1907 - 1908


Source map scale - 1:2,500

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

Map Name(s) and Date(s)



Historical Map - Segment A13




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT


Cheshire

Published 1910


Source map scale - 1:2,500

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

Map Name(s) and Date(s)



Historical Map - Segment A13




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT


Lancashire And Furness

Published 1933


Source map scale - 1:2,500

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

Map Name(s) and Date(s)



Historical Map - Segment A13




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT


Ordnance Survey Plan

Published 1951 - 1958


Source map scale - 1:1,250

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

Map Name(s) and Date(s)



Historical Map - Segment A13




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



LK CONSULT

Ordnance Survey Plan

Published 1952 - 1958

Source map scale - 1:2,500


The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

Map Name(s) and Date(s)

SJ8895
1952
1:2,500

SJ8894
1958
1:2,500

Historical Map - Segment A13




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT

Additional SIMs

Published 1958 - 1989


Source map scale - 1:1,250

The SIM cards (Ordnance Survey's `Survey of Information on Microfilm') are further, minor editions of mapping which were produced and published in between the main editions as an area was updated. They date from 1947 to 1994, and contain detailed information on buildings, roads and land-use. These maps were produced at both 1:2,500 and 1:1,250 scales.

Map Name(s) and Date(s)

SJ8895SW 1985 1:1,250	SJ8895SE 1989 1:1,250
SJ8894NW 1988 1:1,250	SJ8894NE 1986 1:1,250
SJ8894SW 1982 1:1,250	SJ8894SE 1958 1:1,250

Historical Map - Segment A13




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



LK CONSULT


Ordnance Survey Plan

Published 1968 - 1974


Source map scale - 1:1,250

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

Map Name(s) and Date(s)



Historical Map - Segment A13




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292



LK CONSULT


Supply of Unpublished Survey Information

Published 1974


Source map scale - 1:1,250

SUSI maps (Supply of Unpublished Survey Information) were produced between 1972 and 1977, mainly for internal use at Ordnance Survey. These were more of a `work-in-progress' plan as they showed updates of individual areas on a map. These maps were unpublished, and they do not represent a single moment in time. They were produced at both 1:2,500 and 1:1,250 scales.

Map Name(s) and Date(s)



Historical Map - Segment A13




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

0 100 m

LK CONSULT


Additional SIMs

Published 1982 - 1991


Source map scale - 1:1,250

The SIM cards (Ordnance Survey's `Survey of Information on Microfilm') are further, minor editions of mapping which were produced and published in between the main editions as an area was updated. They date from 1947 to 1994, and contain detailed information on buildings, roads and land-use. These maps were produced at both 1:2,500 and 1:1,250 scales.

Map Name(s) and Date(s)



Historical Map - Segment A13




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT


Additional SIMs

Published 1988


Source map scale - 1:1,250

The SIM cards (Ordnance Survey's `Survey of Information on Microfilm') are further, minor editions of mapping which were produced and published in between the main editions as an area was updated. They date from 1947 to 1994, and contain detailed information on buildings, roads and land-use. These maps were produced at both 1:2,500 and 1:1,250 scales.

Map Name(s) and Date(s)



Historical Map - Segment A13




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT

Large-Scale National Grid Data

Published 1992


Source map scale - 1:1,250

'Large Scale National Grid Data' superseded SIM cards (Ordnance Survey's 'Survey of Information on Microfilm') in 1992, and continued to be produced until 1999. These maps were the fore-runners of digital mapping and so provide detailed information on houses and roads, but tend to show less topographic features such as vegetation. These maps were produced at both 1:2,500 and 1:1,250 scales.

Map Name(s) and Date(s)

SJ8895SW 1992 1:1,250	SJ8895SE 1992 1:1,250
SJ8894NW 1992 1:1,250	SJ8894NE 1992 1:1,250
SJ8894SW 1992 1:1,250	SJ8894SE 1992 1:1,250

Historical Map - Segment A13




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT


Large-Scale National Grid Data

Published 1994 - 1995


Source map scale - 1:1,250

'Large Scale National Grid Data' superseded SIM cards (Ordnance Survey's 'Survey of Information on Microfilm') in 1992, and continued to be produced until 1999. These maps were the fore-runners of digital mapping and so provide detailed information on houses and roads, but tend to show less topographic features such as vegetation. These maps were produced at both 1:2,500 and 1:1,250 scales.

Map Name(s) and Date(s)



Historical Map - Segment A13




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2026. All Rights Reserved.

LK CONSULT

Large-Scale National Grid Data

Published 1995


Source map scale - 1:1,250

'Large Scale National Grid Data' superseded SIM cards (Ordnance Survey's 'Survey of Information on Microfilm') in 1992, and continued to be produced until 1999. These maps were the fore-runners of digital mapping and so provide detailed information on houses and roads, but tend to show less topographic features such as vegetation. These maps were produced at both 1:2,500 and 1:1,250 scales.

Map Name(s) and Date(s)

SJ8894SE
1995
1:1,250

Historical Map - Segment A13



Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk




LK CONSULT

Historical Aerial Photography

Published 2000

This aerial photography was produced by Getmapping, these vertical aerial photographs provide a seamless, full colour survey of the whole of Great Britain

Historical Aerial Photography - Segment A13



Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Appendix B – Envirocheck Report

Envirocheck® Report:

Datasheet

Order Details:

Order Number:
401117746_1_1

Customer Reference:
LKC261292

National Grid Reference:
388470, 394810

Slice:
A

Site Area (Ha):
0.02

Search Buffer (m):
1000

Site Details:

Cedar Mount High School Sit:
LKC261292

Client Details:

L Consult
LK Consult Ltd
Unit 29 Eton Business Park
Eton Hill Road
Radcliffe
Greater Manchester
M26 2ZS

LK CONSULT

Contents

Report Section	Page Number
Summary	-
Agency & Hydrological	1
Waste	13
Hazardous Substances	-
Geological	29
Industrial Land Use	33
Sensitive Land Use	55
Data Currency	56
Data Suppliers	62
Useful Contacts	63

Introduction

The Environment Act 1995 has made site sensitivity a key issue, as the legislation pays as much attention to the pathways by which contamination could spread, and to the vulnerable targets of contamination, as it does the potential sources of contamination.
For this reason, Landmark's Site Sensitivity maps and Datasheet(s) place great emphasis on statutory data provided by the Environment Agency/Natural Resources Wales and the Scottish Environment Protection Agency; it also incorporates data from Natural England (and the Scottish and Welsh equivalents) and Local Authorities; and highlights hydrogeological features required by environmental and geotechnical consultants. It does not include any information concerning past uses of land. The datasheet is produced by querying the Landmark database to a distance defined by the client from a site boundary provided by the client.
In this datasheet the National Grid References (NGRs) are rounded to the nearest 10m in accordance with Landmark's agreements with a number of Data Suppliers.

Copyright Notice

© Landmark Information Group Limited 2026. The Copyright on the information and data and its format as contained in this Envirocheck® Report ("Report") is the property of Landmark Information Group Limited ("Landmark") and several other Data Providers, including (but not limited to) Ordnance Survey, British Geological Survey, the Environment Agency/Natural Resources Wales and Natural England, and must not be reproduced in whole or in part by photocopying or any other method. The Report is supplied under Landmark's Terms and Conditions accepted by the Customer.
A copy of Landmark's Terms and Conditions can be found with the Index Map for this report. Additional copies of the Report may be obtained from Landmark, subject to Landmark's charges in force from time to time. The Copyright, design rights and any other intellectual rights shall remain the exclusive property of Landmark and /or other Data providers, whose Copyright material has been included in this Report.
© Environment Agency & United Kingdom Research and Innovation 2026. © Natural Resources Wales & United Kingdom Research and Innovation 2026.

Natural England Copyright Notice

Site of Special Scientific Interest, National Nature Reserve, Ramsar, Special Protection Area, Special Conservation Area, Marine Nature Reserve data (derived from Ordnance Survey 1:10000 raster) is provided by, and used with the permission of, Natural England who retain the copyright and Intellectual Property Rights for the data.

Scottish Natural Heritage Copyright

Contains SNH information licensed under the Open Government Licence v3.0.

Ove Arup Copyright Notice

The Mining Instability data was obtained on licence from Ove Arup & Partners Limited (for further information, contact mining.review@arup.com). No reproduction or further use of such Data is to be made without the prior written consent of Ove Arup & Partners Limited. The supplied Mining Instability data is derived from publicly available records and other third party sources and neither Ove Arup & Partners nor Landmark warrant the accuracy or completeness of such information or data.

Stantec Copyright Notice

The cavity data presented has been extracted from the PBA (now Stantec UK Ltd) enhanced version of the original DEFRA national cavity databases. Stantec UK Ltd retain the copyright & intellectual property rights in the data. Whilst all reasonable efforts are made to check that the information contained in the cavity databases is accurate we do not warrant that the data is complete or error free. The information is based upon our own researches and those collated from a number of external sources and is continually being augmented and updated by Stantec UK Ltd. In no event shall Stantec UK Ltd or Landmark be liable for any loss or damage including, without limitation, indirect or consequential loss or damage arising from the use of this data.

Radon Potential dataset Copyright Notice

Information supplied from a joint dataset compiled by The British Geological Survey and Public Health England. The probability result is only valid for properties above ground. All basement and cellar areas are considered to be at additional risk from high radon levels. If an underground room such as a cellar or basement makes up part of the living or working accommodation, the property should be tested regardless of Radon Affected Area status.

Natural Resources Wales Copyright Notice

Contains Natural Resources Wales information © Natural Resources Wales and Database Right. All rights Reserved. Contains Ordnance Survey Data. Ordnance Survey Licence number 100019741. Crown Copyright and Database Right. Contains Natural Resources Wales information © Natural Resources Wales and Database Right. All rights Reserved. Some features of this information are based on digital spatial data licensed from the Centre for Ecology & Hydrology © NERC (CEH). Defra, Met Office and DARD Rivers Agency © Crown copyright. © Cranfield University. © James Hutton Institute. Contains OS data © Crown copyright and database right 2026. Land & Property Services © Crown copyright and database right.

LK CONSULT

Report Version v53.0

Contents

LK CONSULT

Summary

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Agency & Hydrological					
BGS Groundwater Flooding Susceptibility	pg 1	Yes	Yes		n/a
Contaminated Land Register Entries and Notices					
Discharge Consents	pg 1				3
Prosecutions	pg 1			1	4
Enforcement and Prohibition Notices					
Integrated Pollution Controls					
Integrated Pollution Prevention And Control					
Local Authority Integrated Pollution Prevention And Control					
Local Authority Pollution Prevention and Controls	pg 2		1	1	1
Local Authority Pollution Prevention and Control Enforcements					
Nearest Surface Water Feature	pg 2		Yes		
Pollution Incidents to Controlled Waters	pg 2		1	1	7
Historical Prosecutions					
Registered Radioactive Substances					
Substantiated Pollution Incident Register	pg 4		2	1	
Water Abstractions	pg 4		1		(*10)
Water Industry Act Referrals					
Groundwater Vulnerability Map	pg 7	Yes	n/a	n/a	n/a
Groundwater Vulnerability - Soluble Rock Risk			n/a	n/a	n/a
Groundwater Vulnerability - Local Information			n/a	n/a	n/a
Bedrock Aquifer Designations	pg 7	Yes	n/a	n/a	n/a
Superficial Aquifer Designations	pg 7	Yes	n/a	n/a	n/a
Source Protection Zones					
Extreme Flooding from Rivers or Sea without Defences				n/a	n/a
Flooding from Rivers or Sea without Defences				n/a	n/a
Areas Benefiting from Flood Defences				n/a	n/a
Flood Water Storage Areas				n/a	n/a
Flood Defences				n/a	n/a
OS NGD Water Network Links	pg 8		8	3	23
Water Framework Directive - Catchment	pg 11	Yes			
Water Framework Directive - Groundwater	pg 11	Yes			
Water Framework Directive - Surface Waters	pg 12				Yes

LK CONSULT

Summary

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Waste					
BGS Recorded Landfill Sites	pg 13			1	
Historical Landfill Sites	pg 13		1	1	4
Integrated Pollution Control Registered Waste Sites					
Licensed Waste Management Facilities (Landfill Boundaries)					
Licensed Waste Management Facilities (Locations)	pg 14		4	10	2
Local Authority Landfill Coverage		1	n/a	n/a	n/a
Local Authority Recorded Landfill Sites					
Potentially Infilled Land (Non-Water)	pg 18				6
Potentially Infilled Land (Water)	pg 18		6	22	71
Registered Landfill Sites	pg 24		1		1
Registered Waste Transfer Sites	pg 26		2	2	1
Registered Waste Treatment or Disposal Sites					
Hazardous Substances					
Control of Major Accident Hazards Sites (COMAH)					
Explosive Sites					
Notification of Installations Handling Hazardous Substances (NIHHS)					
Planning Hazardous Substance Consents					
Planning Hazardous Substance Enforcements					

LK CONSULT

Summary

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Geological					
BGS 1:625,000 Solid Geology	pg 29	Yes	n/a	n/a	n/a
BGS Estimated Soil Chemistry	pg 29	Yes			Yes
BGS Recorded Mineral Sites	pg 29				3
BGS Urban Soil Chemistry	pg 30			Yes	Yes
BGS Urban Soil Chemistry Averages	pg 31	Yes			
CBSCB Compensation District			n/a	n/a	n/a
Coal Mining Affected Areas			n/a	n/a	n/a
Mining Instability			n/a	n/a	n/a
Man-Made Mining Cavities					
Natural Cavities					
Non Coal Mining Areas of Great Britain				n/a	n/a
Potential for Collapsible Ground Stability Hazards	pg 31	Yes	Yes	n/a	n/a
Potential for Compressible Ground Stability Hazards				n/a	n/a
Potential for Ground Dissolution Stability Hazards				n/a	n/a
Potential for Landslide Ground Stability Hazards	pg 32	Yes	Yes	n/a	n/a
Potential for Running Sand Ground Stability Hazards	pg 32	Yes	Yes	n/a	n/a
Potential for Shrinking or Swelling Clay Ground Stability Hazards	pg 32	Yes	Yes	n/a	n/a
Radon Potential - Radon Affected Areas			n/a	n/a	n/a
Radon Potential - Radon Protection Measures			n/a	n/a	n/a
Industrial Land Use					
Contemporary Trade Directory Entries	pg 33		7	45	92
Fuel Station Entries	pg 45			1	
Points of Interest - Commercial Services	pg 45		2	16	25
Points of Interest - Education and Health					
Points of Interest - Manufacturing and Production	pg 49		6	9	23
Points of Interest - Public Infrastructure	pg 52		3	2	7
Points of Interest - Recreational and Environmental	pg 53			4	3
Underground Electrical Cables					

LK CONSULT

Summary

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Sensitive Land Use					
Ancient Woodland					
Areas of Adopted Green Belt					
Areas of Unadopted Green Belt					
Areas of Outstanding Natural Beauty					
Environmentally Sensitive Areas					
Forest Parks					
Local Nature Reserves	pg 55				1
Marine Nature Reserves					
National Nature Reserves					
National Parks					
Nitrate Sensitive Areas					
Nitrate Vulnerable Zones					
Ramsar Sites					
Sites of Special Scientific Interest					
Special Areas of Conservation					
Special Protection Areas					
World Heritage Sites					

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13SW (SW)	0	1	388473 394807
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13NW (N)	183	1	388473 395000
1	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Gore Brook Sewer Stage 2, Manchester, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016941091 Permit Version: 1 Effective Date: 1st January 1900 Issued Date: Not Supplied Revocation Date: 31st December 1994 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Gore Brook **Status: Pre National Rivers Authority Legislation where issue date < 01/09/1989** Positional Accuracy: Located by supplier to within 100m	A17SE (NW)	600	2	388070 395265
1	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Mount Road Combined Sewer Overflow 59 Mount Road, Gorton, Manchester, Greater Manchester, M18 7bw Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 01MAN0246 Permit Version: 2 Effective Date: 1st January 1995 Issued Date: Not Supplied Revocation Date: 5th November 2019 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Gore Brook Via Sws **Status: Post National Rivers Authority Legislation where issue date > 31/08/1989** Positional Accuracy: Located by supplier to within 10m	A17SE (NW)	603	2	388070 395270
1	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Mount Road Combined Sewer Overflow 59 Mount Road, Gorton, Manchester, Greater Manchester, M18 7bw Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 01man0246 Permit Version: 1 Effective Date: 1st July 1991 Issued Date: Not Supplied Revocation Date: 31st December 1994 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Gore Brook Via Sws **Status: Authorisation revoked** Positional Accuracy: Located by supplier to within 10m	A17SE (NW)	603	2	388070 395270
2	**Prosecutions** Location: 8/9 Pink Skips Printworks Lane Manchester Greater Manchester M19 3jp Prosecution Text: Not Supplied Prosecution Act: Environmental Permitting (England and Wales) Regulations 2010 Regulation 38(2) Hearing Date: 21st January 2014 Verdict: Not Supplied Fine: Not Supplied Cost: Not Supplied Positional Accuracy: Manually positioned to the road within the address or location	A8NW (SW)	388	2	388308 394444
3	**Prosecutions** Location: Climax Works Unit 1-4 Station Road Stockport Sk5 6yz Prosecution Text: Not Supplied Prosecution Act: Environmental Permitting Regulations 2016 Regulation 38(2) Hearing Date: 23rd February 2023 Verdict: Guilty Fine: 0 Cost: Not Supplied Positional Accuracy: Automatically positioned to the address	A14NE (E)	731	2	389207 394825

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
3	**Prosecutions** Location: Climax Works Unit 1-4 Station Road Stockport Sk5 6yz Prosecution Text: Not Supplied Prosecution Act: Environmental Permitting Regulations 2016 Regulation 38(3) Hearing Date: 23rd February 2023 Verdict: Guilty Fine: 2800 Cost: Not Supplied Positional Accuracy: Automatically positioned to the address	A14NE (E)	731	2	389207 394825
3	**Prosecutions** Location: Climax Works Unit 1-4 Station Road Stockport Sk5 6yz Prosecution Text: Not Supplied Prosecution Act: Environmental Permitting Regulations 2016 Regulation 38(2) Hearing Date: 23rd February 2023 Verdict: Offered No Evidence Fine: 0 Cost: Not Supplied Positional Accuracy: Automatically positioned to the address	A14NE (E)	731	2	389207 394825
3	**Prosecutions** Location: Climax Works Unit 1-4 Station Road Stockport Sk5 6yz Prosecution Text: Not Supplied Prosecution Act: Environmental Permitting Regulations 2016 Regulation 38(2) Hearing Date: 4th October 2022 Verdict: Offered No Evidence Fine: 0 Cost: Not Supplied Positional Accuracy: Automatically positioned to the address	A14NE (E)	731	2	389207 394825
4	**Local Authority Pollution Prevention and Controls** Name: Mallatite Ltd Location: Sandfold Lane, MANCHESTER, Lancashire, M19 3FT Authority: Manchester City Council, Environmental Health Department Permit Reference: PPC/B/24/05/AW Dated: 8th October 1993 Process Type: Local Authority Air Pollution Control Description: PG6/31 Powder coating processes (including sheradizing) **Status: Authorisation revoked** Positional Accuracy: Located by supplier to within 10m	A13SE (S)	149	3	388501 394651
5	**Local Authority Pollution Prevention and Controls** Name: British Cement Corporation Ltd Location: Unit M5 Levenshulme Trading Estate, Printworks Lane, Levenshulme, MANCHESTER, Lanacashire, M19 3JP Authority: Manchester City Council, Environmental Health Department Permit Reference: Not Given Dated: 28th June 1999 Process Type: Local Authority Air Pollution Control Description: PG3/10 China and ball clay **Status: Authorisation revoked** Positional Accuracy: Located by supplier to within 10m	A13SW (SW)	282	3	388283 394585
6	**Local Authority Pollution Prevention and Controls** Name: Thomas Storey Fabrications Ltd Location: Station Road, Reddish, STOCKPORT, Cheshire, SK5 6ND Authority: Stockport Metropolitan Borough Council, Environmental Health Department, EEDD Permit Reference: Epa040 Dated: 1st March 2001 Process Type: Local Authority Air Pollution Control Description: PG6/23 Coating of metal and plastic **Status: Authorisation revoked** Positional Accuracy: Manually positioned to the address or location	A14NE (E)	933	4	389409 394822
	Nearest Surface Water Feature	A13NW (N)	121	-	388424 394929
7	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Not Given Note: Nico Ditch; Not Known Incident Date: 10th December 1991 Incident Reference: 91641910 Catchment Area: Mersey - Non-Tidal Receiving Water: Not Given Cause of Incident: Not Given Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A13NE (N)	87	2	388500 394900

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
8	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Rubble/Litter Or Solids Note: Sandford/Wingates; Inert Waste Incident Date: 25th June 1996 Incident Reference: 96641535 Catchment Area: Mersey - Non-Tidal Receiving Water: Not Given Cause of Incident: Miscellaneous/Other Pollution Type Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A14SW (E)	434	2	388900 394700
9	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Unknown Note: Not Supplied Incident Date: 19th March 1996 Incident Reference: 96640512 Catchment Area: Mersey - Non-Tidal Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A17NE (NW)	776	2	388100 395500
10	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Not Given Note: None Pollution Found Incident Date: 4th February 1992 Incident Reference: 92640206 Catchment Area: Mersey - Non-Tidal Receiving Water: Not Given Cause of Incident: Not Given Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A18NE (N)	979	2	388500 395795
10	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Unknown Note: Gore Brook; No Pollution Found Incident Date: 9th March 1994 Incident Reference: 94640443 Catchment Area: Mersey - Non-Tidal Receiving Water: Not Given Cause of Incident: Miscellaneous/Other Pollution Type Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A18NE (N)	984	2	388500 395800
11	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Gore Brook Murky, Sunny Browpark, GORTON Authority: Environment Agency, North West Region Pollutant: Miscellaneous - Inert Suspended Solids Note: Not Supplied Incident Date: 24th August 1998 Incident Reference: SO981544 Catchment Area: Mersey - Non-Tidal Receiving Water: Freshwater Stream/River Cause of Incident: High Flow Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A18NE (N)	986	2	388600 395795
11	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Gore Brook, Sunny Brow Park, GORTON Authority: Environment Agency, North West Region Pollutant: Miscellaneous - Inert Suspended Solids Note: Discolouration Incident Date: 15th June 1998 Incident Reference: SO981131 Catchment Area: Mersey - Non-Tidal Receiving Water: Freshwater Stream/River Cause of Incident: Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A18NE (N)	991	2	388600 395800

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
12	**Pollution Incidents to Controlled Waters** Property Type: Connection To Surface Drains Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Unknown Sewage Note: Fallowfield Brook Incident Date: 9th May 1991 Incident Reference: 91640692 Catchment Area: Mersey - Non-Tidal Receiving Water: Not Given Cause of Incident: Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8SE (S)	998	2	388500 393800
13	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Unknown Note: Gore Brook Incident Date: 9th November 1995 Incident Reference: 95642756 Catchment Area: Mersey - Non-Tidal Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A17NE (NW)	1000	2	388000 395700
14	**Substantiated Pollution Incident Register** Authority: Environment Agency - North West Region, South Area Incident Date: 25th February 2014 Incident Reference: 1212017 Water Impact: Category 2 - Significant Incident Air Impact: Category 4 - No Impact Land Impact: Category 4 - No Impact Positional Accuracy: Located by supplier to within 10m Pollutant: Contaminated Water: Firefighting Run-Off Pollutant: Oils And Fuel: Mixed/Waste Oils	A13SW (SW)	209	2	388324 394646
14	**Substantiated Pollution Incident Register** Authority: Environment Agency - North West Region, South Area Incident Date: 13th September 2010 Incident Reference: 821916 Water Impact: Category 3 - Minor Incident Air Impact: Category 2 - Significant Incident Land Impact: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 10m Pollutant: Atmospheric Pollutants and Effects: Smoke	A13SW (SW)	234	2	388285 394653
15	**Substantiated Pollution Incident Register** Authority: Environment Agency - North West Region, South Area Incident Date: 11th June 2007 Incident Reference: 502158 Water Impact: Category 4 - No Impact Air Impact: Category 4 - No Impact Land Impact: Category 2 - Significant Incident Positional Accuracy: Located by supplier to within 10m Pollutant: Inorganic Chemicals : Acids Pollutant: Oils - Unknown Pollutant: Organic Chemicals/Products: Surfactants And Detergents	A14SW (E)	467	2	388940 394743
16	**Water Abstractions** Operator: Cba Enterprises Ltd Licence Number: 2569013018 Permit Version: 100 Location: Borehole At Sandfold Lane Levenshulme Manchester Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: General Use (Medium Loss) Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): 409 Yearly Rate (m3): 117835 Details: Land & Prems At Sandfold Lane Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 29th March 1996 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A13SE (S)	101	2	388500 394700

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Abstractions Operator: G R A Limited Licence Number: 2569006043 Permit Version: 2 Location: Permo-Triassic Sandstone At Belle Vue, Manchester Authority: Environment Agency, North West Region Abstraction: Sports Grounds/Facilities: Dust suppression Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Belle Vue Greyhound Stadium, Gorton Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 1st April 2008 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A22SE (N)	1384	2	387950 396100
	Water Abstractions Operator: Wembley Plc Licence Number: 2569006043 Permit Version: 1 Location: Permo-Triassic Sandstone At Belle Vue, Manchester Authority: Environment Agency, North West Region Abstraction: Sports Grounds/Facilities: Dust suppression Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Belle Vue Greyhound Stadium, Gorton Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 20th June 2003 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A22SE (N)	1384	2	387950 396100
	Water Abstractions Operator: The Chief Operating Officer Of The Eastlands Trust Licence Number: Nw/069/0006/006 Permit Version: 1 Location: Permo-Triassic Sandstone At Belle Vue Leisure Centre Authority: Environment Agency, North West Region Abstraction: Sports Grounds/Facilities: Spray Irrigation - Direct Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Land At Belle Vue Leisure Centre Authorised Start: 01 April Authorised End: 31 March Permit Start Date: 16th May 2014 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A22SW (NW)	1387	2	387591 395891
	Water Abstractions Operator: Mr Clive Back Licence Number: 2569006042 Permit Version: 4 Location: Permo-Triassic Sandstone At Belle Vue Leisure Centre Authority: Environment Agency, North West Region Abstraction: Sports Grounds/Facilities: Spray Irrigation - Direct Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Land At Belle Vue Leisure Centre Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 29th February 2012 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A22SW (NW)	1387	2	387591 395891

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Abstractions Operator: Mr Clive Back Licence Number: 2569006042 Permit Version: 3 Location: Permo-Triassic Sandstone At Belle Vue Leisure Centre Authority: Environment Agency, North West Region Abstraction: Sports Grounds/Facilities: Spray Irrigation - Direct Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Land At Belle Vue Leisure Centre Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 4th February 2009 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A22SW (NW)	1387	2	387590 395890
	Water Abstractions Operator: Manchester City Council Licence Number: 2569006042 Permit Version: 2 Location: Permo-Triassic Sandstone At Belle Vue Leisure Centre Authority: Environment Agency, North West Region Abstraction: Sports Grounds/Facilities: Spray Irrigation - Direct Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Land At Belle Vue Leisure Centre Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 29th November 2005 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A22SW (NW)	1387	2	387590 395890
	Water Abstractions Operator: Manchester City Council Licence Number: 2569006042 Permit Version: 1 Location: Permo-Triassic Sandstone At Belle Vue Leisure Centre Authority: Environment Agency, North West Region Abstraction: Sports Grounds/Facilities: Spray Irrigation - Direct Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Land At Belle Vue Leisure Centre Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 11th July 2002 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A22SW (NW)	1387	2	387590 395890
	Water Abstractions Operator: Millshomes Ltd Licence Number: 2569012134 Permit Version: 102 Location: Borehole At Lh S Premises Reddish Stockport Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: General Use (Medium Loss) Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Lh'S Premises At Reddish, Stockport Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 1st April 2008 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A4NW (S)	1399	2	389000 393500

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Abstractions Operator: Octran Limited Licence Number: 2569012134 Permit Version: 101 Location: Borehole At Lh S Premises Reddish Stockport Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: General Use (Medium Loss) Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Lh'S Premises At Reddish, Stockport Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 15th November 2001 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A4NW (S)	1399	2	389000 393500
	Water Abstractions Operator: Caradon Friedland Ltd Licence Number: 2569012134 Permit Version: 100 Location: Borehole At Lh'S Premises, Reddish, Stockport Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: General Use (Medium Loss) Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): 73 Yearly Rate (m3): 13638 Details: Lh'S Premises At Reddish, Stockport Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 2nd July 1998 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A4NW (S)	1399	2	389000 393500
	Groundwater Vulnerability Map Combined Classification: Secondary Superficial Aquifer - Low Vulnerability Combined Vulnerability: Low Combined Aquifer: Productive Bedrock Aquifer, Productive Superficial Aquifer Pollutant Speed: Low Bedrock Flow: Mixed Dilution: 300-550 mm/year Baseflow Index: <40% Superficial Patchiness: >90% Superficial Thickness: >10m Superficial Recharge: Low	A13SW (SW)	0	2	388473 394807
	Groundwater Vulnerability - Soluble Rock Risk None				
	Bedrock Aquifer Designations Aquifer Designation: Principal Aquifer	A13SW (SW)	0	2	388473 394807
	Superficial Aquifer Designations Aquifer Designation: Secondary Aquifer - Undifferentiated	A13SW (SW)	0	2	388473 394807
	Extreme Flooding from Rivers or Sea without Defences None				
	Flooding from Rivers or Sea without Defences None				
	Areas Benefiting from Flood Defences None				
	Flood Water Storage Areas None				
	Flood Defences None				

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
17	**OS NGD Water Network Links** Description: Drain Length: 270.368 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A13NW (N)	121	5	388424 394929
18	**OS NGD Water Network Links** Description: Drain Length: 3.103 Physical Level: Underground Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A13NW (N)	122	5	388436 394935
19	**OS NGD Water Network Links** Description: Drain Length: 98.691 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A13NW (N)	123	5	388439 394936
20	**OS NGD Water Network Links** Description: Watercourse Length: 24.95 Physical Level: Underground Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A13NE (N)	156	5	388534 394961
21	**OS NGD Water Network Links** Description: Watercourse Length: 908.878 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A13NE (NE)	171	5	388558 394967
22	**OS NGD Water Network Links** Description: Drain Length: 26.686 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A13NE (NE)	171	5	388558 394967
23	**OS NGD Water Network Links** Description: Drain Length: 2.197 Physical Level: Underground Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A13NE (NE)	185	5	388584 394967
24	**OS NGD Water Network Links** Description: Drain Length: 298.316 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A13NE (NE)	186	5	388586 394967
25	**OS NGD Water Network Links** Description: Watercourse Length: 10.207 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A13NW (W)	293	5	388179 394857

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
26	**OS NGD Water Network Links** Description: Watercourse Length: 22.396 Physical Level: Underground Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A14NW (NE)	463	5	388865 395068
27	**OS NGD Water Network Links** Description: Watercourse Length: 106.63 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A14NW (NE)	484	5	388886 395076
28	**OS NGD Water Network Links** Description: Watercourse Length: 144.03 Physical Level: Underground Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A14NW (NE)	588	5	388987 395109
29	**OS NGD Water Network Links** Description: Drain Length: 130.622 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A8SE (S)	697	5	388566 394107
30	**OS NGD Water Network Links** Description: Watercourse Length: 6.376 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A19SW (NE)	730	5	389123 395154
31	**OS NGD Water Network Links** Description: Watercourse Length: 1.667 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A19SW (NE)	736	5	389129 395157
32	**OS NGD Water Network Links** Description: Watercourse Length: 36.398 Physical Level: Underground Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A19SW (NE)	738	5	389130 395158
33	**OS NGD Water Network Links** Description: Watercourse Length: 194.26 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A19SE (NE)	774	5	389164 395172
34	**OS NGD Water Network Links** Description: Drain Length: 7.777 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A8SE (S)	818	5	388538 393982

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
35	**OS NGD Water Network Links** Description: Drain Length: 41.755 Physical Level: Underground Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A8SE (S)	821	5	388545 393979
36	**OS NGD Water Network Links** Description: Drain Length: 56.529 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A8SE (S)	821	5	388655 393996
37	**OS NGD Water Network Links** Description: Drain Length: 52.323 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A8SE (S)	823	5	388587 393983
38	**OS NGD Water Network Links** Description: Drain Length: 78.7 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A8SE (S)	838	5	388686 393987
39	**OS NGD Water Network Links** Description: Watercourse Length: 29.3 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A17NE (NW)	937	5	387811 395484
40	**OS NGD Water Network Links** Description: Watercourse Length: 79.006 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A17NW (NW)	957	5	387782 395484
41	**OS NGD Water Network Links** Description: Watercourse Length: 258.564 Physical Level: Surface level Permanence: Permanent Feature Name: Fallowfield Brook Catchment Name: Mersey Primacy: 1	A8SW (S)	962	5	388332 393846
42	**OS NGD Water Network Links** Description: Watercourse Length: 137.266 Physical Level: Underground Permanence: Permanent Feature Name: Fallowfield Brook Catchment Name: Mersey Primacy: 1	A8SE (S)	980	5	388533 393819
43	**OS NGD Water Network Links** Description: Watercourse Length: 23.594 Physical Level: Surface level Permanence: Permanent Feature Name: Fallowfield Brook Catchment Name: Mersey Primacy: 1	A8SE (S)	980	5	388541 393820

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
44	**OS NGD Water Network Links** Description: Drain Length: 73.387 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A8SE (S)	982	5	388557 393820
45	**OS NGD Water Network Links** Description: Watercourse Length: 524.132 Physical Level: Surface level Permanence: Permanent Feature Name: Fallowfield Brook Catchment Name: Mersey Primacy: 1	A8SE (S)	982	5	388563 393819
46	**OS NGD Water Network Links** Description: Watercourse Length: 3.723 Physical Level: Surface level Permanence: Permanent Feature Name: Not Supplied Catchment Name: Mersey Primacy: 1	A8SE (S)	982	5	388567 393820
47	**OS NGD Water Network Links** Description: Watercourse Length: 6.881 Physical Level: Surface level Permanence: Permanent Feature Name: Fallowfield Brook Catchment Name: Mersey Primacy: 1	A8SE (S)	982	5	388557 393820
48	**OS NGD Water Network Links** Description: Watercourse Length: 4.905 Physical Level: Underground Permanence: Permanent Feature Name: Fallowfield Brook Catchment Name: Mersey Primacy: 1	A8SW (S)	987	5	388363 393817
49	**OS NGD Water Network Links** Description: Watercourse Length: 38.064 Physical Level: Surface level Permanence: Permanent Feature Name: Fallowfield Brook Catchment Name: Mersey Primacy: 1	A8SW (S)	989	5	388367 393814
50	**OS NGD Water Network Links** Description: Watercourse Length: 696.965 Physical Level: Surface level Permanence: Permanent Feature Name: Gore Brook Catchment Name: Mersey Primacy: 1	A18NW (N)	997	5	388219 395782
	Water Framework Directive - Catchment Class Code: River Catchment WaterBody Name: Platt Brook (Source to Fallowfield Bk) WaterBody ID: GB112069061060 Operational Catchment: Bollin Dean Mersey Upper Management Catchment: Mersey Upper Catchment Name: Upper Mersey	A13SW (SW)	0	2	388473 394807
	Water Framework Directive - Groundwater Waterbody Name: Manchester and East Cheshire Permo-Triassic Sandstone Aquifers Waterbody ID: GB41201G101100 URL Address: https://environment.data.gov.uk/catchment-planning/WaterBody/GB41201G101100 Overall Rating: Poor Chemical Rating: Poor Quantitative Measure: Poor Year: 2019	A13SW (SW)	0	2	388473 394807

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Framework Directive - Surface Waters Class Code: River Waterbody Name: Platt Brook (Source To Fallowfield Bk) Waterbody ID: GB112069061060 URL Address: Not Supplied Overall Rating: Not Assessed Chemical Rating: Not Assessed Classification Year: 2022	A18NW (N)	997	2	388218 395782

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
51	**BGS Recorded Landfill Sites** Site Name: Matthews Lane Location: Levenshulme, MANCHESTER, Gt Manchester Authority: British Geological Survey, National Geoscience Information Service Ground Water: Information not available Surface Water: Information not available Geology: N/A Positional Accuracy: Positioned by the supplier Boundary Accuracy: Moderate	A12NE (W)	423	-	388046 394840
52	**Historical Landfill Sites** Licence Holder: Greensite Limited Location: Sandford Lane, Printowork Lane, Levenshulme, Greater Manchester Name: Levenshulme Trading Estate Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD16661 First Input Date: Not Supplied Last Input Date: Not Supplied Specified Waste Type: Deposited Waste included Industrial and Special Waste EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: Not Supplied BGS Ref: Not Supplied Other Ref: F050, RD/LIC/244/82	A13SW (S)	234	2	388464 394564
53	**Historical Landfill Sites** Licence Holder: Greater Manchester Waste Disposal Authority Location: Longsight, Greater Manchester Name: Matthews Lane Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD16635 First Input Date: 31st December 1969 Last Input Date: 11th July 1978 Specified Waste Type: Deposited Waste included Inert, Industrial, Commercial, Household and Special Waste, and Liquid Sludge EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: 4200/9657 BGS Ref: 519 Other Ref: F009	A12NE (W)	416	2	388053 394836
54	**Historical Landfill Sites** Licence Holder: Greater Manchester Waste Disposal Authority Location: East Road, Longsight, Greater Manchester Name: Pink Bank Lane Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD16623 First Input Date: 16th February 1981 Last Input Date: 1st May 1981 Specified Waste Type: Deposited Waste included Inert, Commercial and Household Waste EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: 4200/9640 BGS Ref: Not Supplied Other Ref: F010, RD/RES/024/80	A17SE (NW)	725	2	387880 395240
55	**Historical Landfill Sites** Licence Holder: Not Supplied Location: Greater Manchester Name: Stockport Branch Canal Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD16619 First Input Date: Not Supplied Last Input Date: Not Supplied Specified Waste Type: Not Supplied EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: Not Supplied BGS Ref: Not Supplied Other Ref: J073	A9NE (SE)	900	2	389266 394365

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
56	**Historical Landfill Sites** Licence Holder: Not Supplied Location: Annie Leigh Playing Fields, Greater Manchester Name: Mount Road Plant Site Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD16605 First Input Date: Not Supplied Last Input Date: Not Supplied Specified Waste Type: Deposited Waste included Household Waste EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: Not Supplied BGS Ref: Not Supplied Other Ref: F024	A17NE (NW)	974	2	388064 395703
57	**Historical Landfill Sites** Licence Holder: Greater Manchester Waste Disposal Authority Location: Manchester Name: Cringle Road Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD17237 First Input Date: 1st April 1974 Last Input Date: 1st June 1979 Specified Waste Type: Deposited Waste included Inert, Industrial, Commercial, Household and Special Waste, and Liquid Sludge EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: 4200/9642 BGS Ref: Not Supplied Other Ref: F011, RD/RES/012/79, 4200/9709	A7SE (S)	982	2	388113 393882
58	**Licensed Waste Management Facilities (Locations)** Licence Number: 102497 Location: 1a Unit Sandfold Lane, Levenshulme, Manchester, Greater Manchester, M19 3BJ Operator Name: CORNBROOK METAL RECYCLING LIMITED Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Metal recycling, vehicle storage, depollution **Licence Status: Issued** Issued: 30th March 2011 Last Modified: 30th March 2011 Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A13SW (SW)	142	2	388364 394702
59	**Licensed Waste Management Facilities (Locations)** Licence Number: 407512 Location: Sandfold House, Sandfold Lane, Levenshulme, Manchester, Greater Manchester, M19 3BJ Operator Name: UTILITY RECYCLING NORTH WEST LIMITED Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Not Supplied **Licence Status: Issued** Issued: 26th April 2021 Last Modified: 26th April 2021 Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A13SE (S)	156	2	388513 394646

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
60	**Licensed Waste Management Facilities (Locations)** Licence Number: 53679 Location: Land/premises At, Sandfold Lane, Levenshulme, Manchester, Greater Manchester, M19 3BJ Operator Name: SUEZ RECYCLING AND RECOVERY UK LTD Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Household, Commercial And Industrial Transfer Stations **Licence Status: Issued** Issued: 1st February 1995 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A13SW (SW)	190	2	388387 394626
61	**Licensed Waste Management Facilities (Locations)** Licence Number: 104175 Location: C B A House, Sandfold Lane, Levenshulme, Manchester, Greater Manchester, M19 3BJ Operator Name: ALTERNATIVE RECYCLED MATERIALS LIMITED Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Treatment of waste to produce soil <75,000 tpy **Licence Status: Expired** Issued: 8th June 2012 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Manually positioned to the road within the address or location	A13SW (S)	236	2	388419 394567
61	**Licensed Waste Management Facilities (Locations)** Licence Number: 50337 Location: 6 Sandfold Lane, Levenshulme, Manchester, Greater Manchester, M19 3BJ Operator Name: CORNBROOK METAL RECYCLING LIMITED Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Metal Recycling Sites (Mixed) **Licence Status: Surrendered** Issued: 28th February 2005 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: 28th February 2005 IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A13SW (S)	260	2	388419 394543
61	**Licensed Waste Management Facilities (Locations)** Licence Number: 102719 Location: Unit 17, Sandfold Lane, Gorton, Manchester, Greater Manchester, M19 3BJ Operator Name: RYAN'S SKIP HIRE LIMITED Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: HCI Waste TS + treatment **Licence Status: Revoked** Issued: 11th July 2011 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A13SW (S)	283	2	388424 394518

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
61	**Licensed Waste Management Facilities (Locations)** Licence Number: 120809 Location: Unit 17, Sandfold Lane, Gorton, Manchester, Greater Manchester, M19 3BJ Operator Name: A2B Skip Hire Manchester Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Not Supplied **Licence Status: Issued** Issued: 28th April 2023 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A13SW (S)	301	2	388391 394507
62	**Licensed Waste Management Facilities (Locations)** Licence Number: 100031 Location: Gate 20, Sandfold Lane, Levenshulme, Manchester, Greater Manchester, M19 3BJ Operator Name: Alan Wilkinson Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Household, Commercial And Industrial Transfer Stations **Licence Status: Revoked** Issued: 28th March 2008 Last Modified: 28th March 2008 Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A13SW (SW)	257	2	388349 394570
62	**Licensed Waste Management Facilities (Locations)** Licence Number: 50479 Location: 19a Sandfold Lane, Levenshulme, Manchester, Greater Manchester, M19 3BJ Operator Name: SKIP IT WASTE MANAGEMENT Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Household, Commercial And Industrial Transfer Stations **Licence Status: Expired** Issued: 31st July 2007 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A13SW (SW)	294	2	388352 394528
62	**Licensed Waste Management Facilities (Locations)** Licence Number: 50479 Location: 19a Sandfold Lane, Levenshulme, Manchester, Greater Manchester, M19 3BJ Operator Name: SKIP IT WASTE MANAGEMENT Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Household, Commercial And Industrial Transfer Stations **Licence Status: Expired** Issued: 31st July 2007 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A13SW (SW)	294	2	388352 394528

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
63	**Licensed Waste Management Facilities (Locations)** Licence Number: 50320 Location: Unit 9 Levenshulme Trading Est, Levenshulme, Manchester, Greater Manchester, M19 3JP Operator Name: A2B Skip Hire Manchester Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Household, Commercial And Industrial Transfer Stations **Licence Status: Issued** Issued: 30th September 2004 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A13SW (SW)	342	2	388317 394491
63	**Licensed Waste Management Facilities (Locations)** Licence Number: 53599 Location: Yard 9 Printworks Lane, Printworks Lane, Levenshulme, Manchester, Greater Manchester, M19 3JP Operator Name: Gary Connor Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Household, Commercial And Industrial Transfer Stations **Licence Status: Expired** Issued: 10th July 1996 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 100m	A13SW (SW)	342	2	388300 394500
63	**Licensed Waste Management Facilities (Locations)** Licence Number: 53599 Location: Yard 9 Printworks Lane, Printworks Lane, Levenshulme, Manchester, Greater Manchester, M19 3JP Operator Name: Gary Connor Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Household, Commercial And Industrial Transfer Stations **Licence Status: Expired** Issued: 10th July 1996 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 100m	A13SW (SW)	342	2	388300 394500
64	**Licensed Waste Management Facilities (Locations)** Licence Number: 50280 Location: 8 Marquis Street, Levenshulme, Manchester, Greater Manchester, M19 3JZ Operator Name: Anthony Wilson Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: End of Life Vehicles **Licence Status: Revoked** Issued: 14th May 2004 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A8NE (S)	428	2	388570 394380

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
65	**Licensed Waste Management Facilities (Locations)** Licence Number: 404234 Location: Climax Works, Station Road, Stockport, Cheshire, SK5 6YZ Operator Name: REDDISH CAR SPARES LIMITED Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Vehicle depollution facility **Licence Status: Surrendered** Issued: 29th November 2017 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: 29th November 2017 IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14NE (E)	726	2	389200 394881
65	**Licensed Waste Management Facilities (Locations)** Licence Number: 100102 Location: Unit 7 Climax Works, Durham Street, Reddish, Cheshire, SK5 6YZ Operator Name: R & T ELECTRONIC RECYCLING LLP Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Material Recycling Treatment Facilities **Licence Status: Surrendered** Issued: 19th November 2007 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: 19th November 2007 IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14NE (E)	746	2	389220 394872
	Local Authority Landfill Coverage Name: Manchester City Council - Had landfill data but passed it to the relevant environment agency		0	6	388473 394807
	Local Authority Landfill Coverage Name: Stockport Metropolitian Borough Council - Has not been able to supply Landfill data		244	4	388631 394610
66	**Potentially Infilled Land (Non-Water)** Bearing Ref: E Use: Unknown Filled Ground (Pit, quarry etc) Date of Mapping: 1990	A14SW (E)	509	-	388985 394765
67	**Potentially Infilled Land (Non-Water)** Bearing Ref: NW Use: Unknown Filled Ground (Pit, quarry etc) Date of Mapping: 1993	A12NE (NW)	534	-	387998 395070
68	**Potentially Infilled Land (Non-Water)** Bearing Ref: SW Use: Unknown Filled Ground (Pit, quarry etc) Date of Mapping: 1990	A7NE (SW)	731	-	388023 394218
69	**Potentially Infilled Land (Non-Water)** Bearing Ref: NW Use: Unknown Filled Ground (Pit, quarry etc) Date of Mapping: 1993	A17SE (NW)	764	-	387844 395258
70	**Potentially Infilled Land (Non-Water)** Bearing Ref: E Use: Unknown Filled Ground (Pit, quarry etc) Date of Mapping: 1990	A14NE (E)	938	-	389406 394937
71	**Potentially Infilled Land (Non-Water)** Bearing Ref: S Use: Unknown Filled Ground (Pit, quarry etc) Date of Mapping: 1990	A7SE (S)	988	-	388106 393879
72	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1938	A13NW (NW)	1	-	388467 394810
73	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A13SW (W)	135	-	388336 394776
74	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A13NW (N)	190	-	388469 395006

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
75	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A13NE (E)	227	-	388698 394868
76	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1923	A13SW (SW)	229	-	388273 394678
77	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A13SW (S)	237	-	388461 394561
78	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A13SW (S)	292	-	388442 394507
79	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A13SE (E)	302	-	388779 394782
80	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A13NW (N)	308	-	388400 395117
81	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A13NE (E)	314	-	388790 394825
82	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A13SE (S)	329	-	388559 394480
83	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A13NE (E)	333	-	388801 394894
84	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1911	A13SW (SW)	339	-	388164 394650
85	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A13NE (NE)	379	-	388693 395128
86	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A18SW (NW)	405	-	388276 395174
87	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1908	A12SE (W)	406	-	388064 394763
88	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1908	A12SE (W)	409	-	388078 394677
89	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A13NW (NW)	414	-	388184 395118
90	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A12NE (NW)	424	-	388123 395063
91	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1938	A18SW (NW)	426	-	388207 395153
92	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A14NW (NE)	426	-	388851 395018
93	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A18SE (NE)	438	-	388664 395213
94	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1923	A12SE (SW)	447	-	388119 394520
95	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A12NE (NW)	452	-	388117 395102

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
96	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A18SE (N)	463	-	388495 395280
97	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1908	A12SE (W)	464	-	388024 394664
98	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A12NE (W)	467	-	388026 394967
99	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1923	A18SW (NW)	493	-	388264 395266
100	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A18SE (N)	503	-	388649 395289
101	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1923	A18SW (N)	506	-	388309 395297
102	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1911	A18SW (NW)	510	-	388236 395271
103	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A14NW (NE)	522	-	388893 395131
104	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A19SW (NE)	553	-	388821 395250
105	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A8NE (S)	568	-	388583 394240
106	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A8NE (SE)	570	-	388735 394290
107	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A19SW (NE)	571	-	388848 395250
108	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A18SW (NW)	575	-	388222 395336
109	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A19SW (NE)	576	-	388907 395199
110	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1938	A8NE (S)	581	-	388499 394217
111	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A8NW (S)	586	-	388463 394212
112	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A12NE (W)	592	-	387876 394821
113	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1923	A18SW (N)	601	-	388398 395413
114	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A8NW (S)	609	-	388404 394193
115	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1894	A12SE (W)	612	-	387871 394664
116	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A9NW (SE)	617	-	388875 394327

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
117	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1908	A12SE (SW)	646	-	387903 394485
118	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1923	A18SE (N)	647	-	388561 395458
119	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1923	A18SE (NE)	651	-	388739 395412
120	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A14SW (E)	667	-	389130 394662
121	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1923	A12NE (W)	667	-	387811 394931
122	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1938	A8NE (S)	676	-	388714 394165
123	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1923	A19SW (NE)	691	-	388842 395403
124	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A12NE (W)	694	-	387810 395035
125	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1923	A18NW (N)	720	-	388354 395528
126	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A18NE (N)	721	-	388481 395537
127	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A14SE (E)	725	-	389197 394711
128	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1908	A7NE (SW)	741	-	387954 394265
129	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A17SE (NW)	743	-	387926 395325
130	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A17SE (NW)	745	-	388081 395453
131	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A17SE (NW)	754	-	387845 395241
132	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1894	A8SE (S)	762	-	388743 394084
133	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A12SW (W)	764	-	387732 394593
134	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1894	A12SW (W)	770	-	387699 394758
135	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1923	A18NE (N)	787	-	388648 395584
136	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1938	A8SW (S)	793	-	388320 394019
137	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1923	A18NE (N)	823	-	388763 395588

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
138	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A8SW (S)	826	-	388261 393998
139	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A19SW (NE)	832	-	389145 395311
140	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A19NW (NE)	840	-	388834 395577
141	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A9SW (SE)	842	-	388887 394062
142	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A9SW (SE)	844	-	388950 394099
143	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A12NW (W)	850	-	387665 395095
144	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1910	A19SE (NE)	850	-	389236 395197
145	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A7NW (SW)	888	-	387748 394279
146	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1894	A12SW (W)	889	-	387587 394684
147	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A8SE (S)	889	-	388658 393927
148	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1894	A8SW (S)	896	-	388145 393962
149	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A8SW (S)	902	-	388449 393896
150	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1894	A12SW (W)	902	-	387568 394753
151	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1894	A7NW (SW)	911	-	387671 394357
152	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1923	A14SE (E)	916	-	389389 394723
153	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A17NE (NW)	917	-	387956 395577
154	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1923	A19NW (NE)	918	-	388963 395595
155	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A18NE (N)	919	-	388713 395705
156	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A9NE (SE)	921	-	389294 394375
157	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A17NE (NW)	933	-	387971 395606
158	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A7NW (SW)	933	-	387616 394416

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
159	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A14NE (E)	938	-	389403 394968
160	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1956	A14NE (E)	940	-	389389 395041
161	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A17SW (NW)	940	-	387598 395171
162	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A19NW (NE)	958	-	389084 395558
163	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1895	A18NW (N)	962	-	388412 395777
164	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1894	A12SW (W)	962	-	387544 394533
165	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A12NW (W)	971	-	387507 394952
166	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A7NW (SW)	979	-	387578 394392
167	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1955	A8SE (S)	981	-	388517 393818
168	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1848	A18NW (N)	990	-	388331 395797
169	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1909	A18NW (N)	992	-	388338 395800
170	**Potentially Infilled Land (Water)** Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1923	A19NW (NE)	995	-	389074 395612

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Registered Landfill Sites				
171	Licence Holder: Robin Arnold Transport Ltd Licence Reference: 00244/82 Site Location: Levenshulme Trading Estate, Printworks Lane, Levenshulme, Manchester, Greater Manchester Licence Easting: 388500 Licence Northing: 394550 Operator Location: As Site Address Authority: Environment Agency - North West Region, South Area Site Category: Landfill Max Input Rate: Large (Equal to or greater than 75,000 and less than 250,000 tonnes per year) Waste Source Restrictions: No known restriction on source of waste Status: Licence lapsed/cancelled/defunct/not applicable/surrendered Dated: 1st March 1984 Preceded By Licence: Not Given Superseded By Licence: Not Given Positional Accuracy: Manually positioned to the address or location Boundary Accuracy: Not Applicable Authorised Waste: Ceramic Waste Excavated Natural Materials $ Glass/Cullet Hardcore And Rubble Metal Scrap Non Leachate Forming Waste Prohibited Waste: Carcasses And Flesh Chemical Wastes Food Waste Liquid Wastes Paper/Cardboard Waste Plasterboard/Plaster Plastic/Polythene (Including Sacks) Poisonous, Noxious And Polluting N.O.S Sawdust/Bark Sludge Wastes Textiles, Rag,Wool,Cloth,Hessian Etc Timber And Other Organic Material Vegetable/Processing Waste	A13SE (S)	249	2	388500 394550

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Registered Landfill Sites				
172	Licence Holder: G.M.W.D.A. Licence Reference: R/024 Site Location: Pink Bank Lane, East Road, Longsight, Manchester, Greater Manchester Licence Easting: 387700 Licence Northing: 395400 Operator Location: Blackfriars House, Parsonage, MANCHESTER, Greater Manchester, M3 2JA Authority: Environment Agency - North West Region, South Area Site Category: Landfill Max Input Rate: Very Large (Equal to or greater than 250,000 tonnes per year) Waste Source Restrictions: No known restriction on source of waste Status: Licence lapsed/cancelled/defunct/not applicable/surrendered Dated: 25th February 1981 Preceded By Licence: Not Given Superseded By Licence: Not Given Positional Accuracy: Manually positioned to the address or location Boundary Accuracy: Not Applicable Authorised Waste: Alkalis Aluminium Asbestos Cellulose Wastes (Natural/Synth.) Construction And Demolition Wastes Dyestuffs Waste Empty Used Containers Fats, Waxes And Greases Gulley Emptyings Household + Commercial Waste Ind. Non-Haz. Waste Medical, Surgical, Veterinary Wastes Metal Oxides Metal Scrap Metals (Elemental) Non-Toxic Metal Compounds Other Inorganic Materials Polymeric Material, Products/Scrap Scrap Rubber (Including Tyres) Silt And Dredgings Slag, Boiler/Flue Cleanings Tannery & Fellmongers Waste Tar, Pitch, Bitumen, Asphalts Used Filter Materials $ Waste Treated Timber Prohibited Waste: Acid Tars Ammonia Ammonium Salts Blood, Fat, Grease, Etc Cadmium Carcasses And Flesh Contaminated Rubbish/Bags/Sacks Distillation Residues Excrement Food Processing Wastes/Starch Fuel Oil Glue Wastes Industrial Effluent Treatment Sludge Interceptor Pit Wastes $ Iron, Titanium, Aluminium Oxides Kerosene And Derv. Latex, Latex/Rubber Sol'Ns/Susp'Ns Magnesium Mercury Mineral Oils Mineral Processing Wastes Oil/Water Mixtures Other Elemental Metals Other Industrial Wastes Other Inorganic Materials Other Non-Toxic Metal Compounds Paint Waste $ Printing Industry Wastes/Ink $ Prod'Ts Of Incomplete Polymerisation $ Proprietary Alkaline Cleaners Soaps & Detergents Sodium/Potassium Sodium/Potassium Oxides/Hydroxides Tank Cleaning Sludge $ Vegetable And Other Oils Water (Contaminated)	A17SW (NW)	965	2	387700 395400

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
173	**Registered Waste Transfer Sites** Licence Holder: Greater Manchester Waste Ltd Licence Reference: 00885 Site Location: Sandfold Lane C.A.Site, Levenshulme, Manchester, Greater Manchester Operator Location: PO Box 151, Higher Swan Lane, BOLTON, Lancashire, BL3 3WW Authority: Environment Agency - North West Region, South Area Site Category: Civic Amenity Max Input Rate: Medium (Equal to or greater than 25,000 and less than 75,000 tonnes per year) Waste Source Restrictions: No known restriction on source of waste Licence Status: Operational as far as is knownOperational Dated: 1st February 1995 Preceded By Licence: Not Given Superseded By Licence: Not Given Positional Accuracy: Manually positioned to the address or location Boundary Quality: Not Supplied Authorised Waste: Asbestos Gmwda Group 1 - Non/V.Slow Decomp.Wast Gmwda Group 2 - Slow Decomp./Slight So Gmwda Group 3 - Decomp./Sol.Waste = No Gmwda Group 5 - Chemical/Toxic Waste Max.Waste Permitted By Licence Prohibited Waste: Acid Tars Clinical - Grp A As In Hse '92 Distillation Residues Dyestuffs Waste Foundry Sand Incinerator Residues Industrial Effluent Treatment Sludge Interceptor Pit Wastes Laboratory Chemicals Pharmaceuticals Polymeric Material, Products/Scrap Printing Industry Wastes/Ink Prod'Ts Of Incomplete Polymerisation Sewage Tank Cleaning Sludge Used Filter Mat'Ls/Cake/Screenings	A13SW (SW)	199	2	388380 394620
174	**Registered Waste Transfer Sites** Licence Holder: Uk Waste Management Ltd Licence Reference: 00700/90/M1 Site Location: Sandfold Lane, Levenshulme, Manchester, Greater Manchester Operator Location: Church Street East, Radcliffe, BURY, Lancashire, M26 9PT Authority: Environment Agency - North West Region, South Area Site Category: Transfer Max Input Rate: Large (Equal to or greater than 75,000 and less than 250,000 tonnes per year) Waste Source Restrictions: No known restriction on source of waste Licence Status: Licence lapsed/cancelled/defunct/not applicable/surrendered Dated: 1st July 1991 Preceded By Licence: Not Given Superseded By Licence: Not Given Positional Accuracy: Manually positioned to the road within the address or location Boundary Quality: Not Supplied Authorised Waste: Asbestos All Forms - But Only Admixed Electrical Fitting/Fixture/Appliance Empty Used Containers General Ind./Com. Rubbish Gmwda Group 1 - Non/V.Slow Decomp.Wast Gmwda Group 2 - Slow Decomp. Plus Gmwda Group 3 - Decomp./Sol. -But Only H'Core/Rubble -Contam.With Gps 1,2,3,4 Household Waste Max.Waste Permitted By Licence-Stated Non-Spec.Effl.Tr'T Cake Ex Paper Ind. Plasterboard/Plaster Scrap Machinery - Ferrous/Non-Ferrous Scrap Rubber (Including Tyres) Slightly Contam. Soil = Gmwda Class B Prohibited Waste: All Other Waste N.O.S. Explosive Waste Odiferous Wastes Special Wastes Violently Reactive Wastes Waste In Drums Waste In Pressurised Cont'Rs	A13SW (S)	238	2	388400 394570

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
175	**Registered Waste Transfer Sites** Licence Holder: G Connor t/a Kwik Skip Licence Reference: 01159 Site Location: No.9 Yard Printworks Lane, Levenshulme, Manchester, Greater Manchester Operator Location: 8 Beechwood Lane, Heyrod, STALYBRIDGE, Cheshire, SK15 3BU Authority: Environment Agency - North West Region, South Area Site Category: Transfer Max Input Rate: Very Small (Less than 10,000 tonnes per year) Waste Source Restrictions: No known restriction on source of waste Licence Status: Operational as far as is knownOperational Dated: 1st July 1996 Preceded By Licence: Not Given Superseded By Licence: Not Given Positional Accuracy: Approximate location provided by supplier Boundary Quality: Not Supplied Authorised Waste: Electrical Fitting/Fixture/Appliances Empty Used Containers Ferrous/Non-Ferrous Scrap Machinery Ferrous/Non-Ferrous Scrap Metal Fibreglass Gmwda Group 1 - Non/V.Slow Decomp.Wast Household Refuse Max.Waste Permitted By Licence Paper/Cardboard (Inc.Tarred/Oiled) Plasterboard/Plaster/Gypsum Plastics Vegetation (Tree/Bush/Hedge Cuttings) Wood/Prods Treated Wood/Prods Untreated Prohibited Waste: Boiler Scale Carbon, Kieselguhr Glass,Pottery,China,Enamel,Ceramic Mineral Processing Wastes Slag/Ash/Clinker Waste N.O.S.	A13SW (SW)	260	2	388300 394600
176	**Registered Waste Transfer Sites** Licence Holder: S Dew t/a S D Tyres Licence Reference: 00763 Site Location: Units 14/15 Levenshulme Trading Estate, Sandfold Lane, Levenshulme, MANCHESTER, Greater Manchester, M19 3BJ Operator Location: As Site Address Authority: Environment Agency - North West Region, South Area Site Category: Transfer Max Input Rate: Very Small (Less than 10,000 tonnes per year) Waste Source Restrictions: No known restriction on source of waste Licence Status: Licence lapsed/cancelled/defunct/not applicable/surrendered Dated: 1st September 1992 Preceded By Licence: Not Given Superseded By Licence: Not Given Positional Accuracy: Manually positioned to the road within the address or location Boundary Quality: Not Supplied Authorised Waste: Max.Storage Scrap Tyres & Inner Tubes Prohibited Waste: Explosive Waste Liquid/Sludge Wastes Malodorous Waste Pressurised Wastes Pretreated Waste Not Permit.By Lic. Special Wastes Violently Reactive Wastes Waste In Drums Waste N.O.S.	A13SW (S)	298	2	388450 394500

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
177	**Registered Waste Transfer Sites** Licence Holder: Fox Petroleum Ltd Licence Reference: 00738 Site Location: Kenwood Road, North Reddish, Reddish, STOCKPORT, Cheshire, SK5 6PW Operator Location: As Site Address Authority: Environment Agency - North West Region, South Area Site Category: Transfer Max Input Rate: Very Small (Less than 10,000 tonnes per year) Waste Source Restrictions: No known restriction on source of waste Licence Status: Licence lapsed/cancelled/defunct/not applicable/surrendered Dated: 1st June 1992 Preceded By Licence: Not Given Superseded By Licence: Not Given Positional Accuracy: Manually positioned to the road within the address or location Boundary Quality: Not Supplied Authorised Waste: Liquids Solvents & Thinners Max.Storage Petrol,Kerosene,Derv,Fuel Oil Prohibited Waste: Explosive Waste Malodorous Wastes Pressurised Waste Pretreated Wastes Not Permit.By Lic. Violently Reactive Wastes Waste N.O.S.	A14NW (E)	602	2	389050 395000

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	BGS 1:625,000 Solid Geology Description: Triassic Rocks (Undifferentiated)	A13SW (SW)	0	1	388473 394807
	BGS Estimated Soil Chemistry Source: British Geological Survey, National Geoscience Information Service Soil Sample Type: Rural Soil Arsenic Concentration: 15 - 25 mg/kg Cadmium Concentration: <1.8 mg/kg Chromium Concentration: 60 - 90 mg/kg Lead Concentration: <100 mg/kg Nickel Concentration: 15 - 30 mg/kg	A13SW (SW)	0	1	388473 394807
	BGS Estimated Soil Chemistry Source: British Geological Survey, National Geoscience Information Service Soil Sample Type: Rural Soil Arsenic Concentration: 15 - 25 mg/kg Cadmium Concentration: <1.8 mg/kg Chromium Concentration: 60 - 90 mg/kg Lead Concentration: <100 mg/kg Nickel Concentration: 30 - 45 mg/kg	A14NW (E)	513	1	388968 394965
	BGS Estimated Soil Chemistry Source: British Geological Survey, National Geoscience Information Service Soil Sample Type: Rural Soil Arsenic Concentration: 15 - 25 mg/kg Cadmium Concentration: <1.8 mg/kg Chromium Concentration: 60 - 90 mg/kg Lead Concentration: 100 - 200 mg/kg Nickel Concentration: 15 - 30 mg/kg	A18NW (N)	683	1	388473 395500
	BGS Estimated Soil Chemistry Source: British Geological Survey, National Geoscience Information Service Soil Sample Type: Rural Soil Arsenic Concentration: 15 - 25 mg/kg Cadmium Concentration: <1.8 mg/kg Chromium Concentration: 60 - 90 mg/kg Lead Concentration: <100 mg/kg Nickel Concentration: 30 - 45 mg/kg	A9SW (SE)	955	1	389028 394018
	BGS Estimated Soil Chemistry Source: British Geological Survey, National Geoscience Information Service Soil Sample Type: Rural Soil Arsenic Concentration: 15 - 25 mg/kg Cadmium Concentration: <1.8 mg/kg Chromium Concentration: 60 - 90 mg/kg Lead Concentration: 100 - 200 mg/kg Nickel Concentration: 15 - 30 mg/kg	A12NW (W)	986	1	387500 395000
178	**BGS Recorded Mineral Sites** Site Name: Parkfield Brick Works Location: Reddish, Stockport, Greater Manchester Source: British Geological Survey, National Geoscience Information Service Reference: 91118 Type: Opencast **Status: Ceased** Operator: Unknown Operator Operator Location: Not Supplied Periodic Type: Quaternary, Devensian Geology: Till, Devensian Commodity: Common Clay and Shale Positional Accuracy: Located by supplier to within 10m	A14NE (E)	816	1	389280 394959

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
179	**BGS Recorded Mineral Sites** Site Name: Craddock Fold Brick Works Location: Levenshulme, Manchester, Lancashire Source: British Geological Survey, National Geoscience Information Service Reference: 91148 Type: Opencast **Status: Ceased** Operator: Unknown Operator Operator Location: Not Supplied Periodic Type: Quaternary, Devensian Geology: Till, Devensian Commodity: Common Clay and Shale Positional Accuracy: Located by supplier to within 10m	A7NE (SW)	889	1	387848 394161
180	**BGS Recorded Mineral Sites** Site Name: Sandfold Gravel Pit Location: Reddish, Stockport, Greater Manchester Source: British Geological Survey, National Geoscience Information Service Reference: 91108 Type: Opencast **Status: Ceased** Operator: Unknown Operator Operator Location: Not Supplied Periodic Type: Quaternary Geology: Glaciofluvial Deposits, Devensian Commodity: Sand and Gravel Positional Accuracy: Located by supplier to within 10m	A14NE (E)	971	1	389443 394906
	BGS Measured Urban Soil Chemistry Source: British Geological Survey, National Geoscience Information Service Grid: 388340, 395140 Soil Sample Type: Topsoil Sample Area: Manchester Arsenic Measured Concentration: 54.60 mg/kg Cadmium Measured Concentration: 2.20 mg/kg Chromium Measured Concentration: 102.50 mg/kg Lead Measured Concentration: 362.80 mg/kg Nickel Measured Concentration: 59.50 mg/kg	A13NW (N)	348	1	388340 395140
	BGS Measured Urban Soil Chemistry Source: British Geological Survey, National Geoscience Information Service Grid: 388740, 395330 Soil Sample Type: Topsoil Sample Area: Manchester Arsenic Measured Concentration: 12.90 mg/kg Cadmium Measured Concentration: 0.90 mg/kg Chromium Measured Concentration: 52.90 mg/kg Lead Measured Concentration: 132.60 mg/kg Nickel Measured Concentration: 18.10 mg/kg	A18SE (NE)	577	1	388740 395330
	BGS Measured Urban Soil Chemistry Source: British Geological Survey, National Geoscience Information Service Grid: 387750, 395250 Soil Sample Type: Topsoil Sample Area: Manchester Arsenic Measured Concentration: 19.00 mg/kg Cadmium Measured Concentration: 0.50 mg/kg Chromium Measured Concentration: 92.40 mg/kg Lead Measured Concentration: 175.90 mg/kg Nickel Measured Concentration: 42.70 mg/kg	A17SW (NW)	839	1	387750 395250

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	BGS Measured Urban Soil Chemistry Source: British Geological Survey, National Geoscience Information Service Grid: 388750, 395680 Soil Sample Type: Topsoil Sample Area: Manchester Arsenic Measured Concentration: 23.30 mg/kg Cadmium Measured Concentration: 0.60 mg/kg Chromium Measured Concentration: 76.20 mg/kg Lead Measured Concentration: 314.80 mg/kg Nickel Measured Concentration: 27.00 mg/kg	A18NE (N)	906	1	388750 395680
	BGS Measured Urban Soil Chemistry Source: British Geological Survey, National Geoscience Information Service Grid: 388360, 395720 Soil Sample Type: Topsoil Sample Area: Manchester Arsenic Measured Concentration: 19.90 mg/kg Cadmium Measured Concentration: 1.60 mg/kg Chromium Measured Concentration: 105.60 mg/kg Lead Measured Concentration: 214.80 mg/kg Nickel Measured Concentration: 54.60 mg/kg	A18NW (N)	910	1	388360 395720
	BGS Urban Soil Chemistry Averages Source: British Geological Survey, National Geoscience Information Service Sample Area: Manchester Count Id: 300 Arsenic Minimum Concentration: 3.00 mg/kg Arsenic Average Concentration: 28.00 mg/kg Arsenic Maximum Concentration: 1008.00 mg/kg Cadmium Minimum Concentration: 0.30 mg/kg Cadmium Average Concentration: 1.40 mg/kg Cadmium Maximum Concentration: 80.30 mg/kg Chromium Minimum Concentration: 29.00 mg/kg Chromium Average Concentration: 92.00 mg/kg Chromium Maximum Concentration: 1252.00 mg/kg Lead Minimum Concentration: 20.00 mg/kg Lead Average Concentration: 270.00 mg/kg Lead Maximum Concentration: 2687.00 mg/kg Nickel Minimum Concentration: 5.00 mg/kg Nickel Average Concentration: 32.00 mg/kg Nickel Maximum Concentration: 137.00 mg/kg	A13SW (SW)	0	1	388473 394807
	Coal Mining Affected Areas In an area that might not be affected by coal mining				
	Non Coal Mining Areas of Great Britain No Hazard				
	Potential for Collapsible Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13SW (SW)	0	1	388473 394807
	Potential for Collapsible Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NW (N)	183	1	388473 395000

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Potential for Compressible Ground Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13SW (SW)	0	1	388473 394807
	Potential for Compressible Ground Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13NW (N)	183	1	388473 395000
	Potential for Ground Dissolution Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13SW (SW)	0	1	388473 394807
	Potential for Ground Dissolution Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13NW (N)	183	1	388473 395000
	Potential for Landslide Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13SW (SW)	0	1	388473 394807
	Potential for Landslide Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NW (N)	183	1	388473 395000
	Potential for Running Sand Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13SW (SW)	0	1	388473 394807
	Potential for Running Sand Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NW (N)	183	1	388473 395000
	Potential for Shrinking or Swelling Clay Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13SW (SW)	0	1	388473 394807
	Potential for Shrinking or Swelling Clay Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13NW (N)	183	1	388473 395000
	Radon Potential - Radon Affected Areas Affected Area: The property is in a Lower probability radon area (less than 1% of homes are estimated to be at or above the Action Level). Source: British Geological Survey, National Geoscience Information Service	A13SW (SW)	0	1	388473 394807
	Radon Potential - Radon Protection Measures Protection Measure: No radon protective measures are necessary in the construction of new dwellings or extensions Source: British Geological Survey, National Geoscience Information Service	A13SW (SW)	0	1	388473 394807

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
181	**Contemporary Trade Directory Entries** Name: C B A Enterprises Ltd Location: Sandfold Lane, Manchester, M19 3UU Classification: Food Products - Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SE (S)	175	-	388489 394624
182	**Contemporary Trade Directory Entries** Name: Viridor Location: Sandfold Lane, MANCHESTER, M19 3BJ Classification: Waste Disposal Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	188	-	388361 394644
182	**Contemporary Trade Directory Entries** Name: R & K Commercial Ltd Location: Sandfold Lane, Manchester, M19 3BJ Classification: Commercial Vehicle Bodybuilders & Repairers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	188	-	388361 394644
182	**Contemporary Trade Directory Entries** Name: A S T Express Ltd Location: Sandfold House,Sandfold Lane, Manchester, Greater Manchester, M19 3BJ Classification: Road Haulage Services **Status: Active** Positional Accuracy: Manually positioned within the geographical locality	A13SW (SW)	219	-	388338 394622
182	**Contemporary Trade Directory Entries** Name: European Rubber Regeneration Location: Sandfold La, Manchester, Lancashire, M19 3BJ Classification: Tyre Disposal **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A13SW (SW)	220	-	388341 394618
183	**Contemporary Trade Directory Entries** Name: Doman Auto Safety Centre Location: Unit 1, Sandfold Lane, Manchester, M19 3BJ Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	235	-	388315 394619
183	**Contemporary Trade Directory Entries** Name: Doman Auto Safety Centre Location: Unit 1, Sandfold Lane, Manchester, M19 3BJ Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	236	-	388315 394619
183	**Contemporary Trade Directory Entries** Name: Reco Location: Unit 1A, Sandfold Lane, Manchester, M19 3BJ Classification: Pallets, Crates & Packing Cases **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	252	-	388302 394609
183	**Contemporary Trade Directory Entries** Name: Espaul Motor Co Location: Unit F, Sandfold Lane, Manchester, M19 3BJ Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	268	-	388296 394593
183	**Contemporary Trade Directory Entries** Name: Doman Auto Safety Centre Location: Unit 1, Sandfold Lane, Manchester, M19 3BJ Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	268	-	388296 394593
183	**Contemporary Trade Directory Entries** Name: Nearly New Tyres Location: Unit F, Sandfold Lane, Manchester, M19 3BJ Classification: Tyre Dealers **Status: Active** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	268	-	388296 394593
183	**Contemporary Trade Directory Entries** Name: Cornbrook Metal Recycling Ltd Location: Unit 1a, Sandfold Lane, MANCHESTER, M19 3BJ Classification: Scrap Metal Merchants **Status: Active** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	269	-	388277 394609

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
184	**Contemporary Trade Directory Entries** Name: Mcdonnell Haulage Location: UNIT 7, SANDFOLD LANE, MANCHESTER, M19 3BJ Classification: Road Haulage Services **Status: Active** Positional Accuracy: Automatically positioned to the address	A13SW (S)	254	-	388463 394544
184	**Contemporary Trade Directory Entries** Name: Gb Coaches Ltd Location: Unit 7, Sandfold Lane, Manchester, M19 3BJ Classification: Bus & Coach Operators & Stations **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (S)	259	-	388463 394539
184	**Contemporary Trade Directory Entries** Name: G & L Autoservices Location: Unit 13, Sandfold Lane, Manchester, M19 3BJ Classification: Mechanical Engineers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SE (S)	287	-	388498 394512
184	**Contemporary Trade Directory Entries** Name: S D Tyres Ltd Location: Unit 14-15, Sandfold Lane, Manchester, M19 3BJ Classification: Tyre Dealers **Status: Active** Positional Accuracy: Automatically positioned to the address	A13SW (S)	302	-	388459 394496
184	**Contemporary Trade Directory Entries** Name: Plastics (Manchester) Ltd Location: Plasman Industrial Centre, Peter Moss Way, Manchester, M19 3PX Classification: Plastic Products - Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (S)	347	-	388441 394452
184	**Contemporary Trade Directory Entries** Name: Plastics Manchester Ltd Location: Plasman Industrial Centre, Peter Moss Way, Manchester, M19 3PX Classification: Plastics - Vacuum Forming **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (S)	347	-	388441 394452
185	**Contemporary Trade Directory Entries** Name: O' Connor Concrete Location: UNIT 10, SANDFOLD LANE, MANCHESTER, M19 3BJ Classification: Concrete & Mortar Ready Mixed **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SE (S)	269	-	388543 394537
185	**Contemporary Trade Directory Entries** Name: D & G Mckenna Haulage Ltd Location: Sandfold Lane, Manchester, M19 3BJ Classification: Road Haulage Services **Status: Active** Positional Accuracy: Automatically positioned to the address	A13SE (S)	313	-	388530 394489
186	**Contemporary Trade Directory Entries** Name: Ryan M Son Haulage Ltd Location: Unit 19a, Sandfold Lane, Manchester, Lancashire, M19 3BJ Classification: Road Haulage Services **Status: Inactive** Positional Accuracy: Manually positioned within the geographical locality	A13SW (S)	270	-	388391 394539
186	**Contemporary Trade Directory Entries** Name: Ryan Skip Hire Ltd Location: Unit 17, Sandfold Lane, Manchester, M19 3BJ Classification: Waste Disposal Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (S)	315	-	388394 394492
187	**Contemporary Trade Directory Entries** Name: Southside Motor Co Location: 301, Mount Road, Manchester, Lancashire, M19 3ET Classification: Car Dealers - Used **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (W)	273	-	388196 394782
188	**Contemporary Trade Directory Entries** Name: Mount Road Service Centre Location: 303, Mount Road, Manchester, M19 3ET Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (W)	275	-	388209 394707

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
188	**Contemporary Trade Directory Entries** Name: F E Jones Builders Location: 303, Mount Road, Manchester, M19 3ET Classification: Joinery Manufacturers **Status: Active** Positional Accuracy: Automatically positioned to the address	A13SW (W)	275	-	388209 394707
189	**Contemporary Trade Directory Entries** Name: All Clear Rubbish Removals Location: 7, Westlea Drive, Manchester, M18 7NR Classification: Waste Disposal Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13NE (N)	320	-	388590 395116
190	**Contemporary Trade Directory Entries** Name: Rf Commercials Location: Unit X Levenshulme Trading Est,Printworks La, Manchester, Lancashire, M19 3JP Classification: Commercial Vehicle Bodybuilders & Repairers **Status: Inactive** Positional Accuracy: Manually positioned within the geographical locality	A13SW (SW)	336	-	388251 394542
191	**Contemporary Trade Directory Entries** Name: M & H Travel Location: Levenshulme Trading Est,Printwork La, Manchester, Lancashire, M19 3JP Classification: Car Body Repairs **Status: Inactive** Positional Accuracy: Manually positioned within the geographical locality	A13SW (SW)	353	-	388256 394516
191	**Contemporary Trade Directory Entries** Name: British Cement Ltd Location: Levenshulme Trading Est,Printwork La, Manchester, M19 3JP Classification: Cement Manufacturers & Distributors **Status: Inactive** Positional Accuracy: Manually positioned to the address or location	A13SW (SW)	362	-	388272 394494
192	**Contemporary Trade Directory Entries** Name: One Stop Auto Location: Levenshulme Trading Estate,Printworks Lane, Manchester, Greater Manchester, M19 3JP Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	365	-	388288 394481
192	**Contemporary Trade Directory Entries** Name: Brick Presentation Services Location: Unit B, Levenshulme Trading Estate, Printworks Lane, Manchester, M19 3JP Classification: Brick Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	365	-	388288 394481
192	**Contemporary Trade Directory Entries** Name: Binmate Ltd Location: Unit N, Levenshulme Trading Estate, Printworks Lane, Manchester, M19 3JP Classification: Plastic Products - Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	365	-	388288 394481
192	**Contemporary Trade Directory Entries** Name: Msm Autobodies Location: Unit E, Levenshulme Trading Estate, Printworks Lane, Manchester, M19 3JP Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	365	-	388288 394481
192	**Contemporary Trade Directory Entries** Name: Oakfield Timber Products Location: Calico House, Levenshulme Trading Estate, Printworks Lane, Manchester, M19 3JP Classification: Wood Products, Except Furniture - Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	365	-	388288 394480
192	**Contemporary Trade Directory Entries** Name: Cab Repairs Location: Unit B, Levenshulme Trading Estate, Printworks Lane, Manchester, M19 3JP Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	365	-	388288 394481

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
192	**Contemporary Trade Directory Entries** Name: Brick Presentation Services Location: Unit 4, Levenshulme Trading Estate, Printworks Lane, Manchester, M19 3JP Classification: Brick Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	365	-	388288 394481
192	**Contemporary Trade Directory Entries** Name: Printwork Auto Bodies Location: Levenshulme Trading Est,Printwork La, Manchester, M19 3JP Classification: Car Body Repairs **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A8NW (SW)	388	-	388308 394445
193	**Contemporary Trade Directory Entries** Name: Keeping Manchester Clean Location: 1, Flemish Crescent, Manchester, M18 7TR Classification: Commercial Cleaning Services **Status: Active** Positional Accuracy: Automatically positioned to the address	A14NW (E)	378	-	388854 394831
194	**Contemporary Trade Directory Entries** Name: Whiteoak & Sons Location: 12, Mullion Close, Manchester, M19 3ZF Classification: Blacksmiths & Forgemasters **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SE (SE)	384	-	388772 394553
195	**Contemporary Trade Directory Entries** Name: Escort Carpet Cleaning Location: 49, Walton Hall Drive, Manchester, M19 3WH Classification: Carpet, Curtain & Upholstery Cleaners **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (SE)	400	-	388646 394435
196	**Contemporary Trade Directory Entries** Name: Plasman Laminate Products Ltd Location: MARQUIS STREET, MANCHESTER, M19 3JH Classification: Kitchen Furniture Manufacturers **Status: Active** Positional Accuracy: Automatically positioned to the address	A8NE (S)	408	-	388595 394407
196	**Contemporary Trade Directory Entries** Name: Plasman (Laminate Products) Ltd Location: Plasman Industrial Centre, Marquis Street, Manchester, M19 3JH Classification: Floorcoverings - Manufacturers & Wholesalers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	408	-	388595 394407
196	**Contemporary Trade Directory Entries** Name: Parts Line Location: 8, Marquis Street, MANCHESTER, M19 3JZ Classification: Car Breakers & Dismantlers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	423	-	388567 394385
196	**Contemporary Trade Directory Entries** Name: Parts Line Ltd Location: 8, Marquis Street, Manchester, M19 3JZ Classification: Car Breakers & Dismantlers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	423	-	388567 394385
196	**Contemporary Trade Directory Entries** Name: South Manchester Diesels Location: 6, Marquis Street, Manchester, M19 3JZ Classification: Diesel Engine Equipment & Services **Status: Active** Positional Accuracy: Automatically positioned to the address	A8NE (S)	442	-	388563 394365
196	**Contemporary Trade Directory Entries** Name: A1 Mobile Industrial Domestic Service Cleaners Location: Descaling Services Pegasus Works,Nelstrop Road, Manchester, Greater Manchester, M19 3JL Classification: Commercial Cleaning Services **Status: Active** Positional Accuracy: Manually positioned to the address or location	A8NE (S)	445	-	388580 394365

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
196	**Contemporary Trade Directory Entries** Name: P Kenny Location: 2, Marquis Street, Manchester, M19 3JZ Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	460	-	388555 394345
196	**Contemporary Trade Directory Entries** Name: Kenny Location: 2, Marquis Street, Manchester, Lancashire, M19 3JZ Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	460	-	388555 394345
197	**Contemporary Trade Directory Entries** Name: Barlow Service Station Location: 295, Barlow Road, Levenshulme, Manchester, M19 3HQ Classification: Petrol Filling Stations **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (S)	424	-	388327 394398
198	**Contemporary Trade Directory Entries** Name: E Sivori & Co Ltd Location: 289-291, Barlow Road, Levenshulme, Manchester, M19 3HQ Classification: Ice Cream Manufacturers & Suppliers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (SW)	458	-	388255 394393
198	**Contemporary Trade Directory Entries** Name: E Sivori & Co Ltd Location: 289, BARLOW ROAD, MANCHESTER, M19 3HQ Classification: Ice Cream Manufacturers & Suppliers **Status: Active** Positional Accuracy: Automatically positioned to the address	A8NW (SW)	462	-	388270 394380
199	**Contemporary Trade Directory Entries** Name: British Cement Ltd Location: Keenan House, Barlow Road, Levenshulme, Manchester, M19 3JD Classification: Cement Manufacturers & Distributors **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (S)	497	-	388284 394336
200	**Contemporary Trade Directory Entries** Name: M & K Sewing Machines Location: 257-259, Barlow Road, Levenshulme, Manchester, M19 3HQ Classification: Sewing Machines - Industrial **Status: Active** Positional Accuracy: Automatically positioned to the address	A8NW (SW)	511	-	388169 394384
201	**Contemporary Trade Directory Entries** Name: Ms Cleaning Services Location: 64, SHILLINGFORD ROAD, MANCHESTER, M18 7TS Classification: Cleaning Services - Domestic **Status: Active** Positional Accuracy: Automatically positioned to the address	A14NW (E)	518	-	388987 394907
202	**Contemporary Trade Directory Entries** Name: We Will Deliver Them Location: 37, Wembley Road, Manchester, M18 7PP Classification: Distribution Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A18SE (N)	540	-	388496 395356
203	**Contemporary Trade Directory Entries** Name: J & S Commercial Van Sales Ltd Location: Kenwood Road, Stockport, Cheshire, SK5 6PH Classification: Commercial Vehicle Dealers **Status: Active** Positional Accuracy: Manually positioned to the address or location	A14NW (E)	559	-	389035 394836
203	**Contemporary Trade Directory Entries** Name: P & J Ltd Location: Unit 1, Kenwood Road, Stockport, Cheshire, SK5 6PH Classification: Wallpapers & Wall Coverings **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	560	-	389036 394790
203	**Contemporary Trade Directory Entries** Name: J & S Commercial Van Sales Ltd Location: The Dye Works,Kenwood Road, Stockport, Cheshire, SK5 6PH Classification: Commercial Vehicle Dealers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (E)	568	-	389044 394838

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
203	**Contemporary Trade Directory Entries** Name: Manchester Candles Location: The Dye Works, Kenwood Road, Stockport, Cheshire, SK5 6PH Classification: Candle Manufacturers & Suppliers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (E)	568	-	389044 394838
203	**Contemporary Trade Directory Entries** Name: Manchester Colour Co Ltd Location: The Dye Works, Kenwood Road, Stockport, Cheshire, SK5 6PH Classification: Paint Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (E)	568	-	389044 394838
203	**Contemporary Trade Directory Entries** Name: C W Travel Location: Unit 2 Avery Trading Estate,Kenwood Road, Stockport, Cheshire, SK5 6PH Classification: Bus & Coach Operators & Stations **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A14SW (E)	584	-	389061 394803
203	**Contemporary Trade Directory Entries** Name: Silanes & Silicones Location: Unit 17-18, Station Road, Reddish, Stockport, Cheshire, SK5 6ND Classification: Chemical Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (E)	594	-	389071 394824
203	**Contemporary Trade Directory Entries** Name: Elaflex Location: Unit 14, Station Road, Reddish, Stockport, Cheshire, SK5 6ND Classification: Hose, Tubing & Fittings **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	596	-	389073 394795
203	**Contemporary Trade Directory Entries** Name: Thirst Class Ale Ltd Location: UNIT 16, STATION ROAD INDUSTRIAL ESTATE, STATION ROAD, NORTH REDDISH, STOCKPORT, SK5 6ND Classification: Brewers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (E)	597	-	389074 394815
203	**Contemporary Trade Directory Entries** Name: Saferfillsystems Location: UNIT 14, STATION ROAD INDUSTRIAL ESTATE, STATION ROAD, NORTH REDDISH, STOCKPORT, SK5 6ND Classification: Petrol Filling Stations **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	598	-	389075 394795
204	**Contemporary Trade Directory Entries** Name: Kenwood Commercial Services Location: Kenwood Road, Stockport, Cheshire, SK5 6PH Classification: Commercial Vehicle Servicing, Repairs, Parts & Accessories **Status: Active** Positional Accuracy: Automatically positioned to the address	A14NW (E)	562	-	389031 394910
204	**Contemporary Trade Directory Entries** Name: Stockport Ring & Ride Location: Unit 1-4,Kenwood Rd, Stockport, Cheshire, SK5 6PH Classification: Bus & Coach Operators & Stations **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A14NW (E)	579	-	389052 394884
204	**Contemporary Trade Directory Entries** Name: Crown Metal Treatments Ltd Location: Kenwood Rd, Reddish, Stockport, Cheshire, SK5 6PH Classification: Blast Cleaning **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A14NW (E)	580	-	389050 394904
204	**Contemporary Trade Directory Entries** Name: Kenwood Commercial Services Ltd Location: Kenwood Rd, Stockport, Cheshire, SK5 6PH Classification: Commercial Vehicle Breakdown & Recovery Services **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A14NW (E)	584	-	389047 394942

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
204	**Contemporary Trade Directory Entries** Name: Connect Cleaning Machines Ltd Location: Unit 1 Avery Trading Estate, Kenwood Road, Stockport, Cheshire, SK5 6PH Classification: Cleaning Materials & Equipment **Status: Inactive** Positional Accuracy: Manually positioned within the geographical locality	A14NW (E)	607	-	389074 394921
205	**Contemporary Trade Directory Entries** Name: Dolbi Corporation Uk Ltd Location: 22, Kettering Road, Manchester, M19 3FN Classification: Electrical Goods Sales, Manufacturers & Wholesalers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A12SE (W)	591	-	387912 394598
206	**Contemporary Trade Directory Entries** Name: Sabre Waste Recycling Ltd Location: Unit 17 Station Road Industrial Estate,46 Station Road, Reddish, Stockport, Cheshire, SK5 6ND Classification: Recycling Services **Status: Active** Positional Accuracy: Manually positioned to the address or location	A14NW (E)	598	-	389074 394824
206	**Contemporary Trade Directory Entries** Name: Station M O T Centre Location: Unit 6, Station Road, Reddish, Stockport, SK5 6ND Classification: Mot Testing Centres **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SW (E)	633	-	389109 394806
207	**Contemporary Trade Directory Entries** Name: Fast Cash 4 Scrap Cars Stockport Aeg Location: Unit 1, Kenwood Road, Stockport, Cheshire, SK5 6PH Classification: Car Breakers & Dismantlers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (E)	628	-	389082 394984
207	**Contemporary Trade Directory Entries** Name: Grip Hygiene Supplies Location: Unit 1a Avery Trading Estate,Kenwood Road, Stockport, Cheshire, SK5 6PH Classification: Cleaning Materials & Equipment **Status: Active** Positional Accuracy: Manually positioned to the address or location	A14NW (E)	628	-	389081 394988
207	**Contemporary Trade Directory Entries** Name: Clean Solutions Location: Kenwood Road, Stockport, Cheshire, SK5 6PH Classification: Cleaning Materials & Equipment **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (E)	628	-	389082 394984
207	**Contemporary Trade Directory Entries** Name: Approved Hydraulics Location: UNIT 1, AVERY TRADING ESTATE, KENWOOD ROAD, NORTH REDDISH, STOCKPORT, SK5 6PH Classification: Hydraulic Equipment & Accessories - Sales & Service **Status: Active** Positional Accuracy: Automatically positioned to the address	A14NW (E)	633	-	389081 395006
207	**Contemporary Trade Directory Entries** Name: H & J K Davies Bros Ltd Location: Kenwood Road, STOCKPORT, Cheshire, SK5 6PH Classification: Road Haulage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (E)	642	-	389080 395036
207	**Contemporary Trade Directory Entries** Name: Mancunian Spring Location: NORTH REDDISH, STOCKPORT, SK5 6PH Classification: Commercial Vehicle Servicing, Repairs, Parts & Accessories **Status: Active** Positional Accuracy: Automatically positioned to the address	A14NW (E)	671	-	389119 395012
207	**Contemporary Trade Directory Entries** Name: Plasway Location: Unit 2, Kenwood Road, Stockport, Cheshire, SK5 6PH Classification: Door Manufacturers - Industrial **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (E)	677	-	389125 395011

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
208	**Contemporary Trade Directory Entries** Name: Mds Domestic Services Location: 197, Mount Road, Manchester, M18 7GG Classification: Domestic Appliances - Servicing, Repairs & Parts **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A17SE (NW)	632	-	388093 395326
209	**Contemporary Trade Directory Entries** Name: Complete Entrance Solutions Ltd Location: Unit 11, Kenwood Road, Stockport, Cheshire, SK5 6PH Classification: Automation Systems & Equipment **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (NE)	637	-	389055 395083
210	**Contemporary Trade Directory Entries** Name: Nemac Fabrications Ltd Location: Unit 5, Station Road, Reddish, Stockport, Cheshire, SK5 6ND Classification: Machine Shops **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (E)	639	-	389115 394841
210	**Contemporary Trade Directory Entries** Name: Elmax Engineering Ltd Location: Unit 7, Kenwood Road, Stockport, Cheshire, SK5 6PH Classification: Precision Engineers **Status: Active** Positional Accuracy: Automatically positioned to the address	A14NW (E)	639	-	389115 394841
210	**Contemporary Trade Directory Entries** Name: B & H Precision Tooling Location: Crown Works, Kenwood Road, Stockport, SK5 6PH Classification: Precision Engineers **Status: Active** Positional Accuracy: Automatically positioned to the address	A14NW (E)	659	-	389133 394869
210	**Contemporary Trade Directory Entries** Name: P H Lifting Services Location: Unit 11, Station Road, Reddish, Stockport, Cheshire, SK5 6ND Classification: Road Haulage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (E)	659	-	389132 394885
211	**Contemporary Trade Directory Entries** Name: Top Mop Services Location: Shillingford Road, Manchester, Greater Manchester, M18 7TQ Classification: Cleaning Services - Domestic **Status: Active** Positional Accuracy: Manually positioned within the geographical locality	A19SW (NE)	664	-	389037 395173
212	**Contemporary Trade Directory Entries** Name: Didsbury Engineering Location: Manor Road, Levenshulme, MANCHESTER, M19 3EJ Classification: Lifting Equipment **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A12SE (W)	675	-	387841 394550
213	**Contemporary Trade Directory Entries** Name: Interfit Location: Unit 14, Station Road, Reddish, STOCKPORT, Cheshire, SK5 6ND Classification: Commercial Vehicle Servicing, Repairs, Parts & Accessories **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A14SE (E)	690	-	389165 394758
213	**Contemporary Trade Directory Entries** Name: Euroflame Location: Unit 15,Station Rd, Reddish, Stockport, Cheshire, SK5 6ND Classification: Fireplaces & Mantelpieces **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A14SE (E)	696	-	389172 394758
213	**Contemporary Trade Directory Entries** Name: Elsa Recycling Group Ltd Location: Unit 1-3, Station Road, Reddish, Stockport, Cheshire, SK5 6ND Classification: Recycling Centres **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	703	-	389180 394786
213	**Contemporary Trade Directory Entries** Name: The Elsa Recycling Group Location: Unit 1-3, Station Road, Reddish, Stockport, Cheshire, SK5 6ND Classification: Reclaiming - Waste Products **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	703	-	389180 394786

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
213	**Contemporary Trade Directory Entries** Name: Grange Products Ltd Location: Unit 4, Station Road, Reddish, Stockport, Cheshire, SK5 6ND Classification: Electronic Engineers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	703	-	389180 394786
213	**Contemporary Trade Directory Entries** Name: Site & Fabrication Engineering Ltd Location: Unit 5, Climax Works, Station Road, Reddish, Stockport, SK5 6YZ Classification: Engineers - General **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NE (E)	731	-	389207 394825
213	**Contemporary Trade Directory Entries** Name: Ahg Tanks & Systems Ltd Location: Unit 7, Climax Works, Station Road, Reddish, Stockport, SK5 6YZ Classification: Plastic Products - Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NE (E)	731	-	389207 394825
213	**Contemporary Trade Directory Entries** Name: M F G Machinery Ltd Location: Unit 6, Climax Works, Station Road, Reddish, Stockport, Cheshire, SK5 6YZ Classification: Machine Tools - Manufacturers & Distributors **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NE (E)	731	-	389207 394825
213	**Contemporary Trade Directory Entries** Name: Unique Hygiene Location: Unit 10, Climax Works, Station Road, Reddish, Stockport, Cheshire, SK5 6YZ Classification: Cleaning Materials & Equipment **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NE (E)	731	-	389207 394825
213	**Contemporary Trade Directory Entries** Name: R & T Electronic Recycling Ltd Location: Unit 7, Climax Works, Station Road, Reddish, Stockport, Cheshire, SK5 6YZ Classification: Engineers - General **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NE (E)	731	-	389207 394825
213	**Contemporary Trade Directory Entries** Name: Mofab Engineering Location: Unit 2 ,Durham Street, Reddish, Stockport, Cheshire, SK5 6YZ Classification: Engineers - General **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A14SE (E)	737	-	389213 394774
213	**Contemporary Trade Directory Entries** Name: Gas Chillers Uk Ltd Location: Durham Street, Reddish, Stockport, Cheshire, SK5 6YZ Classification: Air Conditioning & Refrigeration Contractors **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A14SE (E)	738	-	389214 394776
213	**Contemporary Trade Directory Entries** Name: Clampco Uk Ltd Location: Unit 10, Climax Works, Station Road, Reddish, Stockport, SK5 6YZ Classification: Exhaust System Manufacturers & Wholesalers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	746	-	389223 394803
214	**Contemporary Trade Directory Entries** Name: Jumbo Laundrette Location: 119, Levenshulme Road, Manchester, M18 7NF Classification: Dry Cleaners **Status: Active** Positional Accuracy: Automatically positioned to the address	A18NE (N)	692	-	388643 395488
215	**Contemporary Trade Directory Entries** Name: A Brickell & Sons Location: 212, Barlow Road, Levenshulme, Manchester, M19 3HF Classification: Damp & Dry Rot Control **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A7NE (SW)	716	-	387965 394289
216	**Contemporary Trade Directory Entries** Name: Just Smarts Location: 24, Bradfield Close, Stockport, Cheshire, SK5 6XP Classification: Car Dealers - Used **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	720	-	389185 394669

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
217	**Contemporary Trade Directory Entries** Name: D C S Cleaning Location: Browning rd, Stockport, Cheshire, SK5 6JT Classification: Cleaning Services - Domestic **Status:** **Active** Positional Accuracy: Manually positioned to the road within the address or location	A14SE (SE)	737	-	389159 394518
218	**Contemporary Trade Directory Entries** Name: Denise'S Cleaning Services Location: 1, Shelley Road, Stockport, SK5 6JG Classification: Cleaning Services - Domestic **Status:** **Active** Positional Accuracy: Automatically positioned to the address	A9NW (SE)	741	-	388984 394258
219	**Contemporary Trade Directory Entries** Name: Lick Sweets & Snacks Location: Unit 14, Hemmons Road, Manchester, M12 5ST Classification: Confectionery Manufacturers **Status:** **Inactive** Positional Accuracy: Automatically positioned to the address	A12NW (W)	765	-	387704 394861
219	**Contemporary Trade Directory Entries** Name: Budget Flooring Location: Unit 10-11, Hemmons Road, Manchester, M12 5ST Classification: Floorcoverings - Manufacturers & Wholesalers **Status:** **Inactive** Positional Accuracy: Automatically positioned to the address	A12NW (W)	765	-	387704 394861
219	**Contemporary Trade Directory Entries** Name: Joseph H Wood & Son Ltd Location: Unit 15, Hemmons Road, Manchester, M12 5ST Classification: Boilers - Servicing, Replacements & Repairs **Status:** **Inactive** Positional Accuracy: Automatically positioned to the address	A12NW (W)	765	-	387704 394861
219	**Contemporary Trade Directory Entries** Name: Premiercode Location: Unit 1, Hemmons Road, Manchester, M12 5ST Classification: Knitwear Manufacturers & Wholesalers **Status:** **Inactive** Positional Accuracy: Automatically positioned to the address	A12NW (W)	765	-	387704 394861
219	**Contemporary Trade Directory Entries** Name: Newlook Windows Manchester Ltd Location: Unit 11, Hemmons Road, Manchester, M12 5ST Classification: Window Frame Manufacturers **Status:** **Inactive** Positional Accuracy: Automatically positioned to the address	A12NW (W)	765	-	387704 394861
219	**Contemporary Trade Directory Entries** Name: Fairway Recycling Location: Unit 9c, Hemmons Road, Manchester, M12 5ST Classification: Computer Recycling & Disposal **Status:** **Inactive** Positional Accuracy: Automatically positioned to the address	A12NW (W)	768	-	387704 394883
219	**Contemporary Trade Directory Entries** Name: Loyalty Motors Location: Unit 5, Longden Road, Manchester, M12 5SJ Classification: Mot Testing Centres **Status:** **Active** Positional Accuracy: Automatically positioned to the address	A12NW (W)	768	-	387704 394883
219	**Contemporary Trade Directory Entries** Name: Hemmons Road M O T Centre Location: Unit 9b, Hemmons Road, MANCHESTER, M12 5ST Classification: Mot Testing Centres **Status:** **Inactive** Positional Accuracy: Automatically positioned to the address	A12NW (W)	768	-	387704 394883
219	**Contemporary Trade Directory Entries** Name: Khan Motors Location: Unit 5, Longden Road, Manchester, Lancashire, M12 5SJ Classification: Garage Services **Status:** **Inactive** Positional Accuracy: Manually positioned to the address or location	A12NW (W)	768	-	387704 394883
219	**Contemporary Trade Directory Entries** Name: Watan Auto Workshop Location: Unit 3, Longden Road, Manchester, M12 5SJ Classification: Garage Services **Status:** **Active** Positional Accuracy: Automatically positioned to the address	A12NW (W)	781	-	387690 394883

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
219	**Contemporary Trade Directory Entries** Name: Renovo Autocentre Location: Unit 9 Hemmons Road Industrial Estate,Hemmons Road, Manchester, Greater Manchester, M12 5ST Classification: Garage Services **Status: Active** Positional Accuracy: Manually positioned within the geographical locality	A12NW (W)	781	-	387690 394883
219	**Contemporary Trade Directory Entries** Name: Uk Cater Equipment Ltd Location: Unit 13, Hemmons Road, Manchester, M12 5ST Classification: Catering Equipment **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A12NW (W)	781	-	387690 394883
219	**Contemporary Trade Directory Entries** Name: O R S Autos Ltd Location: UNIT 9A, LONGDEN ROAD INDUSTRIAL ESTATE, HEMMONS ROAD, MANCHESTER, M12 5ST Classification: Garage Services **Status: Active** Positional Accuracy: Automatically positioned to the address	A12NW (W)	781	-	387690 394883
219	**Contemporary Trade Directory Entries** Name: Gb Mobile Tyres Ltd Location: UNIT 2, LONGDEN ROAD INDUSTRIAL ESTATE, HEMMONS ROAD, MANCHESTER, M12 5SJ Classification: Tyre Dealers **Status: Active** Positional Accuracy: Automatically positioned to the address	A12NW (W)	781	-	387690 394883
220	**Contemporary Trade Directory Entries** Name: Home & Garden Location: Station Road, Reddish, Stockport, Cheshire, SK5 6ND Classification: Garden Ornament Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned in the proximity of the address	A14SE (E)	792	-	389268 394754
221	**Contemporary Trade Directory Entries** Name: Munro'S Tyres Location: 10, Carna Road, Stockport, Cheshire, SK5 6NB Classification: Tyre Dealers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NE (E)	803	-	389279 394835
221	**Contemporary Trade Directory Entries** Name: Munro'S Tyres Location: 10, Carna Road, Stockport, SK5 6NB Classification: Tyre Dealers **Status: Active** Positional Accuracy: Automatically positioned to the address	A14NE (E)	803	-	389279 394835
222	**Contemporary Trade Directory Entries** Name: M D L Location: 70, Browning Road, STOCKPORT, Cheshire, SK5 6JT Classification: Cleaning Services - Domestic **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	808	-	389230 394505
223	**Contemporary Trade Directory Entries** Name: S C C Location: Kenwood Road, Stockport, Cheshire, SK5 6PH Classification: Die-Casting Equipment & Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NE (E)	815	-	389273 394988
224	**Contemporary Trade Directory Entries** Name: Princess Engineering Auto Location: 161, Barlow Road, Levenshulme, Manchester, M19 3HE Classification: Engine Rebuilding & Reconditioning **Status: Active** Positional Accuracy: Automatically positioned to the address	A7NE (SW)	817	-	387808 394317
225	**Contemporary Trade Directory Entries** Name: S C J Plastering & Skimming Service Location: 31, Garfield Avenue, Manchester, M19 3LE Classification: Builders' Tools & Equipment Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A7NE (SW)	826	-	387941 394162

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
226	**Contemporary Trade Directory Entries** Name: Ashwood Preservations Ltd Location: 50, Tennyson Road, STOCKPORT, Cheshire, SK5 6JQ Classification: Damp & Dry Rot Control **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A9SW (SE)	831	-	388914 394090
226	**Contemporary Trade Directory Entries** Name: Ashwood Preservations Ltd Location: 50, Tennyson Road, Stockport, Cheshire, SK5 6JQ Classification: Damp & Dry Rot Control **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A9SW (SE)	831	-	388914 394090
227	**Contemporary Trade Directory Entries** Name: Northwest Catering Location: Hemmons Road Industrial Estate,Unit 9a Hemmons Rd, Manchester, Lancashire, M12 5ST Classification: Catering Equipment **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A12NW (W)	840	-	387633 394904
228	**Contemporary Trade Directory Entries** Name: Haynes Gardening Man & Van Tip Runs Location: 26 Craig Road, Manchester, Greater Manchester, M18 7QW Classification: Waste Disposal Services **Status: Inactive** Positional Accuracy: Manually positioned to the address or location	A18NW (N)	842	-	388149 395595
229	**Contemporary Trade Directory Entries** Name: Fastfreight Location: 58, Hemmons Road, Manchester, M12 5TW Classification: Freight Forwarders **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A12NW (W)	866	-	387625 395009
230	**Contemporary Trade Directory Entries** Name: Links Electrical & Security Location: B, 148, Mount Road, Manchester, Lancashire, M18 7GS Classification: Electrical Goods Sales, Manufacturers & Wholesalers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A17NE (NW)	875	-	388049 395585
231	**Contemporary Trade Directory Entries** Name: Pro Cleaners Burnage Location: 6, Cuthbert Avenue, Manchester, M19 3DG Classification: Cleaning Services - Domestic **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A12SW (W)	882	-	387590 394720
231	**Contemporary Trade Directory Entries** Name: Pro Cleaners Burnage Location: 6, Cuthbert Avenue, Manchester, M19 3DG Classification: Cleaning Services - Domestic **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A12SW (W)	882	-	387590 394720
232	**Contemporary Trade Directory Entries** Name: Pizza House Location: 110, Barlow Road, Levenshulme, Manchester, M19 3EF Classification: Meat - Wholesale **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A7NW (SW)	895	-	387715 394315
233	**Contemporary Trade Directory Entries** Name: The Wash Tub Location: 46, Barlow Road, Levenshulme, Manchester, M19 3DA Classification: Laundries & Launderettes **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A7NW (W)	917	-	387617 394459
234	**Contemporary Trade Directory Entries** Name: Fahrenheit Installations Location: 66, Longford Road West, Stockport, Cheshire, SK5 6ET Classification: Woodburning Stoves **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A9NE (SE)	970	-	389324 394327

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
235	**Contemporary Trade Directory Entries** Name: Mancehster Pest Control Location: Ratcliffe St, Manchester, Lancashire, M19 3QH Classification: Pest & Vermin Control **Status: Inactive** Positional Accuracy: Manually positioned within the geographical locality	A7NW (SW)	972	-	387698 394205
235	**Contemporary Trade Directory Entries** Name: Sorin Scrap Metal Collector Location: 30, Ratcliffe Street, MANCHESTER, M19 3QH Classification: Scrap Metal Merchants **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A7NW (SW)	979	-	387698 394194
235	**Contemporary Trade Directory Entries** Name: Sorin Scrap Metal Collector Location: 30, Ratcliffe Street, Manchester, M19 3QH Classification: Scrap Metal Merchants **Status: Active** Positional Accuracy: Automatically positioned to the address	A7NW (SW)	979	-	387698 394193
236	**Contemporary Trade Directory Entries** Name: Jum Service Location: 12, Buckley Avenue, Manchester, M18 7QD Classification: Oil & Gas Exploration Supplies & Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A18NW (N)	980	-	388211 395762
237	**Contemporary Trade Directory Entries** Name: Appliance Repair Co Location: 19, Broadfield Grove, Stockport, Cheshire, SK5 6XN Classification: Domestic Appliances - Servicing, Repairs & Parts **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NE (E)	999	-	389432 395107
237	**Contemporary Trade Directory Entries** Name: Fixmywasher.Co.Uk Location: 19, Broadfield Grove, Stockport, Cheshire, SK5 6XN Classification: Washing Machines - Servicing & Repairs **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NE (E)	999	-	389432 395107
238	**Fuel Station Entries** Name: Barlow Service Station Location: 295, Barlow Road , Levenshulme , Manchester, Greater Manchester, M19 3HQ Brand: Obsolete Premises Type: Not Applicable **Status: Obsolete** Positional Accuracy: Automatically positioned to the address	A8NW (S)	424	-	388327 394398
239	**Points of Interest - Commercial Services** Name: A S T Express Ltd Location: Sandfold House, Sandfold Lane, Manchester, M19 3BJ Category: Transport, Storage and Delivery Class Code: Distribution and Haulage Positional Accuracy: Positioned to address or location	A13SE (S)	179	8	388508 394622
240	**Points of Interest - Commercial Services** Name: Doman Auto Safety Centre Location: Unit 1, Sandfold Lane, Manchester, M19 3BJ Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A13SW (SW)	236	8	388315 394618
240	**Points of Interest - Commercial Services** Name: I J Kayes Scrap Metal Recycling Ltd Location: Unit 1a, Sandfold Lane, Manchester, M19 3BJ Category: Recycling Services Class Code: Scrap Metal Merchants Positional Accuracy: Positioned to address or location	A13SW (SW)	252	8	388302 394609
240	**Points of Interest - Commercial Services** Name: Sina Auto Repair Location: Unit 1, Sandfold Lane, Manchester, M19 3BJ Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A13SW (SW)	252	8	388302 394609

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
240	**Points of Interest - Commercial Services** Name: Cornbrook Metal Recycling Ltd Location: Unit 1, Sandfold Lane, Manchester, M19 3BJ Category: Recycling Services Class Code: Scrap Metal Merchants Positional Accuracy: Positioned to address or location	A13SW (SW)	252	8	388302 394609
240	**Points of Interest - Commercial Services** Name: Espaul Motor Co Location: Unit F, Sandfold Lane, Manchester, M19 3BJ Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A13SW (SW)	268	8	388296 394593
240	**Points of Interest - Commercial Services** Name: Nearly New Tyres Location: Unit F, Sandfold Lane, Manchester, M19 3BJ Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A13SW (SW)	268	8	388296 394593
240	**Points of Interest - Commercial Services** Name: Doman Auto Safety Centre Location: Unit 1, Sandfold Lane, Manchester, M19 3BJ Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A13SW (SW)	268	8	388296 394593
240	**Points of Interest - Commercial Services** Name: Espaul Motor Co Location: Unit F, Sandfold Lane, Manchester, M19 3BJ Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A13SW (SW)	268	8	388296 394593
240	**Points of Interest - Commercial Services** Name: Nearly New Tyres Location: Unit F, Sandfold Lane, Manchester, M19 3BJ Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A13SW (SW)	268	8	388296 394593
241	**Points of Interest - Commercial Services** Name: McDonnell Haulage Location: Unit 7, Sandfold Lane, Manchester, M19 3BJ Category: Transport, Storage and Delivery Class Code: Distribution and Haulage Positional Accuracy: Positioned to address or location	A13SW (S)	254	8	388463 394544
241	**Points of Interest - Commercial Services** Name: Cornbrook Metal Recycling Location: Unit 6, Sandfold Lane, Manchester, M19 3BJ Category: Recycling Services Class Code: Scrap Metal Merchants Positional Accuracy: Positioned to address or location	A13SW (S)	256	8	388432 394544
241	**Points of Interest - Commercial Services** Name: Ryan M Son Haulage Ltd Location: Unit 19, Sandfold Lane, Manchester, M19 3BJ Category: Transport, Storage and Delivery Class Code: Distribution and Haulage Positional Accuracy: Positioned to address or location	A13SW (SW)	282	8	388346 394544
242	**Points of Interest - Commercial Services** Name: D & G McKenna Haulage Ltd Location: Unit 12, Sandfold Lane, Manchester, M19 3BJ Category: Transport, Storage and Delivery Class Code: Distribution and Haulage Positional Accuracy: Positioned to address or location	A13SE (S)	313	8	388530 394489
243	**Points of Interest - Commercial Services** Name: M Q Autos Location: Unit 4 Levenshulme Trading Estate, Printworks Lane, Manchester, M19 3JP Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A13SW (SW)	365	8	388288 394481
243	**Points of Interest - Commercial Services** Name: One Stop Auto Location: Levenshulme Trading Estate, Printworks Lane, Manchester, M19 3JP Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A13SW (SW)	365	8	388288 394481

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
244	**Points of Interest - Commercial Services** Name: Parts Line Location: 8 Marquis Street, Manchester, M19 3JZ Category: Recycling Services Class Code: Scrap Metal Merchants Positional Accuracy: Positioned to address or location	A8NE (S)	423	8	388566 394384
245	**Points of Interest - Commercial Services** Name: Cuppello Securities Location: 292 Mount Road, Manchester, M19 3HN Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A12SE (SW)	456	8	388134 394488
246	**Points of Interest - Commercial Services** Name: Kenwood Commercial Services Location: Kenwood Commercial Vehicles Ltd, Kenwood Road, North Reddish, Stockport, SK5 6PH Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A14NW (E)	561	8	389030 394909
246	**Points of Interest - Commercial Services** Name: Kenwood Commercial Services Ltd Location: Kenwood Road, Stockport, SK5 6PH Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A14NW (E)	562	8	389031 394910
247	**Points of Interest - Commercial Services** Name: Sabre Waste Recycling Ltd Location: Unit 17 Station Road Industrial Estate, 46 Station Road, Reddish, Stockport, SK5 6ND Category: Recycling Services Class Code: Recycling, Reclamation and Disposal Positional Accuracy: Positioned to address or location	A14NW (E)	598	8	389074 394824
247	**Points of Interest - Commercial Services** Name: Station M O T Centre Location: Unit 6 Station Road Industrial Estate, Station Road, North Reddish, Stockport, SK5 6ND Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A14SW (E)	632	8	389109 394806
248	**Points of Interest - Commercial Services** Name: H & J K Davies Bros Ltd Location: Kenwood Road, Stockport, SK5 6PH Category: Transport, Storage and Delivery Class Code: Distribution and Haulage Positional Accuracy: Positioned to address or location	A14NW (E)	642	8	389080 395036
248	**Points of Interest - Commercial Services** Name: H & J K Davies Bros Ltd Location: Kenwood Road, Stockport, SK5 6PH Category: Transport, Storage and Delivery Class Code: Distribution and Haulage Positional Accuracy: Positioned to address or location	A14NW (E)	642	8	389080 395036
248	**Points of Interest - Commercial Services** Name: Mancunian Spring Location: Mancunian Spring Company, Kenwood Road, North Reddish, Stockport, SK5 6PH Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A14NW (E)	671	8	389118 395012
249	**Points of Interest - Commercial Services** Name: Elsa Waste Paper Ltd Location: Unit 1-3, Station Road, Reddish, Stockport, SK5 6ND Category: Recycling Services Class Code: Recycling, Reclamation and Disposal Positional Accuracy: Positioned to address or location	A14SE (E)	703	8	389180 394786
249	**Points of Interest - Commercial Services** Name: Elsa Waste Paper Location: Unit 1-3, Station Road, Reddish, Stockport, SK5 6ND Category: Recycling Services Class Code: Recycling, Reclamation and Disposal Positional Accuracy: Positioned to address or location	A14SE (E)	703	8	389180 394786

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
249	**Points of Interest - Commercial Services** Name: Elsa Recycling Group Location: Unit 1-3, Station Road, Reddish, Stockport, SK5 6ND Category: Recycling Services Class Code: Recycling, Reclamation and Disposal Positional Accuracy: Positioned to address or location	A14SE (E)	703	8	389180 394786
249	**Points of Interest - Commercial Services** Name: A C Motors Location: Unit 8 Climax Works, Station Road, Reddish, Stockport, SK5 6YZ Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A14NE (E)	731	8	389207 394825
249	**Points of Interest - Commercial Services** Name: R & T Electronic Recycling LLP Location: Unit 7 Climax Works, Durham Street, North Reddish, Stockport, SK5 6YZ Category: Recycling Services Class Code: Recycling, Reclamation and Disposal Positional Accuracy: Positioned to address or location	A14NE (E)	731	8	389207 394825
249	**Points of Interest - Commercial Services** Name: John Harrop & Son Location: Unit 4, Climax Works Durham Street, Reddish, Stockport, SK5 6YZ Category: Transport, Storage and Delivery Class Code: Distribution and Haulage Positional Accuracy: Positioned to address or location	A14NE (E)	731	8	389207 394825
250	**Points of Interest - Commercial Services** Name: Khan Motors Location: Unit 5, Longden Road, Manchester, M12 5SJ Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A12NW (W)	768	8	387704 394883
250	**Points of Interest - Commercial Services** Name: Khan Motors Location: Unit 5, Longden Road, Manchester, M12 5SJ Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A12NW (W)	768	8	387704 394883
250	**Points of Interest - Commercial Services** Name: Loyalty Motors Location: Unit 5 Longden Road Industrial Estate, Longden Road, Manchester, M12 5SJ Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A12NW (W)	781	8	387690 394883
250	**Points of Interest - Commercial Services** Name: Hemmons Road M O T Centre Location: Unit 9b Longden Road Industrial Estate, Hemmons Road, Manchester, M12 5ST Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A12NW (W)	781	8	387690 394883
250	**Points of Interest - Commercial Services** Name: Watan Auto Workshop Location: Unit 3, Longden Road, Manchester, M12 5SJ Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A12NW (W)	781	8	387690 394883
250	**Points of Interest - Commercial Services** Name: Renovo Autocentre Location: Unit 9a Longden Road Industrial Estate, Hemmons Road, Manchester, M12 5ST Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A12NW (W)	781	8	387690 394883
250	**Points of Interest - Commercial Services** Name: O R S Autos Ltd Location: Unit 9a Longden Road Industrial Estate, Hemmons Road, Manchester, M12 5ST Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A12NW (W)	781	8	387690 394883

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
251	**Points of Interest - Commercial Services** Name: Princess Engineering Autos Ltd Location: 161 Barlow Road, Levenshulme, Manchester, M19 3HE Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A7NE (SW)	817	8	387808 394317
251	**Points of Interest - Commercial Services** Name: Princess Engineering Auto Location: 161 Barlow Road, Manchester, M19 3HE Category: Repair and Servicing Class Code: Vehicle Repair, Testing and Servicing Positional Accuracy: Positioned to address or location	A7NE (SW)	817	8	387808 394316
252	**Points of Interest - Commercial Services** Name: Fastfreight Location: 58 Hemmons Road, Manchester, M12 5TW Category: Transport, Storage and Delivery Class Code: Distribution and Haulage Positional Accuracy: Positioned to address or location	A12NW (W)	866	8	387625 395009
253	**Points of Interest - Commercial Services** Name: J C R Light Transport Location: 36 Laburnum Road, Manchester, M18 7FT Category: Transport, Storage and Delivery Class Code: Distribution and Haulage Positional Accuracy: Positioned to address or location	A18NE (N)	908	8	388688 395699
254	**Points of Interest - Commercial Services** Name: Sorin Scrap Metal Collector Location: 30 Ratcliffe Street, Manchester, M19 3QH Category: Recycling Services Class Code: Scrap Metal Merchants Positional Accuracy: Positioned to address or location	A7NW (SW)	979	8	387698 394193
255	**Points of Interest - Manufacturing and Production** Name: Tank Location: M19 Category: Industrial Features Class Code: Tanks (Generic) Positional Accuracy: Positioned to an adjacent address or location	A13SE (S)	94	8	388483 394704
256	**Points of Interest - Manufacturing and Production** Name: Works Location: M19 Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A13SE (S)	148	8	388487 394650
256	**Points of Interest - Manufacturing and Production** Name: Works Location: M19 Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A13SE (S)	157	8	388509 394644
256	**Points of Interest - Manufacturing and Production** Name: Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A13SE (S)	157	8	388513 394645
256	**Points of Interest - Manufacturing and Production** Name: Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A13SW (S)	186	8	388446 394613
256	**Points of Interest - Manufacturing and Production** Name: Tank Location: M19 Category: Industrial Features Class Code: Tanks (Generic) Positional Accuracy: Positioned to an adjacent address or location	A13SW (S)	224	8	388409 394582
257	**Points of Interest - Manufacturing and Production** Name: Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A13SW (SW)	256	8	388233 394698

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
257	**Points of Interest - Manufacturing and Production** Name: Works Location: M19 Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A13SW (SW)	259	8	388230 394697
258	**Points of Interest - Manufacturing and Production** Name: Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A8NE (S)	346	8	388530 394456
259	**Points of Interest - Manufacturing and Production** Name: Factory Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A8NW (S)	351	8	388441 394448
259	**Points of Interest - Manufacturing and Production** Name: Factory Location: M19 Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to address or location	A8NW (S)	355	8	388450 394443
260	**Points of Interest - Manufacturing and Production** Name: Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A8NE (S)	419	8	388581 394392
260	**Points of Interest - Manufacturing and Production** Name: Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A8NE (S)	436	8	388563 394370
260	**Points of Interest - Manufacturing and Production** Name: Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A8NE (S)	453	8	388592 394360
260	**Points of Interest - Manufacturing and Production** Name: Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A8NE (S)	462	8	388547 394341
261	**Points of Interest - Manufacturing and Production** Name: Station Road Industrial Estate Location: SK5 Category: Industrial Features Class Code: Business Parks and Industrial Estates Positional Accuracy: Positioned to an adjacent address or location	A14SW (E)	620	8	389096 394781
261	**Points of Interest - Manufacturing and Production** Name: Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A14NW (E)	665	8	389141 394826
261	**Points of Interest - Manufacturing and Production** Name: Climax Works Location: SK5 Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A14SE (E)	710	8	389187 394796
261	**Points of Interest - Manufacturing and Production** Name: Works Location: SK5 Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A14NE (E)	729	8	389205 394819

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
261	**Points of Interest - Manufacturing and Production** Name: Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A14NE (E)	736	8	389212 394820
262	**Points of Interest - Manufacturing and Production** Name: Works Location: SK5 Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A14NW (NE)	632	8	389056 395070
262	**Points of Interest - Manufacturing and Production** Name: Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A14NW (NE)	637	8	389060 395071
262	**Points of Interest - Manufacturing and Production** Name: Tank Location: SK5 Category: Industrial Features Class Code: Tanks (Generic) Positional Accuracy: Positioned to address or location	A14NW (E)	680	8	389113 395056
262	**Points of Interest - Manufacturing and Production** Name: Tanks Location: SK5 Category: Industrial Features Class Code: Tanks (Generic) Positional Accuracy: Positioned to an adjacent address or location	A14NW (E)	680	8	389113 395056
262	**Points of Interest - Manufacturing and Production** Name: Works Location: SK5 Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A14NW (NE)	680	8	389083 395125
262	**Points of Interest - Manufacturing and Production** Name: Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A14NW (NE)	685	8	389088 395126
263	**Points of Interest - Manufacturing and Production** Name: Tank Location: SK5 Category: Industrial Features Class Code: Tanks (Generic) Positional Accuracy: Positioned to an adjacent address or location	A14NW (E)	677	8	389116 395038
263	**Points of Interest - Manufacturing and Production** Name: Tanks Location: SK5 Category: Industrial Features Class Code: Tanks (Generic) Positional Accuracy: Positioned to an adjacent address or location	A14NW (E)	687	8	389127 395037
263	**Points of Interest - Manufacturing and Production** Name: Tank Location: SK5 Category: Industrial Features Class Code: Tanks (Generic) Positional Accuracy: Positioned to address or location	A14NE (E)	699	8	389152 394998
263	**Points of Interest - Manufacturing and Production** Name: Tank Location: SK5 Category: Industrial Features Class Code: Tanks (Generic) Positional Accuracy: Positioned to address or location	A14NE (E)	703	8	389155 395000
263	**Points of Interest - Manufacturing and Production** Name: Tanks Location: SK5 Category: Industrial Features Class Code: Tanks (Generic) Positional Accuracy: Positioned to an adjacent address or location	A14NE (E)	709	8	389163 394994

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
264	**Points of Interest - Manufacturing and Production** Name: Clifton Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A12SW (W)	779	8	387726 394563
265	**Points of Interest - Manufacturing and Production** Name: Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A12NW (W)	793	8	387677 394862
265	**Points of Interest - Manufacturing and Production** Name: Works Location: M12 Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A12NW (W)	799	8	387671 394861
266	**Points of Interest - Manufacturing and Production** Name: Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A8SW (S)	858	8	388210 393980
267	**Points of Interest - Manufacturing and Production** Name: Works Location: Not Supplied Category: Industrial Features Class Code: Unspecified Works Or Factories Positional Accuracy: Positioned to an adjacent address or location	A14NE (E)	902	8	389377 394866
267	**Points of Interest - Manufacturing and Production** Name: Tank Location: SK5 Category: Industrial Features Class Code: Tanks (Generic) Positional Accuracy: Positioned to an adjacent address or location	A14NE (E)	916	8	389393 394811
268	**Points of Interest - Manufacturing and Production** Name: Sandfold Piggeries Location: SK5 Category: Farming Class Code: Livestock Farming Positional Accuracy: Positioned to address or location	A14SE (E)	953	8	389410 394603
269	**Points of Interest - Public Infrastructure** Name: Viridor Ltd Location: Sandfold Lane, Manchester, M19 3BJ Category: Infrastructure and Facilities Class Code: Waste Storage, Processing and Disposal Positional Accuracy: Positioned to address or location	A13SW (SW)	188	8	388361 394644
269	**Points of Interest - Public Infrastructure** Name: Refuse Tip (Public) Location: M19 Category: Infrastructure and Facilities Class Code: Refuse Disposal Facilities Positional Accuracy: Positioned to an adjacent address or location	A13SW (SW)	196	8	388382 394622
269	**Points of Interest - Public Infrastructure** Name: Refuse Tip (Public) Location: M19 Category: Infrastructure and Facilities Class Code: Refuse Disposal Facilities Positional Accuracy: Positioned to an adjacent address or location	A13SW (SW)	196	8	388382 394622
270	**Points of Interest - Public Infrastructure** Name: GB Coaches Ltd Location: Unit 7, Sandfold Lane, Manchester, M19 3BJ Category: Public Transport, Stations and Infrastructure Class Code: Bus and Coach Stations, Depots and Companies Positional Accuracy: Positioned to address or location	A13SW (S)	259	8	388463 394539
271	**Points of Interest - Public Infrastructure** Name: Barlow Service Station Location: 295 Barlow Road, Levenshulme, Manchester, Lancashire, M19 3HQ Category: Road And Rail Class Code: Petrol and Fuel Stations Positional Accuracy: Positioned to address or location	A8NW (SW)	450	8	388291 394384

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
272	**Points of Interest - Public Infrastructure** Name: Saferfillsystems Location: Unit 14 Station Road Industrial Estate, Station Road, North Reddish, Stockport, SK5 6ND Category: Road And Rail Class Code: Petrol and Fuel Stations Positional Accuracy: Positioned to address or location	A14SW (E)	597	8	389074 394795
273	**Points of Interest - Public Infrastructure** Name: Stockport Ring & Ride Location: Kenwood Road, Stockport, SK5 6PH Category: Public Transport, Stations and Infrastructure Class Code: Bus and Coach Stations, Depots and Companies Positional Accuracy: Positioned to address or location	A14NW (E)	606	8	389074 394921
274	**Points of Interest - Public Infrastructure** Name: Elsa Recycling Group Ltd Location: Unit 1-3, Station Road, Reddish, Stockport, SK5 6ND Category: Infrastructure and Facilities Class Code: Recycling Centres Positional Accuracy: Positioned to address or location	A14SE (E)	703	8	389180 394786
275	**Points of Interest - Public Infrastructure** Name: Ryder Brow Rail Station Location: Levenshulme Road, M18 Category: Public Transport, Stations and Infrastructure Class Code: Railway Stations, Junctions and Halts Positional Accuracy: Positioned to address or location	A18NE (N)	760	8	388589 395568
275	**Points of Interest - Public Infrastructure** Name: Ryder Brow Station Location: Levenshulme Road, M18 Category: Public Transport, Stations and Infrastructure Class Code: Railway Stations, Junctions and Halts Positional Accuracy: Positioned to address or location	A18NE (N)	760	8	388589 395568
276	**Points of Interest - Public Infrastructure** Name: Cemetery Location: M18 Category: Infrastructure and Facilities Class Code: Cemeteries and Crematoria Positional Accuracy: Positioned to an adjacent address or location	A19SE (NE)	886	8	389217 395303
276	**Points of Interest - Public Infrastructure** Name: Cemetery Location: Not Supplied Category: Infrastructure and Facilities Class Code: Cemeteries and Crematoria Positional Accuracy: Positioned to an adjacent address or location	A19SE (NE)	897	8	389229 395305
277	**Points of Interest - Recreational and Environmental** Name: Playground Location: Not Supplied Category: Recreational Class Code: Playgrounds Positional Accuracy: Positioned to an adjacent address or location	A12SE (SW)	387	8	388109 394654
277	**Points of Interest - Recreational and Environmental** Name: Playground Location: Manor Road, M19 Category: Recreational Class Code: Playgrounds Positional Accuracy: Positioned to an adjacent address or location	A12SE (SW)	394	8	388102 394654
278	**Points of Interest - Recreational and Environmental** Name: Play Area Location: Manor Road, M19 Category: Recreational Class Code: Playgrounds Positional Accuracy: Positioned to address or location	A12SE (SW)	407	8	388133 394567
278	**Points of Interest - Recreational and Environmental** Name: Play Area Location: Not Supplied Category: Recreational Class Code: Playgrounds Positional Accuracy: Positioned to an adjacent address or location	A12SE (SW)	408	8	388133 394565
279	**Points of Interest - Recreational and Environmental** Name: Play Area Location: SK5 Category: Recreational Class Code: Playgrounds Positional Accuracy: Positioned to an adjacent address or location	A14NE (E)	889	8	389364 394861

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
279	**Points of Interest - Recreational and Environmental** Name: Play Area Location: SK5 Category: Recreational Class Code: Playgrounds Positional Accuracy: Positioned to an adjacent address or location	A14NE (E)	938	8	389415 394808
280	**Points of Interest - Recreational and Environmental** Name: Play Area Location: M19 Category: Recreational Class Code: Playgrounds Positional Accuracy: Positioned to an adjacent address or location	A7SE (SW)	951	8	387825 394097

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
281	**Local Nature Reserves** Name: Highfield Country Pa Multiple Area: N Area (m2): 285759.2 Source: Natural England Designation Date: 21st November 2007	A8SE (S)	714	11	388534 394086

Agency & Hydrological	Version	Update Cycle
Contaminated Land Register Entries and Notices		
Oldham Metropolitan Borough Council - Environmental Health Department	December 2025	Annual Rolling Update
Stockport Metropolitan Borough Council - Environment Team (Land & Water)	January 2026	Annual Rolling Update
Tameside Metropolitan Borough Council - Environmental Health Department	January 2026	Annual Rolling Update
Trafford Metropolitan Borough Council - Renewal and Environmental Protection	January 2026	Annual Rolling Update
Environment Agency - Head Office	November 2023	Annually
Manchester City Council - Environmental Health Department	November 2025	Annual Rolling Update
Discharge Consents		
Environment Agency - North West Region	January 2026	Quarterly
Enforcement and Prohibition Notices		
Environment Agency - North West Region	March 2013	
Integrated Pollution Controls		
Environment Agency - North West Region	January 2009	
Integrated Pollution Prevention And Control		
Environment Agency - North West Region	October 2025	Bi-Annually
Local Authority Integrated Pollution Prevention And Control		
Tameside Metropolitan Borough Council - Environmental Health Department	June 2015	Variable
Oldham Metropolitan Borough Council - Environmental Health Department	March 2015	Variable
Stockport Metropolitan Borough Council - Environmental Health Department, EEDD	October 2014	Variable
Trafford Metropolitan Borough Council - Environmental Health Department	October 2014	Variable
Manchester City Council - Environmental Health Department	September 2014	Variable
Local Authority Pollution Prevention and Controls		
Tameside Metropolitan Borough Council - Environmental Health Department	June 2015	Annual Rolling Update
Oldham Metropolitan Borough Council - Environmental Health Department	March 2015	Annual Rolling Update
Stockport Metropolitan Borough Council - Environmental Health Department, EEDD	October 2014	Annual Rolling Update
Trafford Metropolitan Borough Council - Environmental Health Department	October 2014	Annual Rolling Update
Manchester City Council - Environmental Health Department	September 2014	Annual Rolling Update
Local Authority Pollution Prevention and Control Enforcements		
Tameside Metropolitan Borough Council - Environmental Health Department	June 2015	Variable
Oldham Metropolitan Borough Council - Environmental Health Department	March 2015	Variable
Stockport Metropolitan Borough Council - Environmental Health Department, EEDD	October 2014	Variable
Trafford Metropolitan Borough Council - Environmental Health Department	October 2014	Variable
Manchester City Council - Environmental Health Department	September 2014	Variable
Nearest Surface Water Feature		
Ordnance Survey	January 2026	
Pollution Incidents to Controlled Waters		
Environment Agency - North West Region	January 2000	
Historical Prosecutions		
Environment Agency, North West Region	March 2013	Not Applicable
Prosecutions		
Environment Agency - Head Office	February 2024	Annually
Registered Radioactive Substances		
Environment Agency - Head Office	May 2023	
Environment Agency - North West Region	May 2023	
Substantiated Pollution Incident Register		
Environment Agency - North West Region - South Area	January 2026	Quarterly
Water Abstractions		
Environment Agency - North West Region	April 2026	Quarterly
Water Industry Act Referrals		
Environment Agency - North West Region	October 2017	
Groundwater Vulnerability Map		
Environment Agency - Head Office	June 2018	As notified

Agency & Hydrological	Version	Update Cycle
Groundwater Vulnerability - Soluble Rock Risk Environment Agency - Head Office	June 2018	As notified
Bedrock Aquifer Designations Environment Agency - Head Office	January 2018	As notified
Superficial Aquifer Designations Environment Agency - Head Office	January 2018	As notified
Source Protection Zones Environment Agency - Head Office	August 2025	Quarterly
Extreme Flooding from Rivers or Sea without Defences Environment Agency - Head Office	December 2023	As notified
Flooding from Rivers or Sea without Defences Environment Agency - Head Office	December 2023	As notified
Areas Benefiting from Flood Defences Environment Agency - Head Office	February 2023	
Flood Water Storage Areas Environment Agency - Head Office	April 2026	Quarterly
Flood Defences Environment Agency - Head Office	August 2022	
OS NGD Water Network Links Ordnance Survey	January 2026	Quarterly
Surface Water 1 in 30 year Flood Extent Environment Agency - Head Office	May 2018	Annually
Surface Water 1 in 100 year Flood Extent Environment Agency - Head Office	May 2018	Annually
Surface Water 1 in 1000 year Flood Extent Environment Agency - Head Office	May 2018	Annually
Surface Water Suitability Environment Agency - Head Office	February 2016	Annually
BGS Groundwater Flooding Susceptibility British Geological Survey - National Geoscience Information Service	May 2013	As notified
Water Framework Directive - Catchment Environment Agency - Head Office	July 2025	Annually
Water Framework Directive - Groundwater Environment Agency - Head Office	July 2025	Annually
Water Framework Directive - Surface Waters Environment Agency - Head Office	July 2025	Annually

Waste	Version	Update Cycle
BGS Recorded Landfill Sites		
British Geological Survey - National Geoscience Information Service	November 2002	As notified
Historical Landfill Sites		
Environment Agency - Head Office	November 2025	Bi-Annually
Integrated Pollution Control Registered Waste Sites		
Environment Agency - North West Region	January 2009	Not Applicable
Licensed Waste Management Facilities (Landfill Boundaries)		
Environment Agency - North West Region - South Area	November 2025	Quarterly
Licensed Waste Management Facilities (Locations)		
Environment Agency - North West Region - South Area	October 2025	Bi-Annually
Local Authority Landfill Coverage		
Manchester City Council - Planning Department	February 2003	Not Applicable
Oldham Metropolitan Borough Council	February 2003	Not Applicable
Stockport Metropolitan Borough Council - Environmental Health Department, EEDD	February 2003	Not Applicable
Tameside Metropolitan Borough Council	February 2003	Not Applicable
Trafford Metropolitan Borough Council - Environmental Health Department	February 2003	Not Applicable
Local Authority Recorded Landfill Sites		
Manchester City Council - Planning Department	October 2018	
Oldham Metropolitan Borough Council	October 2018	
Stockport Metropolitan Borough Council - Environmental Health Department, EEDD	October 2018	
Tameside Metropolitan Borough Council	October 2018	
Trafford Metropolitan Borough Council - Environmental Health Department	October 2018	
Potentially Infilled Land (Non-Water)		
Landmark Information Group Limited	December 1999	
Potentially Infilled Land (Water)		
Landmark Information Group Limited	December 1999	
Registered Landfill Sites		
Environment Agency - North West Region - South Area	March 2006	Not Applicable
Registered Waste Transfer Sites		
Environment Agency - North West Region - South Area	April 2018	
Registered Waste Treatment or Disposal Sites		
Environment Agency - North West Region - South Area	June 2015	
Hazardous Substances	**Version**	**Update Cycle**
Control of Major Accident Hazards Sites (COMAH)		
Health and Safety Executive	June 2025	Bi-Annually
Explosive Sites		
Health and Safety Executive	March 2017	
Notification of Installations Handling Hazardous Substances (NIHHS)		
Health and Safety Executive	August 2001	
Planning Hazardous Substance Enforcements		
Manchester City Council - Planning Department	February 2016	Variable
Oldham Metropolitan Borough Council	February 2016	Variable
Stockport Metropolitan Borough Council - Environment and Economic Development	February 2016	Variable
Trafford Metropolitan Borough Council	July 2023	Variable
Tameside Metropolitan Borough Council - Planning and Building Control	June 2023	Variable
Planning Hazardous Substance Consents		
Manchester City Council - Planning Department	August 2022	Variable
Oldham Metropolitan Borough Council	August 2022	Variable
Trafford Metropolitan Borough Council	November 2022	Variable
Stockport Metropolitan Borough Council - Environment and Economic Development	October 2022	Variable
Tameside Metropolitan Borough Council - Planning and Building Control	October 2022	Variable

Geological	Version	Update Cycle
BGS 1:625,000 Solid Geology British Geological Survey - National Geoscience Information Service	January 2009	As notified
BGS Estimated Soil Chemistry British Geological Survey - National Geoscience Information Service	December 2015	As notified
BGS Recorded Mineral Sites British Geological Survey - National Geoscience Information Service	February 2026	Bi-Annually
BGS Urban Soil Chemistry British Geological Survey - National Geoscience Information Service	December 2015	As notified
BGS Urban Soil Chemistry Averages British Geological Survey - National Geoscience Information Service	December 2015	As notified
CBSCB Compensation District Cheshire Brine Subsidence Compensation Board (CBSCB) Cheshire Brine Subsidence Compensation Board (CBSCB)	August 2011 November 2020	As notified
Coal Mining Affected Areas The Coal Authority - Property Searches	February 2023	
Mining Instability Ove Arup & Partners	June 1998	Not Applicable
Non Coal Mining Areas of Great Britain British Geological Survey - National Geoscience Information Service	May 2015	Not Applicable
Potential for Collapsible Ground Stability Hazards British Geological Survey - National Geoscience Information Service	April 2020	As notified
Potential for Compressible Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	As notified
Potential for Ground Dissolution Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	As notified
Potential for Landslide Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	As notified
Potential for Running Sand Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	As notified
Potential for Shrinking or Swelling Clay Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	As notified
Radon Potential - Radon Affected Areas British Geological Survey - National Geoscience Information Service	November 2025	Annually
Radon Potential - Radon Protection Measures British Geological Survey - National Geoscience Information Service	November 2025	Annually

Industrial Land Use	Version	Update Cycle
Contemporary Trade Directory Entries Thomson Directories	December 2025	Quarterly
Fuel Station Entries Green Street Advisor (UK) Ltd	February 2026	Quarterly
Points of Interest - Commercial Services PointX	March 2026	Quarterly
Points of Interest - Education and Health PointX	March 2026	Quarterly
Points of Interest - Manufacturing and Production PointX	March 2026	Quarterly
Points of Interest - Public Infrastructure PointX	March 2026	Quarterly
Points of Interest - Recreational and Environmental PointX	March 2026	Quarterly
Underground Electrical Cables National Grid	January 2024	

Sensitive Land Use	Version	Update Cycle
Ancient Woodland		
Natural England	March 2026	Bi-Annually
Areas of Adopted Green Belt		
Manchester City Council	March 2026	Quarterly
Oldham Metropolitan Borough Council	March 2026	Quarterly
Stockport Metropolitan Borough Council	March 2026	Quarterly
Tameside Metropolitan Borough Council	March 2026	Quarterly
Trafford Metropolitan Borough Council	March 2026	Quarterly
Areas of Unadopted Green Belt		
Manchester City Council	March 2026	Quarterly
Oldham Metropolitan Borough Council	March 2026	Quarterly
Stockport Metropolitan Borough Council	March 2026	Quarterly
Tameside Metropolitan Borough Council	March 2026	Quarterly
Trafford Metropolitan Borough Council	March 2026	Quarterly
Areas of Outstanding Natural Beauty		
Natural England	April 2026	Bi-Annually
Environmentally Sensitive Areas		
Natural England	August 2023	
Forest Parks		
Forestry Commission	May 2023	Not Applicable
Local Nature Reserves		
Natural England	January 2026	Bi-Annually
Marine Nature Reserves		
Natural England	February 2026	Bi-Annually
National Nature Reserves		
Natural England	January 2026	Bi-Annually
National Parks		
Natural England	September 2025	Annually
Nitrate Sensitive Areas		
Natural England	April 2023	Not Applicable
Nitrate Vulnerable Zones		
Department for Environment, Food and Rural Affairs (DEFRA - formerly FRCA)	April 2016	
Environment Agency - Head Office	February 2026	Annually
Ramsar Sites		
Natural England	February 2026	Bi-Annually
Sites of Special Scientific Interest		
Natural England	November 2025	Bi-Annually
Special Areas of Conservation		
Natural England	January 2026	Bi-Annually
Special Protection Areas		
Natural England	November 2025	Bi-Annually

Data Suppliers

A selection of organisations who provide data within this report


Data Supplier	Data Supplier Logo
Ordnance Survey	
Environment Agency	
Scottish Environment Protection Agency	
The Coal Authority	
British Geological Survey	
Centre for Ecology and Hydrology	
Natural Resources Wales	
Scottish Natural Heritage	
Natural England	
Public Health England	
Ove Arup	
Stantec UK Ltd	

LK CONSULT

Useful Contacts

Contact	Name and Address	Contact Details
1	**British Geological Survey - Enquiry Service** British Geological Survey, Environmental Science Centre, Keyworth, Nottingham, Nottinghamshire, NG12 5GG	Telephone: 0115 936 3143 Fax: 0115 936 3276 Email: enquiries@bgs.ac.uk Website: www.bgs.ac.uk
2	**Environment Agency - National Customer Contact Centre (NCCC)** PO Box 544, Templeborough, Rotherham, S60 1BY	Telephone: 03708 506 506 Email: enquiries@environment-agency.gov.uk
3	**Manchester City Council - Environmental Health Department** PO Box 463, Town Hall Extension, Albert Square, Manchester, Greater Manchester, M60 3NY	[redacted]
4	**Stockport Metropolitan Borough Council - Environmental Health Department, EEDD** Stopford House, Piccadilly, Stockport, SK1 3XE	Telephone: 0161 474 4210 Fax: 0161 477 8589 Email: environment.team@stockport.gov.uk Website: www.stockport.gov.uk
5	**Ordnance Survey** Adanac Drive, Southampton, Hampshire, SO16 0AS	Telephone: 03456 05 05 05 Email: customerservices@ordnancesurvey.co.uk Website: www.ordnancesurvey.co.uk
6	**Manchester City Council - Planning Department** Town Hall, Manchester, Greater Manchester, M60 2LA	Telephone: 0161 234 5000 Fax: 0161 234 4508 Website: www.manchester.gov.uk
7	**The Coal Authority - Property Searches** 200 Lichfield Lane, Mansfield, Nottinghamshire, NG18 4RG	Telephone: 0345 762 6848 Fax: 01623 637 338 Email: groundstability@coal.gov.uk Website: www2.groundstability.com
8	**PointX** 5-6 Abbey Court, Eagle Way, Sowton, Exeter, Devon, EX2 7HY	Website: www.pointx.co.uk
9	**Stockport Metropolitan Borough Council** Hygarth House, 103 Wellington Road South, Stockport, Greater Manchester, SK1 3TP	Telephone: 0161 480 4949 Fax: 0161 477 9530 Website: www.stockport.gov.uk
10	**Tameside Metropolitan Borough Council** Wellington Road, Ashton-under-Lyne, Lancashire, OL6 6DL	Telephone: 0161 342 8355 Fax: 0161 342 3070 Website: www.tameside.gov.uk
11	**Natural England** County Hall, Spetchley Road, Worcester, WR5 2NP	Telephone: 0300 060 3900 Email: enquiries@naturalengland.org.uk Website: www.naturalengland.org.uk
-	**Public Health England - Radon Survey, Centre for Radiation, Chemical and Environmental Hazards** Chilton, Didcot, Oxfordshire, OX11 0RQ	Telephone: 01235 822622 Fax: 01235 833891 Email: radon@phe.gov.uk Website: www.ukradon.org
-	**Landmark Information Group Limited** Landmark Information Group, Imperium, Imperial Way, Reading, Berkshire, RG2 0TD	Telephone: 0330 036 6618 Fax: 0844 844 9951 Email: helpdesk@landmark.co.uk Website: www.landmark.co.uk

Please note that the Environment Agency / Natural Resources Wales / SEPA have a charging policy in place for enquiries.



© Crown copyright and database rights 2026 OS AC0000813445

LK CONSULT

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Map ID
- Several of Type at Location
- Pylon
- Overhead Transmission Line

Agency and Hydrological

- Contaminated Land Register Entry or Notice (Location)
- Contaminated Land Register Entry or Notice
- Discharge Consent
- Enforcement or Prohibition Notice
- Integrated Pollution Control
- Integrated Pollution Prevention Control
- Local Authority Integrated Pollution Prevention and Control
- Local Authority Pollution Prevention and Control
- Local Authority Pollution Prevention and Control Enforcement
- Pollution Incident to Controlled Waters
- Historical Prosecutions
- Prosecutions
- Registered Radioactive Substance
- River Network or Water Feature
- Substantiated Pollution Incident Register
- Water Abstraction
- Water Industry Act Referral

Waste

- BGS Recorded Landfill Site (Location)
- BGS Recorded Landfill Site
- EA Historic Landfill (Buffered Point)
- EA Historic Landfill (Polygon)
- Integrated Pollution Control Registered Waste Site
- Licensed Waste Management Facility (Landfill Boundary)
- Licensed Waste Management Facility (Location)
- Local Authority Recorded Landfill Site (Location)
- Local Authority Recorded Landfill Site
- Potentially Infilled Land (Non-water)
- Potentially Infilled Land (Non-water)
- Potentially Infilled Land (Non-water)
- Potentially Infilled Land (Water)
- Potentially Infilled Land (Water)
- Potentially Infilled Land (Water)
- Registered Landfill Site
- Registered Landfill Site (Location)
- Registered Landfill Site (Point Buffered to 100m)
- Registered Landfill Site (Point Buffered to 250m)
- Registered Waste Transfer Site (Location)
- Registered Waste Transfer Site
- Registered Waste Treatment or Disposal Site (Location)
- Registered Waste Treatment or Disposal Site


Hazardous Substances

- COMAH Site
- Explosive Site
- NIHHS Site
- Planning Hazardous Substance Consent
- Planning Hazardous Substance Enforcement

Geological

- BGS Recorded Mineral Site

Site Sensitivity Map - Segment A13



Order Details


Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Plot Buffer (m):	100

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



LK CONSULT

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Map ID
- Several of Type at Location

Agency and Hydrological

- Contaminated Land Register Entry or Notice (Location)
- Contaminated Land Register Entry or Notice
- Discharge Consent
- Enforcement or Prohibition Notice
- Integrated Pollution Control
- Integrated Pollution Prevention Control
- Local Authority Integrated Pollution Prevention and Control
- Local Authority Pollution Prevention and Control
- Local Authority Pollution Prevention and Control Enforcement
- Pollution Incident to Controlled Waters
- Historical Prosecutions
- Prosecutions
- Registered Radioactive Substance
- River Network or Water Feature
- Substantiated Pollution Incident Register
- Water Abstraction
- Water Industry Act Referral

Waste

- BGS Recorded Landfill Site (Location)
- BGS Recorded Landfill Site
- EA Historic Landfill (Buffered Point)
- EA Historic Landfill (Polygon)
- Integrated Pollution Control Registered Waste Site
- Licensed Waste Management Facility (Landfill Boundary)
- Licensed Waste Management Facility (Location)
- Local Authority Recorded Landfill Site (Location)
- Local Authority Recorded Landfill Site
- Potentially Infilled Land (Non-water)
- Potentially Infilled Land (Non-water)
- Potentially Infilled Land (Non-water)
- Potentially Infilled Land (Water)
- Potentially Infilled Land (Water)
- Potentially Infilled Land (Water)
- Registered Landfill Site
- Registered Landfill Site (Location)
- Registered Landfill Site (Point Buffered to 100m)
- Registered Landfill Site (Point Buffered to 250m)
- Registered Waste Transfer Site (Location)
- Registered Waste Transfer Site
- Registered Waste Treatment or Disposal Site (Location)
- Registered Waste Treatment or Disposal Site


Hazardous Substances

- COMAH Site
- Explosive Site
- NIHHS Site
- Planning Hazardous Substance Consent
- Planning Hazardous Substance Enforcement

Geological

- BGS Recorded Mineral Site

Site Sensitivity Map - Slice A



Order Details


Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



LK CONSULT

Industrial Land Use Map


General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Slice
- Map ID

Industrial Land Use

- Contemporary Trade Directory Entry
- Fuel Station Entry
- Points of Interest - Commercial Services
- Points of Interest - Education and Health
- Points of Interest - Manufacturing and Production
- Points of Interest - Public Infrastructure
- Points of Interest - Recreational and Environmental
- Underground Electrical Cables

Industrial Land Use Map - Slice A



Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and database rights 2026 OS AC0000813445

0 400 m

LK CONSULT


General

- Specified Site
- Specified Buffer(s)
- X Bearing Reference Point

Agency and Hydrological (Flood)

- Extreme Flooding from Rivers or Sea without Defences (Zone 2)
- Flooding from Rivers or Sea without Defences (Zone 3)
- Area Benefiting from Flood Defence
- Flood Water Storage Areas
- Flood Defence

Flood Map - Slice A




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Map ID
- Several of Type at Location


Agency and Hydrological (Boreholes)

- BGS Borehole Depth 0 - 10m
- BGS Borehole Depth 10 - 30m
- BGS Borehole Depth 30m +
- Confidential
- Other

For Borehole information please refer to the Borehole .csv file which accompanied this slice.

A copy of the BGS Borehole Ordering Form is available to download from the Support section of www.envirocheck.co.uk.

Borehole Map - Slice A




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk


387500
388000
388500
389000
389500
396000
395500
395000
394500
394000
393500
A25
A20
A15
A10
A5
A1
A2
A3
A4
A5
Gorton
Levenshulme
North Reddish
Reddish
Ryder Brow
Belle Vue
Gorton Lower Reservoir
Sports/Leisure Centre
Education Facility
Medical Care
Library
Police Station
Reddish North
Levenshulme
PO
PW
Brook
Education Facility
Education Facility
Education Facility



© Crown copyright and database rights 2026 OS AC0000813445

LK CONSULT

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point

Risk of Flooding from Surface Water


- High - 30 Year Return
- Medium - 100 Year Return
- Low - 1000 Year Return

Suitability

See the suitability map below

- National to county
- County to town
- Town to street
- Street to parcels of land
- Property

EA/NRW Suitability Map - Slice A



Order Details


Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



LK CONSULT

WFD Surface Waters Map

General

Specified Site | Specified Buffer(s) | Bearing Reference Point

Slice | Map ID

Water Framework Directive - Surface Water Quality

- High
- Good
- Moderate
- Poor
- Bad

Contours (height in meters)

Standard Contour 105 100 95


Master Contour

Spot Height 167.3

MLW Mean Low Water

MHW Mean High Water

WFD Surface Waters Map - Slice A



N

Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk

Geology 1:50,000 Maps Legends

Artificial Ground and Landslip

Map Colour	Lex Code	Rock Name	Rock Type	Min and Max Age
	WMGR	Infilled Ground	Artificial Deposit	Not Supplied - Holocene
	MGR	Made Ground (Undivided)	Artificial Deposit	Not Supplied - Holocene

Superficial Geology

Map Colour	Lex Code	Rock Name	Rock Type	Min and Max Age
	ALV	Alluvium	Clay, Silt, Sand and Gravel	Not Supplied - Holocene
	TILLD	Till, Devensian	Diamicton	Not Supplied - Devensian
	GFICD	Glaciofluvial Ice Contact Deposits, Devensian	Sand and Gravel	Not Supplied - Devensian
	GFDUD	Glaciofluvial Deposits, Devensian	Sand and Gravel	Not Supplied - Devensian
	RTDU	River Terrace Deposits (Undifferentiated)	Sand and Gravel	Not Supplied - Quaternary

Bedrock and Faults

Map Colour	Lex Code	Rock Name	Rock Type	Min and Max Age
	CHES	Chester Formation	Sandstone	Not Supplied - Olenekian
	MM	Manchester Marls Formation	Mudstone	Not Supplied - GUADALUPIAN
	CS	Collyhurst Sandstone Formation	Sandstone	Not Supplied - Cisuralian
	HA	Halesowen Formation	Mudstone, Siltstone and Sandstone	Not Supplied - Westphalian
	GML	Great Mine Limestone	Limestone	Not Supplied - Westphalian
	ETM	Etruria Formation	Sandstone and Mudstone	Not Supplied - Westphalian
		Faults		

LK CONSULT


Geology 1:50,000 Maps

This report contains geological map extracts taken from the BGS Digital Geological map of Great Britain at 1:50,000 scale and is designed for users carrying out preliminary site assessments who require geological maps for the area around the site. This mapping may be more up to date than previously published paper maps.
The various geological layers - artificial and landslip deposits, superficial geology and solid (bedrock) geology are displayed in separate maps, but superimposed on the final 'Combined Surface Geology' map. All map legends feature on this page. Not all layers have complete nationwide coverage, so availability of data for relevant map sheets is indicated below.

Geology 1:50,000 Maps Coverage

Map ID:	**2**	**Map ID:**	**1**
Map Sheet No:	**098**	**Map Sheet No:**	**085**
Map Name:	**Stockport**	**Map Name:**	**Manchester**
Map Date:	**1962**	**Map Date:**	**2010**
Bedrock Geology:	**Available**	**Bedrock Geology:**	**Available**
Superficial Geology:	**Available**	**Superficial Geology:**	**Not Available**
Artificial Geology:	**Not Available**	**Artificial Geology:**	**Not Available**
Faults:	**Not Supplied**	**Faults:**	**Not Supplied**
Landslip:	**Available**	**Landslip:**	**Not Available**
Rock Segments:	**Not Supplied**	**Rock Segments:**	**Not Supplied**

Geology 1:50,000 Maps - Slice A




Order Details:

Order Number:	401117746_1_1
Customer Reference:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details:

Cedar Mount High School Sit:, LKC261292



© Crown copyright and database rights 2026 OS AC0000813445

LK CONSULT

Artificial Ground and Landslip


Artificial ground is a term used by BGS for those areas where the ground surface has been significantly modified by human activity. Information about previously developed ground is especially important, as it is often associated with potentially contaminated material, unpredictable engineering conditions and unstable ground.

Artificial ground includes:

- Made ground - man-made deposits such as embankments and spoil heaps on the natural ground surface.
- Worked ground - areas where the ground has been cut away such as quarries and road cuttings.
- Infilled ground - areas where the ground has been cut away then wholly or partially backfilled.
- Landscaped ground - areas where the surface has been reshaped.
- Disturbed ground - areas of ill-defined shallow or near surface mineral workings where it is impracticable to map made and worked ground separately.

Mass movement (landslip) deposits on BGS geological maps are primarily superficial deposits that have moved down slope under gravity to form landslips. These affect bedrock, other superficial deposits and artificial ground. The dataset also includes foundered strata, where the ground has collapsed due to subsidence.

Artificial Ground and Landslip Map - Slice A




Order Details:

Order Number:	401117746_1_1
Customer Reference:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details:

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and database rights 2026 OS AC0000813445

LK CONSULT


Superficial Geology

Superficial Deposits are the youngest geological deposits formed during the most recent period of geological time, the Quaternary, which extends back about 1.8 million years from the present.

They rest on older deposits or rocks referred to as Bedrock. This dataset contains Superficial deposits that are of natural origin and 'in place'. Other superficial strata may be held in the Mass Movement dataset where they have been moved, or in the Artificial Ground dataset where they are of man-made origin.

Most of these Superficial deposits are unconsolidated sediments such as gravel, sand, silt and clay, and onshore they form relatively thin, often discontinuous patches or larger spreads.

Superficial Geology Map - Slice A




Order Details:

Order Number:	401117746_1_1
Customer Reference:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details:

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and database rights 2026 OS AC0000813445

LK CONSULT

Bedrock and Faults


Bedrock geology is a term used for the main mass of rocks forming the Earth and are present everywhere, whether exposed at the surface in outcrops or concealed beneath superficial deposits or water.

The bedrock has formed over vast lengths of geological time ranging from ancient and highly altered rocks of the Proterozoic, some 2500 million years ago, or older, up to the relatively young Pliocene, 1.8 million years ago.

The bedrock geology includes many lithologies, often classified into three types based on origin: igneous, metamorphic and sedimentary.

The BGS Faults and Rock Segments dataset includes geological faults (e.g. normal, thrust), and thin beds mapped as lines (e.g. coal seam, gypsum bed). Some of these are linked to other particular 1:50,000 Geology datasets, for example, coal seams are part of the bedrock sequence, most faults and mineral veins primarily affect the bedrock but cut across the strata and post date its deposition.

Bedrock and Faults Map - Slice A




Order Details:

Order Number:	401117746_1_1
Customer Reference:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details:

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and database rights 2026 OS AC0000813445

LK CONSULT

Combined Surface Geology

The Combined Surface Geology map combines all the previous maps into one combined geological overview of your site.

Please consult the legends to the previous maps to interpret the Combined "Surface Geology" map.


Additional Information

More information on 1:50,000 Geological mapping and explanations of rock classifications can be found on the BGS website. Using the LEX Codes in this report, further descriptions of rock types can be obtained by interrogating the 'BGS Lexicon of Named Rock Units'. This database can be accessed by following the 'Information and Data' link on the BGS website.

Contact

British Geological Survey
Kingsley Dunham Centre
Keyworth
Nottingham
NG12 5GG
Telephone: 0115 936 3143
Fax: 0115 936 3276
email: enquiries@bgs.ac.uk
website: www.bgs.ac.uk

Combined Geology Map - Slice A




Order Details:

Order Number:	401117746_1_1
Customer Reference:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details:

Cedar Mount High School Sit:, LKC261292



©Crown copyright and database rights 2026 OS AC0000813445

LK CONSULT

Groundwater Vulnerability

General


Specified Site | Specified Buffer(s) | Bearing Reference Point
Slice | Map ID

Agency and Hydrological

Bedrock Aquifers	Superficial Aquifers
High Vulnerability, Principal Aquifer	High Vulnerability, Principal Aquifer
High Vulnerability, Secondary Aquifer	High Vulnerability, Secondary Aquifer
Medium Vulnerability, Principal Aquifer	Medium Vulnerability, Principal Aquifer
Medium Vulnerability, Secondary Aquifer	Medium Vulnerability, Secondary Aquifer
Low Vulnerability, Principal Aquifer	Low Vulnerability, Principal Aquifer
Low Vulnerability, Secondary Aquifer	Low Vulnerability, Secondary Aquifer

Unproductive Aquifer
Soluble Rock

Site Sensitivity Context Map - Slice A



Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



LK CONSULT

Bedrock Aquifer Designation

General


Specified Site | Specified Buffer(s) | Bearing Reference Point | Slice | Map ID

Agency and Hydrological

Geological Classes

- Principal Aquifer
- Secondary A Aquifer
- Secondary B Aquifer
- Secondary Undifferentiated
- Unproductive Strata
- Unknown
- Unknown (Lakes and Landslip)

Site Sensitivity Context Map - Slice A




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292



LK CONSULT

Superficial Aquifer Designation

General


Specified Site | Specified Buffer(s) | Bearing Reference Point | Slice | Map ID

Agency and Hydrological

Geological Classes

- Principal Aquifer
- Secondary A Aquifer
- Secondary B Aquifer
- Secondary Undifferentiated
- Unproductive Strata
- Unknown
- Unknown (Lakes and Landslip)

Site Sensitivity Context Map - Slice A




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



LK CONSULT

Source Protection Zones


General

Specified Site | Specified Buffer(s) | Bearing Reference Point | Slice | Map ID

Agency and Hydrological

- Inner zone (Zone 1)
- Inner zone - subsurface activity only (Zone 1c)
- Outer zone (Zone 2)
- Outer zone - subsurface activity only (Zone 2c)
- Total catchment (Zone 3)
- Total catchment - subsurface activity only (Zone 3c)
- Special interest (Zone 4)

Site Sensitivity Context Map - Slice A



Order Details


Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



©Crown copyright and database rights 2026 OS AC0000813445

LK CONSULT

Sensitive Land Uses


General

Specified Site | Specified Buffer(s) | Bearing Reference Point
Slice | Map ID

Sensitive Land Uses

- Ancient Woodland
- Area of Adopted Green Belt
- Area of Unadopted Green Belt
- Area of Outstanding Natural Beauty
- Environmentally Sensitive Area
- Forest Park
- Local Nature Reserve
- Marine Nature Reserve
- National Nature Reserve
- National Park
- Nitrate Sensitive Area
- Nitrate Vulnerable Zone
- Ramsar Site
- Site of Special Scientific Interest
- Special Area of Conservation
- Special Protection Area
- World Heritage Sites

Site Sensitivity Context Map - Slice A




Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



©Crown copyright and database rights 2026 OS AC0000813445

LK CONSULT

BGS Flood GFS Data


General

Specified Site
Specified Buffer(s)
Bearing Reference Point
Slice

Agency and Hydrological (Flood)

Limited Potential for Groundwater Flooding to Occur
Potential for Groundwater Flooding of Property Situated Below Ground Level
Potential for Groundwater Flooding to Occur at Surface

Site Sensitivity Context Map - Slice A



Order Details

Order Number:	401117746_1_1
Customer Ref:	LKC261292
National Grid Reference:	388470, 394810
Slice:	A
Site Area (Ha):	0.02
Search Buffer (m):	1000

Site Details

Cedar Mount High School Sit:, LKC261292

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk

Appendix C – Historical BGS Boreholes

British Geological Survey

BGS ID: 865848 : BGS Reference: SJ89SE168
British National Grid (27700) : 388550,394740

SJ 89 SE 168

For Institute use only

Geological Classification	Nature of Strata *If measurements start below ground surface, state how far.*	Thickness Feet	Thickness Inches	Thickness Metres	Depth Feet	Depth Inches	Depth Metres
	FILLED GROUND			1			1
	GREY SILTY CLAY			3			4
	LOOSE PEAT			6			10
	STIFF BROWN BOLDER CLAY (SILTY)			17			27
	SAND + GRAVEL			10			37
	BUNTER SANDSTONE			36			73

Contact BGS: ngdc@bgs.ac.uk

British Geological Survey

BGS ID: 865848 : BGS Reference: SJ89SE168
British National Grid (27700) : 388550,394740

RECORD OF WELL

Central L.S. Northwest N.W.R.A.

RICHMOND CRISPS

At SANDFOLD LANE

LEVENSHULME

Town or Village GTR MANCHESTER

County

For Institute use only Licence No.

N

SJ89 / 231

85 SJ89SE168

EXACT SITE OF WELL

Six-inch National Grid sheet and reference SJ 88559474

For CBA ENTERPRISES LIMITED

State whether owner, tenant, builder, contractor, consultant, etc.: OWNER

Address (if different from above)

Level of ground surface above sea level (O.D.) ft (183 m)

*DELETE AS NECESSARY

If well top is not at ground level state how far above:* below: ft (G/L m)

SHAFT ~~239~~ ft (~~72.85~~ m); diameter ~~12"~~ (reducing to 8") # (m);

HEADINGS (please attach details—dimensions and directions)

BORE 239 ft (~~72.85~~ 73.00 m); diameter: at top 12" in (300 mm);

at bottom 8" in (203 mm)

Full details of permanent lining tubes (position, length, inner and outer diameters, plain slotted etc.):

10 mtrs x 300 mm SOLID STEEL CASING (¼" WALL THICKNESS) FROM SURFACE

40 " x 203 mm " " " " TO ROCK HEAD.

TEST CONDITIONS

Water struck at depths of ft (25.68 m) below well top

Rest level of water ft (2.6 m) above* below well top. Suction at 200 ft (60.96 m)

Yield on hours'* days' test pumping at galls per (l/s) with

depression to ft (m) below well top. Recovery to rest level in mins* hours

Capacity of pump g.p.h. (l/s) SEE ATTACHED PUMP TEST DATA SHEETS

Date of measurements 10-14/2/92

NORMAL CONDITIONS

DESCRIPTION OF PERMANENT PUMPING EQUIPMENT:

Make and/or type GRUNDFOS SP16/16 Motive power ELECTRIC

Capacity 4000 galls (18 m³) per hour. Suction at 200 ft (60 m)

below well top. Amount pumped 4000 galls (18 m³) per day. Estimated

consumption ~~288,000~~ galls (1309 m³) per week

Well made by BLAIR CONTRACTORS LIMITED Date of sinking SEPT/OCT '91

ADDITIONAL NOTES ANALYSIS (please attach copy if available)

LOG OF STRATA OVERLEAF

11432

RECEIVED: 20th April 93

Received from Blair Contractors Ltd

Date 29.3.93

Observation well

Recorder

ER log

Site marked on

1" map

6" map—Grid Sheet

(use symbol)

Copy to

Date

INSTITUTE OF GEOLOGICAL SCIENCES
HYDROGEOLOGY UNIT
EXHIBITION ROAD
LONDON SW7 2DE

IGS 2494 10 000 7/79

Contact BGS: ngdc@bgs.ac.uk

British Geological Survey

BGS ID: 865848 : BGS Reference: SJ89SE168
British National Grid (27700) : 388550,394740

RECORD OF WELL

RICHMOND CRISPS

Central L.S. Northwest N.W.R.A.

At SANDFOLD LANE,
LEVENSHULME
Town or Village GTR MANCHESTER
County

For Institute use only Licence No.

N

SJ89|231

85 SJ89SE

EXACT SITE OF WELL

Six-inch National Grid sheet and reference SJ 8855 9474

For CBA ENTERPRISES LIMITED

State whether owner, tenant, builder, contractor, consultant, etc.: OWNER

Address (if different from above)

Level of ground surface above sea level (O.D.) ft (183 m)

*DELETE AS NECESSARY

If well top is not at ground level state how far above:* below: ft (G/L m)

SHAFT ~~239~~ ft (~~72.85~~ m); diameter ~~12"~~ reducing to 8" # (m);

HEADINGS (please attach details—dimensions and directions)

BORE 239 ft (~~72.85~~ 73.00 m); diameter: at top 12" in (300 mm);

at bottom 8" in (203 mm)

Full details of permanent lining tubes (position, length, inner and outer diameters, plain slotted etc.):

10 MTRS x 300 mm SOLID STEEL CASING (1/4" WALL THICKNESS) FROM SURFACE

40 " x 203 mm " " " " TO ROCK HEAD.

Water struck at depths of ft (25.68 m) below well top

TEST CONDITIONS

Rest level of water ft (2.6 m) above* below well top. Suction at 200 ft (60.96 m)

Yield on hours'* days' test pumping at galls per (l/s) with

depression to ft (m) below well top. Recovery to rest level in mins* hours

Capacity of pump g.p.h. (l/s) SEE ATTACHED PUMP TEST DATA SHEETS

Date of measurements. 10-14|2|92

NORMAL CONDITIONS

DESCRIPTION OF PERMANENT PUMPING EQUIPMENT:

Make and/or type GRUNDFOS SP16|16 Motive power. ELECTRIC

Capacity. 4000 galls (18 m³) per hour. Suction at 200 ft (60 m)

below well top. Amount pumped 4000 galls (18 m³) per day. Estimated

consumption 288,000 galls (1309 m³) per week

Well made by BLAIR CONTRACTORS LIMITED Date of sinking SEPT/OCT '91

ADDITIONAL NOTES ANALYSIS (please attach copy if available)

LOG OF STRATA OVERLEAF

Received from Blair Contractors Ltd

Date 29.3.93

Observation well

Recorder

ER log

Site marked on

1" map

6" map—Grid Sheet

(use symbol)

Copy to

Date

INSTITUTE OF GEOLOGICAL SCIENCES
HYDROGEOLOGY UNIT
EXHIBITION ROAD
LONDON SW7 2DE

IGS 2494 10 000 7/79

Contact BGS: ngdc@bgs.ac.uk

British Geological Survey

BGS ID: 865848 : BGS Reference: SJ89SE168
British National Grid (27700) : 388550,394740

For Institute use only

Geological Classification	Nature of Strata *If measurements start below ground surface, state how far.*	Thickness Feet	Inches	Metres	Depth Feet	Inches	Metres
	FILLED GROUND			1			1
	GREY SILTY CLAY			3			4
	LOOSE PEAT			6			10
	STIFF BROWN BOLDER CLAY (SILTY)			17			27
	SAND + GRAVEL			10			37
	BUNTER SANDSTONE			36			73

Contact BGS: ngdc@bgs.ac.uk

British Geological Survey

BGS ID: 865848 : BGS Reference: SJ89SE168
British National Grid (27700) : 388550,394740

SJ89/231

NRA

SITE AT
SANDFOLD LANE
LEVENSHULME

PUMPING TEST DATA

LEVEL DATA FROM Richmond Crisps (CBA ENTERPRISES) SHEET No. 1

PUMPED BOREHOLE ..... ~~CONSTANT RATE~~ / STEP DRAWDOWN* / ~~RECOVERY~~

OBSERVER M.D. THEWSEY DATUM MH Cover Level

N.G.R. ..... W.R.B. No. SJ89/231

10. FEB 92 Date	10.40 Time	(dec.mins)	(t mins)	25.50 (SWL) LEVEL m.b.d.	Δs (metres)	Comments
10th FEB 1992	11.29		0	25.737 SUSPECT 26.73 READING		START STEP ONE FLOW = 115 l/min.
			1	26.44		
			2	26.47		
			3	26.50		
			4	26.55		
			5	– MISSED.		
			6	26.57		
			7	26.58		
			8	26.59		
			9	26.61		
			10	26.61		
			12	26.61		
			14	26.62		
			16	26.63		
			18	26.65		
			20	26.65		
			25	26.60		
			30	26.58		
			35	26.57		
			40	26.59		
			50	–		FLOW CHECK: 107 l/min
			60	26.54 ?		SUSPECT READING
			70	26.58		
			80	26.58		
			90	26.58		
			100	26.58		
			~~120~~ *	RATE INCREASED		SEE PAGE 2.
			~~150~~			
			~~180~~			
			~~210~~			

* NB WL TURBULENT THOUGHOUT TEST – CIRCA ±3 cm OR 30
DIFFICULT TO READ BECAUSE OF THIS

Contact BGS: ngdc@bgs.ac.uk

British Geological Survey

BGS ID: 865848 : BGS Reference: SJ89SE168
British National Grid (27700) : 388550,394740

SJ89/231

NRA

SITE AT
SANDFOLD LANE
LEVENSHULME.

PUMPING TEST DATA

LEVEL DATA FROM Richmond Crisps (CBA ENTERPRISES) SHEET No. 2

PUMPED BOREHOLE ..... [redacted] / STEP DRAWDOWN / [redacted]

OBSERVER M.P. THELWELL DATUM MH Cover Level.

N.G.R. SJ8855 9474 W.R.B. No. SJ89/231

Date	Time	(dec.mins)	(t mins)	LEVEL m.b.d.	Δs (metres)	Comments
10th Feb 1992	13:09		0	26.58		START STEP ~~TWO~~ FLOW = 200 l/m.
			1	27.09		
			2	–		FIELD SHEET BLEW AWAY!
			3	27.12		
			4	27.14		
			5	27.17		
			6	27.18		
			7	27.21		
			8	27.22		
			9	27.23		
			10	27.24		
			12	27.25		
			14	27.26		
			16	27.27		
			18	27.29		
			20	27.30		
			25	27.34		
			30	27.34		
			35	27.36		
			40	27.37		
			50	27.38		FLOW CHECK = 195 l/m
			60	27.39		
			70	27.43		
			80	27.43		
			90	27.44		
			100	27.40		
			~~120~~	RATE INCREASED		SEE PAGE 3
			~~150~~			
			~~180~~			
			~~210~~			
* SEE	NOTE ON	PAGE 1				

Contact BGS: ngdc@bgs.ac.uk

British Geological Survey

BGS ID: 865848 : BGS Reference: SJ89SE168
British National Grid (27700) : 388550,394740

SJ89/231

NRA

PUMPING TEST DATA

LEVEL DATA FROM RICHMOND CRISPS (CBA ENTERPRISES) SHEET No. 3

PUMPED BOREHOLE ..... ~~CONSTANT RATE~~ / STEP DRAWDOWN / ~~RECOVERY~~

OBSERVER M.D. THEWSEY DATUM MK. Source level.

N.G.R. SJ 8855 9474 W.R.B. No. SJ 89/231

Date	Time	(dec.mins)	(t mins)	LEVEL m.b.d.	Δs (metres)	Comments
10th FEB 1992	14:49		0			THIRD STEP FLOW = 280 l/m.
			1	27.70		
			2	27.84		
			3	27.87		
			4	27.90		
			5	27.91		
			6	27.92		
			7	27.93		
			8	27.94		
			9	27.95		
			10	27.96		
			12	27.97		
			14	28.00		
			16	28.01		
			18	28.02		
			20	28.02		
			25	28.03		
			30	28.04		FLOW CHECK = 260 l/m.
			35	28.05		
			40	28.06		
			50	28.07		
			60	28.08		
			70	28.11		
			80	28.11		
			90	28.12		
			100	28.13		FLOW CHECK CIRCA 260 l/m.
			120	—	NEXT READING TAKEN	
			150	—	OF THIS 'STEP' ON	
			180	—	11th FEB - SEE DRILLERS	
			210	—	SHEETS.	
* SEE	NOTE ON	PAGE 1.				

Contact BGS: ngdc@bgs.ac.uk

British Geological Survey

BGS ID: 865848 : BGS Reference: SJ89SE168
British National Grid (27700) : 388550,394740

SJ89/231

NRA National Rivers Authority North West Region

TRANSCRIPT OF DRILLERS READINGS

3rd step Maintained as a constant rate test

PUMPING TEST DATA

LEVEL DATA FROM RICHMONDS CRISPS (CBA ENTERPRISES) SHEET No. 4

PUMPED BOREHOLE ..... CONSTANT RATE / STEP DRAWDOWN ~~/ RECOVERY~~

OBSERVER M.D. THENJET DATUM COVER LEVEL.

N.G.R. ..... W.R.B. No. SJ 89/231

Date	Time	(dec.mins)	(t mins)	LEVEL mbd.	Δs (metres)	Comments
11.2.92	08.25			28.20		THIRD STEP CONTINUED FROM PAGE 3
11.2.92	12.00			28.21		FLOWRATE 265l/min
11.2.92	16.00			28.22		"
12.2.92	09.00			28.15		"
12.2.92.	12.30			28.15		"
12.2.92	17.15			28.15		"
13.2.92	08.30			28.15		"
13.2.92	12.15			28.15		"
13.2.92	16.15			28.15		"
14.2.92	08.30			28.25		"
14.2.92	11.45			28.23		"
14.2.92	15.45 *			28.21		"
14.2.92.	15.47					PUMP TURNED OFF
						SUBSEQUENT
						READINGS ON
						RECOVERY SHEET
14.2.92	15.47	FINAL	METER	READING =	1639.6	
10.2.92	11.29	START	METER	READING =	51.6	
DURATION =	6018 MINS		TOTAL ABSTRACTION =		1588 thl	
	100 hrs 18 mins					
		MEAN	ABSTRACTION =		264l/min.	
AT 15.45	IT WAS	NOTED THAT	WATER LEVEL	WAS	STILL	
	'HUNTING'	CIRCA ±	3 cm - THIS	IS AN	AVERAGE	
	READING					

Contact BGS: ngdc@bgs.ac.uk

British Geological Survey

BGS ID: 865848 : BGS Reference: SJ89SE168
British National Grid (27700) : 388550,394740

SJ89/231

NRA National Rivers Authority North West Region

PUMPING TEST DATA

LEVEL DATA FROM Richmonds Crisps (CBA ENTERPRISES) SHEET No. 5

PUMPED BOREHOLE 100 hour @ 165l/Hr. ~~CONSTANT RATE~~ / ~~STEP DRAWDOWN~~ /RECOVERY

OBSERVER M. D. THEWSEY DATUM

N.G.R. W.R.B. No. SJ89/231

Date	Time	(dec.mins)	(t mins)	LEVEL mbd.	Δs (metres)	Comments
1992 Fri 14th Feb	15.45			28.21		Pre Switch off.
"	15.47		0	28.25		Pump OFF.
"	15.48		1	26.42		
"	15.49		2	26.47		
"	15.50		3	26.47		
"	15.51		4	26.45		
"	15.52		5	26.41		
"	15.53		6	26.35		
"	15.54		7	26.31		
"	15.55		8	26.29		
"	15.56		9	26.26		
"	15.57		10	26.22		
"	16.02		15	26.11		
"	16.07		20	26.03		
"	16.12		25	25.97		
"	16.17		30	25.92		
"	16.22		35	25.88		
"	16.27		40	25.85		
"	16.32		45	25.81		
"	16.37		50	25.79		
"	16.47		60	25.77		
"	16.57		70	25.74		
"	17.07		80	25.72		
"	17.17		90	25.72		
"	17.27		100	25.69		
"						
"						

Contact BGS: ngdc@bgs.ac.uk

Appendix D – Risk Evaluation

RISK EVALUATION

The method for risk evaluation is a qualitative method of interpreting the output from the risk estimation stage of the assessment, based on CIRIA 552[13]. It involves the classification of the:

- Magnitude of the potential consequence (severity) of the risk occurring (Table A).
- Magnitude if the probability (likelihood) of the risk occurring (Table B).

Consequence (Severity)		
Classification	**Definition**	**Example**
Severe	Short term (acute) risk to human health likely to results in 'significant harm' as defined by the Environment Protection Act 1990, Part IIA. Short term risk of pollution (note: water Resources Act contains no scope for considering significance of pollution) of sensitive water resource. Catastrophic damage to buildings/properties. A short-term risk to a particular ecosystem, or organism forming part of such ecosystem (note: the definition of ecological systems within the Draft Circular on Contaminated Land, DETR, 2000).	High Concentrations of cyanide on the surface of an informal recreation area. Major spillage of contaminants from site into controlled waters. Explosion, causing building collapse (can also equate to short term human health risk if buildings are occupied).
Medium	Chronic damage to Human Health ('significant harm' as defined in DETR, 2000). Pollution of sensitive water resources (note Water Resources Act contains no scope for considering significance of pollution). A significant change in a particular ecosystem, or organism forming part of such ecosystem.	Concentrations of a contaminant from site exceed generic, or site-specific assessment criteria. Leaching of contaminants from a site to a major or minor aquifer (Principal and Secondary). Death of a species within a designated nature reserve.
Mild	Pollution of non-sensitive water resources. Significant damage to crops, buildings, structures, and services ('significant harm' as defined in DETR, 2000). Damage to sensitive buildings/structures/services or the environment.	Pollution of non-classified groundwater. Damage to building rendering it unsafe to occupy (e.g., foundation damage resulting in instability).
Minor	Harm, although not necessarily significant harm, which may result in a financial loss, or expenditure to resolve. Non-permanent health effects to human health (easily prevented by means such as personal protective clothing etc). Easily repairable damage to buildings, structures, and services.	The presence of contaminants at such concentrations that protective equipment is required during site works. The loss of plants in a landscaping scheme. Discoloration of concrete.

Table A. Classification of Consequence

Probability (Likelihood)	
Classification	**Definition**
High Likelihood	There is a pollutant linkage and an event that either appears very likely in the short term and almost inevitable over the long term, or there is evidence at the receptor of harm or pollution.
Likely	There is a pollutant linkage, and all the elements are present and in the right place, which means that it is probable that an event will occur. Circumstances are such that an event is not inevitable, but possible in the short term and likely over the long term.
Low Likelihood	There is a pollutant linkage and circumstances are possible under which an event could occur. However, it is by no means certain that even over a longer period such event would take place and is less likely in the shorter term.
Unlikely	There is a pollutant linkage, but circumstances are such that it is improbable that an event would occur in the very long term.

Table B. Classification of Probability.

These classifications are then compared to indicate the risk presented by each pollutant linkage (Table C). It is important that this classification is only applied where there is a possibility (which can range from high likelihood to unlikely) of a pollutant linkage existing.

		Consequence			
		Severe	**Medium**	**Mild**	**Minor**
Probability	**High Likelihood**	Very High Risk	High Risk	Moderate Risk	Moderate / Low Risk
	Likely	High Risk	Moderate Risk	Moderate / Low Risk	Low Risk
	Low Likelihood	Moderate Risk	Moderate / Low Risk	Low Risk	Very Low Risk
	Unlikely	Moderate / Low Risk	Low Risk	Very Low Risk	Very Low Risk

Table C. Comparison of Consequence against Probability

Once the risk has been determined the corresponding action can be assessed (Table D).

Risk	**Action Required**
Very High Risk	There is a high probability that severe harm could arise to a designated receptor from an identified hazard, OR there is evidence that sever harm to a designated receptor is currently happening. This risk, if realised, is likely to results in a substantial liability. Urgent investigation (if not already undertaken) and remediation are likely to be required.
High Risk	Harm is likely to arise to a designated receptor from an identified hazard. Realisation of the risk is likely to present a substantial liability. Urgent investigation (if not undertaken already) is required and remedial works may be necessary in the short term and are likely over the longer term.
Moderate Risk	It is possible that harm could arise to a designated receptor from an identified hazard. However, it is either relatively unlikely that any such harm would be severe, or if any harm were to occur it is more likely that the harm would be relatively mild. Investigation (if not already undertaken) is normally required to clarify the risk and to determine the potential liability. Some remedial works may be required in the longer term.
Low Risk	It is possible that harm could arise to a designated receptor from an identified hazard, but it is likely that this harm, if realised, would at worst normally be mild.
Very Low Risk	There is a low possibility that harm could arise to a receptor. In the event of such harm being realised it is not likely to be severe.

Table D. Description of the Classification and Likely Action Required.

Where a very low risk is identified no specific remediation is required.

Where a low risk is identified, some form of remediation may be required depending on the pollutant linkage, the type and concentration of contaminants present and the proposed development.

Where there is a moderate/low risk is identified, an assessment will be undertaken to establish what category the pollutant linkage will fall into.

Where LKC identifies a moderate or higher risk, remediation or further investigation work is recommended.

Appendix E - References

[1] Environment Agency, October 2020, “Land contamination risk management (LCRM). How to assess and manage the risks from land contamination”.
[2] Ministry of Housing, Communities and Local Government, December 2024, “National Planning Policy Framework”.
[3] Environment Agency, October 2020, “Land contamination risk management (LCRM). How to assess and manage the risks from land contamination”.
[4] DEFRA & Environment Agency, March 2002, "Potential Contaminants for the Assessment of Land", R&D Publication CLR 8.
[5] Environment Agency, January 2009, "Updated technical background to the CLEA model", Science Report SC050021/SR3.
[6] CIRIA, January 2001, "Contaminated land risk assessment. A guide to good practice", C552.
[7] Health & Safety Executive, 1991, "Protection of Workers and the General Public during the Development of Contaminated Land", HSG66.
[8] The British Standards Institution (BSI), December 2017, "Investigation of potentially contaminated sites. Code of practice - Code of practice", BS 10175:2011+A2:2017.
[9] The British Standards Institution (BSI), May 2020, "Code of practice for ground investigations", BS 5930:2015+A1:2020.
[10] CIRIA, December 2007, "Assessing risks posed by hazardous ground gases to buildings", C665.
[11] CL:AIRE, November 2012, "A Pragmatic Approach to Ground Gas Risk Assessment", RB 17.
[12] The British Standards Institution (BSI), January 2019, "Code of practice for the design of protective measures for methane and carbon dioxide ground gases for new buildings", BS 8485:2015+A1:2019.
[13] CIRIA, January 2001, "Contaminated land risk assessment. A guide to good practice", C552.

Based across the UK with offices in Manchester, Liverpool, Swindon and Glasgow.

Manchester (Head Office)

Unit 29
Eton Business Park
Eton Hill Rd, Radcliffe
M26 2ZS

0161 763 7200
info@thelkgroup.com

Manchester (Ancoats Office)

84 Silk Street
Ancoats
Manchester
M4 6BJ

0161 763 7200
info@thelkgroup.com

Glasgow

Wright Business Centre
1 Lonmay Road
Glasgow
G33 4EL

0141 773 6269
info@thelkgroup.com

Swindon

39 Bowman House Business Centre
Bowman Court
Whitehill Lane
Royal Wootton Bassett
Swindon
SN4 7DB

01793 987390
info@thelkgroup.com

LK GROUP