


		Inspection Report		40 Francis Road Irlam Manchester M44 6AY	
Section: MH 01 DOWNSTREAM	Date: 2021-11-25	Job Number: 32 M21 9LA	Weather: No rain or snow	PLR:	
Operator: A JONES			Cleaned:		

Place: Road: Location:	HAPMTON ROAD Gardens	Direction: Catchment: Total Length: Pipe Length:	Downstream	Start ref: Start depth: End ref: End depth:	MH 01 HIGHWAY OFF BOUNDARY
Use: Year Laid: Purpose: Lining: Comments:	Combined Sample survey to determine asset condition of a sewer system	Pipe Shape: Width / Height: Flow Control: Pipe Material:	circular ? / 150mm vitrified clay		

-2.22m (MH 01)



-0.66m (HIGHWAY OFF BOUNDARY)

		Inspection Report		40 Francis Road Irlam Manchester M44 6AY
Section: MH 01 DOWNSTREAM	Date: 2021-11-25	Job Number: 32 M21 9LA	Weather: No rain or snow	PLR:
Operator: A JONES			Cleaned:	



(1)



(2)

		Inspection Report		40 Francis Road Irlam Manchester M44 6AY	
Section: MH 01 DOWNSTREAM	Date: 2021-11-25	Job Number: 32 M21 9LA	Weather: No rain or snow	PLR:	
Operator: A JONES			Cleaned:		



(3)



(4)