

		Inspection Report		40 Francis Road Irlam Manchester M44 6AY	
Section: MH 01 UPSTREAM	Date: 2021-11-25	Job Number: 32 M21 9LA	Weather: No rain or snow	PLR:	
Operator: A JONES			Cleaned:		

Place: Road: Location:	HAPMTON ROAD Gardens	Direction: Catchment: Total Length: Pipe Length:	Upstream	Start ref: Start depth: End ref: End depth:	MH 01 HEAD OF LINE
Use: Year Laid: Purpose: Lining: Comments:	Combined Sample survey to determine asset condition of a sewer system		Pipe Shape: Width / Height: Flow Control: Pipe Material:	circular ? / 150mm vitrified clay	

0.00m (MH 01)

	Meterage	CD	Code	Observation	Video	Pic.
	0.00m		IC	Start node type, inspection chamber reference number: MH 01	00:00:01	(1)
	0.83m		RF	Roots, fine	00:00:15	(2)
	1.44m		RFJ	Roots, fine at joint	00:00:23	(3)
	6.03m		RFJ	Roots, fine at joint	00:00:55	(4)
	6.54m		JN	Junction from 2 O'Clock diameter: 100 mm RAINWATER GULLY	00:00:58	(5)
	7.59m		RF	Roots, fine	00:01:04	(6)
	8.86m		RFJ	Roots, fine at joint	00:03:31	(7)
8.86m						

		Inspection Report		40 Francis Road Irlam Manchester M44 6AY	
Section: MH 01 UPSTREAM	Date: 2021-11-25	Job Number: 32 M21 9LA	Weather: No rain or snow	PLR:	
Operator: A JONES			Cleaned:		


8.86m




Meterage	CD	Code	Observation	Video	Pic.
10.76m		RFJ	Roots, fine at joint	00:03:48	(8)
14.04m		WLT	Turbid water level 15% UNABLE TO PUSH	00:04:13	(9)
14.04m		SA	Survey abandoned NEEDS JETTING	00:04:15	(10)

14.04m (HEAD OF LINE)

		Inspection Report		40 Francis Road Irlam Manchester M44 6AY	
Section: MH 01 UPSTREAM	Date: 2021-11-25	Job Number: 32 M21 9LA	Weather: No rain or snow	PLR:	
Operator: A JONES			Cleaned:		




(1)




(2)

		Inspection Report		40 Francis Road Irlam Manchester M44 6AY	
Section: MH 01 UPSTREAM	Date: 2021-11-25	Job Number: 32 M21 9LA	Weather: No rain or snow	PLR:	
Operator: A JONES			Cleaned:		



(3)



(4)

		Inspection Report		40 Francis Road Irlam Manchester M44 6AY	
Section: MH 01 UPSTREAM	Date: 2021-11-25	Job Number: 32 M21 9LA	Weather: No rain or snow	PLR:	
Operator: A JONES			Cleaned:		



(5)



(6)

		Inspection Report		40 Francis Road Irlam Manchester M44 6AY	
Section: MH 01 UPSTREAM	Date: 2021-11-25	Job Number: 32 M21 9LA	Weather: No rain or snow	PLR:	
Operator: A JONES			Cleaned:		




(7)




(8)

		Inspection Report		40 Francis Road Irlam Manchester M44 6AY	
Section: MH 01 UPSTREAM	Date: 2021-11-25	Job Number: 32 M21 9LA	Weather: No rain or snow	PLR:	
Operator: A JONES			Cleaned:		



(9)



(10)