

Appendix I – Maps and Figures



Figure 1 - External view of western and southern facades of Canada House (AA022681 – English Heritage Archives).




Figure 2 – Location Plan



Figure 3 – Central staircase and art nouveau banister (Photograph - <https://historicengland.org.uk/research/heritage-counts/2018-heritage-in-commercial-use/case-studies/canada-house-manchester/>)



Figure 4 - Entrance and Reception Area at Canada House (Photograph - <https://historicengland.org.uk/research/heritage-counts/2018-heritage-in-commercial-use/case-studies/canada-house-manchester/>)



Figure 5 – Recent Office Refurbishment at Canada House (Photograph - <https://historicengland.org.uk/research/heritage-counts/2018-heritage-in-commercial-use/case-studies/canada-house-manchester/>)



Figure 6 – Internal view looking south showing the different style in columns throughout the floor (Photograph by HE)



Figure 7: Original inspection/cutting bench encased with the boxing out running along the western side of the office. Sash windows also shown in connection to actuator installation.
(Photograph by HE)



Figure 8 – Inspection/cutting desk in the fourth floor wareroom of Asia House, Manchester (EH 2002, 39.). Parallels can be drawn with that in the current HE demise at Canada House.



Figure 9 –Boxing out detail over heating system and sash windows visible (Photograph by HE)



Figure 10 – Existing tea point arrangement (Photograph by HE)