

DYE TESTED AND CAME OUT AT OUTFALL IN BROOK NO MH COULD BE FOUND BETWEEN

SA FROM MH1 JET STOPPING IN REAR GARDEN AND HOLDING WATER WHEN CCTV ATTEMPT

MH BURIED

225MM

MH1 DEPTH 3-500MM

PRESUMED ROUTE MH1 POSS DROPS INTO CULVERT

NO REAL ACCESS TO CAMERA AND CLEAN FROM BROOK PIPE 40% DEBRIS BRICKS STONES ECT

375MM



General Utilities Northwest Limited  
Unit 1, Boundary Trading Park,  
Liverpool Road, Irlam, Manchester M44 6FB  
tel: 0161 776 0011 fax: 0161 776 0044  
email: generalutilities@btconnect.com  
website: www.generalutilitiesnorthwest.co.uk