



CETCO Inspection Report

Project Name:

Oxygen Towers, Store Street, Manchester, M1 5NZ

Inspection Date:

14-11-18

Report No.

03

To be included on email distribution list:

CETCO

☒

Owner

☐

General Contractor

☒

Approved Applicator

☒

Design Team

☐

Project/PSA-I.D

Drive Time

2H

Weather Conditions:

Sunny

Time In:

11.00

Time Out:

12.00

Main Contractor:

Russell

Approved Applicator:

Reddington

Person on Site:

Andrew Faith

Title/Company

Reddington

Person on Site:

Title/Company

Person on Site:

Title/Company

CETCO products installed on project

Voltex

☐

Voltex DS

☐

Voltex CR

☒

Voltex CRDS

☐

Coreflex 60

☐

CoreFlash

☐

Swelltite

☐

Ultraseal XP

☐

RX101

☐

RX101-DH

☐

RX103

☐

Akwastop

☐

Akwaswell

☐

CETSEAL

☐

LCD 60

☐

Hydrofix

☐

Bentoseal

☐

Hydrobar Tubes

☐

Bentogrout

☐

Granules

☒

Other

Volseal 250

Certified Inspector:

Andy Rowell


Date:

14-11-18

Product Installation Notes / Sketch Illustrating Item of Concern

Area inspected, Voltex CR at GL, A-D/15-16 & GL, A-D11-12 etched in red on inspection map. GL are to the nearest position possible.

Cetco materials to standards.



Photographs



Location: GL, 12/B



Location: GL, 12/D



Location: GL, A/12



Location: GL, 11-12/D

Photographs



Location:

GL, 11/C



Location:

GL, 11/B



Location:

GL, 15-16/A-D




Location:

GL, 15-16/D

Inspection Map

Reference:

Area inspected, etched in red on inspection map, signed and dated.



Tracking of Action Items and Repairs

Project: 73 Deverex Drive

Date: 09/11/18

[illegible]