

sample

kampus listed buildings

12 05 2021

sample sign-off 02.02 • external existing features

description:

repair strategy for existing external hoists, grillage and shutters submitted under condition 33k (CDN/19/0966) + listed building condition 6k (CDN/19/0971)

agreed via above noted condition approval dated 12 05 2021.

location:

both buildings / all elevations.

image:

refer condition submissions noted above.