

sample

kampus listed buildings

19 07 2021

sample sign-off 04.01 • existing doors**description:**

retention and repair of existing doors as below:

Doors to be removed for conservation repair. All areas of degraded timber to be removed and repairs carried out to maximise the retention of original timberwork. Frame to be repaired on site following similar guidelines. Any areas of degraded / softened timber to be removed to scarf in similar Douglas Fir/Oak species dependant on door. Loose fragments of timber to be removed and indentations to be filled with a Repair Care Resin. With Chorlton St door to Chorlton street plywood centre of fielded panels to be removed and replaced with new oak faced plywood panels as would've been in original door.

painted finish - RAL 7021 to match new windows and shopfronts. paint specification as below:

Manufacturer: Dulux

Preparation: Ensure the surface is clean and the environment free of building dust and dirt.

Initial coats: Doors and frame to be treated with 'Blackfriars Wood Preservative Gold Star'.

Number of coats: 1 x Aluminium Primer

Undercoats: 2 x Weathershield Quick Dry Undercoat

Finishing coats: 1 x Weathershield Gloss Paint

ironmongery as pictured below and approved via email 30.11.20

location:

minshull & turner building (chorlton street + little david street elevations) / minshull house (chorlton street elevation only).

image:

chorlton street doors - knob handle
(elite ironmongery)
finish - grade 316 stainless steel
(not as pictured)



little david street door - 19mm
diameter mitred lever handle (elite
ironmongery)
finish - grade 316 stainless steel



refurbished little david street door prior to install