

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.118	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	Paint	Low	Remove flaking paint			
	Floor Finish	Wood block Glazed tile	High Low	Retain Retain			
	Fixtures & Fittings						
	M&E Items	Early light switch Conduit Light Plug socket	Low None None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.119	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	Paint	Low	Remove flaking paint			
	Floor Finish	Wood block (lifted) Glazed tile	High Low	Retain Retain			
	Fixtures & Fittings						
	M&E Items	Early light switch Light	Low None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.120	Wall Finish(es)	Wallpaper White tile	None None	Remove Remove			
	Ceiling Finish	Paint	Low	Remove flaking paint			
	Floor Finish	Red clay tile	Low	Retain			
	Fixtures & Fittings						
	M&E Items	Early light switch Light Switch Plug sockets	Low None None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.121	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	Paint	Low	Remove flaking paint Approx. 1m2 of plaster missing			
	Floor Finish	Wood block Glazed tile	High Low	Retain Retain			
	Fixtures & Fittings						
	M&E Items	Early light switch Conduit Light	Low None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.122	Wall Finish(es)	Paint	Low	Remove flaking paint			
	Ceiling Finish	Paint	Low	Remove flaking paint Approx. 10m2 of plaster missing			
	Floor Finish	Wood block (lifted) Glazed tile	High Low	Retain Retain			
	Fixtures & Fittings						
	M&E Items	Light switch Conduit Light	None None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.123	Wall Finish(es)	Paint	Low	Remove flaking paint			
	Ceiling Finish	Paint	Low	Remove flaking paint Approx. 15m2 of plaster missing			
	Floor Finish	Wood block (lifted) Glazed tile	High Low	Retain Retain			
	Fixtures & Fittings						
	M&E Items	Light switch Conduit	None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.124	Wall Finish(es)	Paint	Low	Remove flaking paint			
	Ceiling Finish	Paint	Low	Remove flaking paint			
	Floor Finish	Wood block (lifted)	High	Retain			
	Fixtures & Fittings						
	M&E Items						

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.125	Wall Finish(es)	Paint	Low	Remove flaking paint			
	Ceiling Finish	Paint	Low	Remove flaking paint Approx. 2m2 of plaster missing			
	Floor Finish	Wood block (partially lifted)	High	Retain			
	Fixtures & Fittings	Timber boxing in Timber boards	None None	Remove Remove			
	M&E Items	Light Misc. pipe	None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.126	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	Paint	Low	Remove flaking paint Approx. 3m2 of plaster missing			
	Floor Finish	Wood block (lifted) Glazed tile	High Low	Retain Retain			
	Fixtures & Fittings						
	M&E Items	Light switch Conduit Light Gas pipe	None None None Low	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.127	Wall Finish(es)	Painted brick	Low	Remove flaking paint			
	Ceiling Finish	Paint	Low	Remove flaking paint			
	Floor Finish	Asphalt	None	Remove			
	Fixtures & Fittings						
	M&E Items						


Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.128	Wall Finish(es)	Paint	Low	Remove flaking paint			
	Ceiling Finish	N/A	N/A	N/A			
	Floor Finish	Wood block	High	Retain			
	Fixtures & Fittings						
	M&E Items	Light switch Conduit Misc. pipe	None None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.129	Wall Finish(es)	Painted brick	Low	Remove flaking paint			
	Ceiling Finish	Paint	Low	Remove flaking paint			
	Floor Finish	Exposed concrete	N/A	N/a			
	Fixtures & Fittings						
	M&E Items	Light switch Conduit Light	None None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.130	Wall Finish(es)	Paint	Low	Remove flaking paint			
	Ceiling Finish	Paint	Low	Remove flaking paint Approx. 5m2 of plaster missing			
	Floor Finish	Wood block (lifted)	High	Retain			
	Fixtures & Fittings	Timber boxing in Timber boards	None None	Remove Remove			
	M&E Items	Light switch Conduit Light	None None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.131	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	Paint	Low	Remove flaking paint			
	Floor Finish	Red clay tile	Low	Retain			
	Fixtures & Fittings	Ceiling hatch	None	Remove			
	M&E Items	Early light switch Conduit Misc. electrical items Plug socket	Low None None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.132	Wall Finish(es)	Painted brick	Low	Remove flaking paint	4 		
	Ceiling Finish	Exposed concrete	N/A	N/A			
	Floor Finish	Exposed concrete	N/A	N/A			
	Fixtures & Fittings	Fireman's pole	High	Retain			
	M&E Items	Conduit Light	None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.133	Wall Finish(es)	Paint	Low	Remove flaking paint			
	Ceiling Finish	Paint	Low	Remove flaking paint			
	Floor Finish	Exposed concrete	N/A	N/A			
	Fixtures & Fittings	Ceiling hatch Timber batten Mesh vent	None None None	Retain Remove Remove			
	M&E Items	Switch Light Plug socket	None None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.134	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	Paint	Low	Remove flaking paint Approx. 10m2 of plaster missing			
	Floor Finish	Painted concrete	Low	Remove flaking paint			
	Fixtures & Fittings	Ceiling hatch	Low	Retain			
	M&E Items	Switch Light Plug socket Heating pipe	None None None Low	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.135	Wall Finish(es)	Paint White tile	Low None	Remove flaking paint Remove			
	Ceiling Finish	Ceiling tile	None	Remove Approx. 1m2 of plaster missing			
	Floor Finish	Floor tile over red clay tile	None / low	Remove floor tile and adhesive, retain red clay tile			
	Fixtures & Fittings						
	M&E Items	Switch Plug socket	None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.136	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	Ceiling tile	None	Remove			
	Floor Finish	Red clay tile	Low	Retain			
	Fixtures & Fittings						
	M&E Items	Switches Conduit	None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.137	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	Paint	Low	Remove flaking paint			
	Floor Finish	Red clay tile	Low	Retain			
	Fixtures & Fittings						
	M&E Items	Conduit Light Misc. electrical items	None None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.138	Wall Finish(es)	Wallpaper White tile	None None	Remove Remove			
	Ceiling Finish	Ceiling paper Paint	None None	Remove Remove flaking paint Approx. 1m2 of plaster missing			
	Floor Finish	Floor tile over red clay tile	None / low	Remove floor tile and adhesive, retain red clay tile			
	Fixtures & Fittings						
	M&E Items	Switch Plug socket Misc. wires	None None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.139	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	Ceiling tile	None	Remove			
	Floor Finish	Red clay tile	Low	Retain			
	Fixtures & Fittings	Cupboard	None	Remove			
	M&E Items	Early light switch Conduit Misc. electrical items	Low None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.140	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	Paint	Low	Remove flaking paint Approx. 1m2 of plaster missing			
	Floor Finish	Red clay tile	Low	Retain			
	Fixtures & Fittings	Timber battens	None	Remove			
	M&E Items	Conduit Light Misc. electrical items	None None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.141	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	Ceiling paper	None	Remove			
	Floor Finish	Red clay tile	Low	Retain			
	Fixtures & Fittings	Timber boards	None	Remove			
	M&E Items	Early light switch Misc. electrical items Plug socket	Low None None	Remove all			


Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.142	Wall Finish(es)	Paint	Low	Remove flaking paint			
	Ceiling Finish	Paint Timber boards	Low Low	Remove flaking paint Remove Approx. 4m2 of plaster missing			
	Floor Finish	Timber staircase with carpet and vinyl over Wood block (lifted)	High / none / none High	Remove carpet and vinyl, retain timber staircase Retain			
	Fixtures & Fittings						
	M&E Items	Light switch Conduit Light Misc. electrical items	None None None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.143	Wall Finish(es)	Paint on glazed brick Wallboard to light shaft	None / High None	Remove paint and retain glazed brick Remove			
	Ceiling Finish	Paint	Low	Remove flaking paint			
	Floor Finish	Paint	Low	Remove flaking paint			
	Fixtures & Fittings	Fireman's hose pipe outlet Lift shutters Boxing in	High High None	Retain Retain Remove			
	M&E Items	Fuse box Conduit Light	None None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.144	Wall Finish(es)	Paint	Low	Remove flaking paint			
	Ceiling Finish	Paint	Low	Remove flaking paint Approx. 1m2 of plaster missing			
	Floor Finish	Red clay tile	Low	Retain			
	Fixtures & Fittings	Shelves Ceiling hatch	None None	Remove Retain			
	M&E Items	Conduit Light Waste pipe	None None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.145	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	N/A	N/A	4m2 of plaster missing			
	Floor Finish	Red clay tile	Low	Retain			
	Fixtures & Fittings						
	M&E Items	Light	None	Remove			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.146	Wall Finish(es)	Wallpaper Paint	None Low	Remove Remove flaking paint			
	Ceiling Finish	Paint	Low	Remove flaking paint Approx. 2m2 of plaster missing			
	Floor Finish	Red clay tile	Low	Retain			
	Fixtures & Fittings						
	M&E Items	Conduit Switch	None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.147	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	Paint	Low	Remove flaking paint Approx. 6m2 of plaster missing			
	Floor Finish	Wood block Vinyl and plastic nosing over timber staircase	High None / none / high	Retain Remove vinyl and nosing, retain staircase			
	Fixtures & Fittings	Timber staircase Hooks on timber board Door rail	High None None	Retain Remove Remove			
	M&E Items	Heating pipes Misc. wires	Low None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.148	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	Paint	Low	Remove flaking paint Approx. 1m2 of plaster missing			
	Floor Finish	Red clay tile	Low	Retain			
	Fixtures & Fittings	Shelves	None	Remove			
	M&E Items	Misc. Wires Light	None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.149	Wall Finish(es)	Wallpaper White tile	None None	Remove Remove			
	Ceiling Finish	Ceiling tile	None	Remove			
	Floor Finish	Red clay tile	Low	Retain			
	Fixtures & Fittings						
	M&E Items	Conduit	None	Remove			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.150	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	Paint	Low	Remove flaking paint Approx. 4m2 of plaster missing			
	Floor Finish	Red clay tile	Low	Retain			
	Fixtures & Fittings	Brackets Timber board Cupboard	None None None	Remove Remove Remove			
	M&E Items	Misc. electrical items Gas pipe	None Low	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.151	Wall Finish(es)	Paint	Low	Remove flaking paint			
	Ceiling Finish	Paint	Low	Remove flaking paint			
	Floor Finish	Exposed concrete	N/A	N/A			
	Fixtures & Fittings	Timber battens	None	Remove			
	M&E Items						

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.152	Wall Finish(es)	Wallpaper	None	Remove			
	Ceiling Finish	Paint	Low	Remove flaking paint			
	Floor Finish	Vinyl	None	Remove			
	Fixtures & Fittings	Spiral staircase	High	Retain			
	M&E Items	Switches Conduit Light Plug socket	None None None None	Remove all			

Room Reference	Element	Description	Significance	Removed or Retained	Photographs		
3.153	Wall Finish(es)	Painted brick	Low	Remove flaking paint			
	Ceiling Finish	Paint	Low	Remove flaking paint			
	Floor Finish	Exposed concrete	N/A	N/A			
	Fixtures & Fittings	Spiral staircase	High	Retain			
	M&E Items						

5 ROOM PLANS

6 SIGNIFICANCE PLANS

7 SUMMARY

- (i) The soft strip survey and report has provided a comprehensive list of all finishes, fixtures and fittings within London Road Fire Station.
- (ii) Below we have summarised the items found within the building, their significance and action for any avoidance of doubt, unless otherwise stated in the schedules above. However, if there is any uncertainty over the significance of an item, please consult the Conservation Consultant or Project Architect for clarification.

Wall Finishes:

Item and significance	Action
• Glazed Brick – High Significance	Retain in situ
• Glazed timber screen – High Significance	Retain in situ
• Paint on bricks–Low Significance	Retain in good condition and remove flaking paint.
• Paint on plaster – Low Significance	Retain in good condition and remove flaking paint.
• Paint on glazed bricks – No Significance	Remove paint.
• Wallpaper – No Significance	Remove wallpaper without damaging the underlying plaster.
• Timber panelling – High / Low Significance	Retain in situ panelling of high significance. Remove panelling of low significance.
• Timber stud partition and plyboard – No Significance	Remove and dispose off site.
• MDF board – No Significance	Remove and dispose off site.
• Exposed brick – N/A	
• White tiles – No Significance	Remove and dispose off site.
• Yellow / Blue / Black / Other Tiles – No Significance	Remove and dispose off site.
• Timber effect / modern wall panelling – No Significance	Remove and dispose off site.

Ceiling Finishes:

Item and significance	Action
• Paint to concrete slab - Low Significance	Retain in good condition and remove flaking paint.
• Paint on plaster – Low significance	Retain in good condition and remove flaking paint.
• Ceiling Paper – No Significance	Remove and dispose off site.
• Ceiling Tile – No Significance	Remove and dispose off site.
• Plasterboard – No Significance	Remove and dispose off site.
• MDF board – No Significance	Remove and dispose off site.
• Pavement Lights – N/A	No action at present.
• Exposed concrete – N/A	No action required.

Floor Finishes:

Item and significance	Action
• Painted Concrete – Low Significance	Retain in good condition and remove flaking paint.
• Exposed concrete – N/A	No action required.
• Metal floor hatch – Low Significance	Retain in situ.
• Timber plyboard – No Significance	Remove and dispose off site.
• Wood block – High Significance	Lift and store in the corner of the room it has been lifted from.
• Red Clay Tile – Low Significance	Retain in situ.
• White tile – Low Significance	Retain in situ.
• Glazed tile – Low Significance	Retain in situ.
• Decorative tile – High Significance	Retain in situ.
• Terrazzo – High Significance	Retain in situ.
• Mosaic – High Significance	Retain in situ.
• Vinyl – No Significance	Remove and dispose off site.
• Floor tile – No Significance	Remove and dispose off site.
• Carpet – No Significance	Remove and dispose off site.
• Herringbone brick – High Significance	Retain in situ.
• Clay brick – High Significance	Retain in situ.
• Timber sleepers – Low Significance	Retain in situ.
• Adhesives – No Significance	Remove.
• Metal fixings / Termination strips – No Significance	Remove and dispose off site.
• Plastic stair nosing's – No Significance	Remove and dispose off site.

Fixtures & Fittings:

Item and significance	Action
• Coal Shoot – Medium Significance	Retain in situ.
• Concrete Gulley – Low Significance	Retain in situ.
• Concrete drainage channel – Low Significance	Retain in situ.
• Timber boards – No Significance	Remove and dispose off site.
• Timber battens – No Significance	Remove and dispose off site.
• Early coat hooks – Low significance	Remove and retain for reinstatement.
• Modern coat hooks – No Significance	Remove and dispose off site.
• All screws and nails – No Significance	Remove and dispose off site.
• Urinals – Medium Significance	Remove and retain for reinstatement.

• W.C. - Low	Remove and retain for reinstatement.
• Sink – No Significance	Remove and dispose off site.
• Soap dispenser – No significance	Remove and dispose off site.
• Towel rail – No Significance	Remove and dispose off site.
• Toilet Roll Holder – No Significance	Remove and dispose off site.
• Brackets for sinks and cisterns – No / Low significance	Remove and dispose off site.
• Hanging rails and hooks – Low Significance	Remove and dispose off site.
• Timber shelves – No Significance	Remove and dispose off site.
• Ventilation grill – Low Significance	Retain in situ.
• Mesh vent – No Significance	Remove and dispose off site.
• Lift Doors – Medium Significance	Retain in situ.
• Metal ladders – Low significance	Retain in situ.
• Kitchen cupboards – No Significance	Remove and dispose off site.
• Timber cupboards – No significance	Remove and dispose off site.
• Staircases – High Significance	Retain in situ.
• Original stalls – High Significance	Retain in situ.
• Timber and metal cell benches – High Significance	Retain in situ.
• Fire alarm bell – Low Significance	Retain in situ.
• Timber Racks – Low Significance	Retain in situ.
• Shower tap – No significance	Remove and dispose off site.
• Mirrors – No Significance	Remove and dispose off site.
• Gas lamp outlets – Low significance	Retain in situ.
• Coat rail – No significance	Remove and dispose off site.
• Iron panel – High Significance	Retain in situ.
• Glazed windows – Low Significance	Retain in situ.
• Fireplace surround – Low Significance	Retain in situ.
• Original Fireplace – High Significance	Retain in situ.
• Gas Fire – No Significance	Remove and dispose off site.
• Cell signalling box – High Significance	Retain in situ.
• Fireman's pole – High Significance	Retain in situ.
• Fireman's cupboard – High Significance	Retain in situ.
• Modern timber handrail – No Significance	Remove and dispose off site.
• Original staircase handrails – High Significance	Retain in situ.
• Window security bars – No Significance	Remove and dispose off site.

• Original lifting equipment – Medium Significance	Retain in situ.
• Fuel tank gauge – Low Significance	Retain in situ.
• Suspended ceilings rail / fixings – No Significance	Remove and dispose off site.
• Built in fridge – Low Significance	Remove but retain for reinstatement.
• Radiator Brackets – No Significance	Remove and dispose off site.
• Pipe fixings – No Significance	Remove and dispose off site.
• Fire exit signs – High Significance	Remove but retain for reinstatement.
• Sink unit - No Significance	Remove and dispose off site.
• Fire extinguisher brackets – Low Significance	Remove but retain for reinstatement.
• Kitchen Equipment – Low / No Significance	Remove and dispose off site.
• Clothes drying equipment – High Significance	Retain in situ.
• Key hooks – No significance	Remove and dispose off site.
• No smoking sign – No Significance	Remove and dispose off site.
• Shutters – No Significance	Remove and dispose off site.
• Pinboard – No Significance	Remove and dispose off site.
• Non-original hearths – No Significance	Remove and dispose off site.
• Timber light switch mounts – No Significance	Remove and dispose off site.
• Chain – No Significance	Remove and dispose off site.
• Ceiling hatch – No Significance	Remove and dispose off site.
• Original Bank Safe – High Significance	Retain in situ.

M&E Items:

Item and significance	Action
• Heating Pipes – Low Significance	Remove and dispose off site.
• Plastic pipes – No Significance	Remove and dispose off site.
• Water pipes – No significance	Remove and dispose off site.
• Gas Pipes – Low Significance	Remove and dispose off site.
• Copper pipes – Low Significance	Remove and dispose off site.
• Waste pipes – Low Significance	Retain in situ.
• Modern (plastic) light switches – No Significance	Remove and dispose off site.
• Early light switches – Low Significance	Remove and retain for re-use.
• Modern / other switches – No Significance	Remove and dispose off site.
• Metal conduit – No Significance	Remove and dispose off site.
• Plastic conduit – No Significance	Remove and dispose off site.
• Timber conduit – No Significance	Remove and dispose off site.

• Electrical cables – No significance	Remove and dispose off site.
• Electrical Wires – No Significance	Remove and dispose off site.
• Telephone wires – No Significance	Remove and dispose off site.
• Electrical cable trays – No Significance	Remove and dispose off site.
• Early / original light fittings – Low – High Significance	Remove and retain for re-use.
• Modern light fittings – No Significance	Remove and dispose off site.
• Plug Sockets – Low / No Significance	Remove and dispose off site.
• Cooker switch / socket – No Significance	Remove and dispose off site.
• Early Ventilation fan – Low significance	Remove and retain for re-use.
• Original ventilation equipment and associated items (Musgrave & Co.) – High Significance	Remove and retain for reinstatement.
• Ventilations grilles -low significance	Retain in situ.
• Ventilation ductwork – No significance	Remove and dispose off site.
• Original hot air and ventilation control – Medium significance	Retain in situ.
• Fuse board – Non / Low Significance	Remove and dispose off site.
• Misc. electrical items – No Significance	Remove and dispose off site.
• Early gas meter – Low Significance	Retain in situ.
• Modern gas meter – No Significance	Remove and dispose off site.
• Modern heating equipment – No Significance	Remove and dispose off site.
• Vent-Axia / Thermostat Controls – No Significance	Remove and dispose off site.
• Hot water unit – No significance	Remove and dispose off site.
• Cistern – No Significance	Remove and dispose off site.
• Gas heater – No Significance	Remove and dispose off site.
• Diesel Generator – Low Significance	Remove and dispose off site.
• Telephone distribution equipment – No Significance	Remove and dispose off site.
• Batteries – No Significance	Remove and dispose off site.
• Shower tap – No significance	Remove and dispose off site.
• Original radiators – Low Significance	Remove and retain for re-use.
• Later radiators – No Significance	Remove and dispose off site.
• Speaker – Low significance	Retain in situ or remove and retain for re-use.
• Water tank - Low significance	Remove and dispose off site.

• Electrical heating unit – No Significance	Remove and dispose off site.
• Modern fire alarm unit – No Significance	Remove and dispose off site.
• Security camera – No Significance	Remove and dispose off site.
• Smoke detector – No Significance	Remove and dispose off site.
• Emergency light – No Significance	Remove and dispose off site.

**APPENDIX A – CONTRACTORS METHOD STATEMENTS FOR PROTECTION OF VULNERABLE ITEMS
PRIOR TO SOFT STRIP-OUT WORKS**



Stephen Levrant Heritage Architecture Ltd
CONSERVATION ARCHITECTS & HERITAGE CONSULTANTS

London. 62 British Grove, Chiswick, 0208 748 5501 (Tel)
Manchester. Canada House, 3 Chepstow Street, M1 5FW 0161 247 8335 (Tel)