

3.2 Facade Condition Photographs - 2012

2012 Deterioration of the Facade

During 2012 a member of the Corstorphine + Wright team visited Hexagon Tower to photograph it out of personal interest in the building. When viewing these photos and comparing them to the photographs recorded this month (overleaf) it is apparent that the façade is deteriorating in a progressive manner, qualifying the statement made in the IF Building Consultancy report.

