





General Notes:	
Discovery Caveat:	This schedule records the building assets as at the end of the Soft Strip of the building . However, as the perimeter boxing and other coverings are removed during the MEP strip and other genral alterations further assets of heritage significance will be discovered and will be recorded on later revisions of this schedule which will be issued under the EWN and change control procedures of the contract and will be managed in LBC terms by the Watching Brief Discovery Protocols and Heritage Surgery Review System as already agreed with the LPA.
Protection in situ:	This schedule records the building assets that are to be kept in situ and protected in the building . The fixed and unfixed assets listed will be protected in the same ways as the rest of the building fabric. There is an agreed provision of physical protection measures for the primary routes and vulnerable areas which remains in place throughout the duration of the works (refer to protection provision drawings and specifications issued by Lendlease). In addition to this there is a system of monitoring environmental and vibration conditions in the building to protect against damage. The Work Package Contractors will be responsible for bespoke and proportionate protection (both in terms of working methods, controls and physical guarding) of the building fabric and assets related to mitigation of the risks of particular operations in specific locations and this will be managed in LBC terms by the Heritage/Technical Submittal Approval Protocols and Heritage Surgery Review System as already agreed with the LPA. If it is found that an asset cannot remain insitu, due to unacceptable risk of damage or an unavoidable clash with new installations, a proposal will be put to the Heritage Surgery Team as a heritage/technical submittal for it to be catalogued, carefully removed and taken to MCC store for a later decision to be made about its end use (refer to the accepted approach to the items already on the schedule for reinstatement once the works are complete, re-location in the final scheme, storage in perpetuity as part of the acquisitioned collection or other disposal according to the MCC disposal policy).
KEY:	
Fixed Heritage	Retain in-situ: Item will be retained in situ and protected in-situ eg. a) Items located in back of house areas such as FM storage where the alterations to finishes etc. are limited b) Original built in pieces of furniture that can be re-used in the space and would cause too much damage to remove c) Items which do not obstruct the works such as picture rail hooks
	Storage for re-instatement: Item will be recorded, removed and stored for re-instatement in same location: a) Items that have the potential to be damaged by the works and can be removed b) Items that will obstruct the works but will not cause an issue with the proposed room use
	Storage for re-location: Item will be recorded & removed as the item is not appropriate for re-instatement for the following reasons: a) change in room use resulting in the item being unsuitable for current location b) the structure the item is fixed to is removed as part of the alts and demos c) There is a clash with proposed construction (eg. MEP installation, new walls, raised floor etc.)
Conditioned Storage requirements	Building construction: •The building must be of robust, brick or stone construction. •The building must be well-insulated to maintain a stable temperature. •The building envelope must be watertight and free from the risk of water penetration from piped water or damp. •The roof must be of solid construction without roof lights. •Internal walls and floors should be sealed and non-friable. Heating: •The storage spaces must have low-level, radiant heating to maintain a stable temperature within the range 16-20C and a Relative Humidity (RH) below 65%. Security: •The building must be alarmed for both intruders and fire. These should be connected to a 24-hour call out service. •The building should be monitored by CCTV. Access: All items to be catalogued and a record kept of the storage locations with access to be provided as and when required.
Standard Storage requirements	Building construction: •The building must be of robust construction. •The building envelope must be watertight and free from the risk of water penetration from piped water or damp. •The roof must be of solid construction. •Internal walls and floors should be sealed and non-friable. Access: All items to be catalogued and a record kept of the storage locations with access to be provided as and when required.
Unfixed Heritage	All Items to be removed and stored in room 034b awaiting further review
Highlighted items	These items are on the asbestos register

Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-101-001	Reception/ events	GF-007			Original timber shelving	2	n/a	Fixed Heritage	Shelving	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		



Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-101-002	Reception/ events	GF-007			Picture rail hooks	17	n/a	Fixed Heritage	Picture Rails/Hooks	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-101-003	Reception/ events	GF-007			Low level fixed panelling	Perimeter	n/a	Fixed Heritage	Joinery	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-102.a-001	Store	GF-008b			Historic metal shelving with timber inserts	2	n/a	Fixed Heritage	Shelving	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-102.a-003	Store	GF-008b			Historic pipework	1	n/a	Fixed Heritage	Pipework	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-102.a-004	Store	GF-008b			Heritage hook on wall	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-102.a-005	Store	GF-008b			Strong room door	1	n/a	Fixed Heritage	Doors	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	
BA-OTH-01-102.b-001	Store	GF-008a			Certification safe	1	n/a	Fixed Heritage	Safes	Retain in-situ	Protect during the works as required	Lendlease	MCC		
BA-OTH-01-102.b-002	Store	GF-008a			Bond safe	3	n/a	Fixed Heritage	Safes	Retain in-situ	Protect during the works as required	Lendlease	MCC		
BA-OTH-01-102.b-003	Store	GF-008a		0.25	Conduit	1	Clash with the works	Fixed Heritage	Gas Fittings	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	MEP		
BA-OTH-01-102.b-004	Store	GF-008a			Strong room door	1	n/a	Fixed Heritage	Doors	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	




Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-102-001	Reception/ events	GF-008			Original cupboard	1	n/a	Fixed Heritage	Cupboards	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-102-003	Reception/ events	GF-008			Built in timber bookshelf	1	n/a	Fixed Heritage	Cabinets	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-102-004	Reception/ events	GF-008		0.5	Radiator brackets	8	Room use	Fixed Heritage	Fixtures + Fittings	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	Fit Out	Trip hazard in events space	
BA-OTH-01-102-005	Reception/ events	GF-008			Original sliding door cupboard	1	n/a	Fixed Heritage	Cupboards	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-102-006	Reception/ events	GF-008			Original coat hook	3	n/a	Fixed Heritage	Coat hooks	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-102-009	Reception/ events	GF-008			Radiator	1	n/a	Fixed Heritage	Radiators	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	Fit Out/MEP		
BA-OTH-01-102-010	Reception/ events	GF-008			Low level fixed panelling	Perimeter	n/a	Fixed Heritage	Joinery	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-102-011	Reception/ events	GF-008			Former gas pipe fitting	6	n/a	Fixed Heritage	Gas Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-102-012	Reception/ events	GF-008			Coat Hook	3	n/a	Fixed Heritage	Coat hooks	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-102-013	Reception/ events	GF-008			Timber bench back rest detail	1	n/a	Fixed Heritage	Joinery	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		





Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-103a-001	Reception/ events	GF-009			Built in timber shelf under window	1	n/a	Fixed Heritage	Shelving	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-103a-002	Reception/ events	GF-009			Electrical bell	1	Room use	Fixed Heritage	Fixtures + Fittings	Storage for re-location	MCC to select sample to retain	MCC	Fit Out/MEP	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-103a-003	Reception/ events	GF-009			Telephone system box	1	Room use	Fixed Heritage	Fixtures + Fittings	Storage for re-location	MCC to select sample to retain	MCC	Fit Out/MEP	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-103c-001	Reception/ events	GF-010			Low level fixed panelling	Perimeter	n/a	Fixed Heritage	Joinery	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-103c-002	Reception/ events	GF-010			Built in cupboard with enclosed safe	1	n/a	Fixed Heritage	Safes	Retain in-situ	Protect during the works as required	Lendlease	MCC		
BA-OTH-01-103c-003	Reception/ events	GF-010			Built in cupboard with sliding door	1	n/a	Fixed Heritage	Cupboards	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-103c-004	Reception/ events	GF-010			Box detailing on skirting board	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-103c-005	Reception/ events	GF-010			Light switch	1	n/a	Fixed Heritage	Electrical Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-103c-006	Reception/ events	GF-010			Original floor covering margin	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-GF-C01i-001	Circulation	GF-C01i			Historic telephone or smoke detector box	1	n/a	Fixed Heritage	Conduits/Trunking	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		





Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-GF-C01i-002	Circulation	GF-C01i			Historic Dumb Waiter Doors	1	n/a	Fixed Heritage	Joinery	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-GF-C01i-003	Circulation	GF-C01i			Historic Secretary sign	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-103d-001	Circulation	GF-C01k			Smoke detector	1	Room use	Fixed Heritage	Smoke Detector	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-103d-002	Circulation	GF-C01k			Historic conduit	1	Room use	Fixed Heritage	Conduits/Trunking	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-103d-003	Circulation	GF-C01k		0.25	Historic conduit next to window	1	Room use	Fixed Heritage	Conduits/Trunking	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	Fit Out/MEP		
BA-OTH-01-103e-002	WC	GF-010a	0.25		Mirror	1	n/a	Fixed Heritage	Mirrors	Storage for re-instatement	Item will be recorded, removed and stored for re-instatement in same location	Lendlease	Fit Out		
BA-OTH-01-103e-003	WC	GF-010a			Built in sink/cupboard	1	n/a	Fixed Heritage	Sanitaryware	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-103e-004	WC	GF-010a			Light switch	1	Room use	Fixed Heritage	Electrical Fittings	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-103e-005	WC	GF-010a			Historic boxing in with connected stop tap	1	n/a	Fixed Heritage	Boxing in	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-103e-006	WC	GF-010a			Fitted heritage cupboards	2	n/a	Fixed Heritage	Cupboards	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		



Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-103e-007	WC	GF-010a			Smoke detector	1	Room use	Fixed Heritage	Smoke Detector	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-103e-008	WC	GF-010a			Original coat hooks	3	n/a	Fixed Heritage	Coat hooks	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-103e-009	WC	GF-010a			Light fittings	3	Room use	Fixed Heritage	Electrical Fittings	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-104-001	Family Room	GF-012			Historic boxing in	1	n/a	Fixed Heritage	Boxing in	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-104-002	Family Room	GF-012			Picture rail hooks	1	n/a	Fixed Heritage	Picture Rails/Hooks	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-105-002	WC	GF-014			Wall fixings / pins	8	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-106-001	WC	GF-015 - 018			Picture rail hooks	2	n/a	Fixed Heritage	Picture Rails/Hooks	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-108a-001	ICT cabinet	GF-020a			Strong room door	1	n/a	Fixed Heritage	Doors	Retain in-situ	Item on the Asbestos Refurb Survey Report (Retain in-situ isolate & protect)	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	
BA-OTH-01-109-001	MCC/Meeting room	GF-021			Smoke detector	1	Room use	Fixed Heritage	Smoke Detector	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-109-002	MCC/Meeting room	GF-021			Picture rail hooks	7	n/a	Fixed Heritage	Picture Rails/Hooks	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		





Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-110-001	MCC/Meeting room	GF-022			Picture rail hooks	4	n/a	Fixed Heritage	Picture Rails/Hooks	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-112-001	Welfare	GF-024			Picture rail hooks	3	n/a	Fixed Heritage	Picture Rails/Hooks	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-113-001	MCC/Meeting room	GF-025			Picture rail hooks	6	n/a	Fixed Heritage	Picture Rails/Hooks	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-113-002	MCC/Meeting room	GF-025			Door Cleat	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	
BA-OTH-01-115-001	MCC/Meeting room	GF-026			Picture rail hooks	12	n/a	Fixed Heritage	Picture Rails/Hooks	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-115-002	MCC/Meeting room	GF-026			Vertical metal electrical conduit	1	n/a	Fixed Heritage	Conduits/Trunking	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-115-003	MCC/Meeting room	GF-026			Door Cleat	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	
BA-OTH-01-117-001	Scrutiny Room	GF-027			Built in cabinet	1	n/a	Fixed Heritage	Cabinets	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-117-002	Scrutiny Room	GF-027			Low level perimeter timber panelling	Perimeter	n/a	Fixed Heritage	Joinery	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-117-003	Scrutiny Room	GF-027			Picture rail hooks	4	n/a	Fixed Heritage	Fixtures + Fittings	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		






Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-118-001	Scrutiny Room	GF-027a			Low level perimeter timber panelling	Perimeter	n/a	Fixed Heritage	Joinery	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-118-002	Scrutiny Room	GF-027a			Built in rolling door cabinet	1	n/a	Fixed Heritage	Cabinets	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-118-003	Scrutiny Room	GF-027a			Built in bookcase and shelving	1	n/a	Fixed Heritage	Shelving	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-118-004	Scrutiny Room	GF-027a			Gas light fixing + pipework	3	n/a	Fixed Heritage	Gas Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-118a-001	AV	GF-027c			Strong room door	1	n/a	Fixed Heritage	Doors	Retain in-situ	Item on the Asbestos Refurb Survey Report (Retain in-situ isolate & protect)	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	
BA-OTH-01-118a-002	AV	GF-027c			Coat and hat hook fixing	1	n/a	Fixed Heritage	Coat hooks	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-118a-003	AV	GF-027c			Documents Safe	1	n/a	Fixed Heritage	Safes	Retain in-situ	Protect during the works as required	Lendlease	MCC		
BA-OTH-01-118a-004	AV	GF-027c			Security Shuttering	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-118a-006	AV	GF-027c			Original Panelling	1	n/a	Fixed Heritage	Joinery	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-118a-007	AV	GF-027c			Heating pipework	4	n/a	Fixed Heritage	Pipework	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		





Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-118a-008	AV	GF-027c			Pipework brackets	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-120-001	Circulation	GF-S08		0.25	Heritage fan	1	Room use	Fixed Heritage	Electrical Fittings	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	Fit Out/MEP		
BA-OTH-01-121-001	Catering Office	GF-028			Picture rail	1	n/a	Fixed Heritage	Fixtures + Fittings	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-121-002	Catering Office	GF-028			Picture rail hooks	7	n/a	Fixed Heritage	Fixtures + Fittings	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-123-001	Catering Storage	GF-030			Original coat hooks	1	n/a	Fixed Heritage	Coat hooks	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-123-002	Catering Storage	GF-030			Picture rail hooks	20	n/a	Fixed Heritage	Fixtures + Fittings	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-123-003	Catering Storage	GF-030			Door Cleat	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	
BA-OTH-01-123-003	Catering Storage	GF-030			Original Coat Hooks and Rail	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-124-002	Circulation	GF-C04a	0.1		Original coat hook	1	Room use	Fixed Heritage	Coat hooks	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	Fit Out		
BA-OTH-01-124-003	Circulation	GF-C04a			Door Cleat	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	




Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-124-004	Circulation	GF-C04a			Picture rail hooks	16	n/a	Fixed Heritage	Fixtures + Fittings	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-124-005	Circulation	GF-C04a			Riser cupboard	2	n/a	Fixed Heritage	Cupboards	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-125-001	Finishing Kitchen	GF-031			Picture rail hooks	16	n/a	Fixed Heritage	Fixtures + Fittings	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-125-003	Finishing Kitchen	GF-031			Door Cleat	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	
BA-OTH-01-128-001	Banqueting Room	GF-033			Stair tread covering and nosing in cast iron and rubber combination	1		Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	To be repaired and refixed in situ	
BA-OTH-01-131a-001	Plant Room	GF-034			Smoke detector	1	Room use Room use	Fixed Heritage	Smoke Detector	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-132-001	Circulation	GF-C04c			Picture rail hooks	6	n/a	Fixed Heritage	Picture Rails/Hooks	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-132-003	Circulation	GF-C04c			Light switch	1	Room use	Fixed Heritage	Electrical Fittings	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-132-004	Circulation	GF-C04c			Door Cleat	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	
BA-OTH-01-133-001	Circulation	GF-S10			Door Cleat	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	






Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-134-001	Circulation	GF-C01b			Picture rail hooks	4	n/a	Fixed Heritage	Picture Rails/Hooks	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-134-003	Circulation	GF-C01b		0.1	MCC Signage	1	Room use	Fixed Heritage	Fixtures + Fittings	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	MCC	MCC	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-135-001	staff / visitor reception	GF-001			Light switch	1	Room use	Fixed Heritage	Electrical Fittings	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-135-003	staff / visitor reception	GF-001			Coat hook	1	n/a	Fixed Heritage	Coat hooks	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-135-004	staff / visitor reception	GF-001			Historic coat hook	1	n/a	Fixed Heritage	Coat hooks	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-135-006	staff / visitor reception	GF-001	2		In-built desk/cupboard	1	n/a	Fixed Heritage	Cupboards	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-135-007	staff / visitor reception	GF-001			Smoke detector	2	Room use	Fixed Heritage	Smoke Detector	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-135-009	staff / visitor reception	GF-001			Picture rail	1	n/a	Fixed Heritage	Picture Rails/Hooks	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-136-001	MCC / Public meeting room	GF-002			Low level perimeter panelling	Perimeter	n/a	Fixed Heritage	Joinery	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-136-002	MCC / Public meeting room	GF-002			Picture rails	5	n/a	Fixed Heritage	Picture Rails/Hooks	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		





Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-136-003	MCC / Public meeting room	GF-002			Heritage bell	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-136-004	MCC / Public meeting room	GF-002			Fire gas point	1	n/a	Fixed Heritage	Gas Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-136-006	MCC / Public meeting room	GF-002			3 pin plug socket	1	Room use	Fixed Heritage	Electrical Fittings	Storage for re-location	MCC to select sample to retain	MCC	Fit Out/MEP	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-136-007	MCC / Public meeting room	GF-002			Historic secondary glazing	1	n/a	Fixed Heritage	Glazing	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-136-008	MCC / Public meeting room	GF-002			Door cleat	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	
BA-OTH-01-137-003	Finishing Kitchen	GF-003			Built in partition	1	n/a	Fixed Heritage	Timber Partitions	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-137-005	Finishing Kitchen	GF-003			Historic Riser	1	n/a	Fixed Heritage	Risers	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-137a-001	Circulation	GF-C01d			Smoke detector	1	Room use	Fixed Heritage	Smoke Detector	Storage for re-location	MCC to select sample to retain	MCC	MCC	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-138-001	Visitor Centre	GF-043			Door Cleat	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	
BA-OTH-01-139-001	Visitor Centre	GF-038			Door Cleat	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	



Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-139-002	Visitor Centre	GF-038			Picture hooks	3	n/a	Fixed Heritage	Picture Rails/Hooks	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-140-001	Visitor Centre	GF-042			Original built-in bench	1	n/a	Fixed Heritage	Seating	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	These benches are important as they show the use of the bracketry underneath that carried the pipework to support the benches	
BA-OTH-01-140-002	Visitor Centre	GF-042			Door Cleat	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	
BA-OTH-01-141-001	Visitor Centre	GF-041			Original built in bench	1	n/a	Fixed Heritage	Seating	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	These benches are important as they show the use of the bracketry underneath that carried the pipework to support the benches	
BA-OTH-01-142-001	Visitor Centre	GF-039			Door Cleat	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	
BA-OTH-01-142-002	Visitor Centre	GF-039			Picture hooks	2	n/a	Fixed Heritage	Picture Rails/Hooks	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-144-001	AV	GF-041a			Smoke detector	1	Room use	Fixed Heritage	Smoke Detector	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-145-001	Visitor Centre	GF-040			Original cupboard	1	n/a	Fixed Heritage	Cupboards	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-147-001	Plant Room	GF-044			Original cupboard	1	n/a	Fixed Heritage	Cupboards	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-150-001	Store	GF-050		0	Smoke detector	2	Room use	Fixed Heritage	Smoke Detector	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	





Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-150-002	Store	GF-050			Lead pipework	1	n/a	Fixed Heritage	Pipework	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-150-003	Store	GF-050			Riser cupboard	1	n/a	Fixed Heritage	Cupboards	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-A1.10A-002	Circulation	GF-S13			Pipework	1	n/a	Fixed Heritage	Pipework	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-A1.10A-003	Circulation	GF-S13			Smoke detector	1	Room use	Fixed Heritage	Smoke Detector	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-A1.10A-004	Circulation	GF-S13			Stair railing	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-A1.18-001	Circulation	GF-C03b	1.5		Original timber cupboard + coat hooks	1	Clash with the works	Fixed Heritage	Coat hooks	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	Fit Out/MEP		
BA-OTH-01-A1.18-002	Circulation	GF-C03b			Original electrical conduit + wire armoured cable and boxing -in	1	n/a	Fixed Heritage	Conduits/Trunking	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-A1.18-004	Circulation	GF-C03b			Firefighting equipment	1	Room use	Fixed Heritage	Firehoses + Equipment	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-A1.21-003	Circulation	GF-C02a	0.5		Entrance door	1	n/a	Unfixed Heritage	Doors	Storage for re-instatement	Item will be recorded, removed and stored for re-instatement in same location	Lendlease	Fit Out	Assume this door is from the Princess Street Entrance Screen?	
BA-OTH-01-A1.21-004	Circulation	GF-C02a			Cabin hook fixing	2	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		



Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-A1.28a-001	MCC/Meeting room	GF-023			Fixed bench	1	n/a	Fixed Heritage	Seating	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-A1.41-002	Circulation	GF-C01j			Historic vertical pipework	1	n/a	Fixed Heritage	Pipework	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-A1.47-001	Circulation	GF-C01g		0.25	Original light fitting	1	n/a	Fixed Heritage	Electrical Fittings	Storage for re-instatement	Item will be recorded, removed and stored for re-instatement in same location	Lendlease	Fit Out/MEP		
BA-OTH-01-A1.47-003	Circulation	GF-C01g			Radiator casing North side	1	n/a	Fixed Heritage	Radiators	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-A1.47-003	Circulation	GF-C01g			Radiator casing South side	1	n/a	Fixed Heritage	Radiators	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	Fit Out/MEP		
BA-OTH-01-A1.48-001	Sculpture Hall Café	GF-004		0	Statue plinth	4	Room use	Unfixed Heritage	Misc. Items	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	Enabling		
BA-OTH-01-A1.48-002	Sculpture Hall Café	GF-004		0	Fairbairn Statue	1	Room use	Unfixed Heritage	Misc. Items	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	Enabling		
BA-OTH-01-A1.48-003	Sculpture Hall Café	GF-004			Picture rail hooks	2	n/a	Fixed Heritage	Fixtures + Fittings	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-A1.48-004	Sculpture Hall Café	GF-004			Belgian refugee plaque	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-A1.48-005	Sculpture Hall Café	GF-004		0	1919 plaque	1	Room use	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	Fit Out		



Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-A1.51-001	Circulation	GF-S06			Radiator	1	n/a	Fixed Heritage	Radiators	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-A1.51-001	Circulation	GF-S09			Radiator	1	n/a	Fixed Heritage	Radiators	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-A1.51-002	Circulation	GF-S09			Light switch	1	Room use	Fixed Heritage	Electrical Fittings	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-A1.53A-001	Circulation	GF-C01c		0.25	Historic light	1	n/a	Fixed Heritage	Electrical Fittings	Storage for re-instatement	Item will be recorded, removed and stored for re-instatement in same location	Lendlease	Fit Out/MEP		
BA-OTH-01-A1.53A-003	Circulation	GF-C01c			Smoke detector	1	Room use	Fixed Heritage	Smoke Detector	Storage for re-location	MCC to select sample to retain	MCC	MCC	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-A1.54A-001	Circulation	GF-C01b			Picture rail hooks	7		Fixed Heritage	Picture Rails/Hooks	Storage for re-instatement	Item will be recorded, removed and refurbished for reinstatement or relocation	Lendlease	Fit Out		
BA-OTH-01-A1.54A-002	Circulation	GF-C01b		1	Safe	1	Room use	Unfixed Heritage	Safes	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	MCC	MCC		
BA-OTH-01-A1.54A-004	Circulation	GF-C01b			Smoke detector	1	Room use	Fixed Heritage	Smoke Detector	Storage for re-location	MCC to select sample to retain	MCC	MCC	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-A1.54A-005	Circulation	GF-C01b			Light switch	1	Room use	Fixed Heritage	Electrical Fittings	Storage for re-location	MCC to select sample to retain	MCC	MCC	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-A1.55-001	Lift	GF-C01h	0.25		Fire Alarm Box	2	Room use	Fixed Heritage	Fixtures + Fittings	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell	Fit Out/MEP		




Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-A1.55-002	Lift	GF-C01h	4		Low level cabinet	2	Room use	Fixed Heritage	Cabinets	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell	Fit Out	Items to be relocated to level 05 room 05-009	
BA-OTH-01-A1.55-003	Lift	GF-C01h	5		Large timber and glazed cabinet	1	Room use	Fixed Heritage	Cabinets	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell	Fit Out	Items to be relocated to level 05 room 05-009	
BA-OTH-01-A1.55-004	Lift	GF-C01h			Door Cleat	1	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	See Door schedule for further information: OTH-PUR-TH-ZZ-SCH-A-5802	
BA-OTH-01-A1.55-002	Lift	GF-C01h	4		Low level cabinet and associated fixed glazed screen	2	Room use	Fixed Heritage	Cabinets	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell	Fit Out	Items to be relocated to adjacent doorways	
BA-OTH-01-A1.74-001	Circulation	GF-C05			Light switch	1	Room use	Fixed Heritage	Electrical Fittings	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-A1.78-002	Event Support	GF-049			Original duct + housing	1	n/a	Fixed Heritage	Ducting	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-A1.79-001	WC	GF-047 GF-046 GF-045			Lead pipework + casing	3	n/a	Fixed Heritage	Pipework	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-A1.79-002	WC	GF-047 GF-046 GF-045			Light switch	1	Room use	Fixed Heritage	Electrical Fittings	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-A1.79-003	WC	GF-047 GF-046 GF-045			Coat hook	1	n/a	Fixed Heritage	Coat hooks	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-A1.79-005	Riser	GF-R16			Original storage cupboard screen	1	n/a	Fixed Heritage	Cupboards	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		



Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-A1.79-004	Riser	GF-R16			Original storage cupboard shelf and bracket	1	n/a	Fixed Heritage	Cupboards	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	Shelf needs renewal - shelf bracket requires repair.	
BA-OTH-01-A1.79-006	WC	GF-047 GF-046 GF-045			Historic pipe supports and tank	1	n/a	Fixed Heritage	Pipework	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-A1.79-007	WC	GF-047 GF-046 GF-045			Historic sanitary-ware and pipework	2	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-A1.79-008	WC	GF-047 GF-046 GF-045			Historic Pipe Casinnings	1	n/a	Fixed Heritage	Ducting	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-A1.82-002	Circulation	GF-C02		0.25	Sign Hanging rail	1	n/a	Fixed Heritage	Fixtures + Fittings	Storage for re-instatement	Item will be recorded, removed and stored for re-instatement in same location	Lendlease	Fit Out/MEP	Assuming this goes back in the same position depends on wayfinding strategy / security strategy	
BA-OTH-01-A1.82-003	Circulation	GF-C02	10		Cooper Street Porters boxes	2	Room use	Fixed Heritage	Fixtures + Fittings	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	Fit Out	Fit out team to determine if they require re-location or re-instatement	
BA-OTH-01-A1.82-004	Circulation	GF-C02			Plug socket & electrical conduit	1	n/a	Fixed Heritage	Electrical Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	Assuming Porter's box will be retained as heritage feature - could be fitted out with heritage lamp etc.	
BA-OTH-01-A1.82-005	Circulation	GF-C02			Princess Street Porter's Box	1	n/a	Unfixed Heritage	Misc. Items	Retain in-situ	Protect during the works as required	Lendlease	Fit Out	Fit out team to determine repairs	
BA-OTH-01-A1.82-006	Circulation	GF-C02		0.25	Hanging sign fixings	2	n/a	Fixed Heritage	Fixtures + Fittings	Storage for re-instatement	Item will be recorded, removed and stored for re-instatement in same location	Lendlease	Fit Out/MEP	Assuming this goes back in the same position depends on wayfinding strategy / security strategy	
BA-OTH-01-A1.82-007	Circulation	GF-C02			Built-in corridor seating	5	n/a	Fixed Heritage	Seating	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		



Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-A1.82-008	Circulation	GF-C02			Heritage cuboarding and doors	5	n/a	Fixed Heritage	Cupboards	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	Fit Out		
BA-OTH-01-A1.82-008	Circulation	GF-C02			Heritage Donation Box	5	n/a	Fixed Heritage	Cupboards	Storage for re-instatement	Item will be recorded, removed and stored for re-instatement in same location	Purcell / MCC	Fit Out		
BA-OTH-01-A1.83-001	Circulation	GF-C04			Built-in corridor seating	5		Fixed Heritage	Seating	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-A1.84-001	Cloakroom	GF-006		0.25	Historic gas pipework	1	Room use	Fixed Heritage	Gas Fittings	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Lendlease	MEP		
BA-OTH-01-A1.84c-001	Cloaks	GF-005	1.5		Historic timber door + screen	1	Room use	Fixed Heritage	Doors	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	Fit Out	Screen to be relocated to the new entrance to the cloakroom and restored.	
BA-OTH-01-A1.84c-002	Cloakroom	GF-005			Light switch	1	Room use	Fixed Heritage	Electrical Fittings	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-A1.84c-003	Cloakroom	GF-005			Original Heat Emitter	1	Room use	Fixed Heritage	Pipework	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-AS.3.6-001	Circulation	GF-C01		0	Historic battery	1	Room use	Fixed Heritage	Fixtures + Fittings	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	MCC		
BA-OTH-01-AS.3.6-002	Circulation	GF-C01	0.5		Key Cupboard	1	Room use	Fixed Heritage	Cupboards	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	Fit Out		
BA-OTH-01-AS.3.6-003	Circulation	GF-C01		0.5	Safe Cupboard	1	Room use	Unfixed Heritage	Safes	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	MCC	MCC		



Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-AS.3_2-001	Circulation	GF-S11			Firefighting equipment	1	Room use	Fixed Heritage	Firehoses + Equipment	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
BA-OTH-01-AS.3_2-002	Circulation	GF-S11		0.5	Pipework with enclosed casing	1	Demolition	Fixed Heritage	Pipework	Storage for re-instatement	Item will be recorded, removed and stored for re-instatement in same location	Lendlease	Fit Out/MEP		
BA-OTH-01-AS.3_2-003	Circulation	GF-S11			Original Gas pipe housing	1	n/a	Fixed Heritage	Gas Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-AS.3_2-004	Circulation	GF-S11			Original Gas Light Fitting	1	n/a	Fixed Heritage	Gas Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-AS.8_3-001	Circulation	GF-S05			Light switch	3	n/a	Fixed Heritage	Electrical Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP	Not going to be a public entrance therefor can keep as existing.	
BA-OTH-01-P-037-001	Circulation	Lord Mayors Stair			Original radiator	1	n/a	Fixed Heritage	Radiators	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP	Not going to be a public entrance therefor can keep as existing.	
BA-OTH-01-P-037-002	Circulation	Lord Mayors Stair		0	Original Heat Emitter	1	n/a	Fixed Heritage	Pipework	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-P-037-003	Circulation	Lord Mayors Stair		0	Original Gas Light Lantern, Coat Rail and Hooks, and Bench	1	n/a	Fixed Heritage	Misc. Items	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-P-037-004	Circulation	Lord Mayors Stair			Light fitting + cabling	1	n/a	Fixed Heritage	Electrical Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP	Not going to be a public entrance therefor can keep as existing.	
BA-OTH-01-A1.84b-002	Cloakroom	GF-006	1.5		Historic timber door + screen	1	Room use	Fixed Heritage	Doors	Storage for re-location	Item will be recorded, removed and stored for re-use / re-location	Purcell / MCC	Fit Out	Screen to be relocated to the new entrance to the cloakroom and restored.	



Basic Information							Reason for removal	Asset Category	Item Category	Action	Instruction of next steps	Responsibility	Cluster	Additional notes	Photo
Ref	Proposed room use	Room	Conditioned Storage Estimate sqm	Standard Storage Estimate sqm	Item Description	Quantity	Please specify	Please specify:	Please specify:	Query for:	Please specify:	Please specify:	Please specify:		
BA-OTH-01-A1.84b-004	Cloakroom	GF-006			Curtain wire hooks	3	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-A1.84b-005	Cloakroom	GF-006			Ornate metal peg	3	n/a	Fixed Heritage	Fixtures + Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out		
BA-OTH-01-A1.84b-001	Cloakroom	GF-006			Gas light fitting + pipework	1	n/a	Fixed Heritage	Gas Fittings	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-01-A1.84b-003	Cloakroom	GF-006			Radiators	3	n/a	Fixed Heritage	Radiators	Retain in-situ	Protect during the works as required	Lendlease	Fit Out/MEP		
BA-OTH-GF-ZZ-L04-001	Lift	ZZ-L04			Firefighting equipment	1	Room use	Fixed Heritage	Firehoses + Equipment	Storage for re-location	MCC to select sample to retain	MCC	Enabling	Decommissioned functional installations such as plugs, switches and fire detectors not appropriate for these locations	
TOTAL			31.1	4.6											