




Photograph:	01
Description:	No.23



Photograph:	02
Description:	No.22



Photograph:	03
Description:	No.21



Photograph:	04
Description:	Internal timber framed windows in Apartment 23 overlooking Oxford Road.



Photograph:	05
Description:	Internal timber framed windows in Apartment 23 overlooking Oxford Road.



Photograph:	06
Description:	Internal timber framed windows in Apartment 23 overlooking Sydney Street.



Photograph:	07
Description:	Timber access doors to balcony Oxford Street elevation.



Photograph:	08
Description:	




Photograph:	09
Description:	Extent of window wall Oxford Road side.



Photograph:	10
Description:	Inswinging large windows.



Photograph:	11
Description:	uPVC RWP.



Photograph:	12
Description:	Glazed panel and balustrade.



Photograph:	13
Description:	Glazed panel to the top at soffit.



Photograph:	14
Description:	Glazed panel.



Photograph:	15
Description:	Oxford Road elevation.



Photograph:	16
Description:	Balcony outside No.23.



Photograph:	17
Description:	No.23 access doors Oxford Road.



Photograph:	18
Description:	Corner profile outside No.23.



Photograph:	19
Description:	Detail under window wall.



Photograph:	20
Description:	Extent of window wall Sidney Street side.



Photograph:	21
Description:	Sidney Street elevation.



Photograph:	22
Description:	Glazed panel under soffit.



Photograph:	23
Description:	RWP.



Photograph:	24
Description:	Glazed panel near balustrade between apartments.



Photograph:	25
Description:	Access doors to balcony on Sidney Street.



Photograph:	26
Description:	Sidney Street elevation.



Photograph:	27
Description:	Sidney Street elevation.



Photograph:	28
Description:	Limited access to windows on Sidney Street.



Photograph:	29
Description:	Sidney Street elevation.



Photograph:	30
Description:	RWP on Sidney Street.