Appendix B - Beswick Co-op - "Bottle Tops" retail unit



01. Internals to be redecorated.JPG



02. Internals to be redecorated.JPG

Appendix B - Beswick Co-op - "Bottle Tops" retail unit



03. Damaged stud walls to be replaced.JPG




04. Damaged stud walls to be replaced.JPG

Appendix B - Beswick Co-op - "Bottle Tops" retail unit



05. New vinyl floor coverings to be laid.JPG



06. New vinyl floor coverings to be laid.JPG

Appendix B - Beswick Co-op - "Bottle Tops" retail unit




07. full rewire within shop.JPG



08. New kitchen to be fitted.JPG

Appendix B - Beswick Co-op - "Bottle Tops" retail unit



09. Defective plumbing to be resolved.JPG



10. New sanitaryware to be installed.JPG

Appendix B - Beswick Co-op - "Bottle Tops" retail unit



11. Damaged walls to be repaired.JPG



12. Damaged stud walls to be replaced.JPG

Appendix B - Beswick Co-op - "Bottle Tops" retail unit



13. New vinyl floor coverings to be replaced.JPG



14. Internals to be redecorated.JPG

Appendix B - Beswick Co-op - "Bottle Tops" retail unit



15. Internals to be redecorated.JPG



16. New vinyl floor coverings to be laid.JPG

Appendix B - Beswick Co-op - "Bottle Tops" retail unit



17. Internals to be redecorated.JPG



18. Internals to be redecorated.JPG

Appendix B - Beswick Co-op - "Bottle Tops" retail unit



19. External timbers to be redecorated.JPG



20. Glazing to be reinstated.JPG

Appendix B - Beswick Co-op - "Bottle Tops" retail unit



21. Glazing to be reinstated.JPG



22. New roller shutter to be fitted and boxed in.JPG

Appendix B - Beswick Co-op - "Bottle Tops" retail unit



23. New roller shutter to be fitted and boxed in.JPG



24. Damaged glazing to be replaced.JPG

Appendix B - Beswick Co-op - "Bottle Tops" retail unit




25. Damaged glazing to be replaced.JPG



26. Unauthorised shutter to be removed.JPG

Appendix B - Beswick Co-op - "Bottle Tops" retail unit




27. Unauthorised shutter to be removed.JPG



28. Damaged faience to be repaired.JPG

Appendix B - Beswick Co-op - "Bottle Tops" retail unit



29. Unauthorised signage to be removed.JPG



30. Unauthorised signage to be removed.JPG

Appendix B - Beswick Co-op - "Bottle Tops" retail unit



31. Unauthorised signage to be removed.JPG