

Appendix 2

Tree Stump Schedule and Photographs

Tree Stump Schedule

The table below lists the existing tree stumps located in the line of the original fence location, causing damage to the concrete gravel boards and fence panels and necessitating the moving of the new fence to the current location. **The trees were felled by the Council previously but the stumps were left as shown.**

Stump No.	Distance from East End (Metres)	Stump Girth	Attached Photograph Reference No.
1	0.92	535mm	01
2	7.05	1380mm	02
3	8.22	610mm	03
4	11.06	1490mm	04
5	14.79	1015mm	05
6	16.53	**3335mm (3.3 metres)**	06
7	20.05	950mm	07
8	21.28	1080mm	08



Photo 01: Tree Stump at Distance 0.92m from East End. Girth 535mm



Photo 02: Tree Stump at Distance 7.05m from East End. Girth 1380mm



Photo 03: Tree Stump at Distance 8.22m from East End. Girth 610mm



Photo 04: Tree Stump at Distance 11.06m from East End. Girth 1490mm



Photo 05: Tree Stump at Distance 14.79m from East End. Girth 1015mm



Photo 06: Tree Stump at Distance 16.53m from East End. Girth 3335mm



Photo 07: Tree Stump at Distance 20.05m from East End. Girth 950mm



Photo 08: Tree Stump at Distance 21.28m from East End. Girth 1080mm