Ref.095055 10 Plumpton Walk, Longsight Surveyed: PG

Pic1. Rear of 2 Plumpton Walk



Wall Height: 1970mm

Wall Height: 2350mm

Supply and fit single metal gate to fit existing opening, as detailed on AG5

1860mm

Pic.2 Rear of 10 Plumpton Walk





Wall Height: 2310mm

Wall Height: 1960mm

Supply and fit single metal gate to fit existing opening, as detailed on AG5

1860mm

PLANNING
ACKD
REFUED
RECD 13 JUN 2008