

Photograph 01- Summerfield Existing



Photograph 02- Summerfield Existing



Photograph 03- Existing Radiator 2nd Floor of Summerfield



Photograph 04- Floor covering of shower cubicles



Photograph 05- Ceiling void (Summerfield Wing)



Photograph 06- Manor Existing



Photograph 07- Manor Existing



Photograph 08- Existing shower cubicles-Manor wing



Photograph 08- Existing window