


2 LIME TREES DAMAGEING PROPERTY
CUT BACK TO GIVE 2MT CLEARANCE

REMOVE 1 CHERRY TO CLOSE TO PROP & DRAIN

REMOVE GROUP OF SAPLINGS ACROSS ENTRANCE