Site photographs - 1st Floor Internal - West Wing



1. VIEW TOWARDS HERITAGE APEX OF SUITE
2. VIEW TOWARDS FOUNTAIN STREET ELEVATION
3. GENERAL VIEW TOWARDS TEAPOINT AND ENTRANCE - SHOWING WALL PANELLING (TO BE RETAINED)
4. GENERAL VIEW - EXISTING GLAZED MEETING ROOM (TO BE RETAINED)
5. VIEW FROM INTERIOR OF RETAINED MEETING ROOM INTO OFFICE SPACE.
6. GENERAL VIEW THROUGH OFFICE SPACE SHOWING CEILING BUKHEAD DEATILS (TO BE RETAINED)













Site photographs - 1st Floor Internal East Wing



1. VIEW THROUGH RECEPTION
2. VIEW TOWARDS FOUNTAIN STREET ELEVATION BAY WINDOW.
3. GENERAL VIEW THROUGH INTERNAL MEETING ROOM TO REAR TEAPOINT.
4. GENERAL VIEW TOWARDS TEAPOINT
5. VIEW FROM REAR TOWARDS TEAPOINT AND INTERNAL MEETING ROOM.
6. CEILING DETAIL SHOWING DROPPED SOFFITS, A/C VENTS AND SUSPENDED CEILING.











