
CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Zone 2

Defect Survey

Defect Survey Sheet




Notes

Numbers 53, 54, 79, 80 and 113 are stones with large amounts of repairs in them which look like they could be from where a previous sign, or another object used to be on the face of the building.

Throughout the rest of the zone there are lots of repairs which have what appear to be stitching either side of them and a lot of these are where the system will need to be placed.


CONCRETE REPAIRS LIMITED
multi-disciplined *structural* renovation

Photo References












5


6


7


8


9


10


11



12


13



14


15


16


17


18


19



20


21


22



23


24


25


26


27


28


29


30


31


32


33


34


35


36



37



38


39


40



41


42


43


45
44


46


47


48


49


50


51


52


55


53



54



56


57


58


59


60


61


62


63


64


66
65



67


68


69


70
71
72


73


74
75


76
77



78



79



80


81



82



90
89
87
88
86
85
84
83



91


92
93



94


95


96


97


98


99



100



101



102


103


104


105
106


107


108
109


110


113



111
112


114


115


116


117


123
122
124
121
120
119
118


125


126


127


128


129


130


131


132


133


134


135


136


137


138


139


140


141


142


143


144


145


147
146
148


149


150


151


153


154


155


156


157


158


159